Fair Wear: deposit evidence pack


Demo flat (simulated) · 2-year tenancy · generated 30 October 2026

DEMO PACK. All rooms and damage are generated by Muse Image and labelled simulated. Findings were produced by SAM 3.1 (segmentation) and Muse Spark (judging) and are an aid for the tenant, not legal advice.

Ref	Item	Verdict	Tenant share
E1	bedroom carpet	Damage	71%
E2	bedroom wall	Damage	50%
E3	living-room carpet	Damage	71%
E4	kitchen worktop	Damage	87%
E5	kitchen oven	Cleaning	100%
E6	bathroom bath	Cleaning	100%
E7	living-room wall	Fair Wear & Tear	0%

Tenant share = share of a like-for-like repair a tenant could fairly bear after allowing for the item's useful life and the tenancy length (betterment principle). Cleaning is shown at 100% of reasonable cleaning cost.


E1 · bedroom carpet · Damage · model confidence 82%



The bedroom carpet developed a large dark stain in front of the wardrobes during the two-year tenancy that was not present at move-in.

Carpet is expected to flatten and fade in high-traffic areas.

E2 · bedroom wall · Damage · model confidence 70%



The bedroom wall shows new scuffed and peeling paint patches to the right of the radiator at move-out that were not visible at move-in.

Paint lasts about 4 years; small nail holes and light marks are wear.

E3 · living-room carpet · Damage · model confidence 95%



A large dark brown stain is present in the middle of the living-room carpet at move-out that was clean and uniform at move-in.

Carpet is expected to flatten and fade in high-traffic areas.


E4 · kitchen worktop · Damage · model confidence 82%



After image shows dark circular burn marks on the wooden worktop beside the hob that were not present before.

Light knife marks are wear; burns and deep cuts are damage.


E5 · kitchen oven · Cleaning · model confidence 92%



The oven front was clean at move-in but is covered in grease splatters and food marks at move-out that cleaning would remove.

Grease is a cleaning matter.


E6 · bathroom bath · Cleaning · model confidence 90%



The bath is intact but the white sealant has developed heavy black mould along the edges that was clean before.

Surface wear is expected; chips are damage.

E7 · living-room wall · Fair Wear & Tear · model confidence 70%



The living-room wall shows a few extra small nail-hole marks and light scuffs after two years consistent with normal use.

Paint lasts about 4 years; small nail holes and light marks are wear.

Draft reply to the landlord

Drafted by Muse Spark from the findings above. Review before sending.

Dear Landlord,

Re: Demo flat (simulated) – deposit deductions after 2-year tenancy

Thank you for your deduction list. I reply below to each item as claimed, referring to the photo evidence pack.

E1 – bedroom carpet stain in front of wardrobes: Part-accept. This is damage beyond fair wear and tear. To avoid betterment, cost must be apportioned by useful life. I accept 71%, based on 2 years' use of a 7-year life.

E2 – bedroom wall scuffed/peeling paint right of radiator: Part-accept. This is damage, not fair wear and tear. I accept 50%, based on 2 years' use of a 4-year life.

E3 – living-room carpet large brown stain: Part-accept. This is damage. To avoid betterment, I accept 71%, based on 2 years' use of a 7-year life.

E4 – kitchen worktop burn marks by hob: Part-accept. This is damage. To avoid betterment, I accept 87%, based on 2 years' use of a 15-year life.

E5 – kitchen oven grease and food marks: Accept. This is cleaning, not fair wear and tear. I accept 100% of the reasonable cleaning cost.

E6 – bathroom bath sealant black mould: Accept. This is cleaning. I accept 100% of the reasonable cleaning cost.

E7 – living-room wall nail holes and light scuffs: Dispute. After two years this is fair wear and tear from normal use. I accept 0%.

Please send invoices for the cleaning and like-for-like replacement claimed, with the above apportionment applied. If we cannot agree, I may use the scheme's free dispute resolution.

Kind regards,
Tenant