

CORA Flood Risk Analysis Report


Analysis Summary

Analysis Date	2025-09-03 21:45:00
DEM File	copernicus_dem_25.4500_25.5500_-80.5500_-80.4500.tif
Coordinates	25.500139, -80.500139
Sea Level Rise	0.50m
Sea Wall Applied	No
Tidal Baseline	0.667m
Tidal Station	Virginia Key

Impact Assessment Results

Metric	Result
Flooded Buildings	1
Critical Infrastructure	0
Hospitals Affected	0/0 (0.0%)
Roads Flooded	0.07
Economic Damage	\$11
Population Exposed	44.0K

Flood Inundation Map



Methodology

This analysis was performed using the Coastal Risk Analyzer (CORA) tool. The flood modeling uses a connected flood algorithm that considers topographic connectivity to determine inundation areas. Economic damage estimates are based on building footprints and standardized damage factors. Population exposure calculations utilize WorldPop demographic data where available.

Report generated by CORA v0.4.0 on 2025-09-03 at 21:45:07