

Rue de Terrebonne at night, 2015: parked cars (red) and the buildings' own parking (markers)

LiDAR surfaces by height, trees removed; red = car-height objects at the curbs and in driveways that night; one marker per building: garage as built (1954–55) and/or driveway visible today.





ground, pavement, lawns (< 0.3 m)
low objects: fences, hedges, steps (0.3–0.9 m)
car height (0.9–2.3 m): parked cars
garages, sheds, vans, porches (2.3–3.6 m)
houses (> 3.6 m)
Side where the lane would become parking each winter (the proposal, as the councillor described it)
Garage as built and a driveway or apron today
Garage as built, no driveway or apron visible today
No garage as built, driveway or parking pad today
Neither
Corner building addressed on the cross street

Source: Ville de Montréal, LiDAR aérien 2015 (CC-BY 4.0), height above ground from the point cloud with vegetation returns removed (pdal), 0.2 m cells, hillshaded; parcels: unités d'évaluation foncière (CC-BY 4.0). On the whole street, 183 car-height objects were counted by eye at the Terrebonne curbs that night (north 93, south 90); an automatic detector finds 85. Terrebonne-open-sources, 1954-underwriters-plans-terrebonne-garages.