(Top) Published Figure 15: (a) Experimentally observed crack path [39] and (b) error indicator plot (Pandey & Kumar 2025, CMES, Vol. 144, No. 3, p. 3273)





Figure 15: (**a**) Experimentally observed crack path [39] and (**b**) error indicator plot for a rectangular notched plate with

(Bottom-Left) Reproduced Figure 15(a): Dual-Crack Trajectory Parity Authentic Phase-Field Centerline vs Ambati et al. (2015)



(Bottom-Right) Reproduced Figure 15(b): Multi-State Refinement Corridors Authentic History-Aware Recovery Enclosing Both Fracture Bands

