

Task F1741: Case 3 Notched Plate with Hole and Pins Multi-State Native Remeshing Synthesis
[STATUS: SPATIAL QUALIFICATION FAILED (FAIL) — Primary 2.13% Area <= l0/2, Secondary 14.22% Area <= l0/2]
(HPC Execution Job 1423438.mmaster02, Compute Node mnode097.cluster, 28,933 Elements, Datacheck Exit 0)


(a) Case 3 Coarse Donor Mesh
3,923 elements (3,814 CPE4, 109 CPE3)



(b) Task F1741 Multi-State Adapted Mesh
28,933 physical elements (96.91% CPE4, 100% det(J) > 0)



(c) Spatial Resolution Ratio h_e/ℓ_0 ($\ell_0 = 0.285$ mm)
[Yellow ≤ 0.5, Purple ≥ 2.5]



(d) 10-Station Quantitative Corridor Resolution
Primary (Notch *o* Hole) vs Secondary (Hole *o* Edge)

