




(a) Pre-Peak Ligament Damage Profiles ($u \leq 0.0050$ mm)**(b) Peak-Load Neighborhood ($u \approx 0.0058$ mm)****(c) Post-Peak Complete Crack Traversal ($u = 0.006, 0.007$ mm)****(d) Terminal Solved State ($u \approx 0.0079 - 0.0080$ mm)**