

(a) Authentic Donor Damage $d(\mathbf{x})$
($d_{\max} = 0.9976$, sharp crack core)
(b) Receiver Integration-Point Field (FV1)
($d_{\max} = 0.8842$, smeared crack core)
(c) Crack Ligament Profile ($x = y$)
Peak Smearing & Stiffness Dilution
y [mm]
x [mm]
Damage d [-]
Field Variable FV1 [-]
Donor Job 1 ($d_{\max} \to 1.0$)
Receiver FV1 ($d_{\max} = 0.884$)
Broken Threshold ($d = 0.8$)
Coordinate along diagonal $x = y$ [mm]