

(a) Authentic Donor Damage $d(\mathbf{x})$
($d_{max} = 0.9976$, sharp crack core)
(b) Receiver Integration-Point Field (FV1)
($d_{max} = 0.8842$, smeared crack core)
(c) Crack Ligament Profile ($x = y$)
Peak Smearing & Stiffness Dilution
Damage $d$ [-]
Field Variable FV1 [-]
$x$ [mm]
$y$ [mm]
Coordinate along diagonal $x = y$ [mm]
Donor Job 1 ($d_{max} \to 1.0$)
Receiver FV1 ($d_{max} = 0.884$)
Broken Threshold ($d = 0.8$)