


Figure 14: Triangular Element Subroutine Verification (TRI_JTYPE3_4_ABAQUS_RUNTIME_PATCH_QUALIFIED)



(b) Abaqus Runtime Patch Parity Ledger (Job 1408559)

Phase Field State (Step 2, Mechanical State (Step 1)	Reference CPE3	UEL JTYPE=4	Delta / Parity
	RF_1 at Node 1 (kN)	$+2.019231 \times 10^{-2}$	$+2.019231 \times 10^{-2}$
	RF_2 at Node 1 (kN)	$+4.038462 \times 10^{-3}$	$+4.038462 \times 10^{-3}$
	Elastic Strain Energy E_e	2.221154×10^{-6}	2.2212×10^{-6}
Phase Field State (Step 2, Analytical Formula	Companion SDV	Parity Status	
	Degradation Factor $g(d)$	0.250000	0.250000
	Fracture Energy E_{frac} (m)	1.1250×10^{-6}	1.1250×10^{-6}
	Degraded E_{elas} (mJ)	5.5529×10^{-7}	5.5529×10^{-7}
	Degraded Reaction RF	$0.25 \times RF_{1,0}$	5.048079×10^{-3}