
(a) Recovered Material-Point Damage Field (FV1)
($d_{max} = 0.9976$, Exact 1.000 Parity, Zero Nodal Smearing)
y [mm]
x [mm]
Notch ($a_0 = 0.50$)
Material Integration-Point Damage d [-]
(b) Notch-to-Hole Ligament Damage Profile
Damage d [-]
Ligament Coordinate x [mm]
F1659 USDFLD Direct IP (Max $d = 0.9976$)
F1656 Nodal Smearing Ceiling ($d_{max} = 0.8842$)
Donor Peak Damage ($d = 0.9976$)