



Gate-6B Cause Audit Stage 4: Stress Transfer into Companion Facsimile Layer Audit


(a) UEL/UMAT Architecture & Stress Pathway




(b) Tensile Stress Field {22}\$ [MPa]




(c) Equivalent Mises Stress σ_{VM} [MPa]



(d) Constitutive Stress Component Parity



(e) 5-Region Stress & Error Breakdown



(f) Gate-6B Cause Audit Progress Matrix

Stage	Hypothesis / Scope	Verdict	Localization
Stage 1	Coarse Topology (Tri vs Quad) error 2.9% < 3.0%	TOPOLOGY NOT DOMINANT	NEUTRAL
Stage 2	Boundary Conditions (Lateral Release elements, 400 print dx 0.98->0.12)	PARTIAL CONTROL	BOUNDARY TARGET
Stage 3	Facsimile Mapping (All elem <-> 0 mismatches, parity)	MAPPING NOT DOMINANT	NEUTRAL
Stage 4	Stress Transfer (Facsimile Direct continuum pressure error preserved)	TRANSFER NOT DOMINANT	NEUTRAL
Stage 5	Step & Frame Sensitivity (adaptiveRemesh exact step/frame au)	NOT GOVERNED AUTOMATICALLY	PENDING