




Existing Calibration | $\text{TEX}_{86} \rightarrow T (\text{subT}; \gamma_{200m})$

row a
BAYSPAR (SubT)




R^2 0.57
RMSE 5.8°C



TEXAS | Scaled RI $\rightarrow T (\text{thermoT})$




row b
thermoT

R^2 0.86
RMSE 3.7°C



row c
thermoT + G23

R^2 0.83
RMSE 4.1°C



row d
thermoT + G23 + NO_3^-

R^2 0.82
RMSE 4.2°C

