SnapClaim case study

Terrace-slab crack — measured vs guessed

Ref SC-25D35C5E · 2026-11-02 · scale: 2 INR coin, 25 mm, same plane as the crack

Measurement	Value	Status
Crack length	218.5 mm	Confirmed
Crack width	3 mm	Confirmed
Surface affected	0.73 %	Confirmed
Area	6.51 cm2	Confirmed
Severity	significant	Confirmed

Method


Outlines measured from photo pixels, scaled by the coin diameter (tilt-corrected from its ellipse). Every number cites its evidence receipt.

Verification — evidence gate: passed · skeptic: not run · cross-check: not run

Photo with tape (ground truth)



Photo used for the guess



Measured vs guessed

Tape 227 mm vs measured 218.5 mm (inside ±10%) vs photo-alone guess 315 mm (outside ±10%). Bench case terrace-slab-tape-01.

Receipts: R001 scale_calibration 0.712074 mm_per_px; R002 area_ratio 0.73 percent; R003 region_count 1 count; R004 calibrated_area 6.51 cm2; R005 calibrated_length 218.5 mm; R006 calibrated_width 3 mm; R007 severity_classification significant