CASE STUDY

Terrace-slab crack — measured vs guessed

Ref SC-25D35C5E · 2026-11-02 · scale: 2 INR coin, 25 mm, same plane as the crack

1 · Observed damage



Figure 1 — photo with tape: the measuring tape held along the crack is the ground truth.




Figure 2 — photo used for the guess: the same crack as the app measured it, photo + coin.

In the tenant's words

> *“crack above the slab”*

2 · Measurements

Item	Value	Evidence	Status
Crack length	218.5 mm	R005	Confirmed
Crack width	3 mm	R006	Confirmed
Surface affected	0.73 %	R002	Confirmed
Area	6.51 cm2	R004	Confirmed
Severity	significant	R007	Confirmed

3 · Method

Outlines measured from photo pixels, scaled by the coin diameter (tilt-corrected from its ellipse). Every number cites its evidence receipt.

4 · Verification

Evidence gate: **passed** · Independent skeptic: not run · Mask cross-check: not run

Measured vs guessed

	Value	Reading
Tape truth	227 mm	ground truth
SnapClaim measured	218.5 mm	**inside ±10%**
Photo-alone guess	315 mm	**outside ±10%**

Bench case terrace-slab-tape-01.

Receipts

R001	`scale_calibration 0.712074 mm_per_px`
R002	`area_ratio 0.73 percent`
R003	`region_count 1 count`
R004	`calibrated_area 6.51 cm2`
R005	`calibrated_length 218.5 mm`
R006	`calibrated_width 3 mm`
R007	`severity_classification significant`