


STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-25 22:45:57 | Method: Deep Learning Classification



Metric Parameter	Inspection Value
Class Diagnosis	PAVEMENT_CRACKED
Structure Element	Pavement
Condition Status	DAMAGED
Confidence Score	82.61%
Severity Assessment	Critical
Safety Factor	0.20
Camera Distance	2000 mm
Focal Length	800 px

Measured Avg Width	23.696 mm
Measured Max Width	31.872 mm
Crack Length	257.5 mm
Crack Orientation	45 deg

Engineering Recommendation:

PAVEMENT EVALUATION: Immediate repair mandatory. Restrict access to area. Licensed engineer review within 48 hours.
(Critical Limit: 6.0mm | Allowable Max: 12.0mm) | Measured: 23.70mm