



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:30:37

Oper.: TESTE

Datatable: 3071014.DAT

Program: 3071014_120.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial: 260911 0100-2

Operação: OP_120

Máquina : TESTE

Razao :Teste

Coment:TESTE

Part: DW5 CRB 3.071.014

SerialNo:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Diâmetro (Inferior)						
Mancal A	35,967	-,008	,008	35,967	,000	
Mancal B	35,967	-,008	,008	35,966	-,001	
Mancal C	35,967	-,008	,008	35,965	-,002	
Mancal D	35,967	-,008	,008	35,965	-,002	
Mancal E	35,967	-,008	,008	35,969	,002	
Mancal F Inferior	47,967	-,008	,008	47,969	,002	
Mancal F Superior	47,967	-,008	,008	47,976#	,009	
☒ Diâmetro (Inferior)						
Ø52	51,982	-,009	,009	51,989	,007	
☒ Diâmetro (Central)						
Mancal A	35,967	-,008	,008	35,967	,000	
Mancal B	35,967	-,008	,008	35,969	,002	
Mancal C	35,967	-,008	,008	35,968	,001	
Mancal D	35,967	-,008	,008	35,968	,001	
Mancal E	35,967	-,008	,008	35,972	,005	
Mancal F Inferior	47,967	-,008	,008	47,970	,003	
Mancal F Superior	47,967	-,008	,008	47,978#	,011	
☒ Diâmetro (Central)						
Ø72	71,963	-,037	,037	48,001#	-23,962	
Ø52	51,982	-,009	,009	51,990	,009	
☒ Diâmetro (Superior)						
Mancal A	35,967	-,008	,008	35,969	,002	
Mancal B	35,967	-,008	,008	35,968	,001	
Mancal C	35,967	-,008	,008	35,967	,000	
Mancal D	35,967	-,008	,008	35,967	,000	
Mancal E	35,967	-,008	,008	35,967	,000	
Mancal F Inferior	47,967	-,008	,008	47,965	-,002	
Mancal F Superior	47,967	-,008	,008	47,972	,005	
☒ Diâmetro (Superior)						
Ø52	51,982	-,009	,009	51,984	,002	
☒ Circularidade (Processo)						
Mancal A	,000	,000	,006	,002	,002	
Mancal B	,000	,000	,006	,008#	,008	
Mancal C	,000	,000	,006	,001	,001	
Mancal D	,000	,000	,006	,001	,001	
Mancal E	,000	,000	,006	,002	,002	
Mancal F Inferior	,000	,000	,006	,002	,002	
Mancal F Superior	,000	,000	,006	,002	,002	
☒ Circularidade						
Ø72	,000	,000	,010	,002	,002	
Ø52	,000	,000	,010	,001	,001	
☒ Desvio em Relação aos Mancais						
Mancal A	,000	,000	,030	,002	,002	
Mancal B	,000	,000	,030	,009	,009	
Mancal C	,000	,000	,030	,006	,006	
Mancal D	,000	,000	,030	,007	,007	
Mancal E	,000	,000	,030	,004	,004	
Mancal F Inferior	,000	,000	,030	,002	,002	
Mancal F Superior	,000	,000	,030	,002	,002	

Date: 11/set/26

Time: 09:30:38

Oper.:

Datatable: 3071014.DAT

Program: 3071014_120.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
Desvio em Relação aos Mancais						
Ø72	,000	,000	,020	,007	,007	
Ø52	,000	,000	,020	,001	,001	
Desvio / A-F						
Mancal A	,000	,000	,120	,002	,002	
Mancal B	,000	,000	,120	,014	,014	
Mancal C	,000	,000	,120	,022	,022	
Mancal D	,000	,000	,120	,025	,025	
Mancal E	,000	,000	,120	,017	,017	
Mancal F Inferior	,000	,000	,120	,001	,001	
Mancal F Superior	,000	,000	,120	,000	,000	
Desvio Furos de Centro (Processo)						
Mancal A	,000	,000	,050	,022	,022	
Mancal B	,000	,000	,050	,019	,019	
Mancal C	,000	,000	,050	,012	,012	
Mancal D	,000	,000	,050	,015	,015	
Mancal E	,000	,000	,050	,033	,033	
Mancal F Inferior	,000	,000	,050	,058#	,058	
Mancal F Superior	,000	,000	,050	,062#	,062	
Ø72	,000	,000	,040	,060#	,060	
Ø52	,000	,000	,040	,068#	,068	
Paralelismo Perfil (Adjacentes)						
Mancal A	,000	,000	,015	7,046#	7,046	
Mancal B	,000	,000	,020	,021#	,021	
Mancal C	,000	,000	,020	,012	,012	
Mancal D	,000	,000	,020	,008	,008	
Mancal E	,000	,000	,020	,006	,006	
Mancal F Inferior	,000	,000	,020	,009	,009	
Mancal F Superior	,000	,000	,020	,017	,017	
Ø52	,000	,000	,020	,019	,019	
Paralelismo Eixo						
Mancal A	,000	,000	,020	,002	,002	
Mancal B	,000	,000	,020	,001	,001	
Mancal C	,000	,000	,020	,001	,001	
Mancal D	,000	,000	,020	,001	,001	
Mancal E	,000	,000	,020	,004	,004	
Mancal F Inferior	,000	,000	,020	,026#	,026	
Mancal F Superior	,000	,000	,020	,028#	,028	
Cilindricidade						
Mancal A	,000	,000	,020	,008	,008	
Mancal B	,000	,000	,020	,015	,015	
Mancal C	,000	,000	,020	,005	,005	
Mancal D	,000	,000	,020	,005	,005	
Mancal E	,000	,000	,020	,019	,019	
Mancal F Inferior	,000	,000	,020	,035#	,035	
Mancal F Superior	,000	,000	,020	,037#	,037	
Referencia 1 Face de Referencia						
Ângulo entre as superfícies U-Z	40,000	-,007	,007	41,960#	1,960	
Referencia 1 Face de Referencia						
Distancia U para o Eixo de Rot	39,700	-,050	,050	25,959#	-13,741	
Referencia 1 Face de Referencia						
Distancia Z para o Eixo de Rot	39,700	-,050	,050	25,975#	-13,725	

Date: 11/set/26

Time: 09:30:38

Oper.:

Datatable: 3071014.DAT

Program: 3071014_120.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
/ Desvio Circulo Base Furos de Centro (Processo)						
A1	,000	,000	,050	,631#	,631	
CRB1	,000	,000	,050	,013	,013	
A2	,000	,000	,050	,014	,014	
CRB2	,000	,000	,050	,021	,021	
A3	,000	,000	,050	,009	,009	
CRB3	,000	,000	,050	,014	,014	
A4	,000	,000	,050	,009	,009	
CRB4	,000	,000	,050	,790#	,790	
A5	,000	,000	,050	,048	,048	
CRB5	,000	,000	,050	,032	,032	
Raio do Circulo Base						
A1	25,000	-,100	,100	25,006	,006	
CRB1	32,000	-,100	,100	32,014	,014	
A2	25,000	-,100	,100	24,998	-,002	
CRB2	32,000	-,100	,100	32,016	,016	
A3	25,000	-,100	,100	25,005	,005	
CRB3	32,000	-,100	,100	32,011	,011	
A4	25,000	-,100	,100	24,999	-,001	
CRB4	32,000	-,100	,100	32,010	,010	
A5	25,000	-,100	,100	24,996	-,004	
CRB5	32,000	-,100	,100	32,018	,018	
/ Desvio Circulo Base (Mancais Adjacentes)						
A1	,000	,000	,040	,002	,002	
CRB1	,000	,000	,040	,004	,004	
A2	,000	,000	,040	,002	,002	
CRB2	,000	,000	,040	,002	,002	
A3	,000	,000	,040	,003	,003	
CRB3	,000	,000	,040	,003	,003	
A4	,000	,000	,040	,002	,002	
CRB4	,000	,000	,040	,005	,005	
A5	,000	,000	,040	,009	,009	
CRB5	,000	,000	,040	,019	,019	
// Paralelismo Perfil (Mancais Adjacentes)						
A1	,000	,000	,020	,505#	,505	
CRB1	,000	,000	,020	10,912#	10,912	
A2	,000	,000	,020	2,591#	2,591	
CRB2	,000	,000	,020	,887#	,887	
A3	,000	,000	,020	1,754#	1,754	
CRB3	,000	,000	,020	8,335#	8,335	
A4	,000	,000	,020	1,609#	1,609	
CRB4	,000	,000	,020	,031#	,031	
A5	,000	,000	,020	1,313#	1,313	
CRB5	,000	,000	,020	,001	,001	

Date: 11/set/26

Time: 09:30:38

Oper.:

Datatable: 3071014.DAT

Program: 3071014_120.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Côncavo/Convexo						
A1	,000	-,005	,005	,786#	,786	
CRB1	,000	-,005	,005	,122#	,122	
A2	,000	-,005	,005	,354#	,354	
CRB2	,000	-,005	,005	,108#	,108	
A3	,000	-,005	,005	,015#	,015	
CRB3	,000	-,005	,005	,157#	,157	
A4	,000	-,005	,005	-,001	-,001	
CRB4	,000	-,005	,005	,278#	,278	
A5	,000	-,005	,005	,001	,001	
CRB5	,000	-,005	,005	,158#	,158	
☒ Paralelismo (Mancais Adjacentes)						
A1	,000	,000	,020	2,991#	2,991	
CRB1	,000	,000	,020	,473#	,473	
A2	,000	,000	,020	1,387#	1,387	
CRB2	,000	,000	,020	,423#	,423	
A3	,000	,000	,020	,060#	,060	
CRB3	,000	,000	,020	,587#	,587	
A4	,000	,000	,020	,003	,003	
CRB4	,000	,000	,020	,960#	,960	
A5	,000	,000	,020	,003	,003	
CRB5	,000	,000	,020	,579#	,579	
☒ Ângulo Referência U-Z						
A1	58,000	-,100	,100	343,953#	285,953	
CRB1	204,500	-,100	,100	130,442#	-74,058	
A2	347,800	-,100	,100	273,745#	-74,055	
CRB2	134,400	-,100	,100	60,348#	-74,052	
A3	134,200	-,100	,100	60,148#	-74,052	
CRB3	280,800	-,100	,100	206,748#	-74,052	
A4	280,600	-,100	,100	206,560#	-74,040	
CRB4	67,200	-,100	,100	353,143#	285,943	
A5	210,500	-,100	,100	136,455#	-74,045	
CRB5	357,000	-,100	,100	282,951#	-74,049	
☒ Erro Ângulo para Referência A1 (Processo)						
A1	,000	-,125	,125	,000	,000	
CRB1	,000	-,125	,125	,011	,011	
A2	,000	-,125	,125	,008	,008	
CRB2	,000	-,125	,125	,005	,005	
A3	,000	-,125	,125	,005	,005	
CRB3	,000	-,125	,125	,005	,005	
A4	,000	-,125	,125	-,007	-,007	
CRB4	,000	-,125	,125	,010	,010	
A5	,000	-,125	,125	-,002	-,002	
CRB5	,000	-,125	,125	,002	,002	
☒ Erro de Perfil do Cículo Base						
A1	,000	-,025	,025	,002	,002	
CRB1	,000	-,025	,025	-,015	-,015	
A2	,000	-,025	,025	-,001	-,001	
CRB2	,000	-,025	,025	-,013	-,013	
A3	,000	-,025	,025	-,002	-,002	
CRB3	,000	-,025	,025	-,014	-,014	
A4	,000	-,025	,025	-,001	-,001	
CRB4	,000	-,025	,025	-,015	-,015	
A5	,000	-,025	,025	,006	,006	
CRB5	,000	-,025	,025	-,005	-,005	



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 11/set/26

Time: 09:30:39

Oper.:

Datatable: 3071014.DAT

Program: 3071014_120.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)


Cam: 50 upr (Gauss)


Part : DW5 CRB 3.071.014


Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☐ Erro de Perfil Abertura do Flanco						
A1	,000	-,050	,050	,028	,028	
CRB1	,000	-,050	,050	,015	,015	
A2	,000	-,050	,050	,023	,023	
CRB2	,000	-,050	,050	,015	,015	
A3	,000	-,050	,050	,022	,022	
CRB3	,000	-,050	,050	,016	,016	
A4	,000	-,050	,050	,021	,021	
CRB4	,000	-,050	,050	,017	,017	
A5	,000	-,050	,050	,031	,031	
CRB5	,000	-,050	,050	-,020	-,020	
☐ Erro de Perfil Topo						
A1	,000	-,100	,100	,019	,019	
CRB1	,000	-,025	,025	-,013	-,013	
A2	,000	-,100	,100	,019	,019	
CRB2	,000	-,025	,025	-,013	-,013	
A3	,000	-,100	,100	,018	,018	
CRB3	,000	-,025	,025	-,012	-,012	
A4	,000	-,100	,100	,016	,016	
CRB4	,000	-,025	,025	-,011	-,011	
A5	,000	-,100	,100	,030	,030	
CRB5	,000	-,025	,025	-,022	-,022	
☐ Erro de Perfil Fechamento do Flanco						
A1	,000	-,050	,050	,020	,020	
CRB1	,000	-,050	,050	,022	,022	
A2	,000	-,050	,050	,016	,016	
CRB2	,000	-,050	,050	,018	,018	
A3	,000	-,050	,050	,015	,015	
CRB3	,000	-,050	,050	,018	,018	
A4	,000	-,050	,050	,014	,014	
CRB4	,000	-,050	,050	,018	,018	
A5	,000	-,050	,050	,023	,023	
CRB5	,000	-,050	,050	-,026	-,026	
☐ Desvio de Velocidade						
A1	,000	-,010	,010	,003	,003	
CRB1	,000	-,010	,010	,004	,004	
A2	,000	-,010	,010	,003	,003	
CRB2	,000	-,010	,010	,004	,004	
A3	,000	-,010	,010	,003	,003	
CRB3	,000	-,010	,010	,004	,004	
A4	,000	-,010	,010	,003	,003	
CRB4	,000	-,010	,010	,003	,003	
A5	,000	-,010	,010	,003	,003	
CRB5	,000	-,010	,010	,004	,004	









ADCOLE

Model 911



Scania

Brazil

Date: 11/set/26

Time: 09:30:45

Part: 3071014

SerNo:

