



Model 911 SN-8609

Scania Brazil
Camshaft Measurement

Date: 18/mar/26

Time: 13:39:30

Oper.: PEDRO

Datatable: 3071014.DAT

Program: 3071014_190.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial: 2345665433

Operação: OP_120

Máquina : Landis_B

Razao :Teste

Coment:edef

Part: DW5 CRB 3.071.014

SerialNo:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Diâmetro (Inferior)						
Mancal A	36,000	-,050	-,025	35,964	-,036	
Mancal B	36,000	-,050	-,025	35,970	-,030	
Mancal C	36,000	-,050	-,025	35,967	-,033	
Mancal D	36,000	-,050	-,025	35,974	-,026	
Mancal E	36,000	-,050	-,025	47,973#	11,973	
Mancal F Inferior	48,000	-,050	-,025	47,978#	-,022	
Mancal F Superior	48,000	-,050	-,025	72,009#	24,009	
☒ Diâmetro (Inferior) Ø52	52,000	-,029	-,010	94,892#	42,892	
☒ Diâmetro (Central)						
Mancal A	36,000	-,050	-,025	35,970	-,030	
Mancal B	36,000	-,050	-,025	35,969	-,031	
Mancal C	36,000	-,050	-,025	35,971	-,029	
Mancal D	36,000	-,050	-,025	35,979#	-,021	
Mancal E	36,000	-,050	-,025	35,981#	-,019	
Mancal F Inferior	48,000	-,050	-,025	47,988#	-,012	
Mancal F Superior	48,000	-,050	-,025	47,990#	-,010	
☒ Diâmetro (Central) Ø72	72,000	-,074	,000	51,998#	-20,002	
Ø52	52,000	-,029	-,010	51,994#	-,006	
☒ Diâmetro (Superior)						
Mancal A	36,000	-,050	-,025	35,967	-,033	
Mancal B	36,000	-,050	-,025	35,962	-,038	
Mancal C	36,000	-,050	-,025	35,966	-,034	
Mancal D	36,000	-,050	-,025	35,964	-,036	
Mancal E	36,000	-,050	-,025	35,969	-,031	
Mancal F Inferior	48,000	-,050	-,025	47,970	-,030	
Mancal F Superior	48,000	-,050	-,025	47,974	-,026	
☒ Diâmetro (Superior) Ø52	52,000	-,029	-,010	51,993#	-,007	
☐ Circularidade (Processo)						
Mancal A	,000	,000	,006	,002	,002	
Mancal B	,000	,000	,006	,004	,004	
Mancal C	,000	,000	,006	,001	,001	
Mancal D	,000	,000	,006	,016#	,016	
Mancal E	,000	,000	,006	,002	,002	
Mancal F Inferior	,000	,000	,006	,003	,003	
Mancal F Superior	,000	,000	,006	,005	,005	
☐ Circularidade						
Ø72	,000	,000	,010	,020#	,020	
Ø52	,000	,000	,010	,002	,002	
☒ Desvio em Relação aos Mancais						
Mancal A	,000	,000	,030	,002	,002	
Mancal B	,000	,000	,030	,021	,021	
Mancal C	,000	,000	,030	,033#	,033	
Mancal D	,000	,000	,030	,044#	,044	
Mancal E	,000	,000	,030	,023	,023	
Mancal F Inferior	,000	,000	,030	,003	,003	
Mancal F Superior	,000	,000	,030	,008	,008	

Date: 18/mar/26

Time: 13:39:30

Oper.:

Datatable: 3071014.DAT

Program: 3071014_190.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
Desvio em Relação aos Mancais						
Ø72	,000	,000	,020	,030#	,030	
Ø52	,000	,000	,020	,002	,002	
Desvio / A-F						
Mancal A	,000	,000	,120	,002	,002	
Mancal B	,000	,000	,120	,019	,019	
Mancal C	,000	,000	,120	,005	,005	
Mancal D	,000	,000	,120	,040	,040	
Mancal E	,000	,000	,120	,006	,006	
Mancal F Inferior	,000	,000	,120	,001	,001	
Mancal F Superior	,000	,000	,120	,000	,000	
Desvio Furos de Centro (Processo)						
Mancal A	,000	,000	,050	,023	,023	
Mancal B	,000	,000	,050	,036	,036	
Mancal C	,000	,000	,050	,018	,018	
Mancal D	,000	,000	,050	,044	,044	
Mancal E	,000	,000	,050	,028	,028	
Mancal F Inferior	,000	,000	,050	,028	,028	
Mancal F Superior	,000	,000	,050	,030	,030	
Ø72	,000	,000	,040	,036	,036	
Ø52	,000	,000	,040	,035	,035	
Paralelismo Perfil (Adjacentes)						
Mancal A	,000	,000	,015	,014	,014	
Mancal B	,000	,000	,020	,027#	,027	
Mancal C	,000	,000	,020	,016	,016	
Mancal D	,000	,000	,020	,032#	,032	
Mancal E	,000	,000	,020	,009	,009	
Mancal F Inferior	,000	,000	,020	,007	,007	
Mancal F Superior	,000	,000	,020	,008	,008	
Ø52	,000	,000	,020	,023#	,023	
Paralelismo Eixo						
Mancal A	,000	,000	,020	,005	,005	
Mancal B	,000	,000	,020	,020	,020	
Mancal C	,000	,000	,020	,014	,014	
Mancal D	,000	,000	,020	,029#	,029	
Mancal E	,000	,000	,020	,006	,006	
Mancal F Inferior	,000	,000	,020	,023#	,023	
Mancal F Superior	,000	,000	,020	,015	,015	
Cilindricidade						
Mancal A	,000	,000	,020	,017	,017	
Mancal B	,000	,000	,020	,018	,018	
Mancal C	,000	,000	,020	,022#	,022	
Mancal D	,000	,000	,020	,031#	,031	
Mancal E	,000	,000	,020	6,017#	6,017	
Mancal F Inferior	,000	,000	,020	,020#	,020	
Mancal F Superior	,000	,000	,020	12,019#	12,019	
Referencia 1 Face de Referencia						
Ângulo entre as superfícies U-Z	40,000	-,007	,007	136,047#	96,047	
Referencia 1 Face de Referencia						
Distancia U para o Eixo de Rot	39,700	-,050	,050	17,063#	-22,637	
Referencia 1 Face de Referencia						
Distancia Z para o Eixo de Rot	39,700	-,050	,050	17,063#	-22,637	

Date: 18/mar/26

Time: 13:39:31

Oper.:

Datatable: 3071014.DAT

Program: 3071014_190.S01

ReportNo: rept1300.CAM

Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
/ Desvio Circulo Base Furos de Centro (Processo)						
A1	,000	,000	,050	,016	,016	
CRB1	,000	,000	,050	,029	,029	
A2	,000	,000	,050	,025	,025	
CRB2	,000	,000	,050	,014	,014	
A3	,000	,000	,050	,025	,025	
CRB3	,000	,000	,050	,016	,016	
A4	,000	,000	,050	,012	,012	
CRB4	,000	,000	,050	,021	,021	
A5	,000	,000	,050	,024	,024	
CRB5	,000	,000	,050	,021	,021	
Raio do Circulo Base						
A1	25,000	-,100	,100	24,992	-,008	
CRB1	32,000	-,100	,100	32,053	,053	
A2	25,000	-,100	,100	24,998	-,002	
CRB2	32,000	-,100	,100	32,052	,052	
A3	25,000	-,100	,100	24,998	-,002	
CRB3	32,000	-,100	,100	32,051	,051	
A4	25,000	-,100	,100	25,005	,005	
CRB4	32,000	-,100	,100	32,054	,054	
A5	25,000	-,100	,100	24,992	-,008	
CRB5	32,000	-,100	,100	32,054	,054	
/ Desvio Circulo Base (Mancais Adjacentes)						
A1	,000	,000	,040	,002	,002	
CRB1	,000	,000	,040	,004	,004	
A2	,000	,000	,040	,003	,003	
CRB2	,000	,000	,040	,009	,009	
A3	,000	,000	,040	,004	,004	
CRB3	,000	,000	,040	,004	,004	
A4	,000	,000	,040	,007	,007	
CRB4	,000	,000	,040	,004	,004	
A5	,000	,000	,040	,005	,005	
CRB5	,000	,000	,040	,007	,007	
// Paralelismo Perfil (Mancais Adjacentes)						
A1	,000	,000	,020	4,509#	4,509	
CRB1	,000	,000	,020	,116#	,116	
A2	,000	,000	,020	10,924#	10,924	
CRB2	,000	,000	,020	2,551#	2,551	
A3	,000	,000	,020	3,578#	3,578	
CRB3	,000	,000	,020	2,249#	2,249	
A4	,000	,000	,020	3,982#	3,982	
CRB4	,000	,000	,020	2,107#	2,107	
A5	,000	,000	,020	,019	,019	
CRB5	,000	,000	,020	1,214#	1,214	

Date: 18/mar/26

Time: 13:39:31

Oper.:

Datatable: 3071014.DAT

Program: 3071014_190.S01

ReportNo: rept1300.CAM


Filter

Journal: 50 upr (Gauss)

Cam: 50 upr (Gauss)

Part : DW5 CRB 3.071.014

Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☒ Côncavo/Convexo						
A1	,000	-,005	,005	4,601#	4,601	
CRB1	,000	-,005	,005	3,694#	3,694	
A2	,000	-,005	,005	-2,813#	-2,813	
CRB2	,000	-,005	,005	2,950#	2,950	
A3	,000	-,005	,005	-2,742#	-2,742	
CRB3	,000	-,005	,005	2,874#	2,874	
A4	,000	-,005	,005	-2,724#	-2,724	
CRB4	,000	-,005	,005	2,816#	2,816	
A5	,000	-,005	,005	-2,608#	-2,608	
CRB5	,000	-,005	,005	2,867#	2,867	
☒ Paralelismo (Mancais Adjacentes)						
A1	,000	,000	,020	3,935#	3,935	
CRB1	,000	,000	,020	,741#	,741	
A2	,000	,000	,020	4,687#	4,687	
CRB2	,000	,000	,020	3,848#	3,848	
A3	,000	,000	,020	3,698#	3,698	
CRB3	,000	,000	,020	4,115#	4,115	
A4	,000	,000	,020	3,268#	3,268	
CRB4	,000	,000	,020	4,330#	4,330	
A5	,000	,000	,020	3,410#	3,410	
CRB5	,000	,000	,020	4,295#	4,295	
☒ Ângulo Referência U-Z						
A1	58,000	-,100	,100	266,355#	208,355	
CRB1	204,500	-,100	,100	52,881#	-151,619	
A2	347,800	-,100	,100	196,158#	-151,642	
CRB2	134,400	-,100	,100	342,762#	208,362	
A3	134,200	-,100	,100	342,559#	208,359	
CRB3	280,800	-,100	,100	129,155#	-151,645	
A4	280,600	-,100	,100	128,963#	-151,637	
CRB4	67,200	-,100	,100	275,573#	208,373	
A5	210,500	-,100	,100	58,833#	-151,667	
CRB5	357,000	-,100	,100	205,367#	-151,633	
☒ Erro Ângulo para Referência A1 (Processo)						
A1	,000	-,125	,125	,000	,000	
CRB1	,000	-,125	,125	-,026	-,026	
A2	,000	-,125	,125	-,003	-,003	
CRB2	,000	-,125	,125	-,007	-,007	
A3	,000	-,125	,125	-,004	-,004	
CRB3	,000	-,125	,125	,000	,000	
A4	,000	-,125	,125	-,008	-,008	
CRB4	,000	-,125	,125	-,018	-,018	
A5	,000	-,125	,125	,022	,022	
CRB5	,000	-,125	,125	-,012	-,012	
☒ Erro de Perfil do Cículo Base						
A1	,000	-,025	,025	,001	,001	
CRB1	,000	-,025	,025	-,005	-,005	
A2	,000	-,025	,025	-,002	-,002	
CRB2	,000	-,025	,025	-,010	-,010	
A3	,000	-,025	,025	,003	,003	
CRB3	,000	-,025	,025	-,009	-,009	
A4	,000	-,025	,025	,004	,004	
CRB4	,000	-,025	,025	-,009	-,009	
A5	,000	-,025	,025	-,004	-,004	
CRB5	,000	-,025	,025	-,009	-,009	



Model 911 SN-8609


Scania Brazil
Camshaft MeasurementDate: 18/mar/26
Time: 13:39:31
Oper.:Datatable: 3071014.DAT
Program: 3071014_190.S01
ReportNo: rept1300.CAMFilter
Journal: 50 upr (Gauss)
Cam: 50 upr (Gauss)


Part : DW5 CRB 3.071.014


Serial:

Nome	Nominal	Mínimo Tolerância	Máximo Tolerância	Medido	Desvio	Gráfico.
☐ Erro de Perfil Abertura do Flanco						
A1	,000	-,050	,050	,033	,033	
CRB1	,000	-,050	,050	,010	,010	
A2	,000	-,050	,050	,028	,028	
CRB2	,000	-,050	,050	,018	,018	
A3	,000	-,050	,050	,029	,029	
CRB3	,000	-,050	,050	,015	,015	
A4	,000	-,050	,050	,030	,030	
CRB4	,000	-,050	,050	,013	,013	
A5	,000	-,050	,050	,029	,029	
CRB5	,000	-,050	,050	,015	,015	
☐ Erro de Perfil Topo						
A1	,000	-,100	,100	,044	,044	
CRB1	,000	-,025	,025	-,008	-,008	
A2	,000	-,100	,100	,038	,038	
CRB2	,000	-,025	,025	-,003	-,003	
A3	,000	-,100	,100	,040	,040	
CRB3	,000	-,025	,025	-,007	-,007	
A4	,000	-,100	,100	,040	,040	
CRB4	,000	-,025	,025	-,007	-,007	
A5	,000	-,100	,100	,039	,039	
CRB5	,000	-,025	,025	-,004	-,004	
☐ Erro de Perfil Fechamento do Flanco						
A1	,000	-,050	,050	,025	,025	
CRB1	,000	-,050	,050	,014	,014	
A2	,000	-,050	,050	,020	,020	
CRB2	,000	-,050	,050	-,018	-,018	
A3	,000	-,050	,050	,021	,021	
CRB3	,000	-,050	,050	-,014	-,014	
A4	,000	-,050	,050	,020	,020	
CRB4	,000	-,050	,050	,015	,015	
A5	,000	-,050	,050	,020	,020	
CRB5	,000	-,050	,050	-,019	-,019	
☐ Desvio de Velocidade						
A1	,000	-,010	,010	,003	,003	
CRB1	,000	-,010	,010	,002	,002	
A2	,000	-,010	,010	,003	,003	
CRB2	,000	-,010	,010	,002	,002	
A3	,000	-,010	,010	,003	,003	
CRB3	,000	-,010	,010	,002	,002	
A4	,000	-,010	,010	,003	,003	
CRB4	,000	-,010	,010	,002	,002	
A5	,000	-,010	,010	,003	,003	
CRB5	,000	-,010	,010	,002	,002	









ADCOLE

Scania

Date: 18/mar/26

Time: 13:39:38

Model 911

Brazil

Part: 3071014

SerNo:

