
BIM.Fundamentals Assignment 2


Door Clearance Check

- 1. The doors of offices ECO 14, 19, and 26 do not meet the required clearance due to nearby furniture placement.
- 2. Move the Furniture away from the Door to meet the required clearance space.




Window Area Ratio Check

- 1. In offices ECO 23, 11, and 16, the ratio between window area and room area exceeds 50%, which violates the requirement.
- 2. Reduce the window area or increase the room size to fulfill the requirement.




Space Accessibility Check

- 1. Office ECO 4 is inaccessible due to the lack of a connecting door.
- 2. A door should be added to this space to ensure proper accessibility.




Space Area Check

- 1. The confidential meeting room CMR9 has an area smaller than 5 m², which violates the minimum area requirement.
- 2. The room layout should be adjusted or merged with adjacent space to meet the required minimum of 5 m².



Wrong Property Set Check

- 1. Wall.2.38 is marked as isExternal = true, but it is located on the inner side of the building, which violates the definition of an external wall.
- 2. Reclassify this wall as internal (isExternal = false)



E2 Power supply room[PSR6], Power supply room[PSR5], Breakout space[BKS3]