

Car Damage Detector & Reporter

Upload a car image...




Drag and drop file here

Limit 200MB per file • JPG, JPEG, PNG, WEBP




damaged_car_3.jpg 28.3KB

Original Image



Detected Damage Highlighted



Damage Analysis Report

Okay, here's a detailed damage assessment of the vehicle in the image:

Overall Impression: This vehicle has sustained a severe front-end collision. The front of the vehicle is heavily crumpled and damaged.

Specific Damage Breakdown:

- · Headlight & Assembly: The headlight assembly is completely detached and lying on the ground. The damage extends significantly into the front bumper.
- Front Bumper: The front bumper is severely crushed, torn, and detached from the vehicle's structure. It appears to be missing much of its upper portion.
- · Hood: The hood is severely dented and crumpled, with possible damage to internal components.
- Grille: The grille is crumpled and likely damaged.
- Front Wheel Well: The front wheel well is crushed and impacted, possibly affecting suspension components.
- Front Suspension: It appears the damage extends to the front suspension components, given the extent of the wheel well damage.
- Radiator: The radiator is exposed and likely damaged, along with its support structure.
- Wheel: The front wheel is intact but sits at an abnormal angle, indicating possible damage to the hub and potentially suspension.

Severity Assessment:

• Severe: This damage is categorized as severe due to the extensive structural damage, particularly to the front end. It will require significant repairs.

Disclaimer: This assessment is based solely on the provided image. A full, on-site inspection would be required for a complete damage evaluation.

Would you like me to focus on a specific aspect of the damage, such as the suspension or potential repair costs (though I can't give actual costs)?