



A

Supervised probe on held-out TFs (edge features only)




B

Recovery collapses at the construction covariates



C

Degree features: no rescue



D

Per-TF recovery spread

