

Task 1 QA Report

Automation & QA Developer Take-Home Skills Assessment

Candidate Name	Piyush Kumar
Tested Application	TaskPilot web application (with TaskTracker branding visible in multiple sections)
Live URL	https://taskpilot-swart.vercel.app/
Repository / Project Context	Piyushkr001/tasktracker / TaskPilot deployment
Application Type	Task management / productivity web application
Testing Type	Manual QA, functional testing, navigation testing, auth flow review, UX review, responsiveness review
Test Scope	Public landing page, sign-in/sign-up pages, protected dashboard redirect behavior, profile route, footer, branding consistency, and basic responsive behavior

1. Overview

This updated QA report documents issues observed in the TaskPilot deployment at <https://taskpilot-swart.vercel.app/>. The application appears to be a task management/productivity web app, but several public routes and UI areas show inconsistent naming between TaskPilot and TaskTracker. The review focuses on production-readiness risks visible from the public pages and authentication routes, including navigation reliability, branding consistency, user-facing states, and basic responsive behavior.

The assessment requires documenting issues clearly using title, reproduction steps, expected vs actual behavior, severity, and suspected cause. This report includes evidence-focused issues supported by the screenshots stored in the repository under [task-1-qa-report/screenshots/](#).

2. Tested User Flows and Pages

1	Homepage / landing page	Checked brand identity, hero content, CTA visibility, footer consistency, and public navigation.
2	Sign-in page	Checked authentication UI, field presentation, Google sign-in option, and branding consistency.
3	Sign-up page	Checked account creation entry point and navigation availability.
4	Dashboard route	Opened /dashboard as an unauthenticated user and verified redirect behavior.
5	Profile route	Opened /profile and checked whether the public navigation target resolves correctly.
6	Mobile responsiveness	Reviewed public landing page on smaller viewport from available screenshot evidence.

Note: The authenticated task CRUD flow should be fully re-tested with valid credentials after auth access is available. The issues below are still valid for the currently visible public deployment and should be fixed before final submission or production use.

3. Bug Report Table

#	Title / Summary	Steps to Reproduce	Expected vs Actual	Severity	Suspected Cause
1	Branding mismatch on homepage	1. Open https://taskpilot-swart.vercel.app/ . 2. Observe the navbar logo and hero section. 3. Compare brand names shown on the same page.	Expected: The app should use one consistent product name across navbar, hero, footer, and auth screens. Actual: Navbar shows TaskPilot, while the hero references TaskTracker / TaskTracker v2.0.	High	Project rename or copy updates were not applied consistently across layout, marketing copy, and auth pages.
2	Profile route returns 404	1. Open https://taskpilot-swart.vercel.app/profile . 2. Observe the rendered page.	Expected: Profile route should show a profile page, redirect to sign-in, or be hidden if not implemented. Actual: The route returns a generic 404 page.	High	Navbar/public route may point to an unimplemented page, or the /profile route is missing from the Next.js app directory.
3	Sign-in page has inconsistent app branding	1. Open /sign-in. 2. Compare the navbar name with the left authentication panel. 3. Observe product text in the auth card.	Expected: Auth page should match the same product name used in the navbar and deployment. Actual: Navbar shows TaskPilot but the auth panel shows TaskTracker.	Medium	Authentication layout likely uses old static copy/component values after product rename.
4	Protected dashboard redirect lacks contextual messaging	1. Open /dashboard while logged out. 2. Observe redirect to /sign-in?redirect_url=%2Fdashboard.	Expected: Redirect should clearly explain that sign-in is required to access the dashboard. Actual: User is redirected to sign-in but no clear context is shown for why the redirect happened.	Low/Medium	Auth middleware correctly protects route, but the sign-in page does not read redirect_url or display contextual helper copy.
5	Footer copy and resource links need cleanup	1. Open homepage. 2. Scroll to footer. 3. Review product name, resource links, and link readability.	Expected: Footer should use consistent branding and clearly separated resource links. Actual: Footer uses TaskPilot while page content uses TaskTracker; resource links are visually small and may be easy to miss.	Medium	Footer component copy and link styling were not reviewed after branding changes.
6	Public navigation exposes unstable Profile destination	1. Open homepage. 2. Notice Profile link in navbar. 3. Navigate to profile.	Expected: Public navigation should include only working routes, or protected routes should redirect to auth. Actual: Profile destination leads to 404, creating a broken navigation experience.	High	Navigation menu includes a route that has not been implemented or protected correctly.
7	Mobile/compact layout should be reviewed for readability	1. Open homepage in a mobile viewport. 2. Review hero spacing, CTA layout, and navbar behavior.	Expected: Hero, CTAs, and navigation should remain readable and balanced on mobile. Actual: Available mobile evidence suggests the public landing page should be manually rechecked for compact spacing and CTA stacking.	Low/Medium	Responsive design may need additional breakpoint testing and spacing adjustments.

4. Root-Cause Analysis

Selected issue: Branding mismatch between TaskPilot and TaskTracker

The application shows inconsistent product naming across multiple user-facing surfaces. The deployment and navbar present the product as TaskPilot, while the hero and authentication panel still reference TaskTracker. This usually happens when a project is renamed but static copy, layout components, metadata, and authentication templates are not updated together. The issue can reduce user trust because visitors may feel they are moving between two different products. It also makes the submission look unfinished even if the underlying functionality works. The fix is to define a single source of truth for product metadata, such as an app config file containing name, tagline, description, and support links. All navbar, footer, hero, auth, metadata, and README references should consume that config instead of hard-coded strings. After updating the copy, the app should be regression-tested across public pages, auth pages, mobile layout, and browser metadata. This is a low-complexity but high-impact fix because it improves professionalism and consistency immediately.

5. Detailed Recommendations

Brand consistency	Create a central app configuration file and replace all hard-coded TaskTracker/TaskPilot strings with one consistent value.
Navigation reliability	Remove public links to unfinished routes or implement the /profile route with either a profile page or an authentication redirect.
Auth UX	On protected-route redirects, show helper text such as "Please sign in to continue to your dashboard."
Footer polish	Review footer copy, spacing, resource links, and product naming for readability and consistency.
Regression checklist	After fixes, re-test homepage, sign-in, sign-up, dashboard redirect, profile route, footer, and mobile viewport.
Authenticated CRUD testing	With valid credentials, complete full task flow testing: create, edit, delete, logout, validation, duplicate submission, and API error handling.


6. Severity Summary

Critical	0
High	3
Medium	2
Low/Medium	2

7. Conclusion

The TaskPilot deployment is visually polished, but the public QA pass found important production-readiness issues. The highest-priority fixes are the inconsistent TaskPilot/TaskTracker branding and the broken Profile route. These issues are visible to first-time users and can reduce confidence in the product. Before final delivery, the team should also complete an authenticated CRUD regression pass using valid user credentials to verify create, edit, delete, logout, validation, and loading/error states.


Appendix A - Screenshot Evidence




Homepage evidence: navbar shows TaskPilot while hero/marketing copy references TaskTracker.

404 | This page could not be found.


Profile evidence: /profile resolves to a generic 404 page.



Sign-in evidence: auth page uses TaskTracker branding inside the panel while navbar uses TaskPilot.



Dashboard evidence: protected dashboard redirects to sign-in route.



Footer evidence: footer area should be reviewed for consistency and resource-link readability.