

2016.0 RANGE ROVER (LG), 204-04

WHEELS AND TIRES

DIAGNOSIS AND TESTING

PRINCIPLES OF OPERATION

NOTE:

Check DDW for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

For a detailed description of the Wheels and Tires refer to the relevant description and operation section in the workshop manual.

TIRE CHIP & CHUNK

NOTE:


If the level of chip and chunking is excessive or overall tire condition is poor the tire should be treated as any damaged/punctured tire. Where detrimental damage to the tire is evident, it must be reported to the customer with recommendations to accordingly replace damaged tires.

Symptoms

Typical example of a serviceable tire exhibiting chip and chunk phenomenon



E157078



Possible Causes:

Tire Chip and Chunk is a phenomenon that may develop on the tire tread when vehicles are driven on rough gravel or aggressive road surfaces. Typically the tread may lose small pieces of tread rubber within and around the periphery of the tread block. This loss of rubber ultimately leads, with extended usage, to an overall rough appearance to the tread area of the tire.

Action:

When a customer contacts a retailer concerning the chip and chunk phenomenon, dealers must:

- Conduct a thorough evaluation of the tire condition and, where no detrimental damage has occurred, inform the customer that the chip and chunk condition does not affect the overall tire integrity or significantly affect performance
- Inform the customers of the conditions that generate chip and chunk

phenomenon

Complaints associated with this phenomenon must initially include a thorough examination of the vehicles tires for the following:

- Excessive chip and chunk (tread cuts or loss of tread block section, extending deep into the tread rubber beyond the tread wear indicators or in the shoulder area extending beyond the groove depth)
- Cuts and bulges especially within the sidewall
- Overall tire condition including tread depth.

Where the tires do not exhibit excessive chip and chunk, cuts, sidewall bulges and are in generally good condition the customer should be advised that the condition does not affect the overall tire integrity or significantly affect performance and as such are serviceable.

TIRE FLAKING

NOTES:

- If the level of tire flaking is excessive or overall tire condition is poor the tire should be treated as any damaged/punctured tire. Where detrimental damage to the tire is evident, it must be reported to the customer with recommendations to accordingly replace damaged tires.
- Perform a tread depth measurement to make sure the tire is within local regulations. If specifications are not met inform customer that they require replacement.

Symptoms

Typical example of a serviceable tire exhibiting tire flaking phenomenon



Possible Causes:

Tire Flake damage may develop on the outer sections of the tire tread when vehicles are driven enthusiastically and peak available grip has been surpassed. Typically the tread may lose small pieces of tread rubber within and around the periphery of the tread blocks on the outer sections of the tire.

Action:

When a customer contacts a retailer concerning the tire flaking

phenomenon, dealers must:

- Conduct a thorough evaluation of the tire condition and determine that they are seeing flake damage on the outer sections of the tire. If damage is seen in the central tread, please refer to the Tire Chip & Chunk section
- Inform the customers of the driving styles that generate tire flaking (Mid corner understeer that generates high pitched tire noise, and/or over application on throttle inputs when exiting junctions that cause the traction control light to come on).

Complaints associated with this phenomenon must initially include a thorough examination of the vehicles tires for the following:

- Excessive flaking (tread cuts or loss of tread block section, extending deep into the tread rubber beyond the tread wear indicators or in the shoulder area extending beyond the groove depth)
- Cuts and bulges especially within the sidewall
- Overall tire condition including tread depth.

Where the tires do not exhibit excessive flaking, cuts, sidewall bulges and are in generally good condition the customer should be advised that the condition does not affect the overall tire integrity or significantly affect performance and as such are serviceable.

D T C I N D E X

For a list of Diagnostic Trouble Codes (DTCs) that could be logged on this vehicle, please refer to Section 100-00.