


LED Beacon



- H1 MountingHole
- H2 MountingHole
- H3 MountingHole
- H4 MountingHole

Wires & Bits		
Sheet: /		
File: emf_beacon.kicad_sch		
Title: LED Beacon		
Size: A4	Date: 2026-06-05	Rev: 1
KiCad E.D.A. 9.0.9		Id: 1/5



DMX512

Failsafe Bias
+3V3_ISO


ESD Protection

Isolated RS485 TRX

To XLRs



CA-IS3092W has pin 14 as NC but to maintain compatibility with CA-IS3092VW it's connected to 3V3_ISO



I²C Addr: 0x20
MCP23017 has a fault with GPA7 & GPB7.
The can corrupt an I²C transaction if they change state during it.

Wires & Bits


Sheet: /DMX512/
File: dmx512.kicad_sch

Title: DMX512

Size: A4 Date: 2026-06-05
KiCad E.D.A. 9.0.9


Rev: 1
Id: 3/5

LED Driver





Power Supplies

LED Buck



Logic Buck



EMC ferrites /CMC?

Wires & Bits

Sheet: /POWER/
File: power.kicad_sch

Title: Power

Size: A4
Date: 2026-06-05
KiCad E.D.A. 9.0.9

Rev: 1
Id: 5/5