


PlotLens — Site Analysis

12.5223, 76.8951


Overall read: Flag

Strong caution on at least one factor. Treat the flagged categories as deal-critical to verify.


COMPUTED ANALYSIS



Terrain: contours, slope & water-flow accumulation



Then vs now: land-cover change (Sentinel-2)



Access & surroundings: distances to roads, water, services

1 · Topography & Geology

FLAG

Satellite-derived

Elevation	674.2 m
Slope	0.2 %
Below surroundings	0.9 m
Rock/soil	Inferred from regional geology — confirm with a bore test

2 · Water & Drainage

FLAG

Satellite-derived

Water-collection index	9.1x area average
Nearest water body	115 m (Cauvery channel)
Drainage bearing	177 deg
Reading	Low pocket with poor slope and converging water flow — strong drainage/flood caution. Verify with a site visit in monsoon.

3 · Climate & Natural Factors

GOOD

Satellite-derived

Sun path	E-W, standard for latitude
Note	Rainfall, wind & seismic zone added from climate/seismic datasets on deploy

4 · Circulation & Access

CAUTION

Satellite-derived

Nearest road	258 m (Approach track)
Public transport	1746 m
Emergency services	8881 m (fire_station)
Reading	Nearest mapped road ~258 m — check the access path on the ground. Note: OSM coverage is sparse here — absence of a feature may mean it is unmapped, not absent.

5 · Vegetation & Landscaping

CAUTION

Satellite-derived

Vegetation cover	34.0% -> 3.2%
Trend	From Sentinel-2 NDVI differencing

6 · Land-cover change

CAUTION

Satellite-derived

Water cover	13.8% -> 11.2%
-------------	----------------

Reading	Vegetation dropped from 34% to 3%. Significant clearing — confirm what changed and why.
---------	---

7 · Utilities & Infrastructure

CAUTION
Indicative

Adjacent land use	farmland
Mapped utilities	From OSM; underground lines not mapped — confirm with local authority

8 · Development Rules & Legal

CHECK
Needs site / legal check

Title & ownership	Cannot be checked from satellite
Zoning / land-use class	Cannot be checked from satellite
Easements & setbacks	Cannot be checked from satellite
Encumbrance	Cannot be checked from satellite

Satellite data cannot see legal or title status. Verify these with the sub-registrar, a property lawyer, and the local planning authority. This is the costliest place buyers get caught.

SOURCES & LIMITS

Elevation: synthetic:riverside · Map features: synthetic:riverside · Imagery: synthetic:riverside.

Indicators are derived from public satellite, elevation and map data and are indicative only. They support your judgment — they are not a guarantee against flooding, nor a substitute for a site survey, soil test, or legal title check. Elevation is ~30 m resolution; a single plot spans only a few pixels.