Callahan Auto & Diesel

255 W Main St.
Mesa AZ - 85201
Phone# (480) 969-3332

Complete Multi Point Check
Invoice No# 13353
Report Date: 03/06/2026
by Autoflow

2014 Jeep Grand Cherokee

Report URL: https://atxt.me/RdmfrPmGl

Customer Name	Conrad C	Phone No.	(xxx)-xxx-x205
Submodel	Limited	Engine Size	3.0L Eco Diesel
2WD or 4WD	AWD	VIN	1C4RJFBM2EC555481
License	Mpa88z	Mileage	131580
ABS		Transmission	Automatic
Est/Invoice#	13353	Oil Filters	
Notes			

Reason vehicle is here

#	Type	Details	Notes	Acknowledged
1	Concern	Codes for glow plugs		✓
2	Concern	DEF system codes		✓
3	Concern	Needs new battery MTX-49/H8 - Replace battery first and scan it		✓
4	Concern	Inspect overflow		

Complete Multi Point Check

✔ 2 Requires Urgent Attention

#	Insp Item	Notes
✗	Exterior Photos (4 Corner)	

Callahan Auto & Diesel
255 W Main St.
Mesa AZ - 85201
Phone# (480) 969-3332

Complete Multi Point Check
Invoice No# 13353
Report Date: 03/06/2026
by Autoflow



✗	Mirrors	Passenger side door mirror is broken needs replacement

✓ 40 Good Items

#	Insp Item	Notes
✓	Warning Lights	
✓	Windshield and Windows	
✓	Wipers	
✓	Headlights	
✓	Tail Lights	
✓	HVAC	
✓	Other	
✓	Engine Oil	

✓	Transmission Fluid	
✓	Brake Fluid	
✓	Mounts	
✓	Hoses	
✓	Belts	
✓	EVAP System: Canister/Lines/Hoses	
✓	Vacuum Lines	
✓	Timing Belt	
✓	Other	
✓	Ball Joints	
✓	Tie Rods	
✓	Wheel Bearings	
✓	Sway Bar	
✓	Control Arm	
✓	Suspension	
✓	Driveshafts / U-Joints	
✓	CV Shafts / Axles	
✓	Powertrain Mounts	
✓	Exhaust	
✓	Differential Fluid	
✓	Transfer Case Fluid	
✓	Alignment	
✓	Tires	

✓	Front Calipers	
✓	Rear Calipers / Cylinders	
✓	Brake Hardware	
✓	Brake Hoses	
✓	Brake Lines and Fittings	
✓	Battery Test Results	New battery
✓	Battery Terminals	
✓	Battery Cables	
✓	Overall Battery Condition	

✓ 12 Requires Future Attention

#	Insp Item	Notes
!	Power Steering Fluid	Fluid looks ok but was a little low i topped off

!	Coolant/antifreeze	The coolant level is within the acceptable range; however, there is noticeable contamination present. It's important to address this issue to maintain optimal engine performance and prevent potential damage.





!	Filter / Air Intake	The air intake filter is noticeably dirty and has reached the end of its effective lifespan. Replacing it will ensure optimal engine performance and improve air quality within the cabin.

!	Cabin Air Filter	Dirty needs replacement



!	Ignition	Replace glow plug #3
!	Fuel System: Filter/Lines	Replace both Fuel Filters
!	Fluid Leaks	Possibly front rear main seal and oil pan gasket leaking need time to clean and put dye to pinpoint the leak

!	Other	Rear passenger side shock leaked oil recommend replacement of both

!	Front Pads	Pads have 4 mm life left remaining recommend replacement soon 4mm Pad life remaining - near end of usefull life.
!	Front Rotors	Replace with new pads
!	Rear Pads / Shoes	Pads have 3 mm life left remaining recommend replacement
!	Rear Rotors / Drums	Replace with new pads

Callahan Auto & Diesel
255 W Main St.
Mesa AZ - 85201
Phone# (480) 969-3332

Complete Multi Point Check
Invoice No# 13353
Report Date: 03/06/2026
by Autoflow

Front Axle

O.E. - Tread Depth

Actual - Tread Depth

PSI Before

PSI After

[LF]

[RF]

PSI Before

PSI After

Axle#2

O.E. -

Actual -

[LR]

[RR]

PSI Before

PSI After

PSI Before

PSI After

Tread Depth

Tread Depth

This report was signed off on 03/06/2026 03:40 pm

Service Writer: Mitch Callahan

Technician: Luis Cervantes