

Kitchen ground-truth investigation · 3 November 2026


Estimated paths and independent sparse video projections
Lateral magnified; initial grid/body alignment is uncalibrated




No video positions filled through the unobserved interval



End-to-end lateral drift confirmed in the image



Telemetry heading; no reliable calibrated video heading



Green points are elevated-body floor projections, not height-corrected center truth. Gray: no video measurements. No scale factor applied to video.