

NATIONAL RAILWAY AUTHORITY

AI TRACK INSPECTION REPORT

Report ID: INSP-SIM-20260723_210711
Date: 2026-07-23 15:37:13
Status: DEFECTIVE

Overall Status	DEFECTIVE	Max Severity	Medium
Avg Confidence	27.68%	Inference Time	2438.57 ms

Visual Inspection & Defect Localization

Original Rail Track Image	YOLOv8 Bounding Box Detection
	

Detected Defects & Maintenance Recommendations

Defect Type	Confidence	Severity	Bounding Box (x1,y1,x2,y2)	Maintenance Recommendation
Surface Crack	27.68%	**Medium**	[504.2, 404.5, 530.0, 423.1]	Schedule non-destructive testing (NDT) and surface grinding.

This automated report was generated by the AI-Powered Smart Railway Inspection Platform using YOLOv8 Computer Vision. Verified by Authorized Railway Engineer. Confidential Document.