# Progress Report: LAI Estimation using 3D Gaussian Splatting vs. Terrestrial Laser Scanning

June 2, 2026

## Contents


**1 Introduction and Problem Statement** **2**

**2 Initial Setup and Learning Phase** **2**
2.1 Understanding 3DGS and Hardware . . . . . 2
2.2 Implementation Challenges . . . . . 2

**3 Data Collection and Preprocessing** **4**
3.1 TLS Data Collection . . . . . 4
3.2 Preprocessing with FARO SCENE . . . . . 5

**4 3D Gaussian Splatting Generation** **6**
4.1 Workflow . . . . . 6
4.2 Issues Encountered . . . . . 7

**5 Resolving Estimation Issues** **7**
5.1 Addressing Floaters . . . . . 7
5.2 The Dynamic Nature of Outdoor Plants . . . . . 9

**6 Tackling Scale Mismatch and Point Cloud Alignment** **9**
6.1 Failed Attempts at Automated Alignment . . . . . 9
6.2 Successful Manual Registration . . . . . 10

**7 Next Steps** **11**

# 1 Introduction and Problem Statement

The primary goal of this project is to achieve accurate Leaf Area Index (LAI) estimation using 3D Gaussian Splatting (3DGS) and compare it to the true LAI obtained via Terrestrial Laser Scanning (TLS). 3DGS offers a potentially cheaper and significantly less time-consuming alternative to TLS, making it an attractive method for widespread use.

The estimation baseline is maintained using the FDTLS tool, building upon the theoretical foundation from the paper "Estimating the leaf area index from terrestrial laser scanning point cloud data with fractal theory". FDTLS provides the reliable ground truth necessary to validate our 3DGS results.





Figure 1: Overview of the FDTLS baseline tool.

# 2 Initial Setup and Learning Phase

## 2.1 Understanding 3DGS and Hardware

The project began with an in-depth review of the "3D Gaussian Splatting for Real-Time Radiance Field Rendering" paper. Concurrently, it was crucial to learn how LiDAR sensors function and how to properly operate the FARO TLS sensor.

## 2.2 Implementation Challenges

Cloning and implementing the 3DGS repository presented significant challenges, primarily due to library dependency issues. The original 3DGS implementation relies on older versions of specific libraries, which caused version conflicts that had to be manually resolved to get the repository working correctly.





Figure 2: Process of making 3DGS.





Figure 3: Making of LAI configuration files.

# 3 Data Collection and Preprocessing

## 3.1 TLS Data Collection

Data collection involved scanning various indoor and outdoor plants. As a first-time user of the instruments, several mistakes were made which resulted in suboptimal data:

- **Distance Issues:** Placing the TLS sensor too close resulted in important parts of the plant being cut off, while placing it too far made the captured data too sparse.
- **Resolution Issues:** Capturing data at excessively high resolutions caused multiple crashes in the preprocessing software.




Figure 4: A tree that appears dense visually but resulted in a sparse point cloud.



Figure 5: Close-up view of the sparse tree point cloud.

## 3.2 Preprocessing with FARO SCENE

Following data collection, I learned to use the FARO SCENE preprocessing application. This software was used to preprocess and segment multiple trees from the raw TLS data.





Figure 6: Preprocessing of TLS data using FARO SCENE.

# 4 3D Gaussian Splatting Generation

## 4.1 Workflow

Videos of the plants were captured using a DJI camera to generate the 3DGS representations. The workflow is as follows:

1. **Frame Extraction:** Extract frames from the input video using `ffmpeg`.
2. **Structure from Motion:** Map these frames into a sparse point cloud using COLMAP.
3. **Gaussian Generation:** Use `train.py` from the 3DGS repository to generate the final Gaussians.




Figure 7: Example of a generated 3D Gaussian Splatting point cloud.

### 4.2 Issues Encountered

Different formats were produced between the TLS and 3DGS outputs. Furthermore, I unknowingly downsampled the point clouds during the process, leading to poor results in the initial LAI estimations. After exporting `.ply` files from both TLS and 3DGS and comparing them using the FDTLS tool, the results were highly inaccurate.

The two primary reasons for the faulty 3DGS LAI estimation were:

1. **Scale Mismatch:** The TLS point cloud is in meters (world coordinate scale), while the 3DGS point cloud operates on an arbitrary scale.

2. **Floaters in 3DGS:** Extraneous artifacts generated with no real depth.

## 5 Resolving Estimation Issues

### 5.1 Addressing Floaters

Floaters occur because 3DGS lacks a strict sense of depth, causing it to create Gaussians out of thin air. To resolve this, I applied data post-processing on the 3DGS point cloud:

- Applied an opacity filter to remove transparent Gaussians.

- Applied Statistical Outlier Removal (SOR) to eliminate scattered floaters.

I also researched several models designed for floater removal in 3DGS, including StableGS, GaussianFusion, and 3DGS Simplify. Using **3DGS Simplify** proved highly effective at removing floaters, although it does downsample the point cloud.



Figure 8: 3DGS point cloud before floater removal (white floaters are present).



Figure 9: 3DGS point cloud after using 3DGS Simplify for floater removal.

## 5.2 The Dynamic Nature of Outdoor Plants

Another major problem during video data collection was wind causing the movement of leaves. This movement destroys the static structure assumed by 3DGS, rendering the model unusable for precise LAI estimation. Since this is a dynamic problem without an immediate solution, I shifted my focus entirely to **indoor plants**. Indoor leaves move significantly less, allowing me to isolate and tackle the scale mismatch problem first.

# 6 Tackling Scale Mismatch and Point Cloud Alignment

My most recent task has been addressing the scale mismatch to accurately overlap the 3DGS `.ply` clouds with the TLS `.ply` clouds.





Figure 10: Visualizing the scale mismatch fix between 3DGS and TLS.

## 6.1 Failed Attempts at Automated Alignment

1. **Bounding Box Alignment refined by ICP:** This failed because the segmentation of the plant differed between the two point clouds.
2. **Mapping Similar Data Point Clusters:** I attempted a pipeline using:
   - Statistical Outlier Removal (SOR)
   - DBSCAN Clustering
   - Robust Bounding Box alignment
   - Global Registration and Iterative Closest Point (ICP)

   This approach also failed due to having too few correspondences after the mutual filter. Global registration relies on Fast Point Feature Histograms (FPFH), but because plants have many nearly identical leaves, the algorithm became confused and failed to establish robust feature matches.




Figure 11: Attempt at automated alignment.

## 6.2 Successful Manual Registration

Switching to manual registration yielded excellent results. By manually aligning the geometries, I achieved an almost perfect overlap between the 3DGS and TLS point clouds.




Figure 12: Perfect alignment achieved via manual registration.

# 7 Next Steps

Despite the success of manual alignment, my immediate focus is to fully automate the registration process using ICP, though I am currently hitting a wall.

Future tasks include:

- Solving the automated scaling issue (Auto ICP).
- Identifying state-of-the-art (SOTA) baseline models for:
  - Biomass estimation
  - Urban carbon accounting
  - Urban canopy estimation
- Resuming data collection for outdoor plants, specifically bushes, medium trees, and large trees, once dynamic alignment challenges are better understood.