VESSEL CORROSION INSPECTION REPORT

Vessel: **Asia Unity**
Area: **MAIN_DECK**
Inspection Photos: **18**

Metric	Value
Inspection Photos	18
Average Rust %	7.67
Maximum Rust %	46.64

Main Deck Corrosion Map

Asia Unity — MAIN DECK CORROSION MAP

20 fixed inspection points aligned to approved main deck reference map



Photo / Point Reference

Point	Photo	Zone	Rust %	Band	Photo?
1	1	POINT 1	0.5%	LOW	YES
2	2	POINT 2	2.0%	WATCH	YES
3	3	POINT 3	17.9%	HIGH	YES
4	4	POINT 4	7.5%	MOD	YES
5	5	POINT 5	0.3%	LOW	YES
6	6	POINT 6	2.7%	WATCH	YES
7	7	POINT 7	0.4%	LOW	YES
8	8	POINT 8	46.6%	SEVERE	YES
9	9	POINT 9	1.9%	LOW	YES
10	10	POINT 10	0.2%	LOW	YES
11	11	POINT 11	2.4%	WATCH	YES
12	12	POINT 12	5.0%	MOD	YES
13	13	POINT 13	0.2%	LOW	YES
14	14	POINT 14	0.3%	LOW	YES
15	15	POINT 15	14.8%	HIGH	YES
16	16	POINT 16	3.5%	WATCH	YES
17	17	POINT 17	10.8%	MOD	YES
18	18	POINT 18	21.1%	SEVERE	YES
19	19	POINT 19	–	NO PHOTO	NO
20	20	POINT 20	–	NO PHOTO	NO

Legend

- No photo
- 0–2% LOW
- 2–5% WATCH
- 5–12% MOD
- 12–20% HIGH
- >20% SEVERE

Coverage Summary

Photos: 18/20
Avg rust: 7.67%
Max rust: 46.64%

Numbered markers follow the approved 20-point main deck map. White marker means no photo uploaded.

Inspection Photo 1

Location	image1.jpg
Rust %	0.48
Severity	LOW

Inspection Photo 2

Location	image10.jpg
Rust %	2.01
Severity	LOW

Inspection Photo 3

Location	image11.jpg
Rust %	17.90
Severity	SEVERE

Inspection Photo 4

Location	image12.jpg
Rust %	7.55
Severity	MODERATE



Inspection Photo 5

Location	image13.jpg
Rust %	0.31
Severity	LOW

Inspection Photo 6

Location	image14.jpg
Rust %	2.67
Severity	LOW

Inspection Photo 7

Location	image15.jpg
Rust %	0.42
Severity	LOW

Inspection Photo 8

Location	image17.jpg
Rust %	46.64
Severity	SEVERE

Inspection Photo 9

Location	image18.jpg
Rust %	1.91
Severity	LOW



Inspection Photo 10

Location	image19.jpg
Rust %	0.18
Severity	LOW

Inspection Photo 11

Location	image2.jpg
Rust %	2.43
Severity	LOW

Inspection Photo 12

Location	image20.jpg
Rust %	5.01
Severity	MODERATE



Inspection Photo 13

Location	image3.jpg
Rust %	0.20
Severity	LOW

Inspection Photo 14

Location	image5.jpg
Rust %	0.26
Severity	LOW

Inspection Photo 15

Location	image6.jpg
Rust %	14.85
Severity	HIGH



Inspection Photo 16

Location	image7.jpg
Rust %	3.45
Severity	MODERATE

Inspection Photo 17

Location	image8.jpg
Rust %	10.77
Severity	HIGH



Inspection Photo 18

Location	image9.jpg
Rust %	21.09
Severity	SEVERE