VESSEL CORROSION INSPECTION REPORT

Vessel: **Batavia Express**
Area: **CARGO_HOLD**
Inspection Photos: **4**

Metric	Value
Inspection Photos	4
Average Rust %	1.7
Maximum Rust %	2.85

Cargo Hold Corrosion Map - Hold 1



Inspection Photo 1

Location	hold1_fwd_bulkhead
Rust %	1.26
Severity	LOW
Reviewer	-
Notes	-
Reviewed At	2026-03-12T06:47:55.189+00:00

Inspection Photo 2

Location	hold1_fwd_bulkhead
Rust %	1.69
Severity	LOW
Reviewer	-
Notes	-
Reviewed At	2026-03-12T07:07:43.035+00:00

Inspection Photo 3

Location	hold1_fwd_bulkhead
Rust %	2.85
Severity	LOW
Reviewer	-
Notes	-
Reviewed At	2026-03-12T08:15:17.698+00:00

Inspection Photo 4

Location	hold1_fwd_bulkhead
Rust %	1.00
Severity	LOW
Reviewer	-
Notes	-
Reviewed At	2026-03-12T08:21:53.575+00:00