# VESSEL CORROSION INSPECTION REPORT

Vessel: **Batavia Express**
Area: **CARGO_HOLD**
Inspection Photos: **4**

| Metric | Value |
|---|---|
| Inspection Photos | 4 |
| Average Rust % | 1.7 |
| Maximum Rust % | 2.85 |

## Cargo Hold Corrosion Map - Hold 1



### *Inspection Photo 1*

| | |
|---|---|
| Location | hold1_fwd_bulkhead |
| Rust % | 1.26 |
| Severity | LOW |
| Reviewer | - |
| Notes | - |
| Reviewed At | 2026-03-12T06:47:55.189+00:00 |

### *Inspection Photo 2*

| | |
|---|---|
| Location | hold1_fwd_bulkhead |
| Rust % | 1.69 |
| Severity | LOW |
| Reviewer | - |
| Notes | - |
| Reviewed At | 2026-03-12T07:07:43.035+00:00 |

### *Inspection Photo 3*

| | |
|---|---|
| Location | hold1_fwd_bulkhead |
| Rust % | 2.85 |
| Severity | LOW |
| Reviewer | - |
| Notes | - |
| Reviewed At | 2026-03-12T08:15:17.698+00:00 |

### *Inspection Photo 4*

| | |
|---|---|
| Location | hold1_fwd_bulkhead |
| Rust % | 1.00 |
| Severity | LOW |
| Reviewer | - |
| Notes | - |
| Reviewed At | 2026-03-12T08:21:53.575+00:00 |