VESSEL CORROSION INSPECTION REPORT

Vessel: **Eagle Express**
Area: **CARGO_HOLD**
Inspection Photos: **1**

Metric	Value
Inspection Photos	1
Average Rust %	6.73
Maximum Rust %	6.73

Cargo Hold Corrosion Map - Hold 1



Inspection Photo 1

Location	hold1_fwd_bulkhead
Rust %	6.73
Severity	MODERATE
Reviewer	-
Notes	-
Reviewed At	2026-03-14T01:40:01.403+00:00