VESSEL CORROSION INSPECTION REPORT

Vessel: **Sumatera Express**
Area: **CARGO_HOLD**
Inspection Photos: **10**

Metric	Value
Inspection Photos	10
Average Rust %	8.35
Maximum Rust %	14.71

Inspection Photo 1

Location	Hold No. 1_0.jpg
Rust %	13.25
Severity	HIGH



Inspection Photo 2

Location	Hold No. 1_1.jpg
Rust %	14.71
Severity	HIGH

Inspection Photo 3

Location	Hold No. 1_10.jpg
Rust %	5.86
Severity	MODERATE

Inspection Photo 4

Location	Hold No. 1_2.jpg
Rust %	8.69
Severity	MODERATE

Inspection Photo 5

Location	Hold No. 1_3.jpg
Rust %	8.59
Severity	MODERATE

Inspection Photo 6

Location	Hold No. 1_4.jpg
Rust %	5.57
Severity	MODERATE



Inspection Photo 7

Location	Hold No. 1_5.jpg
Rust %	12.20
Severity	HIGH



Inspection Photo 8

Location	Hold No. 1_7.jpg
Rust %	6.25
Severity	MODERATE

Inspection Photo 9

Location	Hold No. 1_8.jpg
Rust %	0.70
Severity	LOW

Inspection Photo 10

Location	Hold No. 1_9.jpg
Rust %	7.69
Severity	MODERATE