Asset inspection report, Riverside works

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

2. Findings by structure

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.



Condition grade summary: two structures need repair within twelve months.

Structure	Grade	Action	Due
Pump house	2	Repoint brickwork	2027-03
Valve chamber	3	Replace cover	2027-01
Outfall	4	Rebuild apron	2026-12
Access road	2	Patch surface	2027-06

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

3. Recommendations

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.