# Asset inspection report, Riverside works

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

## 2. Findings by structure

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.



Condition grade summary: two structures need repair within twelve months.

| Structure | Grade | Action | Due |
|---|---|---|---|
| Pump house | 2 | Repoint brickwork | 2027-03 |
| Valve chamber | 3 | Replace cover | 2027-01 |
| Outfall | 4 | Rebuild apron | 2026-12 |
| Access road | 2 | Patch surface | 2027-06 |

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

## 3. Recommendations

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.

The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank. The inspection covered the pump house, the valve chamber and the outfall structure on the north bank.