Spoor Case report

● Open · likely location

Most likely in the Exception store.

PARCEL
CTX334048419302

CASE
18e3f000a5

CUSTOMER WAITING
4 days before asking

OPENED
21:49, 1 Nov 2026

1 Summary

CTX334048419302 was last scanned at 14:21 on 28 Oct 2026, into cage RC-760. At 14:32 it was carried into the Exception store without a scan-in, and no camera saw it come out. The records say it was in RC-760. The cameras saw it at the exception store. A floor search has been sent to confirm it.

How sure. Likely, not yet confirmed. The carry-in is on the store door camera with SAM's outline; nothing inside the store is on camera, so the floor search decides.

2 Journey on camera



14:10:01 Scanned

Unloaded

No outline: nothing stood out at the scan point at that instant

Unload close-up camera



14:10:40 Scanned

Label read in the tunnel

The tunnel reader's own photo · weight and size measured

Tunnel reader's photo



14:10:50 Scanned

On the sorter

Too close to the next carton to label

Tunnel close-up camera



14:11:16 Scanned

Into chute C12


CAM 11



14:21:33 Last scan

Into cage RC-760

Cage close-up camera



14:21:34 No camera

Waiting in RC-760 for 11 min

14:21 to 14:32 · no scan, and no camera saw it move

No camera




14:32:13 On camera

Taken out of RC-760

The one parcel caged in RC-760 and not scanned since: could be CTX334048419302

Cage close-up camera



14:32:30 On camera

Carried to the door of the Exception store

SAM followed the carton in the carrier's hands

CAM 19



14:32:31 Not scanned in

Carried into the Exception store

Past the scan-in post, not scanned in

Store door close-up camera




14:32:47 On camera

Came out without it

SAM tracked no carton with the person coming out

Store door close-up camera




14:33:25 **Records disagree**

Record says RC-760 loaded on D07

Automatic: the door's RFID reader read the cage's tag, so every parcel in it counts as loaded. The cameras say this carton is still inside

Dock close-up camera

3 Where it went



4 Records against the cameras

STEP	TIME	THE RECORD SAYS	THE CAMERAS SHOW	VERDICT
1	14:10:01	Scan: unloaded	Unload close-up camera, seen	Agree
2	14:10:40	Scan: label read in the tunnel	Tunnel reader's photo, number confirmed	Agree
3	14:10:50	Scan: on the sorter	Tunnel close-up camera, seen	Agree
4	14:11:16	Scan: into chute c12	CAM 11, number confirmed	Agree
5	14:21:33	Scan: into cage rc-760	Cage close-up camera, number confirmed	Agree

STEP	TIME	THE RECORD SAYS	THE CAMERAS SHOW	VERDICT
9	14:32:31	No scan-in at the store's post	Past the scan-in post, not scanned in	Not scanned in
11	14:33:25	Record says RC-760 loaded on D07	Automatic: the door's RFID reader read the cage's tag, so every parcel in it counts as loaded. The cameras say this carton is still inside	Records disagree

To fix. It was scanned into RC-760 at 14:21:33, but CAM 19 saw it at the exception store at 14:32:21, outside the cage. Check why the door's RFID read counts every parcel in a cage as loaded.

5 Floor check

Exception store	Not checked yet
Supervisor office	Not checked yet
Outbound dock	Not checked yet
Cage staging	Not checked yet
Oversize / non-conveyable area	Not checked yet

6 Evidence

STEP	SOURCE	FRAMES	SHA-256
1	Unload close-up camera	10–90	4c36a9c1dee7… Copy
2	Tunnel reader's photo	1 photo	CTX334048419302.jpg
3	Tunnel close-up camera	106–136	abba37780560… Copy
4	CAM 11	8–79	0dcbc73ef053… Copy
5	Cage close-up camera	49–100	815bdf9cfdfa… Copy
6	Cage close-up camera	66–97	67c0a7705a78… Copy
7	CAM 19	139–243	4798cd2f3c4a… Copy
8	Store door close-up camera	20–51	0c6dfc4c7de3… Copy
9	Store door close-up camera	160–210	0c6dfc4c7de3… Copy
10	Dock close-up camera	0–39	5e8747227ac6… Copy

Muse Wonder
Lead investigator

Muse Glimmer · Modal
On-site triage

Muse Spark Open · Baseten
Evidence agent

Muse Spark
Camera analyst

SAM 3.1
Tracker

rules, no AI
Verifier

Run
Took 269 s. Muse Wonder US$0.25; Spark Open 119k tokens on Baseten. 19 wide cameras swept on site, 2 examined closely.

- No camera sees inside the Exception store: where it is inside is for the floor search to confirm.
- Steps without a number: the outline at that moment could not be told apart from a person or the next carton, so no number is shown.
- Ideas the agents tested guide where to look; they are never evidence. Outlines are SAM 3.1's, timed on each camera's fitted clock.