INVENTORY OF HAZARDOUS MATERIALS, IHM (PART I)
BY VISWA LAB, SINGAPORE

Report of Investigation IHM (Part I) for M/V SSL THAMIRABARANI IMO 9312468 according to IMO Hongkong Convention and EU Ship Recycling Regulation

TRANSWORLD SHIPMANAGEMENT PVT LTD

Viswa Report No : SSL THAMIRABARANI 2025 Rev. 2

Report Date: 04-11-2025



Project name:	INVENTORY OF HAZARDOUS MATERIALS, IHM (PART I) BY VISWA LAB, SINGAPORE
Report title:	Report of Investigation IHM (Part I) for MV SSL THAMIRABARANI according to IMO Hongkong Convention and EU Ship Recycling Regulation
Customer:	Mr. Kabilan Sadasivam Deputy General Manager
Customer contact:	Mobile: +91 9489972232 E-mail: kabilan.sadasivam@transworld.com
Date of issue:	04-11-2025
Project No.:	VIHM SMQT25 146
Organisation unit:	Viswa Lab (The Viswa Group)
Testing Laboratory:	Shanghai ULS Testing Technology Co. Ltd
Report No.:	SSL THAMIRABARANI 2025 Rev.2
Document No.:	SSL THAMIRABARANI 2025 Rev.2

Applicable contract(s) governing the provision of this Report:

Prepared by:	Verified by:	Approved by:
Sivaprakash	Matthew	Girivarma
Siva Prakash Senior Hazmat Expert VISWA LAB Singapore	Matthew Operations Manager The Viswa Group	Girivarma Director, Surveys & Inspection The Viswa Group

Copyright © Viswalab. All rights reserved. Unless otherwise agreed in writing: (i) This publication or parts thereof may not be copied, reproduced or transmitted in any form, or by any means, whether digitally or otherwise; (ii) The content of this publication shall be kept confidential by the customer; (iii) No third party may rely on its contents; and (iv) Viswalab undertakes no duty of care toward any third party. Reference to part of this publication which may lead to misinterpretation is prohibited

VISWA GROUP Distribution:

☒ Unrestricted distribution (internal and external)

☐ Unrestricted distribution within VISWA GROUP

☐ Unrestricted distribution within VISWA GROUP contracting party

☐ No distribution (confidential)

Keywords:

IHM, Investigation, lab analysis

Rev. No.	Date	Reason for Issue	Prepared by	Verified by	Approved by
1	2025-11-04	First issue for Class comment	Sivaprakash	Matthew Lalchang	Girivarma
2	2025-11-05	Revision due to ACM Removal	Sivaprakash	Matthew Lalchang	Girivarma
3	2025-12-22	Revision as per Class Comment	Sivaprakash	Matthew Lalchang	Girivarma

Table of Contents

1. EXECUTIVE SUMMARY 5

2. DEVELOPMENT OF THE IHM SCOPE, STRUCTURE & METHODOLOGY 6

2.1 INTRODUCTION 6

2.2 ABBREVIATION 7

2.3 THE LINK BETWEEN THE IHM AND THE HONG KONG INTERNATIONAL CONVENTION 8

2.4 THE LINK BETWEEN THE IHM AND EU REGULATION ON SHIP RECYCLING, REGULATION (EU) NO 1257/2013 8

2.5 STRUCTURE OF THE IHM 9

2.6 METHODOLOGY OF WORK 12

2.6.1 Collection of information 12
2.6.2 Analysis and definition of scope of investigations 12
2.6.3 Preparation of Visual/Sampling Check Plan 12
2.6.4 Onboard Visual/Sampling Check 12
2.6.5 Preparation of IHM, Part I and related documentation 13
2.6.6 Delivery of IHM, Part I 13

3. SHIP PARTICULARS 15

4. INVENTORY OF HAZARDOUS MATERIALS 16

4.1 (PART I): HAZARDOUS MATERIALS CONTAINED IN THE SHIP'S STRUCTURE AND EQUIPMENT 16

4.2 (PART I): PAINTS AND COATING SYSTEMS CONTAINING MATERIALS LISTED IN TABLE A AND TABLE B OF APPENDIX 1 OF THE GUIDELINES 16

4.3 (PART I): EQUIPMENT AND MACHINERY CONTAINING MATERIALS LISTED IN TABLE A AND TABLE B OF APPENDIX 1 OF THE GUIDELINES 17

4.4 (PART I): STRUCTURE AND HULL CONTAINING MATERIALS LISTED IN TABLE A AND TABLE B OF APPENDIX 1 OF THE GUIDELINES 18

5. RESULTS AND CONCLUSION 19

6. APPENDIX 1 – ANTI FOULING CERTIFICATES 21

7. APPENDIX 2 – IHM EXPERT CERTIFICATE 34

8. APPENDIX 3 – VISUAL SAMPLING CHECK PLAN (VSCP) 58

The Viswa Group © 2020

9. APPENDIX 4 – LOCATIONS MAP 66

10. APPENDIX 5–CALCULATIONS ON QUANTITY OF HAZARDOUS MATERIALS & PCHM .. 66

10.1 Calculation of Potentially Containing Hazardous Material (PCHM): 59
10.2 Calculation of Hazardous Material: 75
10.3 Calculation method for Lead and Lead compound in battery for the above: 60

11. APPENDIX 6 – INDIVIDUAL SAMPLE PHOTOS 62

12. APPENDIX 7 – SAMPLING INSPECTION PHOTOS 65

13. APPENDIX 8 – VISUAL INSPECTION PHOTOS FOR CHM 65

14. APPENDIX 9 – LABORATORY REPORT, ANALYSIS RESULT 79

15. APPENDIX 10 – ASBESTOS REMOVAL CERTIFICATE 164

1. Executive Summary

The Company Transworld Ship Management Pvt Ltd (Client) had approached VISWA LAB SINGAPORE LTD. for Inventory of Hazardous Materials, IHM preparation (Part I) in accordance with MEP.379(80) (adopted on 7 July 2023) 2023 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY OF HAZARDOUS MATERIALS.

The IHM investigation (Part I) was carried out onboard SSL THAMIRABARANI from 23/10/2025 to 23/10/2025 by undersigned VISWA LAB IHM Expert during yard stay at Colombo Dry Docks, Sri Lanka.

A total of 96 pieces of samples were sent for lab test, with samples mainly from insulations, penetration filling, gaskets, brake linings, paints, tiles, cables and others. The detailed Visual and Sampling Plan during onboard investigation is attached in Appendix 3 and detailed locations of sampling points are attached in Appendix 4.

Summary result of the laboratory testing & visual inspection may contain the following hazardous substances:

TEST		QUANTITY (SAMPLE)	TESTED CONTAINING	QUANITY (VISUAL)	VERIFIED CONTAINING
ASBESTOS	A1	60	3	3	0
PCBS	A2	6	0	2	0
ODS	A3	4	1	3	0
Anti-fouling system containing organotin compounds as a biocide / containing cybutryne	A4	0	0	1	1
PFOS	A5	3	0	0	0
CD	B1	2	0	0	0
Cr6+	B2	1	0	0	0
PB	B3	10	3	4	5
HG	B4	1	0	1	0
PBB	B5	2	0	0	0
PBDE	B6	2	0	0	0
PCN	B7	1	0	0	0
SCCP	B9	2	0	0	0
HBCDD	B10	2	0	0	0
TOTAL		**96**	**7**	**13**	**6**

The Viswa Group © 2020

2. Development of the IHM Scope, Structure & Methodology

2.1 Introduction

The purpose of this Inventory of Hazardous Materials (IHM) investigation that has been developed for the vessel MV SSL THAMIRABARANI is to provide information on hazardous materials present in structural, equipment and other parts of the vessel (e.g. paints) in order to protect health and safety, and to prevent pollution of the environment at ship recycling facilities. This information has been incorporated in the form of a clear and simplified document that will accompany the ship throughout her operating life, illustrating any changes either to the ship's particulars or the identity, quantity, and location of the hazardous materials.

The Inventory was developed according to the Guidelines for the Development of the Inventory of Hazardous Materials adopted as Resolution MEPC.379 (80) (adopted on 7 July 2023) 2023 GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY OF HAZARDOUS MATERIALS. Its development and maintenance during the operational life of the vessel will assist to demonstrate the ongoing compliance with Regulation 5 of the Hong Kong International Convention for the Safe and Environmentally Sound Recycling of Ships, after its entry into force, as being a reasonable listing of any potentially hazardous materials of the vessel.

The development of the Inventory reflects the proactive approach of Transworld Ship Management Pvt Ltd in ensuring compliance of the vessel with the abovementioned legislative requirements relating to the identification of hazardous materials onboard ships and their management at the end of her life cycle of the vessel. More specifically, the development and maintenance of the IHM for an existing vessel aims at providing:

1. Adequate documentation to enable the safe and environmentally sound decommissioning of hazardous materials for final disposal and recycling when the vessel comes to the end of her life cycle, and
2. The operators of the vessel with information on the nature, location and approximate quantity of hazardous materials found in her structural web and equipment.

This document consists of a summary of methodologies used for the development of the Inventory, an overview of:

- The link between the IHM and Hong Kong International Convention; and
- The link between the IHM and EU Regulation on Ship Recycling.

2.2 Abbreviation

AC	**Air-con**
Acc	Accommodation
AE	Auxiliary Engine
AFS	Anti-fouling systems
Cr (VI)	Hexavalent chromium and hexavalent chromium compounds
ECR	Engine Control Room
Egen	Emergency Generator
ER	Engine Room
EU	EU Regulation on Ship Recycling, (EU) No 1257/2013
FO	Fuel Oil
FW	Fresh Water
Fwd	Forward
HBCDD	Brominated Flame Retardant
HFO	Heavy Fuel Oil
HKC	IMO Hong Kong Convention SR/CON/2009
HM-item#	Hazardous Material No.
HPU	Hydraulic Power-Pack Unit
Hyd	Hydraulic
IHM	Inventory of Hazardous Materials
Lab	Laboratory
LO	Lubricating oil
ME	Main Engine
ODS	Ozone Depleting Substances
PBBs	Polybrominated Biphenyl
PCBs	Polychlorinated Biphenyl
PBDEs	Polybrominated Diphenyl Ethers
PCHM	Potentially Containing Hazardous Materials
PCN	Polychloronaphthalenes (Cl >=3)
PFOS	Perfluorooctane Sulfonic Acid
Rm	Room
SCCP	Certain Shortchain Chlorinated Paraffins
SGR	Steering Gear Room
Stbd	Starboard
SW	Sea Water
Upp	Upper
UPS	Uninterruptible power supply
V	Visual inspection
Vent	Ventilation
VSCP	Visual Sampling Check Plan

The Viswa Group © 2020

2.3 The link between the IHM and the Hong Kong International Convention

The Hong Kong International Convention for the Safe and Environmentally Sound Recycling of Ships was adopted in an IMO Diplomatic Conference that took place in May 2009 in Hong Kong. The provisions of this Convention were progressively developed with inputs provided from IMO Member States and relevant non-governmental organizations in co-operation with the International Labour Organization and the Parties to the Basel Convention.

The regulations of the Convention cover the design, construction, operation and preparation of ships to facilitate their safe and environmentally sound recycling, without compromising the safety and operational efficiency of ships; the operation of ship recycling facilities in a safe and environmentally sound manner; and the establishment of an appropriate enforcement mechanism for ship recycling, incorporating certification and reporting requirements.

Ships to be sent for recycling will be required when the Convention enters into force, to carry an IHM, which will be specific to each ship. In the Convention, a list of hazardous materials is provided; the installation or use of which, is prohibited or restricted in shipyards, ship repair yards, and ships of Parties to the Convention.

Ships will be required to have an initial survey to verify the inventory of hazardous materials, additional surveys during the life of the ship, and a final survey prior to recycling. It should be noted that the development of the IHM constitutes an essential step for the issuing of the International Certificate on Inventory of Hazardous Materials either by the Flag State Administration of the vessel or by any organization authorized by the latter, following a successful completion of an initial or renewal survey as required by the Convention.

According to Regulation 5 (Inventory of Hazardous Materials) of the Convention:

1. Reg 5.1: “Each new ship shall have on-board an Inventory of Hazardous Materials.”
2. Reg 5.2: “Existing ships shall comply as far as practicable with the requirements applied for new ships not later than 5 years after the entry into force of this Convention or before going for recycling if this is earlier.”

2.4 The link between the IHM and EU Regulation on Ship Recycling, REGULATION (EU) No 1257/2013

With regards to the control of certain hazardous materials and the need to compile and carry onboard a ship specific IHM, the European Regulation on ship recycling (thereafter referred to as the ER) is structured in the same way as the HKC, requiring the three-part IHM to be compiled taking into account the guidelines of the HKC. Like the HKC, the ER now differentiates between existing ships and new buildings, with existing ships having to identify “at least” those materials onboard that are listed in ER’s Annex I, while new buildings are being prohibited to be fitted with materials listed in Annex I and being required to identify (location and approximate quantities) materials listed in ER’s Annex II.

One important difference between the ER and the HKC, is in the inclusion of two extra hazardous materials, which are already banned in European Union law, in Annex I of the ER (Perfluoro octane sulfonic acid and its derivatives, or **PFOS**, the main application onboard ships being in some firefighting

The Viswa Group © 2020

foams), and another one in Annex II (Brominated flame retardant, or **HBCDD**, the main application onboard ships being in expanded polystyrene used for cryogenic insulation, such as for liquefied gas tanks but also for refrigerator areas). A relevant footnote in Annex I to the ER states that PFOS "is not applicable to ships flying the flag of a third country", while the HBCDD, being a material of Annex II, strictly speaking need only be included in IHMs of new buildings, and in any retrofits involving changes to structure and equipment of existing ships. As the ER treats all ships flying the flag of a third country as existing ships, regardless of their date of built (see ER's Article 12(1), referring to Art. 5(2)), it follows that inclusion of information on the HBCDD will not be required of IHMs of non-EU flagged ships, unless HBCDD has been installed during a retrofit. Conversely, IHMs compiled for EU flagged ships after the date of application of the ER will fully satisfy the requirements of the HKC.

2.5 Structure of the IHM

In principle, an IHM should consist of three distinct parts, as follows:

- Part I: Materials contained in ship structure or equipment.

Part I of the Inventory which provides information on the potentially hazardous materials identified in the ship's structure and equipment is advised to be properly maintained and updated, especially after repairs, conversions or planned maintenance onboard the ship.

- Part II: Operationally generated wastes

If the waste to be listed in Part II of the Inventory provided in Table C (Potentially hazardous items of the MEPC.379 (80), are intended for delivery with the ship to a Ship Recycling Facility, the quantity of the operationally generated waste should be estimated, and their approximate quantities and locations should be listed in Part II of the Inventory.

- Part III: Stores

If the stores to be listed in Part III of the Inventory provided in Table C (Potentially hazardous items of the MEPC.379 (80), are intended for delivery with the ship to a Ship Recycling Facility, then the unit, quantity and location of these stores should be listed in Part III of the Inventory. Parts II and III of the Inventory which provide information on the operationally generated wastes as well as the stores remaining onboard, should be developed prior to or on the final voyage of the ship to a recycling facility.

The materials that should be listed in the Inventory are classified under "Table A", "Table B", "Table C" or "Table D" of the MEPC.379 (80), according to their properties, as follows:

Table A – Materials listed in appendix 1 of the Annex to the Convention

No.	Materials		Inventory			Threshold value
			Part I	Part II	Part III	
A-1	Asbestos		x			0.1%[4]
A-2	Polychlorinated biphenyls (PCBs)		x			50 mg/kg[5]
A-3	Ozone-depleting substances	CFCs	x			no threshold value[6]
		Halons	x			
		Other fully halogenated CFCs	x			
		Carbon tetrachloride	x			
		1,1,1-Trichloroethane (Methyl chloroform)	x			
		Hydrochlorofluorocarbons	x			
		Hydrobromofluorocarbons	x			
		Methyl bromide	x			
		Bromochloromethane	x			
A-4	Anti-fouling systems containing organotin compounds as a biocide		x			2,500 mg total tin/kg[7]
	Anti-fouling systems containing cybutryne		x			1,000 mg/kg[8]

Table B – Materials listed in appendix 2 of the annex to the Convention

No.	Materials	Inventory			Threshold value
		Part I	Part II	Part III	
B-1	Cadmium and cadmium compounds	x			100 mg/kg[9]
B-2	Hexavalent chromium and hexavalent chromium compounds	x			1,000 mg/kg[8]
B-3	Lead and lead compounds	x			1,000 mg/kg[8]
B-4	Mercury and mercury compounds	x			1,000 mg/kg[8]
B-5	Polybrominated biphenyl (PBBs)	x			50 mg/kg[10]
B-6	Polybrominated diphenyl ethers (PBDEs)	x			1,000 mg/kg[8]
B-7	Polychlorinated naphthalenes (more than 3 chlorine atoms)	x			50mg/kg[11]
B-8	Radioactive substances	x			no threshold value[12]
B-9	Certain short-chain chlorinated paraffins (alkanes, C10-C13, chloro)	x			1%[13]

Scope of the inventory of hazardous materials	Shipbuilding and operating	Preparation prior to recycling	
	Part I Structure and Equipment	Part II Operative Wastes	Part III Stores
Table A Materials Mandatory for new/existing ships and new installations	✓		
Table B Materials Mandatory for new ships/installations; voluntary for existing ships	✓		
Table C Materials Potentially hazardous items		✓	✓
Table D Materials Regular consumer goods potentially containing hazardous materials	List of exclusions		✓

Figure 2-1, Scope of the IHM per phase

Hazardous Materials of concern for IHM Part I of an existing ship are listed in Table A. Hazardous Materials listed in Table B should also be considered where applicable and practicable. The IHM Part I has to be maintained during ship's lifetime by the ship-owner.

IHM Part II and III shall be prepared prior to the last voyage by taking into account the amount of operationally generated wastes and goods in store.

According to Resolution MEPC.379 (80) "The procedures described in subsection 4.2 ("Development of Part I of the Inventory for existing ships") should be carried out by the ship-owner, who may draw upon expert assistance. Such an expert or expert party should not be the same as the person or organization authorized by the Administration to approve the Inventory."

2.6 Methodology of work

An outline of the methodology that is recommended to be used when developing Part I of the IHM is provided in the Resolution MEPC.379 (80). The whole procedure is based on the collection and evaluation of necessary information, the preparation of a visual/sampling check plan, the onboard survey and eventually the preparation of Part I of the IHM.

2.6.1 Collection of information

VISWA LAB SINGAPORE in co-operation with vessel SSL THAMIRABARANI, collected all the necessary documentation to enable the preparation of the visual/sampling check plan facilitating the onboard survey and to assist in locating areas and equipment where hazardous materials were likely to be found. The documentation included relevant drawings and plans of the vessel, manuals and technical specifications, Material Safety Datasheets, etc.

2.6.2 Analysis and definition of scope of investigations

The information collected in the abovementioned step was assessed covering all equipment, system and/or area onboard assumed to contain hazardous materials included in Table A and Table B of the Resolution MEPC.379 (80). The outcome of this assessment was reflected in the visual/sampling check plan.

2.6.3 Preparation of Visual/Sampling Check Plan

To specify the materials listed in the abovementioned, a Visual/Sampling Check Plan was prepared considering the collected information and the expertise of VISWA LAB SINGAPORE. The plan was prepared in such a way, that items installed onboard including new and old machineries will be covered and checked visually of thorough sampling in relation to its prior classification (“contained”, “not contained”, “unknown” etc.) made in the analysis.

Approval of the Visual/Sampling Check Plan by the Classification Society of the vessel is recommended to ensure its completeness and consistency with the ship particulars and to facilitate the verification of the IHM through the issuing of a relevant statement of compliance or of the International Certificate on the Inventory of Hazardous Materials in the long term.

2.6.4 Onboard Visual/Sampling Check

The IHM survey were carried out on board M/V SSL THAMIRABARANI from 23/10/2025 to 23/10/2025 by undersigned VISWA LAB IHM Expert during yard stay at Colombo Dry Docks, Sri Lanka

The objective of the survey was to identify, locate and quantify the potentially hazardous materials onboard the vessel through a close inspection at all accessible areas.

The visual/sampling check was performed according to the approved Visual/ Sampling Check Plan. Check points were marked in ship’s plan while samples were taken. Results were immediately recorded in the prepared Visual/Sampling Check Plan.

2.6.5 Preparation of IHM, Part I and related documentation

Any equipment, system and/or shipboard areas were classed as either “containing Hazardous Material” or “potentially containing Hazardous Materials», their approximate quantity and location was listed in the Part I of the Inventory. In case that, items containing hazardous materials were identified through the analysis of the samples by laboratories accredited with ISO 17025, their approximate quantity was also estimated. The analysis of samples is conducted according to the methods mentioned in the IHM Guidelines MEPC.379 (80) or equivalent / comparable methods.

2.6.6 Delivery of IHM, Part I

Following the development of the Inventory, it will be checked and certified from the selected Classification Society in order to be delivered to the owner of the vessel.

It should be noted that every effort was made to complete the present Inventory of Hazardous Materials for the vessel so that the best factual record of hazardous materials could be provided. Its development draws upon the existing IHM Guidelines and relies on the analysis of collected information and the findings of the onboard survey. As safety and environmental legislation develop, areas within the Inventory will be subject to greater scrutiny and greater detail in the future. Only when ship is being dismantled, can actual accurate checks be made to reveal in detail all hazardous materials and the quantities of them.

VISWA LAB SINGAPORE does not warrant or assume any kind of liability for the up-to-date nature, accuracy, completeness or quality of the HazMat weight calculation provided.

Liability claims against the VISWA LAB SINGAPORE in relation to any loss or damage arising out of or in connection with the use or non–use of HazMat weight calculation provided, including the use of incorrect or incomplete HazMat weight calculation data, are fully excluded permissible by law. All weight calculation data may be subject to alternation and are non-binding.

VISWA LAB SINGAPORE expressly reserves the right without notice to change, supplement or delete parts of the HazMat weight calculation data or to stop the publication and usage temporarily or definitively.

The Viswa Group © 2020




Figure 2-2, Flow diagram of the development of IHM for an existing ship

3. Ship particulars

Name of ship:	SSL THAMIRABARANI
IMO number:	9312468
Gross tonnage :	9520.0 (Tons)
Dimensions :	142.70m (Length OA), 133.50 m (Length BP), 22.60m (Breadth Moulded), 11.20m (Depth Moulded)
Builder:	Dae Sun Shipbuilding & Engineering Co. Ltd.
Year Of Delivery:	July 2005
Ship owner:	Transworld Ship Management India Pvt Ltd
Contact person:	Mr. Kabilan Sadasivam Deputy General Manager
Schedule:	Sample check, 23/10/2025 Visual check, 23/10/2025
Site of Check:	Colombo Dry Docks, Sri Lanka
In-charge of Check:	Matthew Lalchang (Viswalab)
Check Engineer:	Matthew Lalchang (Viswalab)
Sampling Engineer:	Matthew Lalchang (Viswalab)
Sampling method and anti-scattering measure for asbestos:	Wet the sampling location prior to cutting and allow it to harden after cutting to prevent scatter. Notes: Workers performing sampling activities shall wear protective equipment.
Sampling of fragments of paints	Paints suspected to contain TBT should be collected and analysed from load line, directly under bilge keel and flat bottom near amidships.
Chemical analysis method:	Method by ISO/DIS 22262-1 Bulk materials – Part 1: Sampling and qualitative determination of asbestos in commercial bulk materials and ISO/CD 22262-2 Bulk materials – Part 2: Quantitative determination of asbestos by gravimetric and microscopic methods. ICP Luminous analysis (TBT)
Laboratory:	Shanghai ULS Testing Technology Co. Ltd
Lab/Chemical analysis method:	Please refer to Appendix 9

The Viswa Group © 2020

4 Inventory of Hazardous Materials

4.1 (Part I): Hazardous Materials Contained in the Ship's Structure and Equipment

The following three tables summarize both hazardous materials and potentially containing hazardous materials (PCHM).

The detailed visual and sampling check plan (VSCP) during onboard investigation is attached in Appendix 3.

The photos of both visual and sample inspection are attached in Appendix 7 & 8.

The detailed estimation calculation of quantity of hazardous material and potentially containing hazardous materials (PCHM) are documented in Appendix 5.

4.2 (Part I): Paints and coating systems containing materials listed in Table A and Table B of Appendix 1 of the guidelines

No	Name of equipment and machinery	Location	Materials (Classification. in appendix 1)	Approx. quantity		Remark
				Mass	**Unit**	
1	Paints and Coatings (V01)	Side Shell under waterline, Paint and Coating, Out Shell Paint	Anti-fouling system containing containing cybutryne	792 kg		Cybutryne Has been applied on this ship previously, but is not in the external coating layer of the hull or external parts or surfaces on 1 Jan 2023

Note: Hazardous Material (Anti-fouling system containing ocontaining cybutryne were found and Detected

4.3 (Part I): Equipment and machinery containing materials listed in Table A and Table B of Appendix 1 of the guidelines

Item	Name of equipment	Location	Materials (Classification. in appendix 1)	Parts where used	Approx. quantity		Remark
					Mass	Unit	
1	Life / Rescue Boat Port Motor Starting Battery Rocket 12V, 90AH x 2 Nos (V03)	B Deck	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	20.0	Kg	Contained Lead and Lead Compounds
2	Life / Rescue Boat Starboard Motor Starting Battery Rocket 12V, 90AH x 2 Nos (V04)	B Deck	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	20.0	Kg	Contained Lead and Lead Compounds
3	GMDSS Radio Battery Exide, 12V, 200 AH x 6 Nos (V05)	A Deck-Battery RM	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	120.0	Kg	Contained Lead and Lead Compounds
4	General Use Battery Rocket, 12 V, 200AH x 6 Nos (V06)	A Deck-Battery RM	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	120.0	Kg	Contained Lead and Lead Compounds
5	Emergency generator Starting Battery Amaron BL1000 RMF x 2 Nos (V07)	Poop Deck-Emer Generator Room	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	80.0	Kg	Contained Lead and Lead Compounds
6	Spare Cable (ST75)	ER-2nd Deck-Electrician's Workshop	Lead and Lead Compounds	Outer sheath	5.0	Kg	Contained Lead and Lead Compounds
7	Spare Cable (ST76)	ER-2nd Deck-Electrician's Workshop	Lead and Lead Compounds	Inside Insulation layer	5.0	Kg	Contained Lead and Lead Compounds

Note: Hazardous materials (Lead and Lead Compounds) were found and detected, as shown above table.

4.4 (Part I): Structure and hull containing materials listed in Table A and Table B of appendix 1 of the guidelines

No	Name of equipment and machinery	Location	Materials (Classification. in appendix 1)	Parts where used	Approx. quantity		Remark
					Mass	**Unit**	
1	Sliding Door (ST47)	Nav. Bri. Deck-Wheel House	Lead and Lead Compounds	Rubber Packing	4.0 KG		Contained Lead and Lead Compounds
2	Wall Panel (ST60)	Upper Deck-Ref Chamber-Meat	Ozone Depleting Substances	Foam Insulation	30.0 KG		Contained Hydrochloro Fluorocarban (ODS). Assuming all foam insulation in Cold Room Chamber wall panel contained ODS

Note: Hazardous materials (Lead and Lead Compounds & ODS) were found and detected, as shown above table.

.

5. Results and Conclusion

This section analyses the results and conclusion of key findings to identify potential hazardous materials within the ship's structure and equipment. The lab findings show that **Lead and Lead Compounds & Ozone Depleting Substances** were detected at the time of the survey at:

1) Spare Cable (Outer Sheath/Inner Insulation Layer) - ER-2nd Deck-Electrician's Workshop
2) Sliding Door Rubber Packing - Nav. Bri. Deck-Wheel House
3) Wall Panel Foam Insulation - Upper Deck-Ref Chamber-Meat

Other hazardous material besides the above were lead-acid batteries used in lifeboats, emergency generator room, battery room, engine control room and other places. These batteries are to be properly recycled and disposed at the end of battery life.

6. References 1.1

S/No.	Document title
1	General Arrangement, M/V SSL THAMIRABARANI (IMO 9312468)
2	Engine Room Arrangement
3	Arrangement of Battery Room
4	International Anti-fouling System Certificate
5	Fire Alarm System
6	Accommodation Arrangement Plan
7	Storage Battery

The Viswa Group © 2020

6. APPENDIX 1 – ANTI FOULING CERTIFICATES

DNV

INTERNATIONAL ANTI-FOULING SYSTEM CERTIFICATE

DNV Id No: **45765**
Date of issue: **2023-06-24**

Issued under the provisions of the International Convention on the Control of Harmful Anti-Fouling Systems on Ships (the Convention)
under the authority of the Government of

INDIA

by **DNV**

Particulars of ship

Name of Ship:	**SSL THAMIRABARANI**
Distinctive Number or Letters:	**VTUQ**
Port of Registry:	**MUMBAI**
Gross Tonnage:	**9520**
IMO Number:	**9312468**

When a Certificate has been previously issued, this Certificate replaces the Certificate dated:
2023-03-31

This is to certify:

1. the ship has been surveyed in accordance with regulation 1 of Annex 4 to the Convention, and
2. the survey shows that the anti-fouling system on the ship complies with the applicable requirements of Annex 1 to the Convention.

Completion date of survey on which this Certificate is based: **2005-07-18**

Issued at **Colombo, Sri Lanka** on **2023-06-24**

for **DNV**

This document is signed electronically in accordance with IMO FAL.5/Circ.39/Rev.2. Validation and authentication can be obtained from trust.dnv.com by using the Unique Tracking Number (UTN):
nN2540331-msk and ID: 45765

Mohan Ariyaratne

LEGAL DISCLAIMER: Unless otherwise stated in the applicable contract with the holder of this document, or following from mandatory law, the liability of DNV AS, its parent companies and their subsidiaries as well as their officers, directors and employees ("DNV") arising from or in connection with the services rendered for the purpose of the issuance of this document or reliance thereon, whether in contract or in tort (including negligence), shall be limited to direct losses and under any circumstance be limited to 300,000 USD, and any claims made against DNV based upon alleged defective services provided by DNV to designers, yards, manufacturers or other stakeholders in the newbuilding process shall under any circumstance be time-barred if made later than 12 months from delivery of the vessel. Based upon written request to the DNV legal entity which has issued this document, a higher limitation of liability may be agreed on a case-by-case basis.

The Viswa Group © 2020

DNV

DNV Id No: 45765
Date of issue: 2023-06-24

An anti-fouling system controlled under Annex 1 containing:

	Has not been applied during or after construction of this ship	Has been applied on this ship previously, but has been removed by	Has been applied on this ship previously, but has been covered with a sealer coat applied by	Has been applied on this ship previously, but is not in the external coating layer of the hull or external parts or surfaces on	Was applied on this ship prior to
Organotin compounds which act as biocides	No.1 ☐	No.2 **(name of the facility)** on **(yyyy-mm-dd)** ☐	No.3 **(name of the facility)** on **(yyyy-mm-dd)** ☐	Not applicable	Not applicable
Cybutryne	No.4 ☐	No.5 **(name of the facility)** on **(yyyy-mm-dd)** ☐	No.6 **(name of the facility)** on **(yyyy-mm-dd)** ☐	No.7 1 January 2023 ☒	No.8 1 January 2023, but must be removed or covered with a sealer coat prior to on **(yyyy-mm-dd)** ☐

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

RECORD OF ANTI-FOULING SYSTEMS

Details of Anti-Fouling System(s) applied

Name of ship:	**SSL THAMIRABARANI**
Distinctive Number or Letters:	**VTUQ**
IMO Number:	**9312468**
Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2005-07-18**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Dae Sun Shipbuilding & Eng. Co., Ltd., Busan, Korea**
Name(s) of Anti-Fouling System manufacturer(s):	**Sigma Kalon**
Name(s) and colour(s) of Anti-Fouling System(s):	**Sigma Alphagen 20 Series (red brown)**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**2-methylthio-4-tert-butylamino-6-cyclopropylamino-s-triazine (CAS No. 28159-98-0); Copper(1)oxide (CAS No. 1317-39-1)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	-
Date of application of sealer coat:	-

THIS IS TO CERTIFY that this Record is correct in all respects.

Issued at **Colombo, Sri Lanka** on **2023-06-24**

for **DNV**

This document is signed electronically in accordance with IMO FAL.5/Circ.39/Rev.2. Validation and authentication can be obtained from trust.dnv.com by using the Unique Tracking Number (UTN):
nN2540331-msk and ID: 45765

Mohan Ariyaratne

The Viswa Group © 2020

DNV

DNV Id No: 45765
Date of issue: 2023-06-24

Endorsement of the record

AFS

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2008-06-25**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Orient Shipyard Co., Ltd / Gamcheon, Korea**
Name(s) of Anti-Fouling System manufacturer(s):	**Chugoku Samhwa Paints, Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**SEA GRANDPRIX CF-ACE / Red Brown**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Pyridine-triphenyl Borane (CAS No. 971-66-4)** **Zinc Pyrithione (CAS No. 13463-41-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: **2008-06-25**

DNV
SAFEGUARDING LIFE, PROPERTY AND THE ENVIRONMENT
1864

Signature: .....

Confirmed carried out

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 4 of 13

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2010-05-14**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Qingdao Beihai Shipyard / Huangdao, China**
Name(s) of Anti-Fouling System manufacturer(s):	**International Paint(Korea) Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**Interswift 655 / Dark Red**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper pyrithione (CAS No. 14915-37-8)** **Copper(1)oxide (CAS No. 1317-39-1)** **Zineb (CAS No. 12122-67-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: **2010-05-14**

DNV – SAFEGUARDING LIFE, PROPERTY AND THE ENVIRONMENT

Confirmed carried out

Signature: .....

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 5 of 13

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2013-02-26**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Minnan Shipyard / Shanghai, China**
Name(s) of Anti-Fouling System manufacturer(s):	**International Paint (Korea) Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**Interspeed6200, International 867 / Red, Brown**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper(1)oxide (CAS No. 1317-39-1)** **Zineb (CAS No. 12122-67-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: **2013-02-26**

DNV
Confirmed carried out

Signature: .....

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 6 of 13

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2015-07-22**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Longshan Shipyard / Zhoushan, China**
Name(s) of Anti-Fouling System manufacturer(s):	**Nippon Paint Marine Korea Co., Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**Ecoloflex SPC 200 HS, Ecoloflex SPC 200 / Red Brown & Brown**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper pyrithione (CAS No. 14915-37-8)** **Copper(1)oxide (CAS No. 1317-39-1)** **Zinc Pyrithione (CAS No. 13463-41-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: Date: **2015-07-22**

DNV
SAFEGUARDING LIFE, PROPERTY AND THE ENVIRONMENT
Confirmed carried out

Signature:

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 7 of 13

The Viswa Group © 2020

DNV

DNV Id No: 45765
Date of issue: 2023-06-24

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2018-07-30**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Yeosu Ocean Co., Ltd. / Yeosu, Korea**
Name(s) of Anti-Fouling System manufacturer(s):	**Nippon Paint Marine Korea Co., Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**Ecoloflex SPC 200 / Brown Z, D. Brown K**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper(1)oxide (CAS No. 1317-39-1)** **Zinc Pyrithione (CAS No. 13463-41-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: **2018-07-30**

DNV
Confirmed carried out

Signature: .....

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 8 of 13

The Viswa Group © 2020

DNV

DNV Id No: 45765
Date of issue: 2023-06-24

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free self polishing anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2020-07-17**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Yeosu Ocean Co., Ltd. / Yeosu, Korea**
Name(s) of Anti-Fouling System manufacturer(s):	**Nippon Paint Marine Korea Co., Ltd.**
Name(s) and colour(s) of Anti-Fouling System(s):	**Ecoloflex SPC 200 / Light Brown Z, Dark Brown K**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper(1)oxide (CAS No. 1317-39-1)** **Zinc Pyrithione (CAS No. 13463-41-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: **2020-07-17**

DNV
Confirmed carried out

Signature: .....

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 9 of 13

The Viswa Group © 2020

DNV

DNV Id No: 45765
Date of issue: 2023-06-24

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:	**Organotin-free controlled depletion polymer anti fouling system**
Date(s) of application of Anti-Fouling System(s):	**2023-06-23**
Name(s) of company(ies) and Facility(ies)/location(s) where applied:	**Colombo Dockyard PLC Colombo, Sri Lanka**
Name(s) of Anti-Fouling System manufacturer(s):	**International paints**
Name(s) and colour(s) of Anti-Fouling System(s):	**INTERSPEED 6200 BQA 624 RED**
Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):	**Copper(1)oxide (CAS No. 1317-39-1)** **Zineb (CAS No. 12122-67-7)**
Type(s) of sealer coat, if applicable:	**Not applicable**
Name(s) and colour(s) of sealer coat applied, if applicable:	**Not applicable**
Date of application of sealer coat:	**Not applicable**

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: **Colombo, Sri Lanka** Date: **2023-06-24**

DNV

Signature: **Mohan Ariyaratne**

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 10 of 13

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:

Date(s) of application of Anti-Fouling System(s):

Name(s) of company(ies) and Facility(ies)/location(s) where applied:

Name(s) of Anti-Fouling System manufacturer(s):

Name(s) and colour(s) of Anti-Fouling System(s):

Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):

Type(s) of sealer coat, if applicable:

Name(s) and colour(s) of sealer coat applied, if applicable:

Date of application of sealer coat:

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: Date:

Signature:

Stamp

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:

Date(s) of application of Anti-Fouling System(s):

Name(s) of company(ies) and Facility(ies)/location(s) where applied:

Name(s) of Anti-Fouling System manufacturer(s):

Name(s) and colour(s) of Anti-Fouling System(s):

Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):

Type(s) of sealer coat, if applicable:

Name(s) and colour(s) of sealer coat applied, if applicable:

Date of application of sealer coat:

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: Date:

Signature:

Stamp

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:

Date(s) of application of Anti-Fouling System(s):

Name(s) of company(ies) and Facility(ies)/location(s) where applied:

Name(s) of Anti-Fouling System manufacturer(s):

Name(s) and colour(s) of Anti-Fouling System(s):

Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):

Type(s) of sealer coat, if applicable:

Name(s) and colour(s) of sealer coat applied, if applicable:

Date of application of sealer coat:

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: Date:

Signature:

Stamp

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used:

Date(s) of application of Anti-Fouling System(s):

Name(s) of company(ies) and Facility(ies)/location(s) where applied:

Name(s) of Anti-Fouling System manufacturer(s):

Name(s) and colour(s) of Anti-Fouling System(s):

Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)):

Type(s) of sealer coat, if applicable:

Name(s) and colour(s) of sealer coat applied, if applicable:

Date of application of sealer coat:

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: Date:

Signature:

Stamp

The Viswa Group © 2020

DNV

DNV Id No: **45765**
Date of issue: **2023-06-24**

Endorsement of the record

Details of Anti-Fouling System(s) applied

Type(s) of Anti-Fouling System(s) used: .....

Date(s) of application of Anti-Fouling System(s): .....

Name(s) of company(ies) and Facility(ies)/location(s) where applied: .....

Name(s) of Anti-Fouling System manufacturer(s): .....

Name(s) and colour(s) of Anti-Fouling System(s): .....

Active ingredient(s) and their Chemical Abstract Service Registry Number (CAS number(s)): .....

Type(s) of sealer coat, if applicable: .....

Name(s) and colour(s) of sealer coat applied, if applicable: .....

Date of application of sealer coat: .....

THIS IS TO CERTIFY:
that a survey required in accordance with regulation 1(1)(b) of Annex 4 to the AFS Convention on the prohibition of organotin compounds on ships found that the ship was in compliance with the Convention.

Place: ..... Date: .....

Signature: .....

Stamp

Form code: AFS 121 Revision: 2022-12 www.dnv.com Page 13 of 13

The Viswa Group © 2020

7. APPENDIX 2 – IHM EXPERT CERTIFICATE

DNV

CERTIFICATE

Register No.: 144696625

This is to certify that

Matthew Lalchang

successfully completed the HazMat training course, passed the examination and is confirmed as

Approved HazMat Expert

since: 15 November 2019

The participant has the required knowledge and is able to prepare an "Inventory of Hazardous Materials" (IHM) with reference to the following:

- Hong Kong International Convention for the Safe and Sound Recycling of Ships 2009
- EU Ship Recycling Regulation (EC 1257/2013)

Certificate issued on 08 December 2022 Refresher Training

This certificate is valid until 13 November 2025 and subject to revalidation every three years.

Khalid Mahmood

Section Environmental Protection

DNV Headquarters, Veritasveien 1, P.O.Box 300, 1322 Høvik, Norway. Tel: +47 67 57 99 00. www.dnv.com

DNV

CERTIFICATE

Register No.: 144696624

This is to certify that

Sivaprakash Narayanasamy

successfully completed the HazMat training course, passed the examination and is confirmed as

Approved HazMat Expert

since: 15 November 2019

The participant has the required knowledge and is able to prepare an "Inventory of Hazardous Materials" (IHM) with reference to the following:

- Hong Kong International Convention for the Safe and Sound Recycling of Ships 2009
- EU Ship Recycling Regulation (EC 1257/2013)

Certificate issued on 08 December 2022 Refresher Training

This certificate is valid until 13 November 2025 and subject to revalidation every three years.

Khalid Mahmood

Section Environmental Protection

DNV Headquarters, Veritasveien 1, P.O.Box 300, 1322 Høvik, Norway. Tel: +47 67 57 99 00. www.dnv.com

ABS

Certificate Number	**24-6559357-A**
Issue Date	21-AUG-2024
Expiry Date	27-OCT-2027
ABS Port Office	Singapore
Company's Website	www.theviswagroup.com

CERTIFICATE OF

Recognized Service Supplier

This is to certify that

VISWALAB SINGAPORE PTE LTD

located at

80 Tagore Lane, Singapore 787501.

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Supplier to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

Inventory of Hazardous Materials

Attached Certificate Appendix provides specific scope of approval, authorized personnel, manufacturer authorizations, and subcontractors.

It is the responsibility of the Service Supplier to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the Service Supplier is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. Where required by the category of service, the Service Supplier shall provide valid evidence that it is authorized or licensed by the equipment manufacturer to service the makes and models of equipment for which approval is sought. If approval from the manufacturer is not attained, a surveyor must be present at time of survey to continue work. Alternatively, current written instructions from the flag state are to be obtained to continue work without the surveyor present. Service Suppliers must present photo identification, evidence of qualification and authorizations from manufacturers, as applicable, at the time of service.

The ABS office issuing this certificate is to be kept updated with changes to the management of the company, employees, equipment and models on the authorization list and any changes made.

Tneoh Tee Kwang, Surveyor

CLS-SFM-00040 Rev.30

Page 1 of 3

ABS

TERMS AND CONDITIONS

The issuance and interpretation of this Certificate of Service Recognition (hereinafter referred to as "certificate") is subject to the following terms and conditions.

1. REPRESENTATIONS AS TO SERVICE RECOGNITION

The Certificate is a representation only that the specified Company has been audited by ABS and has given a satisfactory practical demonstration of the listed services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys and is issued solely for the use of ABS and its committees. The validity, applicability and interpretation of this certificate are governed by the Rules, Guides, or standards of ABS who shall remain the sole judge thereof.

2. RESPONSIBILITY AND LIABILITY

The Company is not a subcontractor of ABS and is not an agent of ABS for any purpose. The Company remains solely responsible for its equipment, the qualifications and competency of its personnel, the supervision of its personnel, and the safety of its personnel while performing its services. Nothing contained in this certificate or any letter or report issued in contemplation of this certificate shall be deemed to relieve Company or any designer, builder, owner, manufacturer, seller, supplier, repairer, operator or other entity of any warranty express or implied nor to create any interest, right, claim or benefit in any third party. It is understood and agreed that nothing expressed herein is intended or shall be construed to give any person, firm or corporation, other than the parties hereto, any right, remedy or claim hereunder; all provisions hereof are for the sole and exclusive benefit of the parties hereto.

3. LIMITATION

ABS makes no representations beyond those contained herein regarding its reports, letters, audits, certificates or other services.

4. HOLD HARMLESS

The party to whom this certificate is issued, and his assignee and successor in interest, agree to indemnify and hold harmless ABS from and against any and all claims, demands, lawsuits, or actions for damages, including legal fees, to persons and property, tangible, intangible, or otherwise which may be brought against ABS incidental to, arising out of or in connection with the work done, services performed or material to be furnished under this certificate, except for those claims caused solely and completely by the negligence of ABS, its agents, employees, officers, directors or subcontractors.

Company shall defend, indemnify, and hold harmless ABS and its affiliates from and against any and all third party claims and liabilities (including, without limitation, reasonable attorneys' fees and costs), regardless of the form of action, arising out of or in connection with a claim that the service(s) offered by Company for which Company has sought recognition from ABS, infringes, violates, or misappropriates a valid third party patent, copyright, or other proprietary right, provided that Company is promptly notified in writing of such claim, and ABS has not reached any compromise or settlement in such action or made any admissions in respect of the same.

5. ARBITRATION

Any and all differences and disputes of whatsoever nature arising out of or relating to this certificate shall be put to arbitration in the City of New York pursuant to the laws relating to arbitration there in force, before a board of three persons, consisting of one arbitrator to be appointed by ABS, one by Company, and one by the two so chosen. The decision of any two of the three on any point or points shall be final. Until such time as the arbitrators finally close the hearings either party shall have the right by written notice served on the arbitrators and on an officer of the other party to specify further disputes or difference under this Agreement for hearing and determination. The arbitration is to be conducted in accordance with the rules of the Society of Maritime Arbitrators, Inc. The arbitrators may grant any relief, other than punitive damages which they, or a majority of them, deem just and equitable and within the scope of the agreement of the parties, including, but not limited to, specific performance. Awards made in pursuance to this clause may include costs including a reasonable allowance for attorney's fees and judgment may be entered upon any award made hereunder in any court having jurisdiction. ABS and Company hereby mutually waive any and all claims to punitive damages in any forum. Company shall be required to notify ABS within thirty (30) days of the commencement of any arbitration between it and third parties which may concern ABS' work in connection with this certificate and shall afford ABS an opportunity, at ABS' sole option, to participate in the arbitration.

6. TIME BAR TO LEGAL ACTION

Any statutes of limitation notwithstanding, Company expressly agrees for itself and its affiliated companies that its right to bring or to assert against ABS any and all claims, demands or proceedings whether in arbitration or otherwise shall be waived unless (a) notice is received by ABS within thirty (30) days after Company or its affiliates had notice of or should reasonably have been expected to have had notice of the basis for such claims; and (b) arbitration or legal proceedings, if any, based on such claims or demands of whatever nature are commenced within one year of the date of such notice to ABS.

7. LIMITATION OF LIABILITY

The combined liability of American Bureau of Shipping, its officers, employees, agents or subcontractors for any loss, claim, or damage arising from negligent performance or non-performance of any services under this Agreement, or from breach of any implied or express warranty of workmanlike performance in connection with the services, or from any other reason, to any person, corporation, partnership, business entity, sovereign, country or nation, shall be limited to the greater of a) $100,000 or b) an amount equal to ten times the sum actually paid for the services alleged to be deficient. The limitation of liability may be increased up to an amount twenty- five times that sum paid for services upon receipt of Company's written request at or before the time of performance of service and upon payment by Company of an additional fee of $10 for every $1,000.00 increase in the limitation.

8. ETHICS AND COMPLIANCE

Falsification of this certificate, including any alterations by an entity other than ABS, may result in actions against the culpable entity up to and including legal proceedings for the misrepresentation of this document. Measures may include but are not limited to the immediate and indefinite suspension of the certificate in question, delisting of the entity from ABS online certification database, and immediate restriction of use of the authorized ABS service logos. Upon investigation by ABS, ABS reserves the right to permanently disqualify the implicated entity or its Principals from holding any service certifications from ABS.

This certificate is intended only for the use of the individual or entity to which it is addressed, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

CLS-SFM-00040 Rev.30

Page 2 of 3

The Viswa Group © 2020

ABS

APPENDIX TO ABS SERVICE SUPPLIER CERTIFICATION NO. 24-6559357-A

Scope of Approval, Limitations or Restrictions

The service recognition is for preparing visual sampling check plan, onboard visual/sampling check and develop inventory of hazardous materials for existing vessels.

Authorized Personnel

Arvind Kanasan, Girivarma Kamalanathan, Meghraj Makrand Hahagirdar, Kalaiarasan Gunasigren, Matthew S/O Lalchang, Sivaprakash S/O Narayanasamy, Roy Choudhury Jayant

Quality Manager

Matthew S/O Lalchang

Authorization(s) from Equipment Manufacturers and Flag Administrations*

-

Subcontractor and Scope of Subcontracting Work

i. ALS Technichem (S) Pte Ltd

- Scope of work: IHM material analysis

ii. Shanghai ULS Testing Technologies Co Ltd

- Scope of work: IHM material analysis

NOTE: This certificate evidence compliance with one or more of the Rules, Guides, standards or other criteria of the American Bureau of Shipping and is issued solely for the use of the Bureau. This certificate is a representation only that the Company has been assessed in accordance with ABS procedures and found capable of providing the listed service as limited by the associated recognition letter. This certificate is governed by the Terms and Conditions on the above page hereof and by the Rules, Guides or Standards of the American Bureau of Shipping, who shall remain the sole judge thereof.

* For statutory related activities, unless specially directed by the Administration, this approval is not to be construed as a substitute or a Flag Administration's approval for the purpose of SOLAS (2020 Consolidated Edition), as amended.

CLS-SFM-00040 Rev.30 Page 3 of 3

Certificate No.: SNG24A018-Amend(1)

Indian Register of Shipping

CERTIFICATE OF APPROVAL FOR SERVICE SUPPLIERS

This is to certify that, based upon satisfactory audit and witnessing the services carried out by the firm in accordance with IRS procedures

VISWALAB SINGAPORE PTE LTD
TAGORE 8
80 TAGORE LANE, #04-19
SINGAPORE 787805
-
SINGAPORE

has been approved for
- Visual/sampling checks for the preparation of Inventory of Hazardous Materials (IHM) on board ships for hazardous materials.

Completion date of verification on which this certificate is based **25/10/2024.**

This certificate is valid upto **24/10/2027.**

- The approval is subject to the terms and conditions as specified in Annexure I to this certificate.
- The approval is granted for Hazardous Materials as specified in Annexure II to this certificate.

Issued at **Singapore** on **07/03/2025.**

Official Seal

For Indian Register of Shipping
Digitally Signed By: Ashish Panwar
Place: Singapore
Date: 07/03/2025(dd/mm/yyyy)

Surveyors to Indian Register of Shipping

This certificate replaces the previously issued Cert. No. SNG24A018 dated 25/10/2024, which is hereby cancelled.

See overleaf for conditions of issue of this certificate

SSA IHM Cert (Rev.5) Page 1 of 1

TID: IRS/2025/SNG24A018-Amend(1)/05487

The Viswa Group © 2020

This Certificate is issued upon the following terms and conditions as laid down in the Society's Regulations:

Whilst Indian Register of Shipping, a Classification Society, along with its subsidiaries and associates (hereinafter referred to as the Society) and its Board/Committees use their best endeavors to ensure that the functions of the Society are properly carried out, in providing services, information or advice neither the Society nor any of its servants or agents warrants the accuracy of any information or advice supplied. Except as set out herein neither the Society nor any of its servants or agents (on behalf of each of whom the Society has agreed this clause) shall be liable for any loss damage or expense whatever sustained by any person due to any act or omission or error of whatsoever nature and however caused of the Society, its servants or agents or due to any inaccuracy of whatsoever nature and howsoever caused in any information or advice given in any way whatsoever by or on behalf of the Society, even if held to amount to a breach of warranty. Nevertheless, if any person uses services of the Society, or relies on any information or advice given by or on behalf of the Society and suffers loss damage or expenses thereby which is proved to have been due to any negligent act omission or error of the Society, its servants or agents or any negligent inaccuracy in information or advice given by or on behalf of the Society then the Society will pay compensation to such person for his proved loss up to but not exceeding the amount of the fee charged by the Society for that particular service, information or advice.

Any notice of claim for loss, damage or expense, as referred to above, shall be made in writing to the Society's Head Office within six months of the date when the service, information or advice was first provided, failing which all the rights to any such claim shall be forfeited and the Society shall be relieved and discharged from all liabilities.

TID: IRS/2025/SNG24A018-Amend(1)/05487

CERTIFICATE OF APPROVAL OF SERVICE SUPPLIER

No. : HDOHM-0008-23

This is to certify that

VISWALAB SINGAPORE PTE LTD

Address : 80 TAGORE LANE, SINGAPORE 787501

is approved as a service supplier to provide the following service under Guidance for Approval of Service Suppliers and the relevant requirement of the society rule.

Scope of service

Visual / Sampling check and testing for hazardous material

This certificate is valid until **2026.07.02**

Issued at **Busan** on **2023.09.25**

See the appendix for details regarding manufacturer authorizations, etc

This certificate is signed electronically in accordance with IMO FAL.5/Circ.39/Rev.2. Validation and authentication of the certificate can be confirmed from "http://e-cert.krs.co.kr" by using the tracking No(ME23044228685) and certificate No.(HDOHM000823).

KOREAN REGISTER

General Manager of Survey Team

Home page : www.krs.co.kr E-mail : servicesupplier@krs.co.kr TEL : +82 70 8799 8200 FAX : +82 70 8799 8219
Form No.SUP-CE-COM (2021. 1)

The Viswa Group © 2020

TERMS AND CONDITIONS

A. The Responsibility and Duty of the Registered Company

(1) The operator who carries out the service shall possess the appropriate license issued by the Government or have equivalent qualifications.
(2) The registered company shall be responsible for ensuring the safety of the operator from any danger which can arise during operation.
(3) The registered company shall check the equipment to ensure the proper functioning of the equipment before operation.
(4) The registered company, if necessary, shall have the equipment calibrated by authorized organizations in order to maintain the required accuracy within the period prescribed in the standard, and have the contents recorded and maintained.
(5) The registered company shall keep a copy of the service report submitted to this Society and applicant for at least 5 years.
(6) The registered company shall notify this society immediately of any alterations of the condition at the time of the approval, including changes of staff and of any entries on this certificate.

B. Confidentiality

The detail information acquired during the job shall not be disclosed or released to third party without permission of the applicant or this Society.

C. Scope and Limitation

The extent of engagement is limited to the scope stated on this Certificate unless attached otherwise.

D. Renewal of the Approval

Renewal audit should be carried out within 3 months before the expiry date of Certificate. However, the validity of new Certificate will be started from the next day of expiry date of previous Certificate.

E. Cancellation of Approval

The approval may be cancelled in cases:
(1) Where the service provided is improperly carried out or the results are improperly reported.
(2) Where the Society's surveyor has found major deviations in the operating system of the firm.
(3) Where the supplier fails to inform of any alteration to the operation system to this Society.
(4) Where occasional audit, when deemed necessary by this Society, has not been carried out.
(5) Where wilful acts or omissions are ascertained.
(6) Where the approval fees are not paid.

The Viswa Group © 2020

APPENDIX I

No. : HDOHM-0008-23

Endorse

Home page : www.krs.co.kr E-mail : servicesupplier@krs.co.kr TEL : +82 70 8799 8200 FAX : +82 70 8799 8219
Form No.SUP-CE-COM (2021. 1)

APPENDIX I

No. : HDOHM-0008-23

Company :
Address :
Tel :
Fax :
E-mail :
Country :
City :
KR-Branch :

Office of
Deputy Commissioner
of Maritime Affairs

THE REPUBLIC OF LIBERIA
LIBERIA MARITIME AUTHORITY

22980 Indian Creek Drive
Suite 200
Dulles, Virginia 20166, USA
Tel: +1 703 790 3434
Fax: +1 703 790 3655
Email: Regcomdstandards@liscr.com
Web: www.liscr.com

31 October 2023

To,

Viswalab Singapore Pte Ltd
80 Tagore Lane
Singapore, 787501
Singapore

Subject: Acceptance of IHM Expert Company to conduct visual and/or sampling checks and testing of Hazardous Materials and to prepare the Inventory of Hazardous Materials on Liberian registered ships

Dear Sirs,

This Administration has reviewed the documentation submitted for compliance with the requirements for IHM Expert Companies as detailed in Appendix II of Marine Operations Note 06/2023, and the review has confirmed that **Viswalab Singapore Pte Ltd** meets the provisions in Resolution MEPC.379(80) for the development of the Inventory of Hazardous Materials.

Viswalab Singapore Pte Ltd is therefore authorized to conduct visual and/or sampling checks and testing of hazardous materials and to prepare the inventory of hazardous materials on board Liberian registered ships.

This letter will remain valid until the **31 October 2026.**

Regards,

Margaret Ansumana
Senior Deputy Commissioner of Maritime Affairs,
Republic of Liberia

The information contained in this letter is confidential and is intended only for the use of the addressee. Unauthorized use, disclosure, or copying is strictly prohibited. If you have received this communication in error, please notify us immediately at the number listed above.

RLM-033 Rev.03/2020

Page 1 of 1
Certificate No: LR2564328AS
Issue Date: 10/05/2025
Expiry Date: 09/05/2028

Lloyd's Register Approved Service Supplier

Supplier	**Viswalab Singapore Pte Ltd**
Address	80 Tagore Lane, Sindo Industrial Estate, Singapore, 787501, Singapore
Contact Details	Email: bqs@theviswagroup.com / matthew.lalchang@theviswagroup.com
Contact Number	Tel: +65 96154365

The above company having been assessed hereby receives approval in accordance with the requirements of Lloyd's Register Procedures for Approval of Service Suppliers as Supplier from the address(es) listed above for the provision of

Visual/Sampling Checks And Testing For Hazardous Materials, Such As Asbestos, PCBS, TBTS And CFCS Onboard Ships, Including Advise On Numbers And Locations Of Samples, And Preparation Of Reports On The Quantities,Locations And Estimates Of These Materials
Qualified personnel: 1) MATTHEW S/O LALCHANG 2) SIVA PRAKASH NARANASAMY 3) JAYANT K.ROY CHOUDHURY 4) KALAIARASAN 5) ARVIND KANASAN 6) ASCAR ALI 7) SAKTHIYUVARAJ

This approval is conditional upon the Supplier maintaining the documented scheme as audited by any member of the Lloyd's Register Group and hereby approved; and notifying Lloyd's Register in writing of any change to that scheme including any change in personnel, equipment or procedures. This certificate is issued to the Supplier and, subject to the Supplier complying with the necessary conditions, is valid to the date referred to above.

Sam Yap

Senior Surveyor - Marine to Lloyd's Register
Singapore Pte Ltd
A member of the Lloyd's Register group

9 North Buona Vista Drive, #02-01, Metropolis
Tower 1, 138588, Singapore

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

MA33.2.0

REPUBLIC OF THE MARSHALL ISLANDS
MARITIME ADMINISTRATOR

11495 Commerce Park Drive, Reston, Virginia 20191-1506
TELEPHONE: +1-954-763-7775 FAX: +1-954-763-7445
EMAIL: IHM @register-iri.com WEBSITE: www.register-iri.com

2 January 20255

Matthew Lalchang
Viswalab SingaporePTE Ltd
86 Tagore Lane, Sindo Industrial Estate
Singapore, 787501
+65 961 543 65
BQS@THEVISWAGROUP.COM, MATTHEW.LALCHANG@THEVISWAGROUP.COM

Subject: Recognition as an Inventory of Hazardous Material (IHM) Company

Viswalab Singapore Pte. Ltd. is recognized by the Republic of the Marshall Islands (RMI) Maritime Administrator ("the Administrator") as an IHM Company in accordance with MN 2-011-56. The Administrator has deemed the IHM Company as qualified to provide the following IHM services pertaining to and aboard vessels registered in the RMI:

Yes	No	Scope of Services
☒	☐	Collecting the necessary information;
☒	☐	Analyzing and defining the assessment scope;
☒	☐	Preparing Visual Sampling Check Plans;
☒	☐	Conducting onboard sampling
☐	☒	Laboratory analysis; and
☒	☐	Preparing IHM part I.

The following conditions must be met:

1. All work is carried out according to the Hong Kong Convention and EU SRR, as applicable.

2. All work is conducted according to any stipulations conveyed in the Recognized Organization's certification of the company.

3. All reports pertaining to an IHM, Part I include the credentials of IHM expert personnel and certification of the independent laboratories being employed.

By the Authority of
The Trust Company of the Marshall Islands, Inc.
Marshall Islands Maritime and Corporate Administrators, Inc.

The Viswa Group © 2020

4. No payments of money or anything of value or any other advantage will be offered, promised, or given, directly or indirectly, to any domestic or foreign government official or to another person upon the official's request or with the official's assent or acquiescence intending to obtain or retain business or an advantage in the conduct of business; further, Expert Company warrants that it will not offer to, promise to, or perform improperly any of its functions pursuant to this Recognition in exchange for payment of money or anything of value or any other advantage, nor will it offer money or anything of value or any other advantage in exchange for, or as an award for, the improper performance of another individual or entity.

5. No IHM Services performed in connection with this Recognition will be provided to vessels located in, or which IHM Company have actual notice that are *en route to*, a nation or region subject to comprehensive economic sanctions contrary to United States (U.S.), United Nations (U.N.) or other applicable local law.

This recognition is valid for one year, until 1 January 2026, provided that the company maintains a Recognized Organization's approval as an IHM service supplier (attached). The Administrator reserves the right to withdraw its recognition as it solely deems appropriate, including for non-performance, mis-performance, or expiration of the underlying certificate.

Signature: Joseph McKeown
Deputy Commissioner of Maritime Affairs

Name: Joseph McKeown

Certificates Attached:

The Viswa Group © 2020

LETTER OF APPOINTMENT

Under the authority of the Government of the Republic of Palau,
it is hereby certified that,

VISWALAB SINGAPORE PTE LTD

has been approved as

AUTHORIZED

SERVICE PROVIDER

on behalf of

PALAU INTERNATIONAL SHIP REGISTRY

to carry out

Visual/Sampling Checks and testing for Hazardous Materials, such as asbestos, PCBS, TBTS and CFCS onboard ships, including advise on numbers and locations of samples, and preparation of Reports on the Quantities, Locations and estimates of these Materials.

The above service provider is approved based on the requirements of Resolution MEPC. 379(80). The above services to be provided shall comply with the requirements and guidelines of the IMO and the equipment's manufacturer and have been audited and supervised by the latter.

Issued in Piraeus, Greece on 18th of November 2024.
Valid until 17th of November 2026.

Stavros Gonidellis, Technical Officer
Palau International Ship Registry

Electronic Signature

Scan to verify this document or visit www.palaureg.com

Ref: PISR-SP-024-123

This is an electronic document. For verification of this appointment, scan the QR code or visit https://www.palaureg.com/information-centre/approved-suppliers/approval-of-service-suppliers/

PISR L.035
Rev. 13.01.20

Palau International Ship Registry
www.palaureg.com

RINA Services S.p.A.
Via Corsica, 12 - 16128 Genova
Tel. +39 010 53851
Fax +39 010 5351000

CERTIFICATE OF APPROVAL
OF SERVICE SUPPLIER

CERTIFICATE NO. SSU039825X1

This is to certify that

Viswalab Singapore Pte Ltd
80 Tagore Lane Sindo Industrial Estate
787501 Singapore SINGAPORE

Has been approved in compliance with the
RINA "RULES FOR THE CERTIFICATION OF SERVICE SUPPLIERS"
for the supply of the following services to ships and other units classed by RINA:

Z - Surveys for the purpose of developing and maintaining the Inventory of Hazardous Materials (IHM) onboard ships

Date of the audit: **21 Mar 2025**
Issued in **SINGAPORE**
on **24 Mar 2025**

This Certificate is valid from the date of the audit until
20 Mar 2026

This certificate consists of this sheet plus an attachment.

This is an electronically signed document and does not require a handwritten signature.

Kwok Leung Tommy JEN
RINA Services S.p.A.

This certificate consists of 2 pages.

Certificate No. SSU039825X1 Page 2/2

RINA Services S.p.A.
Via Corsica, 12 - 16128 Genova
Tel. +39 010 53851
Fax +39 010 5351000

ATTACHMENT TO CERTIFICATE NO. SSU039825X1

VALIDITY CONDITIONS

General conditions for the approval

a) The initial conditions verified by RINA at the time of the approval are to be maintained
b) Any changes to the initial conditions are to be promptly communicated to RINA, which reserves the right to repeat the relevant assessments
c) RINA personnel are to be allowed to witness during the performance of activities, upon their request
d) The activities are to be carried out in compliance with the RINA Rules and or other applicable rules
e) RINA may revoke the approval at any moment in the case of modifications to requirements or conditions for the approval

This is an electronically signed document and does not require a handwritten signature.

Kwok Leung Tommy JEN
RINA Services S.p.A.

This certificate consists of 2 pages.

Certificate of Approval

Approving a Service Supplier engaged in
Visual and/or Sampling Checks and preparation of Inventory of Hazardous Materials

No. SGP0/KZA/20250107091253

Issued within the scope of the Bureau Veritas Marine & Offshore General Conditions
Délivrée dans le cadre des Conditions Générales de Bureau Veritas Marine & Offshore

Company: **VISWALAB SINGAPORE PTE LTD**

Company address*: 80 TAGORE LANE
SINDO INDUSTRIAL ESTATE
SINGAPORE 787501

Scope of the approval:
Visual and/or Sampling Checks on board ships, development of IHM.

This is to certify that:

The undersigned Surveyor of the Society, acting within the Bureau Veritas Marine & Offshore General Conditions, has performed, at the Company's request, an assessment of the facilities, organisational structure and procedures of the said Company, in compliance with the relevant requirements of the Society Rule Note NR 533.

The facilities, organisational structure and procedures were found satisfactory for the servicing of the equipment described in the attached Schedule of Approval.

The Certificate is valid until**: 05 January 2028

Completion date of the assessment on which this certificate based: 06 January 2025

At: SINGAPORE on 07 January 2025

BUREAU VERITAS
MARINE & OFFSHORE
Siam Nieng SIM

By Order of the Secretary

** Refer to the appendix for the list of subsidiaries covered by this certificate*
*** Not later than 3 years after the date of evaluation*

The latest published Rules of the Bureau Veritas Marine & Offshore and the General Conditions therein are applicable
La dernière édition des Règlements de Bureau Veritas Marine & Offshore ainsi que les conditions Générales qui y figurent sont applicables

Any person not a party to the contract pursuant to which this certificate is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said certificate, or for errors of judgement, fault or negligence committed by personnel of the Society or of its Agents in the establishment or issuance of this certificate, and in connection with any activities for which it may provide.

Toute personne qui n'est pas partie au contrat aux termes duquel ce document est délivré ne pourra engager la responsabilité du Bureau Veritas pour les inexactitudes ou omissions qui pourraient y être relevées ainsi que pour les erreurs de jugement, fautes ou négligences commises par le personnel de la Société ou par ses agents dans l'établissement de ce document et dans l'exécution des interventions qu'il comporte.

The Viswa Group © 2020

Certificate N° SGP0/KZA/20250107091253
Company Name VISWALAB SINGAPORE PTE LTD

SCHEDULE OF APPROVAL

1- List of equipment and systems

-

2- List of Subsidiaries / Agents covered by this certificate

-

3- Condition for the validity of the certificate of approval

The certification is valid insofar as the inspection duties are actually assumed by personnel of the Service Supplier who has been assessed by the Society.

The Society reserves the right to invalidate this certificate of approval in case :

- Where the service was improperly carried out or the results were improperly reported.
- Where a Surveyor finds deficiencies in the approval service operating system of the supplier and appropriate corrective action is not taken.
- Where alterations have been made to the Company's Quality System relevant to the service supplier certificates, without written notification to the Society.
- Where the intermediate audit, if requested, has not been carried out.
- Where wilful acts or omissions are ascertained
- Where any deliberate misrepresentation has been made by the Service Supplier

4- Other conditions

Nil

5- Endorsement where an intermediate audit has been performed

Signed:
(Surveyor to BUREAU VERITAS MARINE & OFFSHORE)

Place:

Date:

BUREAU VERITAS MARINE & OFFSHORE

GENERAL CONDITIONS
(January 2023 version)

1. INDEPENDENCE OF THE SOCIETY AND APPLICABLE TERMS

1.1 The Society shall remain at all times an independent contractor and neither the Society nor any of its officers, employees, servants, agents or subcontractors shall be or act as an employee, servant or agent of any other party hereto in the performance of the Services.

1.2 The operations of the Society in providing its Services are exclusively conducted by way of random inspections and do not, in any circumstances, involve monitoring or exhaustive verification.

1.3 The Society acts as a services provider. This cannot be construed as an obligation bearing on the Society to obtain a result or as a warranty. The Society is not and may not be considered as an underwriter, broker in Unit's sale or chartering, expert in Unit's valuation, consulting engineer, controller, naval architect, designer, manufacturer, shipbuilder, repair or conversion yard, charterer or shipowner; none of the above listed being relieved from any of their expressed or implied obligations as a result of the interventions of the Society.

1.4 Only the Society is qualified to apply and interpret its Rules.

1.5 The Client acknowledges the latest versions of the Conditions and of the applicable Rules applying to the Services' performance.

1.6 Unless an express written agreement is made between the Parties on the applicable Rules, the applicable Rules shall be the Rules applicable at the time of entering into the relevant contract for the performance of the Services.

1.7 The Services' performance is solely based on the Conditions. No other terms shall apply whether express or implied.

2. DEFINITIONS

2.1 **"Certificate(s)"** means classification, statutory or Marine Equipment certificates, attestations and reports following the Society's intervention.

2.2 **"Certification"** means the activity of certification in application of national and international regulations or standards ("Applicable Referential"), in particular by delegation from different governments that can result in the issuance of a Certificate.

2.3 **"Classification"** means the classification of a Unit that can result or not in the issuance of a classification Certificate with reference to the Rules. Classification (or Certification as defined in clause 2.2) is an appraisement given by the Society to the Client, at a certain date, following surveys by its surveyors on the level of compliance of the Unit to the Society's Rules and/or to the Applicable Referential for the Services provided. They cannot be construed as an implied or express warranty of safety, fitness for the purpose, seaworthiness of the Unit or of its value for sale, insurance or chartering.

2.4 **"Client"** means the Party, its affiliates, agents, subcontractors, consultants, employees, and/or its representative requesting the Services.

2.5 **"Conditions"** means the terms and conditions set out in the present document.

2.6 **"Industry Practice"** means international maritime and/or offshore industry practices.

2.7 **"Intellectual Property"** means all patents, rights to inventions, utility models, copyright and related rights, trade marks, logos, service marks, trade dress, business and domain names, rights in trade dress or get-up, rights in goodwill or to sue for passing off, unfair competition rights, rights in designs, rights in computer software, database rights, topography rights, moral rights, rights in confidential information (including know-how and trade secrets), methods and protocols for Services, and any other intellectual property rights, in each case whether capable of registration, registered or unregistered and including all applications for and renewals, reversions or extensions of such rights, and all similar or equivalent rights or forms of protection in any part of the world.

2.8 **"Marine Equipment"** means equipment, material or product placed of to be placed on board a Unit falling within the scope of Certification or Classification and by extension corresponding manufacturer recognition Certification.

2.9 **"Parties"** means the Society and Client together.

2.10 **"Party"** means the Society or the Client.

2.11 **"Register"** means the public electronic register of ships updated regularly by the Society.

2.12 **"Rules"** means the Society's classification rules (available online on veristar.com), guidance notes and other documents. The Society's Rules take into account at the date of their preparation the state of currently available and proven technical minimum requirements but are not a standard or a code of construction neither a guide for maintenance, a safety handbook or a guide of professional practices, all of which are assumed to be known in detail and carefully followed at all times by the Client.

The Viswa Group © 2020

2.13 **"Services"** means the services set out in clauses 2.2 and 2.3 but also other services related to Classification and Certification such as, but not limited to: ship and company safety management certification, ship and port security certification, maritime labour certification, Marine Equipment certification, training activities, all activities and duties incidental thereto such as documentation on any supporting means, software, instrumentation, measurements, tests and trials on board. The Services are carried out by the Society according to the Rules and/or the Applicable Referential and to the Bureau Veritas' Code of Ethics. The Society shall perform the Services according to the applicable national and international standards and Industry Practice and always on the assumption that the Client is aware of such standards and Industry Practice.

2.14 **"Society"** means the classification society **'Bureau Veritas Marine & Offshore SAS'**, a company organized and existing under the laws of France, registered in Nanterre under number 821 131 844, or any other legal entity of Bureau Veritas Group as may be specified in the relevant contract, and whose main activities are Classification and Certification of ships or offshore units.

2.15 **"Taxes"** means any and all taxes imposed by any taxing authority including, without limitation, income tax on nationals and on foreigners, all corporate taxes, imports, duties, levies, stamp duties, charges and other assessments and payments in the nature of taxes, wherever payable, including withholding taxes and VAT.

2.16 **"Unit"** means any ship or vessel or offshore unit or structure of any type or part of it or system whether linked to shore, river bed or sea bed or not, whether operated or located at sea or in inland waters or partly on land, including submarines, hovercrafts, drilling rigs, offshore installations of any type and of any purpose, their related and ancillary equipment, subsea or not, such as well head and pipelines, mooring legs and mooring points or otherwise as decided by the Society.

3. SCOPE AND PERFORMANCE

3.1 Subject to the Services requested and always by reference to the Rules, and/or to the Applicable Referential, the Society shall:

- review the construction arrangements of the Unit as shown on the documents provided by the Client;
- conduct the Unit surveys at the place of the Unit construction;
- class the Unit and enter the Unit's class in the Society's Register;
- survey the Unit periodically in service to note whether the requirements for the maintenance of class are met. The Client shall inform the Society without delay of any circumstances which may cause any changes on the conducted surveys or Services;
- perform design assessments, surveys and audits related to Marine Equipment;
- witness tests at manufacturer's premises.

3.2 The Society will not:

- declare the acceptance or commissioning of a Unit, nor its construction in conformity with its design, such activities remaining under the exclusive responsibility of the Unit's owner or builder;
- engage in any work relating to the design, construction, production or repair checks, neither in the operation of the Unit or the Unit's trade, neither in any advisory services, and cannot be held liable on those accounts;
- be liable for any delay or costs, charges or losses sustained or incurred by the Client in the event where the Society's performance of the Services is prevented or delayed directly or indirectly by any act, omission, missing information, default or negligence of the Client.

4. RESERVATION CLAUSE

4.1 The Client shall always: (i) maintain the Unit in good condition after surveys; (ii) present the Unit for surveys; and (iii) inform the Society in due time of any circumstances that may affect the given appraisement of the Unit or its Marine Equipment or cause to modify the scope of the Services.

4.2 Certificates are only valid if issued by the Society.

4.3 The Society has entire control over the Certificates issued and may at any time withdraw a Certificate at its entire discretion including, but not limited to, in the following situations: where the Client fails to comply in due time with instructions of the Society or where the Client fails to pay in accordance with clause 6.2 hereunder.

4.4 The Society may at times and at its sole discretion give an opinion on a design or any technical element that would 'in principle' be acceptable to the Society. This opinion shall not presume on the final issuance of any Certificate nor on its content in the event of the actual issuance of a Certificate. This opinion shall only be an appraisement made by the Society which shall not be held liable for it.

4.5 The Client shall provide sufficient, timely, accurate, complete and up-to-date information and documents to the Society to enable the Society to perform the Services.

5. ACCESS AND SAFETY

5.1 The Client shall give to the Society all access and information necessary for the efficient performance of the requested Services. The Client shall be the sole responsible for the conditions of presentation of the Unit for tests, trials and surveys and the conditions under which tests and trials are carried out. Any information, drawing, etc. required for the performance of the Services must be made available in due time.

5.2 The Client shall notify the Society of any relevant safety issue and shall take all necessary safety-related measures to ensure a safe work environment (including safe transportation to site and accompaniment on site) for the Society or any of its officers, employees, servants, agents or subcontractors and shall comply with all applicable safety regulations.

The Viswa Group © 2020

6. **PAYMENT OF INVOICES**

6.1 The provision of the Services by the Society, whether complete or not, involves, for the part carried out, the payment of fees thirty (30) days upon issuance of the invoice.

6.2 The fees are exclusive of all applicable Taxes. In the event that Taxes are applicable in respect of the Services, Taxes shall be payable by the Client in addition to the fees. For the avoidance of doubt, in the event tax is required by law to be withheld from the fees, the Society may gross up the invoice sufficiently such that after the deduction of withholding tax the original fees is received by the Society. In the event that any withholding taxes are paid by the Client, the Client shall provide to the Society a valid withholding tax receipt in the Society's name within thirty (30) days following the payment. The Society shall provide to the Client within thirty (30) days following request from the Client reasonable documentation, such as certificates of residence, required to enable the Client to apply any reduced rates of withholding tax given by a double tax treaty, if applicable.

6.3 Without prejudice to any other rights hereunder, in case of Client's payment default, the Society shall be entitled to charge, in addition to the amount not properly paid, (i) interest equal to the ECB reference rate plus three per-cent (3%) per month late as of due date or at the maximum rate allowed by law if said maximum is less, and (ii) the recovery costs. The Society shall also have the right to withhold Certificates and other documents and/or to suspend or revoke the validity of Certificates.

6.4 In case of dispute on the invoice amount, the undisputed portion of the invoice shall be paid and an explanation on the dispute shall accompany payment so that action can be taken to resolve the dispute.

6.5 Unless otherwise agreed in writing by the Society, both the party on whose behalf the Services are requested and its representative requesting the Services, as Client, are jointly and severally liable to pay to the Society any sum due in respect of the Services. In addition, where any Unit is surveyed in the names or on behalf of more persons than one, such persons shall be jointly and severally liable to pay all fees, expenses and other sums due to the Society in respect of such Unit. The receipt by any such person of any payment by the Society shall discharge the others up to the amount received by the Society.

6.6 The Society shall be entitled to require a payment on account payable upon receipt of the corresponding invoice. In this case, The Society's duty to provide the Services will not arise before payment is received in the Society's account.

6.7 The Society shall have a lien on a Unit for all sums due in respect of that Unit, notwithstanding that the class of the Unit may have ceased or been terminated or cancelled. Such lien shall extend to any and all other Units (or formerly classed Units) which are part of the same fleet as that Unit and shall be in addition to, and in no way construed as a waiver or amendment of, any other contractual or maritime lien which the Society may expressly or impliedly possess in respect of such Unit or Units.

7. **LIABILITY**

7.1 The Society bears no liability for consequential loss. For the purpose of this clause consequential loss shall include, without limitation:

- Indirect or consequential loss;
- Any loss and/or deferral of production, loss of product, loss of use, loss of bargain, loss of revenue, loss of profit or anticipated profit, loss of business and business interruption, in each case whether direct or indirect.

The Client shall defend, release, save, indemnify, defend and hold harmless the Society from the Client's own consequential loss regardless of cause.

7.2 Except in case of wilful misconduct of the Society, death or bodily injury caused by the Society's negligence and any other liability that could not be, by law, limited, the Society's maximum liability towards the Client is limited to one hundred and fifty per-cent (150%) of the price paid by the Client to the Society for the Services having caused the damage. This limit applies to any liability of whatsoever nature and howsoever arising, including fault by the Society, breach of contract, breach of warranty, tort, strict liability, breach of statute.

7.3 All claims shall be presented to the Society in writing within three (3) months of the completion of Services' performance or (if later) the date when the events which are relied on were first discovered by the Client. Any claim not so presented as defined above shall be deemed waived and absolutely time barred.

8. **INDEMNITY CLAUSE**

8.1 The Client shall defend, release, save, indemnify and hold harmless the Society from and against any and all claims, demands, lawsuits or actions for damages, including legal fees, for harm or loss to persons and/or property tangible, intangible or otherwise which may be brought against the Society, incidental to, arising out of or in connection with the performance of the Services (including for damages arising out of or in connection with opinions delivered according to clause 4.4 above) except for those claims caused solely and completely by the gross negligence of the Society, its officers, employees, servants, agents or subcontractors.

9. **TERMINATION**

9.1 The Parties shall have the right to terminate the Services (and the relevant contract) for convenience after giving the other Party thirty (30) days' written notice, and without prejudice to clause 6 above.

9.2 The Services shall be automatically and immediately terminated in the event the Client can no longer establish any form of interest in the Unit (e.g. sale, scrapping…).

9.3 The Classification granted to the concerned Unit and the previously issued Certificates shall remain valid until the date of effect of the termination notice issued, or immediately in the event of termination under clause 9.2, subject to compliance with clause 4.1 and 6 above.

9.4 In the event where, in the reasonable opinion of the Society, the Client is in breach, or is suspected to be in breach of clause 16 of the Conditions, the Society shall have the right to terminate the Services (and the relevant contracts associated) with immediate effect.

The Viswa Group © 2020

10. FORCE MAJEURE

10.1 Neither Party shall be responsible or liable for any failure to fulfil any term or provision of the Conditions if and to the extent that fulfilment has been delayed or temporarily prevented by a force majeure occurrence without the fault or negligence of the Party affected and which, by the exercise of reasonable diligence, the said Party is unable to provide against.

10.2 For the purpose of this clause, force majeure shall mean any circumstance not being within a Party's reasonable control including, but not limited to: acts of God, natural disasters, epidemics or pandemics, wars, terrorist attacks, riots, sabotages, impositions of sanctions, embargoes, nuclear, chemical or biological contaminations, laws or action taken by a government or public authority, quotas or prohibition, expropriations, destructions of the worksite, explosions, fires, accidents, any labour or trade disputes, strikes or lockouts.

11. CONFIDENTIALITY

11.1 The documents and data provided to or prepared by the Society in performing the Services, and the information made available to the Society, will be treated as confidential except where the information:

- is properly and lawfully in the possession of the Society;
- is already in possession of the public or has entered the public domain, other than through a breach of this obligation;
- is acquired or received independently from a third party that has the right to disseminate such information;
- is required to be disclosed under applicable law or by a governmental order, decree, regulation or rule or by a stock exchange authority (provided that the receiving Party shall make all reasonable efforts to give prompt written notice to the disclosing Party prior to such disclosure).

11.2 The Parties shall use the confidential information exclusively within the framework of their activity underlying these Conditions.

11.3 Confidential information shall only be provided to third parties with the prior written consent of the other Party. However, such prior consent shall not be required when the Society provides the confidential information to a subsidiary.

11.4 Without prejudice to sub-clause 11.1, the Society shall have the right to disclose the confidential information if required to do so under regulations of the International Association of Classifications Societies (IACS) or any statutory obligations.

11.5 The Client shall not without written approval from the Society make public announcement or press release, press conference, presentation or any public disclosure mentioning the Society, its trademark, trade name or logo, its employees. The Client acknowledges and agrees that damages alone might not be an adequate remedy for any breach of this clause and the Society shall be entitled to seek the remedies of injunction, specific performance and other equitable relief for any threatened or actual breach and no proof of special damage shall be necessary for the enforcement of the present clause and the undertakings under it.

12. INTELLECTUAL PROPERTY

12.1 Each Party exclusively owns all rights to its Intellectual Property created before or after the commencement date of the Conditions and whether or not associated with any contract between the Parties.

12.2 The Intellectual Property developed by the Society for the performance of the Services including, but not limited to drawings, calculations, and reports shall remain the exclusive property of the Society.

13. ASSIGNMENT

13.1 The contract resulting from to these Conditions cannot be assigned or transferred by any means by a Party to any third party without the prior written consent of the other Party.

13.2 The Society shall however have the right to assign or transfer by any means the said contract to a subsidiary of the Bureau Veritas Group.

14. SEVERABILITY

14.1 Invalidity of one or more provisions does not affect the remaining provisions.

14.2 Definitions herein take precedence over other definitions which may appear in other documents issued by the Society.

14.3 In case of doubt as to the interpretation of the Conditions, the English text shall prevail.

15. GOVERNING LAW AND DISPUTE RESOLUTION

15.1 These Conditions shall be construed in accordance with and governed by the laws of England and Wales.

15.2 Any dispute shall be finally settled under the Rules of Arbitration of the Maritime Arbitration Chamber of Paris ("CAMP"), which rules are deemed to be incorporated by reference into this clause. The number of arbitrators shall be three (3). The place of arbitration shall be Paris (France). The Parties agree to keep the arbitration proceedings confidential.

15.3 Notwithstanding clause 15.2, disputes relating to the payment of the Society's invoices may be submitted by the Society to the *Tribunal de Commerce de Nanterre*, France, or to any other competent local Court, at the Society's entire discretion.

16. ETHICS

16.1 Each Party shall conduct all activities in compliance with all laws, statutes, rules, export control, economic and trade sanctions (including but not limited to US, UK and EU sanctions) and regulations applicable to such Party including but not limited to: child labour, forced labour, collective bargaining, discrimination, abuse, working hours and minimum wages, anti-bribery, anti-corruption, antitrust, copyright and trademark protection, personal data protection (https://personaldataprotection.bureauveritas.com/privacy-policy). Each of the Parties warrants that neither it, nor its affiliates, has made or will make, with respect to the matters provided for hereunder, any offer, payment, gift or authorization of the payment of any money directly or indirectly, to or for the use or benefit of any official or employee of the government, political party, official, or candidate.

16.2 In addition, the Client shall act consistently with the Bureau Veritas' Code of Ethics and, when applicable, Business Partner Code of Conduct both available at https://group.bureauveritas.com/group/corporate-social-responsibility/operational-excellence.

8. APPENDIX 3 – VISUAL SAMPLING CHECK PLAN (VSCP) (PENDING TEST RESULT)

Check list for SSL THAMIRABARANI	
Ship Name:	SSL THAMIRABARANI
Port of Registry :	Mumbai
Class :	DNV - IRS
IMO Number	9312468
Gross tonnage (GT):	9,520.00
Registered L x B x D:	142.7 X 22.6 X 11.2
Date of delivery:	July 2005, DAE SUN Shipbuilding & Engineering Co. Ltd.
Ship Owner / Company:	Transworld Ship Management India Pvt Ltd
Check schedule	19/10/2025 - TBC
Site of check	Colombo Yard, Sri Lanka
In charge of check:	Matthew Lalchang
Check engineer:	Matthew Lalchang
Sampling method and anti-scattering measure for asbestos:	Wet the sampling location prior to cutting and allow it to harden after cutting to prevent scatter. Notes: Workers performing sampling activities shall wear protective equipment.
Sampling of fragments of paints:	Paints suspected to contain TBT should be collected and analysed
Laboratory	ULS Shanghai
Chemical analysis method:	Method by ISO/DIS 22262-1 Bulk Materials-Part 1:Sampling and qualitative determination of asbestos in commercial bulk materials ;
Location of visual/sampling check	Refer to lists for visual/sampling check plan
VSCP Prepared by	Matthew lalchang
Tel of Expert	6596154365
Email address of expert	matthew.lalchang@theviswagroup.com
Document check date/place	14/10/2025
Prepared date	15/10/2025
Project No :	VIHM SMQT25 146
Rev :	0

Check List

No.	Table A/B	Hazardous Materials	Location	Name of Equipment /Material	Component or Function	Quantity			Manufacturer /Brand name	Result of Doc.Ana	Procedure of check	Result of check	Reference / DWG No	Remark	Sample No
						Unit (kg)	No	Total (kg)							
Ⅰ－1.Paints and coating systems															
1	A/B	B1/B3/B4	Nav. Deck-Bridge Wing	Paint and coating	Outside Wall Paint				No Info	N	S	N	Painting Specs	N/A	ST01

2	A/B	A1/B3	Nav. Deck-Bridge Wing	Paint and coating	Deck Paint				No Info	N	S	N	Painting Specs	N/A	ST02
3	A/B	B3/B5/B9	C Deck Engine Casing Exterior	Paint and coating	Outside Wall Paint				No Info	N	S	N	Painting Specs	N/A	ST03
4	A	A4	Side Shell under waterline, Paint and Coating, Out Shell Paint	Paint and coating	Out Shell Paint	792 kg			NA	Y	V	Y	Refer to DNV ID 45765 - IAFSC	Cybutryne Has been applied on this ship previously, but is not in the external coating layer of the hull or external parts or surfaces on	V01
5	A/B	A1/B3/B6	Upper Deck	Paint and coating	Cargo Hold Hatch Cover				No Info	N	S	N	Painting Specs	N/A	ST04
6	A/B	A1/B1/B3	Engine Room- 2nd Deck Workshop	Paint and coating	Deck Paint				No Info	N	S	N	Painting Specs	N/A	ST05
I – 2.Equipment and Machinery															
7	B	B4	Nav. Bri. Deck-Wheel House	Gyro compass	Compensation Fluid				Tokimec TG-8000	N	V	N	Fire control and Safety Plan	Digital Type	V02
8	A	A2	Nav. Bri. Deck-Wheel House	Cable	Out Sheath				No Info	N	S	N	GA	N/A	ST06
9	B	B3	B Deck	Life / Rescue Boat Port Motor	Starting Battery	10	2	20	Rocket 12V, 90AH x 2 Nos	Y	V	Y	Battery List	Contained Lead & Lead Compounds	V03
10	B	B3	B Deck	Life / Rescue Boat Starboard Motor	Starting Battery	10	2	20	Rocket 12V, 90AH x 2 Nos	Y	V	Y	Battery List	Contained Lead & Lead Compounds	V04
11	B	B3	A Deck-Battery RM	GMDSS Radio Battery	Battery	20	6	120	Exide, 12V, 200 AH x 6 Nos	Y	V	Y	Battery List	Contained Lead & Lead Compounds	V05
12	B	B3	A Deck-Battery RM	General Use Battery	Battery	20	6	120	Rocket, 12 V, 200AH x 6 Nos	Y	V	Y	Battery List	Contained Lead & Lead Compounds	V06
13	A	A1	Upper Deck	Mooring Winch	Brake lining				No Info	N	S	N	GA	N/A	ST07
14	A	A2	Upper Deck	Mooring Winch	Hydraulic Pipe Laggings				No Info	N	S	N	GA	N/A	ST08
15	A	A1	Forecastle Deck	Anchor Windlass	Brake lining				No Info	N	S	N	GA	N/A	ST09
16	A	A1	Forecastle Deck	Mooring Winch Hydraulic Unit	Gasket/packing				No Info	N	S	N	GA	N/A	ST10

17	B	B3	Poop Deck-Emer Generator Room	Emergency generator	Starting Battery	40	2	80	Amaron BL1000 RMF x 2 Nos	Y	V	Y	Battery List	Contained Lead & Lead Compounds	V07
18	A	A1	Poop Deck-Emer Generator Room	Emergency generator	Exhaust pipe insulation(yard)				No Info	N	S	N	GA	N/A	ST11
19	A	A1	Poop Deck-Emer Generator Room	Emergency generator DO tank	Manhole Gasket				No Info	N	S	N	GA	N/A	ST12
20	A	A2	Poop Deck-Emer Generator Room	Emergency Transformer	Insulation Oil				No Info	N	V	N	GA	Dry type, Air cooling	V08
21	A	A3	Poop deck- Air Conditioning Unit Rm	AC Condensing Unit	Refrigerant				Namirei Showa	N	V	N	GA	R404a refrigerant	V09
22	A	A3	Poop deck- Air Conditioning Unit Rm	AC Condensing Unit	Refrigerant pipe insulation				No Info	N	S	N	GA	N/A	ST13
23	A	A1	Engine Casing-Poop Deck	Aux Boiler	Body insulation				No Info	N	S	N	ER Arr.	N/A	ST14
24	A	A1	Engine Casing-Poop Deck	Drain Cooler	Packing				No Info	N	S	N	ER Arr.	N/A	ST15
25	A	A1	Engine Casing- Upper Deck	Waste Oil Incinerator Exhaust Pipe	Lagging Insulation				No Info	N	S	N	ER Arr.	N/A	ST16
26	A	A1	Engine Casing- Upper Deck	Aux Boiler exhaust pipe	Lagging Insulation				No Info	N	S	N	ER Arr.	N/A	ST17
27	A	A1	Engine Casing- Upper Deck	Waste Oil Incinerator	Firebrick				Kangrim	N	S	N	ER Arr.	N/A	ST18
28	A	A1	Engine Casing- Upper Deck	Waste Oil Incinerator	Door Packing				Kangrim	N	S	N	ER Arr.	N/A	ST19
29	A	A3	ER- 2nd Deck	Ref. Plant	Refrigerant pipe insulation				No Info	N	S	N	ER Arr.	N/A	ST20
30	A	A3	ER- 2nd Deck	Ref. Plant	Refrigerant				Namirei Showa	N	V	N	ER Arr.	R404a refrigerant	V10
31	A	A1	ER- 2nd Deck	Calorifier	Gasket / Packing				Kangrim	N	S	N	ER Arr.	N/A	ST21
32	A	A1	ER- 2nd Deck	Main LO Storage Tk LO Piping	Lagging Insulation				No Info	N	S	N	ER Arr.	N/A	ST22
33	A	A2	ER-2nd Deck	Main Transformer	Cooling Medium				No Info	N	V	N	ER Arr.	Dry type, Air cooling	V11
34	A	A1	ER-2nd Deck	Main Air Compressor	Packing				Jonghap Tanabe	N	S	N	ER Arr.	N/A	ST23
35	A	A1	ER- 2nd Deck	Fresh Water generator	Packing				Donghwa	N	S	N	ER Arr.	N/A	ST24
36	A	A1	ER-2nd Deck	Main engine	Exhaust gas pipe insulation				STX Engine	N	S	N	ER Arr.	N/A	ST25
37	A	A2	ER - 2nd Deck-Steering Gear RM	Steering Gear	Hydraulic oil				Tong Myong heavy Industries	N	S	N	ER Arr.	N/A	ST26

The Viswa Group © 2020

38	A	A2	ER- 2nd Deck-Eng. Control Room	Cable	Out Sheath				No Info	N	S	N	ER Arr.	N/A	ST27
39	A	A1	ER-3rd Deck	Sewage Treatment Plant	Packing				No Info	N	S	N	ER Arr.	N/A	ST28
40	A	A1	ER-3rd Deck	Sewage Treatment Plant	Pipeline Gasket				No Info	N	S	N	ER Arr.	N/A	ST29
41	A	A1	ER-3rd Deck	HFO purifier	Pipeline Insulation				Mitsubishi Selfjector	N	S	N	ER Arr.	N/A	ST30
42	A	A1	ER-3rd Deck	Purifier FO -heater	Casing insulation				Mitsubishi Selfjector	N	S	N	ER Arr.	N/A	ST31
43	A	A1	ER-3rd Deck	Purifier LO Heater	Casing insulation				Mitsubishi Selfjector	N	S	N	ER Arr.	N/A	ST32
44	A	A1	ER-3rd Deck	FW Preheater For ME	packing				No Info	N	S	N	ER Arr.	N/A	ST33
45	A1	A1	ER-3rd Deck	FW Cooler For ME	packing				No Info	N	S	N	ER Arr.	N/A	ST34
46	A1	A1	ER-3rd Deck	LO Cooler for ME	packing				No Info	N	S	N	ER Arr.	N/A	ST35
47	A	A1	ER-3rd Deck	Aux Diesel Generator	Exhaust gas pipe insulation				STX Engine	N	S	N	ER Arr.	N/A	ST36
48	A	A1	ER-3rd Deck	Aux Diesel Generator	Pipeline Gasket				STX Engine	N	S	N	ER Arr.	N/A	ST37
49	A	A1	ER-Lower Floor	Oily Bilge Separator	Packing				Georim Engineering	N	S	N	ER Arr.	N/A	ST38
50	A	A1	ER-Lower Floor	F.O trans. Pump	Insulation				Taiko Kaiko	N	S	N	ER Arr.	N/A	ST39
51	A	A1	ER-Lower Floor	Scan Box Drain Tk	Packing				No Info	N	S	N	ER Arr.	N/A	ST40
No.	**Table A/B**	**Hazardous Materials**	**Location**	**Name of Equipment /Material**	**Component or Function**	**Quantity**			**Manufacturer /Brand name**	**Result of Doc.Ana**	**Procedure of check**	**Result of check**	**Reference / DWG No**	**Remark**	**Sample No**
						Unit (kg)	**No**	**Total (kg)**							
Ⅰ - 3.Structure and hull and relevant systems															
52	A	A1	Nav. Bri. Deck-Wheel House	Staircase Fire door	Packing				No Info	N	S	N	GA	N/A	ST41
53	A	A1	Nav. Bri. Deck-Wheel House	Staircase Fire door	Panel Insulation				No Info	N	S	N	GA	N/A	ST42
54	A	A1	Nav. Bri. Deck-Wheel House	Floor Overlay	All Layers				No Info	N	S	N	GA	N/A	ST43
55	A	A1	Nav. Bri. Deck-Wheel House	Steel Wall	Heat Insulation				No Info	N	S	N	GA	N/A	ST44
56	A	A1	Nav. Bri. Deck-Wheel House	False Ceiling panel	Insulation filling				No Info	N	S	N	GA	N/A	ST45
57	A	A1	Nav. Bri. Deck-Wheel House	Window	Rubber sealing with glue				No Info	N	S	N	GA	N/A	ST46
58	B	B3	Nav. Bri. Deck-Wheel House	Sliding Door	Rubber Packing	4.0 KG			No Info	Y	S	Y	GA	Contained Lead and Lead Compounds	ST47

59	A	A1	Nav. Bri. Deck-Wheel House	Console Cable Deck Penetration	Cable gland				No Info	N	S	N	GA	N/A	ST48
60	A	A1	D Deck- Chief Engineer Bedroom	False Ceiling panel	Insulation filling				No Info	N	S	N	GA	N/A	ST49
61	A	A1/A5	D Deck- Master Bedroom	Floor	All Layers				No Info	N	S	N	GA	N/A	ST50
62	A	A1	C Deck -Corridor	Wall	Skirting				No Info	NA	V	NA	GA	Either Metal skirting or no skirting throughout accommodation	VST51
63	A	A1	C Deck -Corridor	Floor	All Layers				No Info	NA	V	NA	GA	Similar sample as ST43	VST52
64	A	A1	C Deck-Elec Locker	Cable Wall penetration	Cable Gland				No Info	N	S	N	GA	N/A	ST53
65	A	A1	C Deck-Elec Locker	Cable Deck penetration	Cable Gland				No Info	N	S	N	GA	N/A	ST54
66	A	A1/A5	C Deck- Spare Cabin	Floor	All Layers				No Info	N	S	N	GA	N/A	ST55
67	B	B3	B Deck-Corridor	Stairways	Rubber Grip				No Info	N	S	N	GA	N/A	ST56
68	A/B	A1/B3	A Deck -Battery RM	Marine Steel Door	Rubber Packing				No Info	N	S	N	GA	N/A	ST57
69	A	A1	Upper Deck-Galley	Floor	Skid-proof Tile, Cemant,Filler				No Info	N	S	N	GA	N/A	ST58
70	A	A1	Upper Deck - Laundry Room	Hot water Piping	Lagging Insulation				No Info	N	S	N	GA	N/A	ST59
71	A	A3	Upper Deck-Ref Chamber-Meat	Wall Panel	Foam Insulation	30.0 kg			Y	Unknown	S	Y	GA	Contained ODS. Assuming all foam insulation in cold chamber contained ODS	ST60
72	B	B10	Upper Deck-Ref Chamber-Meat	Wall Panel	Foam Insulation				No Info	N	S	N	GA	N/A	ST61
73	A	A3	Upper Deck-Ref Chamber-Meat	Ref Pipe	Pipe Insulation				No Info	N	S	N	GA	N/A	ST62
74	A	A1	Upper Deck-Engine Casing	Aft Steel Wall	A60 fireproof insulation				No Info	N	S	N	GA	N/A	ST63
75	A	A1	Poop Deck-Corridor	Engine room entrance A60 Fire Door	Panel insulation				No Info	N	S	N	GA	N/A	ST64
76	A	A1	ER- 2nd Deck	FWD steel Wall insulation	A60 fireproof insulation				No Info	N	S	N	ER Arr.	N/A	ST65
77	A	A1	ER-2nd Deck-Eng. Control Room	False Ceiling Panel	Insulation filling				No Info	N	S	N	ER Arr.	N/A	ST66

The Viswa Group © 2020

78	A	A1	ER-2nd Deck-Eng. Control Room	Console Cable Deck Penetration	Cable Gland				No Info	N	S	N	ER Arr.	N/A	ST67
79	A	A1	ER-2nd Deck-Eng. Control Room	Floor	All Layers				No Info	N	V	N	ER Arr.	Similar sample as ST43	VST68
80	A	A1	ER-2nd Deck-Eng. Control Room	Eng. Control Room Door (Soundproof)	Panel Insulation				No Info	N	S	N	ER Arr.	N/A	ST69
81	A	A2	ER-2nd Deck-Eng. Control Room	Eng. Control Room Door (Soundproof)	Packing				No Info	N	S	N	ER Arr.	N/A	ST70
82	A	A1	ER- 3rd Deck	H.F.O. Settling Tk	Manhole gasket				No Info	N	S	N	ER Arr.	N/A	ST71
83	A	A1	ER- 3rd Deck	H.F.O. Settling Tk	Heat Insulation				No Info	N	S	N	ER Arr.	N/A	ST72
84	A	A1	ER- 3rd Deck	H.F.O pipe	Insulation				No Info	N	S	N	ER Arr.	N/A	ST73
85	A	A1	ER- 3rd Deck	Steam pipe	Insulation				No Info	N	S	N	ER Arr.	N/A	ST74
No.	**Table A/B**	**Hazardous Materials**	**Location**	**Name of Equipment /Material**	**Component or Function**	**Quantity**			**Manufacturer /Brand name**	**Result of Doc.Ana**	**Procedure of check**	**Result of check**	**Reference / DWG No**	**Remark**	**Sample No**
						Unit (kg)	**No**	**Total (kg)**							
Ⅲ – 1.Stores															
86	B	B8	ER-2nd Deck-Electrician's Workshop	Fire alarm detector	Heat detector				NA	NA	V	NA	ER Arr.	Not found onboard	V12
87	B	B8	ER-2nd Deck-Electrician's Workshop	Fire alarm detector	Flame detector				Consilium NS-AUV Ser 1107549	N	V	N	ER Arr.	Optical Type	V13
88	B	B8	ER-2nd Deck-Electrician's Workshop	Fire alarm detector	Smoke detector				JTY-GD-3100	N	V	N	ER Arr.	Optical Smoke Detector	V14
89	A/B	A2/A5/B3/ B2/B7	ER-2nd Deck-Electrician's Workshop	Spare Cable	Outer sheath	5.0 kg			No Info	Y	S	Y	ER Arr.	Contained Lead and Lead Compounds	ST75
90	B	B3/B5/B6/ B9	ER-2nd Deck-Electrician's Workshop	Spare Cable	Inside Insulation layer	5.0 kg			No Info	Y	S	Y	ER Arr.	Contained Lead and Lead Compounds	ST76
91	A/B	A1/B10	ER-2nd Deck- Mach Store	Spare Gasket 1	Gasket	10.0 KG			NA	Y	S	Y	ER Arr.	Different Black gasket samples from Store. ACM REMOVED. Refer to Asbestos removal cert, pg. 164	ST77
92	A	A1	ER-2nd Deck- Mach Store	Spare Gasket 2	Gasket	10.0 KG			NA	Y	S	Y	ER Arr.	White/Red samples from	ST78

												Store. ACM REMOVED. Refer to Asbestos removal cert, pg. 164	
93	A	A1	ER-2nd Deck- Mach Store	Spare Gland packings	Gland Packings	4.0 KG	NA	Y	S	Y	ER Arr.	Assorted Gland Packings. ACM REMOVED. Refer to Asbestos removal cert, pg. 164	ST79

No.	Table A/B	Hazardous Materials	Location	Name of Equipment /Material	Component or Function	Quantity			Manufacturer /Brand name	Result of Doc.Ana	Procedure of check	Result of check	Reference / DWG No	Remark	Sample No
						Unit (kg)	No	Total (kg)							
Ⅲ – 3.Stores (gas)															
94	A	A3	Poop Deck- Air Conditioning Unit Rm	AC Condensing Unit	Spare Refrigerant				NA	N	V	N	GA	R404a refrigerant	V15

Note: This VSCP is developed in accordance with MEP.379(80) (adopted on 7 July 2023) 2023. GUIDELINES FOR THE DEVELOPMENT OF THE INVENTORY OF HAZARDOUS MATERIALS


Y=Contained Hazardous Materials
N=Not Contained Hazardous Materials
PCHM=Potentially Containing Hazardous Materials
V=Visual Check
S=Sampling Check
A1=Asbestos
A2=PCBs
A3=ODS
A4=Anti-fouling system containing organotin compounds as a biocide / containing cybutryne
A5=PFOS
B1=Cadmium and cadmium compounds
B2=Hexavalent chromium and Hexavalent chromium compounds
B3=Lead and lead compounds
B4=Mercury and mercury compounds
B5=PBBs
B6=PBDEs

The Viswa Group © 2020


B7=PCNs
B8=Radioactive substance
B9=SCCPs
B10=HBCDD


9. APPENDIX 4 – LOCATIONS MAP


All sample locations according to VSCP are shown below.




1	Sliding Door (ST47)	Nav. Bri. Deck-Wheel House	Lead and Lead Compounds	Rubber Packing	4.0 KG	Contained Lead and Lead Compounds


D DECK
ST49
ST50



C DECK
ST53/ST54
VST52
ST55
VST51
ST03




1	Life / Rescue Boat Port Motor Starting Battery Rocket 12V, 90AH x 2 Nos (V03)	B Deck	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	20.0	Kg	Contained Lead and Lead Compounds
2	Life / Rescue Boat Starboard Motor Starting Battery Rocket 12V, 90AH x 2 Nos (V04)	B Deck	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	20.0	Kg	Contained Lead and Lead Compounds




1	GMDSS Radio Battery Exide, 12V, 200 AH x 6 Nos (V05)	A Deck-Battery RM	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	120.0	Kg	Contained Lead and Lead Compounds
2	General Use Battery Rocket, 12 V, 200AH x 6 Nos (V06)	A Deck-Battery RM	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	120.0	Kg	Contained Lead and Lead Compounds





1	Wall Panel (ST60)	Upper Deck-Ref Chamber-Meat	Ozone Depleting Substances	Foam Insulation	30.0 KG	Contained Hydrochloro Fluorocarban (ODS). Assuming all foam insulation in Cold Room Chamber wall panel contained ODS




1	Emergency generator Starting Battery Amaron BL1000 RMF x 2 Nos (V07)	Poop Deck-Emer Generator Room	Lead and Lead Compounds	Maintenance Free Lead Acid Batteries	80.0	Kg	Contained Lead and Lead Compounds






UPPER DECK
ST04


A DECK
ST15
ST14/ST17
POOP DECK
ST16
ST18/ST19
UPPER DECK
ST63



1	Spare Cable (ST75)	ER-2nd Deck-Electrician's Workshop	Lead and Lead Compounds	Outer sheath	5.0	Kg	Contained Lead and Lead Compounds
2	Spare Cable (ST76)	ER-2nd Deck-Electrician's Workshop	Lead and Lead Compounds	Inside Insulation layer	5.0	Kg	Contained Lead and Lead Compounds


ST28/ST29
ST31
ST30
ST32
ST36/ST37
ST71/ST72/
ST73/ST74
ST34
ST33
ST35


ST38
ST40
ST39

10. APPENDIX 5 – CALCULATIONS ON QUANTITY OF HAZARDOUS MATERIALS & PCHM

10.1 Calculation of Hazardous Material:

HM, Item, Life / Rescue Boat Port Motor Starting Batteries (B Deck) (V03)

Material: Battery, Rocket 12V, 90AH x 2 Nos

Estimated weight of lead: 12.0 KG of Lead and Lead Compounds

Working:
Weight of the Battery = 10.0 kg x 2 Nos = 20.0 kg
60% of the battery weight belong to lead and lead compound = 0.6 x 20 KG= 12.0 kg

---

HM, Item, Life / Rescue Boat Starboard Motor Starting Batteries (B Deck) (V04)

Material: Battery, Rocket 12V, 90AH x 2 Nos

Estimated weight of lead: 12.0 KG of Lead and Lead Compounds

Working:
Weight of the Battery = 10.0 kg x 2 Nos = 20.0 kg
60% of the battery weight belong to lead and lead compound = 0.6 x 20 KG= 12.0 kg

---

HM, Item: GMDSS batteries (A Deck-Battery RM) (V05)

Material: Battery, Exide, 12V, 200 AH x 6 Nos

Estimated weight of lead: 72.0 KG of Lead and Lead Compounds

Working:
Weight of the Battery = 20.0 kg x 6 Nos = 120.0 kg
60% of the battery weight belong to lead and lead compound = 0.6 x 120.0 = 72.0 kg

---

HM, Item: General Use Battery (A Deck-Battery RM) (V06)

Material: Battery, Rocket, 12 V, 200AH x 6 Nos

Estimated weight of lead: 72.0 KG of Lead and Lead Compounds

Working:
Weight of the Battery = 20.0 kg x 6 Nos = 120.0 kg
60% of the battery weight belong to lead and lead compound = 0.6 x 120.0 = 72.0 kg

---

HM, Item, Emergency Generator Battery (Poop Deck-Emer Generator Room) (V07)

Material: Amaron BL1000 RMF x 2 Nos

Estimated weight of lead: 48.0 KG of Lead and Lead Compounds

Working:
Weight of the Battery = 40.0 kg x 2 Nos. = 80.0 kg
60% of the battery weight belong to lead and lead compound = 0.6 x 80.0 KG = 48.0 kg

---

HM, Item, Sliding Door (Nav. Bri. Deck-Wheel House) (ST47)

Material: Rubber Packing

Estimated weight of lead: 0.013 KG of Lead and Lead Compounds

Working:
Tested Lead Content : 3125 mg/kg
Estimate weight of Coatings : 4.0 KG
Total = 0.013 kg

HM, Item, Spare Cable (ER-2nd Deck-Electrician's Workshop) (ST75)

Material: Outer sheath

Estimated weight of lead: 0.011 KG of Lead and Lead Compounds

Working:
Tested Lead Content : 2183 mg/kg
Estimate weight of Coatings : 5.0 KG
Total = 0.011 kg

HM, Item, Spare Cable (ER-2nd Deck-Electrician's Workshop) (ST76)

Material: Inner Insulation Layer

Estimated weight of lead: 0.027 KG of Lead and Lead Compounds

Working:
Tested Lead Content : 5408 mg/kg
Estimate weight of Coatings : 5.0 KG
Total = 0.027 kg

---

11. APPENDIX 6 – INDIVIDUAL SAMPLE PHOTOS

Photo of Sample	
 001	 002
 003	 004
 005	 006


ST07
007
ST08
008
ST09
009
ST10
010
ST11
011
ST12
012


ST13
013
ST14
014
ST15
015
ST16
016
ST17
017
ST18
018


019
020
021
022
023
024


025
026
027
028
029
030


031
032
033
034
035
036


037
038
039
040
041
042


5743
043
5744
044
5745
045
5746
046
5747
047
5748
048


049
050
051
052
053
054


ST57
055
ST58
056
ST59
057
ST60
058
ST61
059
ST62
060


061
062
063
064
065
066


ST70
067
ST71
068
ST72
069
ST73
070
ST74
071
ST75
072


ST76
073
ST77
074
ST78
075
ST79
076

12. APPENDIX 7 – SAMPLING & VISUAL INSPECTION PHOTOS



ST- 01;



ST-02;



ST-03;



ST-04;



ST-05;



ST-06;



ST-07;



ST-08;





ST-09;





ST-10;



ST-11;



ST-12;



ST-13;



ST-14;



ST-15;



ST-16;



ST-17;



ST-18;



ST-19;



ST-20;



ST-21;




ST-22;



ST-23;



ST-24;



ST-25;



ST-26;



ST-27;



ST-28;




ST-29;



ST-30;



ST-31;



ST-32;



ST-33;




ST-34;



ST-35;



ST-36;



ST-37;




ST-38;



ST-39;



ST-40;



ST-41;



ST-42;



ST-43;



ST-44;



ST-45;



ST-46;



ST-47;



ST-48;



ST-49;



ST-50;



ST-53;



ST-54;



ST-55;



ST-56;



ST-57;



ST-58;



ST-59;



ST-60;



ST-61;



ST-62;



ST-63;



ST-64;



ST-65;



ST-66;



ST-67;



ST-69;



ST-70;



ST-71;



ST-72;



ST-73;



ST-74;



ST-75;



ST-76;



ST-77;



ST-78;



ST-79;



V-02;



V-03;



V-03;



V-04;



V-04;



V-05;



V-06;



V-07;



V—08;



V-09;



V-10;



V-11;



V-13;



V-14;



V-15;



VST-51;

The Viswa Group © 2020



VST-52;



VST-68;

14. APPENDIX 9 – LABORATORY REPORT, ANALYSIS RESULT

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Applicant:	Viswalab Singapore Pte Ltd.
Address:	80 Tagore Lane Singapore 787501

The following sample information was submitted and identified by/on the behalf of the client

Name of Ship:	SSL THAMIRABARANI		
IMO number:	9312468		
Date of Receipt:	Oct.30,2025	**Test Period:**	Oct.30,2025 - Nov.03,2025
Source of samples:	Samples sent by client		

Test Request: Based on the Hong Kong International Convention for the Safe and Environmentally Sound Recycling of Ships, 2009 (the Hong Kong Convention) by International Maritime Organization (IMO), and the 2023 Guidelines for the Development of the Inventory of Hazardous Materials (MEPC.379.(80)) by Marine Environment Protection Committee, EU Regulation 1257/2013 on ship recycling, EMSA's Best Practice Guidance on the Inventory of Hazardous Materials and according to the customer's request, to determine the content of Asbestos, Polychlorinated Biphenyls(PCBs), Ozone Depleting Substances(ODS), Perfluorooctane Sulfonates(PFOS), Cadmium and cadmium compounds, Hexavalent chromium and hexavalent chromium compounds, Lead and lead compounds, Mercury and Mercury compounds, Polybrominated Biphenyl (PBBs), Polybrominated Diphenyl Ethers(PBDEs), Polychlorinated Naphthalenes (PCNs), Short chain Chlorinated Paraffins (SCCP), Hexabromocyclododecane (HBCDD) in the submitted sample(s).

Test Result: Please refer to following page(s).

Edited by Phoebe Reviewed by Wimi Approved by

Seal of: Shanghai ULS Testing Technology Co., Ltd.

Issue date:Nov.03,2025

Report authenticity query website: https://tsa.nmdc.ac.cn/tatsa/web/#/verify/lims

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

Page 1 of 27

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Sample description

No.	Sample No	Location	Equipment	Component
001	ST01	Nav. Deck-Bridge Wing	Paint and coating	Outside Wall Paint
002	ST02	Nav. Deck-Bridge Wing	Paint and coating	Deck Paint
003	ST03	C Deck Engine Casing	Paint and coating	Outside Wall Paint
004	ST04	Upper Deck	Paint and coating	Cargo Hold Hatch
005	ST05	Engine Room- 2nd Deck	Paint and coating	Deck Paint
006	ST06	Nav. Bri. Deck-Wheel	Cable	Out Sheath
007	ST07	Upper Deck	Mooring Winch	Brake lining
008	ST08	Upper Deck	Mooring Winch	Hydraulic Pipe
009	ST09	Forecastle Deck	Anchor Windlass	Brake lining
010	ST10	Forecastle Deck	Mooring Winch	Gasket/packing
011	ST11	Poop Deck-Emer	Emergency	Exhaust pipe
012	ST12	Poop Deck-Emer	Emergency	Manhole Gasket
013	ST13	Poop deck- Air	AC Condensing	Refrigerant pipe
014	ST14	Engine Casing-Poop	Aux Boiler	Body insulation
015	ST15	Engine Casing-Poop	Drain Cooler	Packing
016	ST16	Engine Casing- Upper	Waste Oil	Lagging Insulation
017	ST17	Engine Casing- Upper	Aux Boiler	Lagging Insulation
018	ST18	Engine Casing- Upper	Waste Oil	Firebrick
019	ST19	Engine Casing- Upper	Waste Oil	Door Packing
020	ST20	ER- 2nd Deck	Ref. Plant	Refrigerant pipe
021	ST21	ER- 2nd Deck	Calorifier	Gasket / Packing
022	ST22	ER- 2nd Deck	Main LO Storage	Lagging Insulation
023	ST23	ER-2nd Deck	Main Air	Packing
024	ST24	ER- 2nd Deck	Fresh Water	Packing
025	ST25	ER-2nd Deck	Main engine	Exhaust gas pipe
026	ST26	ER - 2nd Deck-Steering	Steering Gear	Hydraulic oil
027	ST27	ER- 2nd Deck-Eng.	Cable	Out Sheath
028	ST28	ER-3rd Deck	Sewage	Packing
029	ST29	ER-3rd Deck	Sewage	Piepline Gasket
030	ST30	ER-3rd Deck	HFO purifier	Pipeline Insulation
031	ST31	ER-3rd Deck	Purifier FO	Casing insulation

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

No.	Sample No	Location	Equipment	Component
032	ST32	ER-3rd Deck	Purifier LO Heater	Casing insulation
033	ST33	ER-3rd Deck	FW Preheater For	packing
034	ST34	ER-3rd Deck	FW Cooler For	packing
035	ST35	ER-3rd Deck	LO Cooler for ME	packing
036	ST36	ER-3rd Deck	Aux Diesel	Exhaust gas pipe
037	ST37	ER-3rd Deck	Aux Diesel	Pipeline Gasket
038	ST38	ER-Lower Floor	Oily Bilge	Packing
039	ST39	ER-Lower Floor	F.O trans. Pump	Insulation
040	ST40	ER-Lower Floor	Scan Box Drain	Packing
041	ST41	Nav. Bri. Deck-Wheel	Staircase Fire	Packing
042	ST42	Nav. Bri. Deck-Wheel	Staircase Fire	Panel Insulation
043	ST43	Nav. Bri. Deck-Wheel	Floor Overlay	All Layers
044	ST44	Nav. Bri. Deck-Wheel	Steel Wall	Heat Insulation
045	ST45	Nav. Bri. Deck-Wheel	False Ceiling	Insulation filling
046	ST46	Nav. Bri. Deck-Wheel	Window	Rubber sealing with
047	ST47	Nav. Bri. Deck-Wheel	Sliding Door	Rubber Packing
048	ST48	Nav. Bri. Deck-Wheel	Console Cable	Cable gland
049	ST49	D Deck- Chief Engineer	False Ceiling	Insulation filling
050	ST50	D Deck- Master Bed	Floor	All Layers
051	ST53	C Deck-Elec Locker	Cable Wall	Cable Gland
052	ST54	C Deck-Elec Locker	Cable Deck	Cable Gland
053	ST55	C Deck- Spare Cabin	Floor	All Layers
054	ST56	B Deck-Corridor	Stairways	Rubber Grip
055	ST57	A Deck -Battery RM	Marine Steel Door	Rubber Packing
056	ST58	Upper Deck-Galley	Floor	Skid-proof Tile,
057	ST59	Upper Deck - Laundry	Hot water Pipings	Lagging Insulation
058	ST60	Uper Deck-Ref	Wall Panel	Foam Insulation
059	ST61	Uper Deck-Ref	Wall Panel	Foam Insulation
060	ST62	Uper Deck-Ref	Ref Pipe	Pipe Insulation
061	ST63	Upper Deck-Engine	Aft Steel Wall	A60 fire proof
062	ST64	Poop Deck-Corridor	Engine room	Panel insulation

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

No.	Sample No	Location	Equipment	Component
063	ST65	ER- 2nd Deck	FWD steel Wall	A60 fire proof
064	ST66	ER-2nd Deck-Eng.	False Ceiling	Insulation filling
065	ST67	ER-2nd Deck-Eng.	Console Cable	Cable Gland
066	ST69	ER-2nd Deck-Eng.	Eng. Control	Panel Insulation
067	ST70	ER-2nd Deck-Eng.	Eng. Control	Packing
068	ST71	ER- 3rd Deck	H.F.O. Settling Tk	Manhole gasket
069	ST72	ER- 3rd Deck	H.F.O. Settling Tk	Heat Insulation
070	ST73	ER- 3rd Deck	H.F.O pipe	Insulation
071	ST74	ER- 3rd Deck	Steam pipe	Insulation
072	ST75	ER-2nd	Spare Cable	Outer sheath
073	ST76	ER-2nd	Spare Cable	Inside Insulation layer
074	ST77	ER-2nd Deck- Mach	Spare Gasket 1	Gasket
075	ST78	ER-2nd Deck- Mach	Spare Gasket 2	Gasket
076	ST79	ER-2nd Deck- Mach	Spare Gland	Gland Packings

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Test Method(s)

Test Item(s)	Test method	Instrument	RL
Asbestos	ISO 22262- 1:2012 & NIOSH 9000:2015	PLM and XRD	0.1%
Polychlorinated Biphenyls(PCBs)	EPA 3550C:2007 & EPA 8082A:2007	GC-MS	0.5 mg/kg
Ozone Depleting Substances (ODS)	EPA 5021A:2014 & EPA8260D:2018	HS-GC/MS	1 mg/kg
Perfluorooctane Sulfonates (PFOS)	EPA 3550C:2007 & ISO 25101:2009	LC-MS	1 mg/kg
Cadmium and cadmium compounds	IEC 62321-5:2013	ICP-OES	2 mg/kg
Hexavalent chromium and hexavalent chromium compounds	IEC 62321-7-2:2017	UV-Vis	8 mg/kg
Lead and lead compounds	IEC 62321-5: 2013	ICP-OES	2 mg/kg
Mercury and mercury compound	IEC 62321-4:2013+AMD1:2017	ICP-OES	2 mg/kg
Polybrominated Biphenyl (PBBs)	IEC 62321-6: 2015	GC-MS	5 mg/kg
Polybrominated Diphenyl Ethers(PBDEs)	IEC 62321-6: 2015	GC-MS	5 mg/kg
Polychlorinated Naphthalenes (PCNs)	EPA 3550C:2007 & EPA 8270E:2018	GC-MS	5 mg/kg
Short chain Chlorinated Paraffins (SCCP)	EPA 3550C:2007 & EPA 8270E:2018	GC-MS	0.01%
Hexabromocyclododecane (HBCDD)	EPA 3550C:2007 & EPA 8270E:2018	GC-MS	20 mg/kg

Remark: RL=Reporting Limit

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Test results

1. Asbestos

Tested Item	Asbestos					
Material/CAS No / Test / No. / Results	Chrysotile (12001-29-5)	Amosite (12172-73-5)	Crocidolite (12001-28-4)	Anthophyllite (77536-67-5)	Tremolite (77536-68-6)	Actinolite (77536-66-4)
ST02	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST04	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST05	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST07	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST09	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST10	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST11	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST12	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST14	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST15	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST16	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST17	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST18	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST19	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST21	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST22	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST23	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST24	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST25	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST28	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST29	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST30	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST31	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Tested Item	Asbestos					
Material/CAS No / Test / No. / Results	Chrysotile (12001-29-5)	Amosite (12172-73-5)	Crocidolite (12001-28-4)	Anthophyllite (77536-67-5)	Tremolite (77536-68-6)	Actinolite (77536-66-4)
ST32	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST33	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST34	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST35	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST36	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST37	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST38	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST39	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST40	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST41	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST42	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST43	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST44	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST45	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST46	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST48	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST49	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST50	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST53	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST54	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST55	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST57	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST58	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST59	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST63	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Tested Item	Asbestos					
Material/CAS No / Test No. / Results	Chrysotile (12001-29-5)	Amosite (12172-73-5)	Crocidolite (12001-28-4)	Anthophyllite (77536-67-5)	Tremolite (77536-68-6)	Actinolite (77536-66-4)
ST64	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST65	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST66	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST67	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST69	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST71	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST72	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST73	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST74	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST77	D.E.T. (0.1~5%)	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST78	D.E.T. (0.1~5%)	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.
ST79	D.E.T. (0.1~5%)	N.A.D.	N.A.D.	N.A.D.	N.A.D.	N.A.D.

Remark: N.A.D. =No Asbestos was Detected; D.E.T.= Detected

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

2. Polychlorinated Biphenyls (PCBs)

Tested Item	Polychlorinated Biphenyls (PCBs)(mg/kg)						
Material / Test / No. / Results	2.4.4'-Trichlorobiphenyl (PCB 28)	2.2' .5.5'-Tetrachloro-biphenyl (PCB 52)	2.2' .4.5.5'-Pentachloro-biphenyl (PCB 101)	2.3' .4.4' .5-Pentachloro biphenyl (PCB 118)	2.2'3.4.4' .5'-Hexachloro-biphenyl (PCB 138)	2.2' .4.4' .5.5'-Hexachloro-biphenyl (PCB 153)	2.2' .3.4.4' .5.5'-Heptachloro-biphenyl (PCB180)
ST06	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
ST08	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
ST26	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
ST27	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
ST70	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.
ST75	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

3. Ozone Depleting Substances (ODS)

Tested Item			Ozone Depleting Substances (ODS)(mg/kg)			
Material / Test Results / No.			ST13	ST20	ST60	ST62
CFCs	75-69-4	CFC11	N.D.	N.D.	N.D.	N.D.
Halons	124-73-2	Halon2402	N.D.	N.D.	N.D.	N.D.
Other Fully Halogenated CFCs	353-59-3	Halon1211	N.D.	N.D.	N.D.	N.D.
Carbontetrachloride	56-23-5	CCl4	N.D.	N.D.	N.D.	N.D.
1, 1, 1- trichloroethane	71-55-6	C2 H3Cl3	N.D.	N.D.	N.D.	N.D.
Hydrochloro fluorocarbon	1717-00-6	HCFC141b	N.D.	N.D.	110.3	N.D.
Hydrobromo fluorocarbon	1511-62-2	HBFC22b 1	N.D.	N.D.	N.D.	N.D.
Methyl bromide	74-83-9	CH3 Br	N.D.	N.D.	N.D.	N.D.
Bromo chloromethane	74-97-5	CH2 BrCl	N.D.	N.D.	N.D.	N.D.

Remark: 1) "N.D."= Not Detected (Below Method Detection Limit)

2) ">*" = exceed the range of calibration curve and overloaded, The largest quantitative is 10mg/kg. The result is only for reference

3) ">" = exceed the range of calibration curve, The largest quantitative is 10mg/kg. The result is only for reference

4) All types of ODS classified by MEPC.379.(80) was analyzed, if there was any specific ODS detected positive, the specific substance, CAS Number and concentration to be recorded in above table.

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

Report No. : ULSTEST2510300004

4. Perfluorooctane Sulfonates (PFOS)

Test Item / Test No. / Results	Perfluorooctane Sulfonates (PFOS) (mg/kg)
ST50	N.D.
ST55	N.D.
ST75	N.D.

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

5. Cadmium and cadmium compounds, Hexavalent chromium and hexavalent chromium compounds, Lead and lead compounds, Mercury and mercury compounds.

Test Item / Test No. / Results	Lead and Lead compounds(mg/kg)	Cadmium and cadmium compounds(mg/kg)	Mercury and mercury compounds(mg/kg)	Hexavalent chromium and hexavalent chromium compounds(mg/kg)
ST01	N.D.	N.D.	N.D.	-
ST02	129	-	-	-
ST03	N.D.	-	-	-
ST04	131	-	-	-
ST05	27	N.D.	-	-
ST47	3125	-	-	-
ST56	34	-	-	-
ST57	32	-	-	-
ST75	2183	-	-	N.D.
ST76	5408	-	-	-

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

6. Polybrominated Biphenyl(PBBs),Polybrominated Diphenyl Ethers (PBDEs)

No. / Test / Test Item / Results	Test Results	
	ST03	ST76
Polybrominated Biphenyl(PBBs) (mg/kg)		
Monobromobiphenyl	N.D.	N.D.
Dibromobiphenyl	N.D.	N.D.
Tribromobiphenyl	N.D.	N.D.
Tetrabromobiphenyl	N.D.	N.D.
Pentabromobiphenyl	N.D.	N.D.
Hexabromobiphenyl	N.D.	N.D.
Heptabromobiphenyl	N.D.	N.D.
Octabromobiphenyl	N.D.	N.D.
Nonabromobiphenyl	N.D.	N.D.
Decabromobiphenyl	N.D.	N.D.

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

Report No. : ULSTEST2510300004

No. / Test / Test Item / Results	Test Results	
	ST04	ST76
Polybrominated Diphenyl Ethers (PBDEs) (mg/kg)		
Monobrominated Diphenyl Ether	N.D.	N.D.
Dibrominated Diphenyl Ether	N.D.	N.D.
Tribrominated Diphenyl Ether	N.D.	N.D.
Tetrabrominated Diphenyl Ether	N.D.	N.D.
Pentabrominated Diphenyl Ether	N.D.	N.D.
Hexabrominated Diphenyl Ether	N.D.	N.D.
Heptabrominated Diphenyl Ether	N.D.	N.D.
Octabrominated Diphenyl Ether	N.D.	N.D.
Nonabrominated Diphenyl Ether	N.D.	N.D.
Decabrominated Diphenyl Etherl	N.D.	N.D.

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

7. Polychlorinated Naphthalenes (PCNs)

Test Item / Test / No. / Results	Polychlorinated Naphthalenes (PCNs) (mg/kg)
ST75	N.D.

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

8. Short chain Chlorinated Paraffins (SCCP)

No. / Test Results	Short chain Chlorinated Paraffins (SCCP) (%)
ST03	N.D.
ST76	N.D.

Remark: 1) 1%= 10000mg/kg= 10000ppm
2) "N.D." = Not Detected (Below method detection limit)

9. Hexabromocyclododecane (HBCDD)

No. / Test Results	Hexabromocyclododecane (HBCDD) (mg/kg)
ST61	N.D.
ST77	N.D.

Remark: 1) mg/kg = ppm
2) "N.D." = Not Detected (Below method detection limit)

---------- See next page ----------

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

Photo of Sample	
 001	 002
 003	 004
 005	 006

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

 007	 008
 009	 010
 011	 012

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

Page 16 of 27

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004



Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量檢測 ULS TESTING

Report No. : ULSTEST2510300004

 019	 020
 021	 022
 023	 024

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

TEST REPORT

佑量檢測 ULS TESTING

Report No. : ULSTEST2510300004

 025	 026
 027	 028
 029	 030

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

 031	 032
 033	 034
 035	 036

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004



Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

 043	 044
 045	 046
 047	 048

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量檢測 ULS TESTING

Report No. : ULSTEST2510300004

 049	 050
 051	 052
 053	 054

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

TEST REPORT

佑量檢測 ULS TESTING

Report No. : ULSTEST2510300004

 055	 056
 057	 058
 059	 060

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail: info@ulstesting.com Website: http://www.ulstesting.com

The Viswa Group © 2020

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004



061 062 063 064 065 066

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

TEST REPORT

佑量检测 ULS TESTING

Report No. : ULSTEST2510300004

 067	 068
 069	 070
 071	 072

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

TEST REPORT

佑量檢測 ULS TESTING

Report No. : ULSTEST2510300004



073 074

075 076

---------- End of Report ----------

This test report is responsible for the tested samples only. Without permission of the test centre this test report is not permitted to be duplicated in extracts. The test report is invalid without the specialized stamp of Shanghai ULS Testing Technology Co., Ltd. The test report is invalid if altered. Objections to the test report must be submitted to Shanghai ULS Testing Technology Co., Ltd. within 15 days. ULSTESTING declines any responsibility with deviations required by the customer that may affect the validity of result. The information is provided by the customer in this report may affect the validity of the results, the test lab is not responsible for it. The measurement result is considered in conformance with the requirement if it is within the prescribed limit, It is not necessary to calculate the uncertainty associated with the measurement result, unless the specification, standard or customer have special requirements. The data and results of this test report can only be used for scientific research, teaching, internal quality control.

Shanghai ULS Testing Technology Co., Ltd.
Add: Room 303, building 5, No. 999, Jiangyue Road, Minhang District, Shanghai, 201114, P. R. China Tel:021-26018232
E-mail：info@ulstesting.com Website：http://www.ulstesting.com

15. APPENDIX 10 – ASBESTOS REMOVAL CERTIFICATE



Colombo Dockyard PLC
Ship Repairers, Ship Builders and Heavy Engineers

04th November 2025

To Whom It May Concern,

CERTIFICATE OF ASBESTOS REMOVAL AND SAFE DISPOSAL

This is to certify that Colombo Dockyard PLC has carried out asbestos removal activities onboard the vessel M.V. SSL THAMIRABARANI during her drydocking and repair period at our shipyard as per the vessel request.

All identified asbestos-containing materials (ACM) were safely removed in accordance with applicable international safety standards, IMO guidelines, and local environmental regulations.

The removed materials were duly collected, contained, and disposed of through an authorized hazardous waste management facility.

Total content:

1. Spare Gasket (ST77), Location ER 2nd Deck, Weight: 10.0Kg
2. Spare Gasket (ST78), Location ER 2nd Deck, Weight: 10.0Kg
3. Spare Gland Packings, (ST79), Location ER 2nd Deck, Weight: 4.0Kg

We hereby confirm that no asbestos-containing materials remain onboard the vessel following completion of the removal and disposal process.

For and on behalf of

M.M.P. Cooray

Assistant Business Manager (Ship Management)
COLOMBO DOCKYARD PLC

M. M. Priyanka Cooray
Asst. Business Manager
(Ship Management)
Colombo Dockyard PLC
(Company No: PQ 50)

"... an Odyssey of Excellence"
P. O. Box 906, Port of Colombo, Colombo 15, Sri Lanka (Company Reg. No. PQ 50)
Tel : (+94) 11 242 9000 / (+94) 11 742 9000 | Fax : (+94) 11 244 6441 / (+94) 11 232 9479
E-mail : coldock@cdl.lk | Web Site : www.cdl.lk

LRQA CERTIFIED


ITEM NO-79

