Test Report

Report No. ..... :	SHER220300017871	**Release date ..... :**	2022-03-30
Applicant's name ..... :	Richbeam (Suzhou) Technology Co., LTD		
Address ..... :	NO.788, southeast Avenue, changshu high tech Industrial Development zone		
Laboratory name..... :	SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd.		
address..... :	588 West Jindu Road, Xinqiao, Songjiang, 201612 Shanghai, China		
Test Site ..... :	No. 588 West Jindu Road, Songjiang District, Shanghai, China		
Product Description..... :	2D TOF LIDAR		
Supplier Model No ..... :	LakiBeam 1、LakiBeam 1L		
S/N No ..... :	-		
Sample status ..... :	Good		



Sample receipt date ..... :	2022-03-25	No. of samples ....:	2
Date of Test ..... :	2022-03-29		
Test Standard..... :	IEC 60529:1989/AMD2:2013/COR1:2019 Degrees of protection provided by enclosures (IP Code)		
Conclusion ..... :	See following pages		

Remark /Note ..... :

1) The test result is only valid for the test sample.

2) In addition to copying the full text, can't partial copying of the report without laboratory approval, make sure that the report will not be partially extracted.

Tested By:

Frank Fang

Frank Fang

Approved by:

Ocean Li

Ocean Li

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

NO.588 West Jindu Road, Songjiang District, Shanghai, China 201612 t (86-21) 61915666 f (86-21) 61915678 www.sgsgroup.com.cn
中国·上海·松江区金都西路 588 号 邮编: 201612 t (86-21) 61915666 f (86-21) 61915678 e sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Summary of Results

No	Test Item	Reference Standard	Result	Sample number
1	IP6X dustproof test	IEC 60529:1989/AMD2:2013/COR1:2019 Degrees of protection provided by enclosures (IP Code)	Pass	1#
2	IPX5 waterproof test	IEC 60529:1989/AMD2:2013/COR1:2019 Degrees of protection provided by enclosures (IP Code)	Pass	2#

Note: Pass: Meet the requirements;

Fail: Does not meet the requirements;

/: Not apply to the judgment.

1. Test Item: IP6X dustproof test

Environmental requirement:

Ambient Temperature: 15~35 ℃; Relative Humidity: 45~75 %RH; Atmos: 101 kPa.

Reference standard:

IEC 60529:1989/AMD2:2013/COR1:2019 Degrees of protection provided by enclosures (IP Code)

Test condition:

Simulated dust	Talcum powder
Maximum differential pressure	2kpa
Dust Concentration	2 kg/m³ chamber volume and be kept in suspension during the test
Pumping rate range	40 times shell volume< Pumping rate<60 times shell volume
Test duration	2h

Test acceptance requirements:

After the test, there is no dust inside.

Test result:



Meet the judgment requirements.

Sample Number	Test Result
1#	After the test, there is no dust inside.

Conclusion: Qualified

The sample meets the test requirements.

Photographs of the Test Configuration

Before the Test-1#	During the Test-1#
	
After the Test-1#	**After the Test-1#**
	

2. Test Item: IPX5 waterproof test

Environmental requirement:

Ambient Temperature: 15~35 ℃; Relative Humidity: 45~75 %RH; Atmos: 101 kPa.

Reference standard:

IEC 60529:1989/AMD2:2013/COR1:2019 Degrees of protection provided by enclosures (IP Code)

Test condition:

Water Flow	12.5(1±5%) L/min
Nozzle diameter	6.3 mm
Test Distance	2.5m~3m
Test duration	1 min per square meter calculated according to the surface of the sample shell, test for at least 3 min

Test acceptance requirements:

After the test, there is no water inside.

Test result:


Meet the judgment requirements.

Sample Number	Test Result
2#	After the test, there is no water inside.

Conclusion: Qualified

The sample meets the test requirements.

Photographs of the Test Configuration

Before the Test-2#	During the Test-2#
	
After the test-2#	After the test-2#
	

Testing Instrument and Equipment

Equipment	Model	Equipment No.	Calibration Date	Next Calibration Date
Dust chamber	JYSD-500	SHES806101	2021-12-26	2022-12-25
Waterproof test equipment (IPX1-8)	/	SHES806401	2021-05-08	2022-05-07

------End of Report------