



NABL Accredited
Approved by Govt. of
India Dept. of Science &
Technology for Mechanical
& Chemical Testing



RAJKOT METLAB SERVICES
METALLURGICAL TESTING LABORATORY

Testing Today, Protecting Tomorrow


National Highway - 27, Opp. Tulip Party Plot, Near JCB Showroom, Rajkot - 360022. Call : +91 - 97252 13600, E-mail : testing@rajkotlab.com, Web : www.rajkotlab.com

TEST REPORT

Customer Name :	KSQUARE ENERGY	ULR - TC521219000026213P
Address :	331, Sahjanand Business Park, Sardar Patel Ring Rd, opp. Marigold Restaurant, Odhav, Ahmedabad-382415 Gujarat India	Report No : XME-0227.1
		Date of Reporting : 19/12/2019
		Sample Received Date : 19/12/2019

Type of Test :	Coating Thickness by Microscope & Soil Resistivity by Wenner Four-Electrode Method
*Customer's Reference :	Nil
*Condition of sample :	Test Piece
*Identification of sample :	Solar Rooftop Earthing (As Per IEC 62561-2), 14 mm Dia Copper Bonded Earthing Rod(KE-01)
*Material Specification :	--
Date of Testing :	19/12/2019
Instrument Utilized :	19/12/2019
Test Method :	ASTM B487-1985 (RA2013), **ASTM G57-95a RA 01, (As Per IEC 62561-2)

Result :



Location		(μm)
1	:	308
2	:	312
3	:	307
4	:	304
5	:	306
Average	:	307
Magnification	:	100X

Resistivity in $\Omega\cdot\text{m}$

Reading 1	:	0.101
Reading 2	:	0.106
Reading 3	:	0.110
Average	:	0.106

Requirements : Coating = 250 μm Minimum & Resistivity = 0.12 $\Omega\cdot\text{m}$ Maximum

Remarks : Acceptable. [% of Copper (Cu) : 99.92]

Kuldip
Tested By



Authorized Signature
Kuldip (TM)

Witnessed By

Terms & Conditions :

- 1) The results relate only to the sample tested, Sample(s) drawn by party.
- 2) Test certificate shall not be re-produced except in full without the written approval of Laboratory.
- 3) RMS has made their best endeavors to provide accurate and reliable information, RMS is not responsible for any financial liability due to any act of omission or error made.