

Josh Strange 636-614-8582 assurancegas@gmail.com

Address: 10 Vouga Ln St Louis MO, 63131

AR: Galloway Building Services Inspection Date: 6/17/2022


Inspection ID: 30773

Acceptance and use of this report assume the following terms, conditions, and limitations:

- The gas line inspection is limited to the date and time of the inspection only as conditions in the lines and appliances can change over time.
- 2. The report is based solely on the opinion of the technician with the information he has available at the time of the inspection.
- 3. ASSURANCE Gas Inspections is not offering any sort of guarantee or warranty as part of this inspection report.

Item	Description	Result	Notes
Furnace	Operation	Pass	Water leaking in furnace – recommend clean and service (C)
	Safety/Code Compliance	Pass	
	Combustion Analyzer	Fail	CO too high – recommend clean and service (D)
	Combustion Air	Pass	
Water Heater	Operation	Pass	
	Safety/Code Compliance	Fail	Draft hood needs to be secured (E)
	Combustion Air	Pass	
Stove	Operation	Pass	
	Anti-tip	Pass	
	Code Compliance	Pass	
Gas Log	Operation	Pass	Valve is stiff and missing knob (I)
	Safety/Code Compliance	Pass	
Flue	Condition	Pass	
	Code Compliance	Fail	Water heater flue missing screws – should have 3 per seam (E)
	Seven Times Rule	Pass	
Gas Runs	Pressure Test	N/A	
	Code Compliance	N/A	
Gas Dryer	Operation	N/A	
	Compliance	N/A	
	Venting	N/A	


Air Conditioner	Result	Notes
Operation	OK	
<ul><li>Electrical components and compartment</li><li>Capacitor, contactor</li></ul>	ОК	
Condensing unit clean and free of obstruction	Note	Condensing unit in contained space is restricting air flow. Unit should have 12" clearance on all sides to ensure proper air flow. This unit is also dirty – recommend clean and service (L)
Condensing unit fins in good repair	OK	
Condensing unit suction line	OK	
Refrigerant	OK	
Other	N/A	



attached



Gas log, valve stiff and missing knob



Damper clip



Electric furnace and air handler



Condensing unit restricted air flow, dirty



Downstairs condensing unit



Main condensing unit OK