


Figure 2 Proposed architecture: MobileNetV2 -> FPN(AMFF) -> CSAF -> SEAM -> classifier



Task: six-class steel surface defect classification with CAM-based localization. Trained with image-level cross-entropy only; no detection head, no box regression.