

## Verification Report No.: NGBEC26003492502

Date: Jul 16, 2026

Page 1 of 10

Client Name: Volteroom s.r.o.

Client Address: Znievska 3060/8, 851 06 Bratislava, Slovakia

Sample Name: Flush-type switch

Tested Basic Model No.: E08DA103

Tested Extended Model No.: F08DA103

Client Ref. Information: abDA101,abDA102,abDA103;  
(ab=E01,E02,E03,E05,E06,E07,E08,E09,E10,E11,E12,E13,E14,E15,E16,E17,  
F01,F02,F03,F04,F05,F06,F07,F08,F09,F10)

The above sample(s) and information were provided by the client.

SGS Job No.: NBP26-003558

Sample Receiving Date: May 06, 2026

Verification Period: May 06, 2026 ~ May 28, 2026

Verification Requested: With reference to RoHS Directive (EU) 2015/863 amending 2011/65/EU.

Verification Method(s): Please refer to next page(s).

Verification Result(s): Please refer to next page(s).

### Test Result Summary:

| Test Items                                                                                                                                                                                                                                                                                                                | Conclusion |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| EU RoHS Directive (EU) 2015/863 amending Annex II to Directive 2011/65/EU - Lead, Mercury, Cadmium, Hexavalent chromium, Polybrominated biphenyls (PBB), Polybrominated diphenyl ethers (PBDE), Bis(2-ethylhexyl) phthalate (DEHP), Butyl benzyl phthalate (BBP), Dibutyl phthalate (DBP) and Diisobutyl phthalate (DIBP) | Pass       |

Signed for and on behalf of  
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Hedy Hu

Hedy Hu

Approved Signatory

Scan to see the report



50E81F43





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1层B区, 003幢3层1层B区, 009幢4层1层B区, 009幢4层2-5层, 004幢5层1层, 004幢5层2层, 008幢7号1层B区, 008幢7号1层C区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

Photo of Submitted Sample



### Verification Method(s):

1. With reference to IEC 62321-2:2021, disassembly and disjointment were performed for the submitted samples.
2. With reference to IEC 62321-1:2013, tests were performed for the samples indicated by the photos in this report.
  - (1) With reference to IEC 62321-3-1:2013, screening by EDXRF spectroscopy.
  - (2) Wet chemical test method: With reference to IEC 62321-4:2013+A1:2017, IEC62321-5:2013, IEC



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

SGS-CSI Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemical Services (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7/1/F, & Unit 2, 4/F, Building 5/Unit 2, 1/F, & 2/F to 5/F, Building 4/Unit 2, 1/F, Building 3/4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层, 003幢3号楼2层, 009幢4号楼1层2区, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层2区, 008幢7号楼1层4区, 008幢7号楼2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

62321-7-1:2015, IEC 62321-7-2:2017, IEC 62321-12:2023, IEC 62321-6:2015 and IEC62321-8:2017 , analyzed by ICP-OES,UV-Vis and GC-MS.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

SGS-CS Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemicals Service (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号4层, 003幢3号1层2区, 009幢4号1层2区, 009幢4号2-5层, 004幢5号1层, 004幢5号4层2区, 008幢7号1层4区, 008幢7号2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

**Verification Part Description:**

| SN ID | Sample No. | SGS Sample ID                | Description                                                                          |
|-------|------------|------------------------------|--------------------------------------------------------------------------------------|
| SN1   | A1         | NGB26-0034925-0001.C001      | E08DA103-Silvery metal                                                               |
| SN2   | A2         | NGB26-0034925-0001.C002      | E08DA103-Silvery metal screw                                                         |
| SN3   | A3         | NGB26-0034925-0001.C003      | E08DA103-Silvery metal                                                               |
| SN4   | A4         | NGB26-0034925-0001.C004      | E08DA103-Gray plastic                                                                |
| SN5   | A5         | NGB26-0034925-0001.C005      | E08DA103-Gray plastic                                                                |
| SN6   | A6         | NGB26-0034925-0001.C006      | E08DA103-Silvery metal                                                               |
| SN7   | A7         | NGB26-0034925-0001.C007      | E08DA103-Silvery metal                                                               |
| SN8   | A8         | NGB26-0034925-0001.C008      | E08DA103-Silvery metal                                                               |
| SN9   | A9         | NGB26-0034925-0001.C009      | E08DA103-Silvery metal screw                                                         |
| SN10  | A10        | NGB26-0034925-0001.C010      | E08DA103-Silvery metal                                                               |
| SN11  | A11        | NGB26-0034925-0001.C011      | E08DA103-Golden metal screw                                                          |
| SN12  | A12        | NGB26-0034925-0001.C012      | E08DA103-Black audion body                                                           |
| SN13  | A13        | NGB26-0034925-0001.C013      | E08DA103-Golden metal                                                                |
| SN14  | A14        | NGB26-0034925-0001.C014      | E08DA103-Silvery metal                                                               |
| SN15  | A15.1      | NGB26-0034925-0001.C015.C001 | E08DA103-Silvery metal soldering tin<br>(A15 improved sample submitted by 2026-5-26) |
| SN16  | A16        | NGB26-0034925-0001.C016      | E08DA103-Green PCB body                                                              |
| SN17  | A17        | NGB26-0034925-0001.C017      | E08DA103-Blue capacitor body                                                         |
| SN18  | A18        | NGB26-0034925-0001.C018      | E08DA103-Black audion body                                                           |
| SN19  | A19        | NGB26-0034925-0001.C019      | E08DA103-Golden metal                                                                |
| SN20  | A20        | NGB26-0034925-0001.C020      | E08DA103-Silvery metal                                                               |
| SN21  | A21        | NGB26-0034925-0001.C021      | E08DA103-Silvery metal                                                               |
| SN22  | A22        | NGB26-0034925-0001.C022      | E08DA103-White plastic                                                               |
| SN23  | A23        | NGB26-0034925-0001.C023      | E08DA103-Black plastic                                                               |
| SN24  | A24        | NGB26-0034925-0001.C024      | E08DA103-Black plastic                                                               |
| SN25  | A25        | NGB26-0034925-0001.C025      | E08DA103-White plastic                                                               |
| SN26  | A26        | NGB26-0034925-0001.C026      | E08DA103-Brown plastic                                                               |
| SN27  | A27        | NGB26-0034925-0001.C027      | E08DA103-Silvery metal                                                               |
| SN28  | A28        | NGB26-0034925-0001.C028      | E08DA103-Silvery metal                                                               |
| SN29  | B1         | NGB26-0034925-0002.C001      | F08DA103-White plastic                                                               |
| SN30  | B2         | NGB26-0034925-0002.C002      | F08DA103-White plastic                                                               |



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
 中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1层4层, 003幢3层2层2区, 009幢4号楼1层2区, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层2区, 008幢7号楼1层4区, 008幢7号楼2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)



**Verification Result(s):**

In accordance with the result of material risk assessment, the following disjointed parts in the submitted sample have been verified. (Unless otherwise specified, the unit is mg/kg).

| Test Item(s) | A1   | A2   | A3   | A4   | A5   | A6   | A7   | A8   |
|--------------|------|------|------|------|------|------|------|------|
| Pb           | BL   | BL   | BL   | BL   | BL   | BL   | BL   | BL   |
| Hg           | BL   | BL   | BL   | BL   | BL   | BL   | BL   | BL   |
| Cd           | BL   | BL   | BL   | BL   | BL   | BL   | BL   | BL   |
| Cr(VI)▼      | ND   | BL   | BL   | BL   | BL   | ND   | BL   | ND   |
| PBB          | ---  | ---  | ---  | ND   | ND   | ---  | ---  | ---  |
| PBDE         | ---  | ---  | ---  | ND   | ND   | ---  | ---  | ---  |
| DEHP         | ---  | ---  | ---  | BL   | BL   | ---  | ---  | ---  |
| BBP          | ---  | ---  | ---  | BL   | BL   | ---  | ---  | ---  |
| DBP          | ---  | ---  | ---  | BL   | BL   | ---  | ---  | ---  |
| DIBP         | ---  | ---  | ---  | BL   | BL   | ---  | ---  | ---  |
| Conclusion   | PASS | PASS | PASS | PASS | PASS | PASS | PASS | PASS |

| Test Item(s) | A9   | A10  | A11  | A12  | A13  | A14  | A15.1 | A16  |
|--------------|------|------|------|------|------|------|-------|------|
| Pb           | BL   | BL   | BL   | BL   | BL   | BL   | BL    | BL   |
| Hg           | BL   | BL   | BL   | BL   | BL   | BL   | BL    | BL   |
| Cd           | BL   | BL   | BL   | BL   | BL   | BL   | BL    | BL   |
| Cr(VI)▼      | BL   | BL   | BL   | BL   | ND   | BL   | BL    | BL   |
| PBB          | ---  | ---  | ---  | ND   | ---  | ---  | ---   | BL   |
| PBDE         | ---  | ---  | ---  | ND   | ---  | ---  | ---   | BL   |
| DEHP         | ---  | ---  | ---  | BL   | ---  | ---  | ---   | BL   |
| BBP          | ---  | ---  | ---  | BL   | ---  | ---  | ---   | BL   |
| DBP          | ---  | ---  | ---  | BL   | ---  | ---  | ---   | BL   |
| DIBP         | ---  | ---  | ---  | BL   | ---  | ---  | ---   | BL   |
| Conclusion   | PASS | PASS | PASS | PASS | PASS | PASS | PASS  | PASS |

| Test Item(s) | A17  | A18   | A19    | A20  | A21  | A22  | A23  | A24  |
|--------------|------|-------|--------|------|------|------|------|------|
| Pb           | BL   | 3290▲ | 29016▲ | BL   | BL   | BL   | BL   | BL   |
| Hg           | BL   | BL    | BL     | BL   | BL   | BL   | BL   | BL   |
| Cd           | BL   | BL    | BL     | BL   | BL   | BL   | BL   | BL   |
| Cr(VI)▼      | BL   | BL    | BL     | BL   | BL   | BL   | BL   | BL   |
| PBB          | BL   | BL    | ---    | ---  | ---  | BL   | ND   | ND   |
| PBDE         | BL   | BL    | ---    | ---  | ---  | BL   | ND   | ND   |
| DEHP         | BL   | BL    | ---    | ---  | ---  | BL   | BL   | BL   |
| BBP          | BL   | BL    | ---    | ---  | ---  | BL   | BL   | BL   |
| DBP          | BL   | BL    | ---    | ---  | ---  | BL   | BL   | BL   |
| DIBP         | BL   | BL    | ---    | ---  | ---  | BL   | BL   | BL   |
| Conclusion   | PASS | PASS  | PASS   | PASS | PASS | PASS | PASS | PASS |

| Test Item(s) | A25 | A26 | A27 | A28 | B1 | B2 |
|--------------|-----|-----|-----|-----|----|----|
| Pb           | BL  | BL  | BL  | BL  | BL | BL |
| Hg           | BL  | BL  | BL  | BL  | BL | BL |
| Cd           | BL  | BL  | BL  | BL  | BL | BL |
| Cr(VI)▼      | BL  | BL  | BL  | BL  | BL | BL |



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

SGS-CS Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemical Services (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F, to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgs.com.cn](http://www.sgs.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层, 003幢3号楼1层, 009幢4号楼1层, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层2区, 008幢7号楼1层4区, 008幢7号楼2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

| Test Item(s) | A25  | A26  | A27  | A28  | B1   | B2   |
|--------------|------|------|------|------|------|------|
| PBB          | BL   | BL   | ---  | ---  | ND   | ND   |
| PBDE         | BL   | BL   | ---  | ---  | ND   | ND   |
| DEHP         | ND   | BL   | ---  | ---  | BL   | BL   |
| BBP          | ND   | BL   | ---  | ---  | BL   | BL   |
| DBP          | ND   | BL   | ---  | ---  | BL   | BL   |
| DIBP         | ND   | BL   | ---  | ---  | BL   | BL   |
| Conclusion   | PASS | PASS | PASS | PASS | PASS | PASS |



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention:** To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CSI Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemicals (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgs.com](http://www.sgs.com)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1层4层, 003幢3层1层2区, 009幢4号楼1层2区, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层2区, 008幢7号楼1层4区, 008幢7号楼2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

**Notes:**

(1) Interpretation of screening results by X-ray fluorescence spectrometry (XRF):

(a) Screening limits in mg/kg for regulated elements in various matrices according to IEC 62321-3-1:2013 Annex A as below table.

| Element | Polymers                                             | Metals                                               | Composite Materials                                  |
|---------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------------|
| Cd      | $BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$   | $BL \leq (70-3\sigma) < X < (130+3\sigma) \leq OL$   | $LOD < X < (150+3\sigma) \leq OL$                    |
| Pb      | $BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$ | $BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$ | $BL \leq (500-3\sigma) < X < (1500+3\sigma) \leq OL$ |
| Hg      | $BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$ | $BL \leq (700-3\sigma) < X < (1300+3\sigma) \leq OL$ | $BL \leq (500-3\sigma) < X < (1500+3\sigma) \leq OL$ |
| Br      | $BL \leq (300-3\sigma) < X$                          | Not applicable                                       | $BL \leq (250-3\sigma) < X$                          |
| Cr      | $BL \leq (700-3\sigma) < X$                          | $BL \leq (700-3\sigma) < X$                          | $BL \leq (500-3\sigma) < X$                          |

(b) If the maximum allowed level restricts PBB/PBDE and Cr(VI) rather than Br and Cr, the exceptions are the XRF determinations of Br and Cr. If the quantitative results for the elements Br and/or Cr are higher than the limit (for Br calculated based on the stoichiometry of Br in the most common congeners of PBB/PBDE), the sample is "inconclusive".

(c) Results are obtained by EDXRF for primary screening, LOD = Limit of Detection, BL = Below Limit, OL = Over Limit, IN (The symbol X marks the region) = Inconclusive, where further investigation is necessary, and further chemical testing by ICP-OES (for Cd, Pb, Hg), UV-Vis (for Cr(VI)) and GC-MS (for PBB/PBDE) are recommended to be performed.

(d) The EDXRF screening test for elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

(2) Screening results of Phthalates (PHTH) below the limits are shown as "BL". Further chemical testing by GC-MS is to be performed if the results exceed limits.

| Test Items                         | CAS No.  |
|------------------------------------|----------|
| Bis(2-ethylhexyl) phthalate (DEHP) | 117-81-7 |
| Butyl benzyl phthalate (BBP)       | 85-68-7  |
| Dibutyl phthalate (DBP)            | 84-74-2  |
| Diisobutyl phthalate (DIBP)        | 84-69-5  |

(3) Interpretation of results by chemical tests:

(a) mg/kg = 0.0001%, MDL = Method detection Limit, ND = Not Detected (<MDL), --- = Not Applicable.

(b) Unit and MDL in wet chemical test

| Test Items | Pb    | Hg    | Cd    | DEHP  | BBP   | DBP   | DIBP  |
|------------|-------|-------|-------|-------|-------|-------|-------|
| Unit       | mg/kg | mg/kg | mg/kg | mg/kg | mg/kg | mg/kg | mg/kg |
| MDL        | 10    | 10    | 10    | 100   | 100   | 100   | 100   |

The MDL for single compound of PBB and PBDE is 100 mg/kg,

MDL of Cr(VI) for polymer, composite and leather sample is 10 mg/kg.

MDL of Cr(VI) for metal sample is 0.10 µg/cm².

(c) ▼ = Metal sample

a. The sample is positive for Cr(VI) if the Cr(VI) concentration is greater than 0.13 µg/cm². The sample coating is considered to contain Cr(VI).

b. The sample is negative for Cr(VI) if Cr(VI) is ND (concentration less than 0.10 µg/cm²). The coating is considered a non-Cr(VI) based coating

c. The result between 0.10 µg/cm² and 0.13 µg/cm² is considered to be inconclusive-unavoidable coating variations may influence the determination

Information on storage conditions and production date of the tested sample is unavailable and thus Cr(VI) results represent status of the sample at the time of testing.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CS Standards Technical Services (Ningbo) Co., Ltd. Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7/1/F, & Unit 2, 4/F, Building 5/1 Unit 2, 1/F, & 2/F to 5/F, Building 4/1 Unit 2, 1/F, Building 3/4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgs.com](http://www.sgs.com)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢4层, 003幢3号楼层2区, 009幢4号楼层1层2区, 009幢4号楼层2-5层, 004幢5号楼层1层, 004幢5号楼层4层2区, 008幢7号楼层1层2区, 008幢7号楼层2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)

(4) Restricted substances and maximum concentration values tolerated by weight in homogeneous materials under RoHS Directive: Cd: 0.01%, Pb/Hg/Cr(VI)/PBB/PBDE/DEHP/BBP/DBP/DIBP: 0.1%. The limit is quoted from RoHS Directive (EU) 2015/863.

(5) IEC 62321 series is equivalent to EN 62321 series.

(6) ▲=According to the declaration from the client, Lead (Pb) in sample A19 is exempted by EU RoHS directive 2011/65/EU based on [ANNEX III 6(c)]: Copper alloy containing up to 4 % lead by weight. Lead (Pb) in sample A18 is exempted by EU RoHS directive 2011/65/EU based on [ANNEX III 7(c)-I]: Electrical and electronic components containing lead in a glass or ceramic other than dielectric ceramic in capacitors, e.g. piezoelectronic devices, or in a glass or ceramic matrix compound.  
More information about exemption can be found via the following link:  
<https://rohs.sgsonline.com.cn/PDFLinks/en/RSTS-TP-037%20RoHS%20Exemption%20%28EN%29.pdf>

(7) According to the declaration from applicant, the materials of other parts in Model "F08DA103" are the same as those in Model "E08DA103", and the results of Model "E08DA103" for support the results of other parts in Model "F08DA103". The applicant will take the responsibility of all discrepancy and risk.

(8) According to the declaration from applicant, the materials of Model "E08DA103" are the same as those in Model mentioned in Client Ref. Information and its results for support the results of Model mentioned in Client Ref. Information. The applicant will take the responsibility of all discrepancy and risk.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule ( $w=0$ ) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.


**Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

SGS-CSI Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemicals Technical Services (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1层4层, 003幢3层1层2区, 009幢4号楼1层2区, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层2区, 008幢7号楼1层4区, 008幢7号楼2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)



Sample photos:




Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CS Standards Technical Services (Ningbo) Co., Ltd.  
Central Chemicals (Ningbo) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号4层, 003幢3号1层2区, 009幢4号1层2区, 009幢4号2-5层, 004幢5号1层, 004幢5号4层2区, 008幢7号1层4区, 008幢7号2层2区, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)



SGS authenticate the photo on original report only  
\*\*\* End of Report \*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CS Standards Technical Services (China) Co., Ltd.  
Central Chemicals (China) Co., Ltd.

Unit 6, 1/F, & Unit 2 & Unit 5, 2/F, Building 7 / 1/F, & Unit 2, 4/F, Building 5 / Unit 2, 1/F, & 2/F to 5/F, Building 4 / Unit 2, 1/F, Building 3 / 4/F, Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. [www.sgsgroup.com.cn](http://www.sgsgroup.com.cn)  
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层, 003幢3号楼2层, 009幢4号楼1层, 009幢4号楼2-5层, 004幢5号楼1层, 004幢5号楼4层, 008幢7号楼1层, 008幢7号楼2层, 5区 [sgs.china@sgs.com](mailto:sgs.china@sgs.com)