Legon Fire Station Child Lab and E A Boateng Road Reconstruction Brief

Correct the selected area in the existing University of Ghana bicycle exploration game using 14 paired street comparisons, three annotated real aerial maps and six game overview references. The principal task is to replace unsupported tall institutional templates with the observed low buildings, yards, roof forms and connected road landscape. This brief follows the supplied sample format and addresses this new section only.

Required result

One coherent environment must account for every assigned street direction and all overlapping aerial views. Correct the wrong footprint, height and terrain relationships first; then match roofs, facades, surfaces, planting and limited props. Existing bicycle movement, collision behaviour and completed areas remain functional.

Evidence guide

The paired photographs below preserve the original numbering and ordering. In-game views are on the left and real street views on the right. The nine additional references are reproduced separately, with their original annotations retained.

Reference	View assignments	Main role
R1	Pairs 1 and 2	Courtyard and opposite low building
R2	Pairs 7 through 13	Compound court and Child Study Centre vicinity
R3	Pairs 3 through 6 and 14	Station parcel and road corridor
G1 to G5	Five game aerial angles	Current wrong masses and scene consistency
G6	Game map crop	Locate assets and check route continuity

Limits of the references

These images are visual references rather than surveys. Keep uncertain dimensions, concealed heights and ground levels adjustable. The sample PDF guides presentation only. Building identities follow readable signs and confirmed placements; map labels alone cannot establish architecture or ownership.

Shared layout and terrain corrections

Register the three real map crops before editing

Use R1 for Pairs 1-2, R2 for Pairs 7-13, and R3 for Pairs 3-6 and 14. Match each to the game using road bends, entrances, roof corners and courtyard edges. Keep original arrow assignments and record approximate camera zones; a line crossing is not a junction. Determine how the crops connect through shared anchors before placing a campus-wide transform. Do not infer metres, north orientation or elevation from arrow lengths.

Replace the wrong building types locally

The station needs low gabled service buildings, an open metal canopy, enclosure and near office, not a cluster of tall classrooms. The courtyard/wing targets in Pairs 1-2 need differentiated roofs and facades. The R2 cluster needs a perforated entrance screen, low gabled sign elevation, connected wings, courtyard and landscaped path. Similar roof colours do not make these one asset or one institution. Tall neighbouring buildings can remain where real elevation evidence supports them.

Build ground relationships rather than one lawn plane

Separate road asphalt, station hardstanding, block paving, irregular courtyard stone, planted beds, dirt tracks, taller grass and dense vegetation. Model local curb rises, building plinths, threshold levels and verge falls where visible. Pair 1 has a raised veranda base; Pair 12 has a grassy foreground transition to harder ground; Pair 14 has a contained drain opening. None establishes a large site-wide slope. Pair 10 camera roll must be handled before terrain inference.

Keep unsupported geometry adjustable

Retaining walls, embankments, stairs, terraces and landing levels need visible evidence. Do not add them because an image has diagonal rooflines or dark shadows. No selected street photo clearly proves a particular unfinished building; do not interpret a pale aerial patch as a completed multi-storey block or an unfinished frame without corroboration. Hidden roofs and heights stay simple until verified. If a specific target remains unresolved, ask exactly which pair location needs clarification.

Protect circulation and completed work

Bind each changed mesh to a stable parcel/object ID. Preserve verified scene objects outside the selected area. Replace or disable obsolete colliders with their meshes. Road-to-yard transitions must remain rideable, terrain height must support wheels, and vegetation or AC units must not block required paths. Keep overhead wires visual; use simplified boundary collision and avoid colliders on tiny leaves, sign lettering or surface texture.

Shared asset relationships and correction order

One station ensemble across five street views

Pairs 3-5 observe the same station gables, tank, canopy and enclosure from different framing; Pair 6 addresses a nearby low office/access; Pair 14 checks the road corridor. Confirm their exact placement through R3. Use one canopy and one tank, with view-specific cameras. A tank support is a physical object; the game arrival beam is not.

Courtyard and opposite low building

Pairs 1 and 2 share R1 but point at different outlined targets. Maintain the blue courtyard complex, green long building, road separation, roof connections and garden relationships. Do not clone the Pair 1 veranda into Pair 2 or lift the low marked wing to the height of a neighbouring classroom.

Neighbouring entrance and courtyard views in R2

Pairs 7-8 share the CEDSA entrance screen and gate. Pairs 9-11 and 13 show CEGENSA signs, low gable/wing features, paving and gardens that must be reconciled using roof corners. Keep the two names distinct. Pair 12 points outward toward the longer roofed block and wider Child Study Centre vicinity; visible evidence does not assign every neighbouring roof to Child Lab.

Implementation sequence

First capture baseline and object IDs. Second align roads, parcel limits, courts and footprints. Third correct storey categories, ridges, gables, canopy openness and ground levels. Fourth match visible facade divisions and material families. Fifth add boundaries, mature vegetation and supported signs/utilities. Finish with limited weathering, optional props and collision tests. Approve the blockout in all cameras before adding decorative detail.

Evidence and naming discipline

The user labels the regional scope as the station, Child Lab, E A Boateng Road and environs. Preserve readable CEDSA and CEGENSA signs. A business pin can overlap a different building and must not override facade evidence. This is a new brief; the sample supplies format only, not stadium, highway or La Bawaleshie correction requirements. If GCB becomes relevant later, distinguish the campus classroom building from GCB Bank near Ernest Chemist / Legon Police Station.

Courtyard complex and low wing beside E A Boateng Road

In-game view



Real street view



Pair 1

Mistakes visible in the game

The marked game target is a tall, regular multi-storey block behind the veranda building. The real marked target is a low white wing with a long red roof, small dark openings and mature trees close to its facade. The height, window density and roof hierarchy are wrong. Sparse game planting also exposes buildings that the real canopy partly conceals.

Real target

The real foreground pavilion has a broad tiled roof, projecting gabled veranda, pale columns, dark glazed openings and a stone-faced raised base. A lower adjoining or neighbouring roof sequence continues behind and to the right. The blue outline identifies that low sequence, not every building in the photograph. Hedges, flower beds and trunks layer the frontage.

Geometry and placement instructions

Use R1 to trace the outlined courtyard complex, its perimeter wings and internal cross paths. Keep the courtyard open; do not fill it with a taller block. Remove the unsupported extra storeys in the marked sightline, fit the long wing roof and opening rhythm, and retain the veranda as a distinct projection. Verify roof joints against R1 rather than merging all visible roofs into one pavilion. Fit window and column widths after matching the camera.

Terrain surroundings and connections


Keep the veranda floor and stone plinth above the immediate garden ground, with only supported access level changes. Rebuild the road curb, narrow verge, layered hedges and mature irregular canopy. Connect the courtyard edge and opposite roadside building to Pair 2 through R1; do not duplicate either complex.

Acceptance checks

From the Pair 1 camera, the outlined background reads as a low wing beneath the trees, while the foreground veranda retains its columns and raised base. No invented upper-storey window grid rises above that wing. Confirm the same footprint in the overhead render.

Low roadside building opposite the courtyard complex

In-game view



Real street view



Pair 2

Mistakes visible in the game

The game gives the outlined building a high hip roof and a long run of large uniform windows. The real end elevation is predominantly a pale blank wall under a shallower roof profile, with a door and much smaller side openings. The game lawn and generic tree placement simplify the close planted setting.

Real target

The real building is a low elongated volume. Its visible end has a dark fascia, a shallow pitched roof silhouette, a door near the right edge and a small horizontal wall fitting. On the left-facing side, projecting wall divisions and small openings replace the game window grid. A solar-style light stands in the near garden; the tiled veranda pavilion appears to the right.

Geometry and placement instructions

Use the green-outlined long footprint in R1 for orientation and extent. Keep it separate from the larger roof below it in the displayed map and the adjacent drama-studio roof sequence. Lower and reshape the roof to the photograph; do not copy the hip roof of Pair 1 onto this asset. Place the end door, visible wall divisions and small openings, leaving obscured side details simple. Treat map business pins as location aids, not proof of ownership.

Terrain surroundings and connections

Preserve the slightly raised building base and the garden-to-road transition. Add continuous hedge bands, low shrubs and an irregular mature tree close to the veranda side. Maintain the small gap and paved or garden access between buildings rather than spreading them across an empty lawn.

Acceptance checks

Pair 2 shows a mostly blank pale end wall and low roof, with the Pair 1 veranda visible at the correct side. R1 must show two distinct complexes across E A Boateng Road and no new building occupying the marked courtyard.

Fire station gables and open vehicle canopy

In-game view



Real street view



Pair 3

Mistakes visible in the game

The game replaces the station with three-storey and two-storey classroom-style masses and repeated large windows. The real view shows low gabled service buildings and a thin open-sided canopy. Missing boundary walls, the water tank and yard geometry change both silhouette and function.

Real target

A pale gable on the left carries fire-service lettering behind a ribbed black elevated water tank. A second low pale gable stands to the right. Between them, a broad dark metal canopy on slender posts covers a red fire engine and part of the vehicle yard. A weathered pale wall with metal railing encloses planted ground at the front.

Geometry and placement instructions

Use R3 to locate the station parcel and the Pair 3 direction. Replace only the station assets with individually traced low roof volumes. Model the canopy as a thin sloped or shallow pitched sheet with visible supporting beams and open sides, not a solid building or another storey. Put the tank on its visible support and preserve its separation from the gable. Reproduce only legible fire-service wording; do not fabricate obscured numbers.

Terrain surroundings and connections

Build a hardstanding vehicle yard, planted boundary strip, wall base, entrance curb transitions and practical vehicle clearance. Subtle weathering belongs on the wall and roof edges. Keep the yard approximately continuous at access level unless additional ground evidence establishes a larger step.

Acceptance checks


Pairs 3, 4 and 5 must show the same two gabled buildings, tank, wall and canopy from their different angles. No two- or three-storey classroom facade remains at the station target. The canopy is visibly open and a vehicle-sized access reaches it.

Fire station entrance from the approach road

In-game view



Real street view



Pair 4

Mistakes visible in the game

The game entrance leads across open grass to tall regular blocks and lacks the real enclosure. The exaggerated building heights, broad blank setback and simplified parking erase the reference entrance, wall corners and foreground paving.

Real target

The real entrance opens between pale boundary piers and low walls topped with dark metal bars. The gable on the left and canopy farther back define a compact working yard. A banner is attached near the right side; a utility pole and overhead lines cross the view. The foreground combines asphalt or worn hard ground with a block-paved pedestrian edge.

Geometry and placement instructions

Use R3 and the Pair 4 arrow to place the real road mouth, entrance piers and boundary returns. Reuse the station and canopy from Pair 3, retaining the same roof corners and relative depths. Replace the large invented entrance arrangement with the visible piers, bars and opening. Add the banner as a panel with readable major words only where supported. Do not use a floating game destination label as a physical gate sign.

Terrain surroundings and connections


Fit the driveway to the existing road and yard without floating curbs or a lawn strip through the entrance. Match the right-hand paved edge, worn ground, nearby planting and pole offset. Cars and people are removable scale props; establish the gate and circulation with them hidden.

Acceptance checks


A bicycle-height entrance render shows the low left gable, open canopy behind it and the correct pier-and-wall opening. Turning into the supported access reaches the same yard as Pair 3. No added step blocks the driveway and no roof intersects the gate.

Fire station frontage across the low foreground barrier

In-game view



Real street view



Pair 5

Mistakes visible in the game

The game again presents a tall classroom group and open lawn. It omits the actual station enclosure and the low foreground metal barrier, while using parked cars as a substitute for the service-yard layout.

Real target

This real photograph repeats the station gable, tank, pale boundary wall, fire engine and open canopy seen in Pair 3. Its distinct framing adds a low reddish metal railing across the near foreground, planted flowers at its base and a hard street or forecourt surface. Mature trees sit behind the low roofs.

Geometry and placement instructions

Treat Pair 5 as another observation of the existing station, not a second fire-station asset. Use R3 for its direction and relative viewpoint. Keep the gable lettering, tank position and canopy supports consistent with Pairs 3 and 4. Add the foreground railing as thin uprights and horizontal rails only where the street/map alignment supports it. Its span must not become a fence across the station driveway.

Terrain surroundings and connections

Replace the open green game forecourt with the evidenced asphalt or paved surface and planting strip. Retain gentle local curb transitions; the photograph does not establish a deep ditch or large terrace. Use weathered pale walls and dark canopy sheets, avoiding the game-wide bright terracotta hip-roof material.

Acceptance checks

The saved camera shows the same station roof ensemble and tank as Pair 3, with the low railing correctly nearer the viewer. With vehicles hidden, the enclosure and canopy still explain the scene. A route between Pairs 4 and 5 must not cross duplicate walls or contradictory entrances.

Low service office and planted access beside the station

In-game view



Real street view



Pair 6

Mistakes visible in the game

The game substitutes a two-storey hip-roof block and rows of large windows for a small low service office. Its car grid, continuous lawn and missing pedestrian surfaces hide the real doorway, barred windows, hedged access and street hardware.

Real target

The real near office has an off-white facade, muted reddish-brown lower band and low dark roof edge. A tall pale door and barred windows face the paved edge; exterior air-conditioning units sit below openings. Several short posts carry alternating pale, red and dark paint. A hedge-lined access leads toward a longer low roof behind a large tree, and overhead wires reach a near pole.

Geometry and placement instructions

Locate this frontage with R3 and the Pair 6 direction. Model the near office as a low separate mass, not a scaled-down multi-storey classroom. Place only the visible door, window bars, AC boxes and roof edge. Trace the longer rear roof independently from the aerial; do not extend the near office into an invented continuous upper floor. The pale vertical sign frame can remain blank if its wording is not readable.

Terrain surroundings and connections

Lay block paving along the office frontage and rougher compacted or asphalt access beside it. Put bollards outside the clear route and make the hedge turn reveal the actual access gap. Keep the office base attached to its ground; avoid a sudden grass shelf or deep drain unsupported by the image.

Acceptance checks


The view reads as a low office with barred windows and AC units beside a hedge-lined access. The station compound remains consistent with Pairs 3-5 and the long road view in Pair 14. Posts, pole and curb allow the supported bicycle route to pass.

CEDSA perforated boundary and entrance court

In-game view



Real street view



Pair 7

Mistakes visible in the game

The game shows the rear or plain facade of a white building on grass where the real view presents a perforated boundary screen and central entrance. Tiny game windows cannot substitute for the screen openings, and the foreground surface and compound enclosure are missing.

Real target

The real frontage is a low pale screen with repeated narrow vertical openings and a reddish base strip. A dark gate or door interrupts it centrally under a small tiled entrance roof. A large information panel sits to the right. Mature broad trees and a palm rise behind the enclosure; dark hardstanding fills the near forecourt.

Geometry and placement instructions

Use R2 and the separate arrows for Pairs 7 and 8 to align the frontage and entrance. Build the screen as a boundary element with actual visible apertures or recessed dark slots at close range, then place roofed buildings behind it using the aerial roof outlines. Do not turn the screen into the exterior wall of one large hip-roof box. Retain the central opening and information panel positions.

Terrain surroundings and connections

Replace foreground lawn with the dark worn asphalt or hardstanding in the reference, including scattered leaves and shallow edge variation. Keep the screen base near court level. Preserve the planted canopy behind the wall and the road relationship in R2; do not add a raised terrace from foliage shadows.

Acceptance checks

Pair 7 shows the perforated pale screen, central dark entrance and panel, with roofs and trees behind. Moving to Pair 8 reveals the same opening at closer scale. Use the readable CEDSA identity from Pair 8; map pins must not rename the facility.

CEDSA entrance sign and gate at close range

In-game view



Real street view



Pair 8

Mistakes visible in the game

The game camera meets a plain house wall and an oversized lawn gap. The real target is a pedestrian entrance in the perforated frontage, with a tiled cap, dark gridded gate, sign fascia and adjoining notice panel.

Real target

Pale entrance piers frame a tall black gate with a tight rectangular grid. A small weathered red tile roof covers the opening, and the fascia reads CENTRE FOR DISABILITY STUDIES AND ADVOCACY with CEDSA. The reddish base continues across the nearby screen. A notice panel lies immediately to the right; leaves and wear texture the dark ground.

Geometry and placement instructions

Refine the entrance already built for Pair 7. Model pier thickness, gate recess, grid rhythm, low tiled cap and fascia as separate components. Match the sign wording to the source and fit it inside the fascia; do not place a floating destination label over the roof. Keep the screen apertures and adjacent panel aligned through both cameras. Do not fabricate a ramp, stairs or interior from the name of the facility.

Terrain surroundings and connections

Bring the hard forecourt to the gate threshold with a modest supported transition. Keep movement collision away from decorative gate bars and small leaves; a closed gate may remain closed if the game does not allow entry. Planting behind the cap must retain the real canopy density without blocking the readable sign.

Acceptance checks

At Pair 8 the tiled cap, sign, black grid and pale piers are unmistakable. Pair 7 must still show the same entrance, not a different doorway. The user-assigned R2 arrows remain separate camera directions, and the compound does not receive duplicate gate models.

CEGENSA gable end and planted stone edge

In-game view



Real street view



Pair 9

Mistakes visible in the game

The game offers a hip-roof corner with a blank pale wall and red base. The real elevation has a strong triangular gable, dark fascia, a large readable sign, black louvred openings and a small tiled awning. The game also removes the planted bed and stone-paved ground.

Real target

A low white gabled end carries the CEGENSA sign for the Centre for Gender Studies and Advocacy. A small dark vent sits high in the gable and a tall dark louvred opening lies below the sign, sheltered by a short reddish tile awning. A red lower band, flowering shrubs, low plants and a pale curb edge separate the building from irregular stone paving.

Geometry and placement instructions

Use R2 and the Pair 9 arrow, then reconcile the gable with the roof corners visible in Pairs 10, 11 and 13. Rebuild the end as a low pitched-roof gable rather than forcing a hip roof. Add the high vent, sign panel, louvres, awning thickness and visible roof overhang. Retain the lower band; do not invent upper windows. Keep CEDSA and CEGENSA identities distinct even where nearby geometry overlaps.

Terrain surroundings and connections

Use an irregular planted bed with a low pale curb, exposed soil and the visible stone-paved edge. Fit the building base to this garden ground without an unsupported large retaining wall. Preserve the overhead vegetation while keeping the sign readable from the intended camera.

Acceptance checks

The end silhouette is triangular, with its sign, high vent and tall dark louvres in the correct order. The awning is below the sign. Cross-check that this exact gable and roof reappear in Pair 10 and are not cloned into unrelated corners.

CEGENSA courtyard and connected low roof wings

In-game view



Real street view



Pair 10

Mistakes visible in the game

The game separates low roof boxes across grass and misses the real court and connected frontage sequence. Its uniformly clean lawn and sparse trees replace a broad hard courtyard, close shrubs and distinct low building edges.

Real target

The real view looks across extensive irregular tan stone paving toward the CEGENSA gable and adjoining low pale wings with reddish lower bands. Tall narrow shrubs stand near the facade; a vehicle sits beside one wing. The photograph is noticeably rolled, so the diagonal paving and rooflines are not evidence of a steep site-wide slope.

Geometry and placement instructions

Use the Pair 10 arrow in R2 and share the Pair 9 gable. Trace each roof segment and courtyard gap from R2, checking street elevations before joining volumes. Preserve changes in roof direction and low connector geometry where supported; do not merge all roofs into one long hip-roof bar. Replace grass inside the evidenced court with its hard surface, while retaining gardens at the edges.

Terrain surroundings and connections

Calibrate camera roll before terrain. Set gentle local courtyard fall only where paving-to-base relationships support it; do not reproduce the image tilt as a sloped building foundation. Fit planted beds and small curb steps to the courtyard rather than adding broad stairs, high terraces or a ramp without evidence.

Acceptance checks

After camera roll is matched or corrected, the gable, side wings and stone court have coherent proportions. The same courtyard continues into Pair 11, and its building corners agree with Pairs 9 and 13. No bike wheel floats above the paving or drops through a material boundary.

CEGENSA courtyard side and narrow planting borders

In-game view



Real street view



Pair 11

Mistakes visible in the game

The game depicts an isolated long hip-roof building over grass. The real view is a hard courtyard bounded by low buildings, with a planted border close to the camera and mature narrow shrubs at the opposite frontage.

Real target

Stone paving occupies most of the real foreground and middle ground. A flower bed with low mixed plants lies at the near edge; the gabled sign elevation is farther left behind tall conical shrubs. A pale low wing runs across the back, and the near right building edge partly frames the courtyard. A parked vehicle provides scale but does not define a road.

Geometry and placement instructions

Use the Pair 11 arrow in R2 and the shared roof/court geometry from Pairs 9 and 10. Place the near right edge, far wing and gabled element at the depths supported by the aerial, retaining actual gaps. Keep low building masses and roof ridges separate where the map supports them. Do not build a new duplicate courtyard to reproduce this framing.

Terrain surroundings and connections

Replace lawn with continuous irregular stone paving inside the court. Add the near soil bed and low border; keep curb steps modest and linked to the garden. Use mature narrow crowns near the far gable rather than uniformly spaced spherical trees. Parked vehicles remain optional; courtyard access must work without using them as collision barriers.

Acceptance checks

The Pair 11 camera shows the planted near border, coherent hard courtyard, far low wing and partially screened gable. Pair 10 connects to this court without changing paving level abruptly. The same plan must remain recognizable from the corrected overhead view.

Grassy foreground and longer block toward the Child Lab area

In-game view



Real street view



Pair 12

Mistakes visible in the game

The game foreground is manicured grass crossed by hard paths, with simplified low buildings and a distant bus. The real view contains tall uneven grass, a narrow worn soil track and a longer paved or parking area beyond it. The near left gabled wall includes visible AC units and a dark opening that the game omits.

Real target

A pale gable end fills the left edge, with several exterior AC units and a darker lower opening. Tall grass occupies a shallow foreground verge or depression, crossed by a compacted-earth footpath. Beyond it are low roofed structures, landscaped edges and a parked bus. The reference establishes the local ground relationship but does not provide surveyed elevations.

Geometry and placement instructions

Use the red Pair 12 arrow in R2 to anchor this outward view toward the long roofed block. Retain only roof heights and facade portions visible in the street photograph; aerial roof length alone cannot establish hidden storeys. Do not name the long block as Child Lab solely from the nearby map pin. Place the left gable, background paved area and low roofs in the correct sequence, connecting the foreground complex to the other R2 cameras.

Terrain surroundings and connections

Build an irregular grassy verge, worn earth path and the transition up to the paved parking or circulation surface. Keep the height difference adjustable; avoid a deep invented trench. Add AC boxes, sparse local planting and optional bus parking on actual hardstanding, not in grass.

Acceptance checks

The foreground reads as taller unmanaged grass with a narrow dirt track, and the near gable has the visible AC units. The background bus area sits beyond the verge on coherent ground. R2 footprint alignment and collision checks must confirm the road and path reach the intended parcel.

CEGENSA direction sign and path beside the low wing

In-game view



Real street view



Pair 13

Mistakes visible in the game

The game presents a plain low white wing surrounded by open grass, with few planted edges and no correct directional sign. The reference is a close, shaded entrance landscape beside the same low building family.

Real target

A freestanding pale CEGENSA direction sign on slender posts dominates the near left foreground. Its red arrow points right. Behind it, the low white wing has a red base, dark louvred windows, reddish roof and exterior AC units. Mature trunks and smaller palms sit in patchy grass; a pale curb separates the garden from irregular stone paving on the right.

Geometry and placement instructions

Use R2 and the Pair 13 arrow. Reuse the verified CEGENSA wing and corner geometry from Pairs 9-11 rather than placing another copy. Build the real sign as a physical panel on posts, preserving the visible CEGENSA wording and arrow orientation; omit unreadable contact details instead of inventing them. This physical sign is different from a map arrow or game HUD marker.

Terrain surroundings and connections

Reconstruct the curb-lined stone path, patchy garden, mature tree trunks and modest soil/grass height change. Preserve the route continuing along the building and the gap beyond it. Trees should shade and partly obscure the facade while leaving the sign legible. Keep the AC units attached to the visible wall.

Acceptance checks


The Pair 13 camera shows the sign to the left, arrow pointing right, building behind it and paved route to the right. The route connects to the courtyard and R2 road layout without overlapping walls. Verify the sign is placed once and its arrow is not converted into a ground object.

Road corridor past the station toward the neighbouring buildings

In-game view



Real street view



Pair 14

Mistakes visible in the game

The game adds a broad foreground road spur or paved apron, a two-storey hip-roof frontage, long repeated blocks and regular palms. The real road view is a narrower continuous corridor with low enclosed frontages, worn edges, a near drain opening and irregular mature vegetation. The game road and building rhythm require map alignment before decoration.

Real target

The real asphalt road runs into the distance beside a block-paved or compacted pedestrian margin on the right. A shallow open drainage gap is visible at the near road edge. Low pale boundary walls and roofs follow the right frontage; trees and parked vehicles occupy the opposite side. A slender communications mast and varied streetlights mark the corridor farther ahead.

Geometry and placement instructions

Use R3 and its Pair 14 arrow to set the road axis and near viewing zone. Check the foreground game spur against the aerial; remove or narrow it if no real access supports that shape. Reuse the low station and office ensemble from Pairs 3-6. Place the actual boundary line, low roof sequence, lights and evidenced mast without turning the map label for School of Performing Arts into a large entrance arch.

Terrain surroundings and connections

Fit the worn asphalt, narrow pedestrian margin, local curb and supported drain opening together. Keep drain depth adjustable and prevent a visual hole from becoming an unintended road-wide collision trench. Use mixed mature canopy instead of a palm avenue; maintain continuous rideable road grade through the corridor.

Acceptance checks

The saved view reads as the same road and low frontage in R3, with believable street edges and a visible but contained near drainage opening. Ride toward the station and back without a sudden width or height change. Pairs 3-6 and the corrected game aerials must show the same assets.

Additional reference R1 Real aerial courtyard complex and Pairs 1 and 2



R1 Real aerial courtyard complex and Pairs 1 and 2

What the image establishes

The blue outline encloses a perimeter-roof courtyard with an internal cross of paths and four green quadrants. The green outline identifies a separate long roof on the other side of E A Boateng Road. The numbered arrows assign the Pair 1 and Pair 2 viewing directions. Those two targets must remain distinct; the screenshot does not authorize placing a tall block inside the courtyard.


Instructions for placement

Trace visible roof extents, courtyard openings, cross paths, road separation and tree masses before elevation work. The larger unoutlined roof below the green target and the adjacent drama-studio roofs are neighbouring masses, not automatically extensions of the Pair 2 building. Use the street views for local facade detail and height, and the aerial for overall plan relationships.

Acceptance and limits

An aligned overhead render must retain the open court, two distinct road-side targets and their assigned view directions. Preserve the original annotations in the reference. Arrow lengths are not distances, roof shadows are not surveyed heights, and map pins do not prove a building identity.

Additional reference R2 Real aerial compound near Child Study Centre and Pairs 7 to 13



R2 Real aerial compound near Child Study Centre and Pairs 7 to 13

What the image establishes

The map shows E A Boateng Road curving across the lower part, a compact irregular roof-and-court cluster inside the bend, a long roof toward the upper part, the neighbouring LT3 footprint, an open reddish parcel and substantial vegetation. Separate arrows are assigned to Pairs 7, 8, 9, 10, 11, 12 and 13. The Child Study Centre label is a regional anchor, not proof that every arrow addresses that building.


Instructions for placement

Use the arrow tails as approximate viewing zones and follow their heads to the relevant facade or courtyard. Reconcile CEDSA gate views with the CEGENSA gable and courtyard views through roof corners and street evidence; do not merge their institutional identities. Keep the Pair 12 outward sightline toward the long block distinct from the close courtyard cameras. Retain the open parcel and local tree masses rather than filling all gaps with classroom templates.

Acceptance and limits

One overhead scene must reproduce the bend, compact cluster, court gaps and long-block relationship. The FREDDIES IT SOLUTION pin must not rename the clearly signed CEDSA or CEGENSA elements. Pale aerial patches alone cannot establish an unfinished building, and hidden roof joins or heights remain adjustable.

Additional reference R3 Real aerial station parcel and Pairs 3 to 6 and 14



R3 Real aerial station parcel and Pairs 3 to 6 and 14

What the image establishes

The station vicinity has a road along the left edge of the displayed map, elongated neighbouring roofs, smaller service roofs, paved or compacted yards, parking and a dense tree mass to the right. The numbered arrows assign Pairs 3, 4, 5, 6 and 14; some arrow lines cross. Crossing lines are annotations, not site boundaries or connected roads.


Instructions for placement

Align the road and station access first. Trace the selected low gabled buildings, canopy and office against Pairs 3-6, while retaining neighbouring long roofs as separate objects. Use Pair 14 to check the forward corridor, wall sequence and road margin. Keep yard access, roof setbacks and the wooded patch coherent from every camera. Where overlapping arrow heads make a precise station sub-object ambiguous, resolve it from the gable, tank and canopy in the street photo before assigning an object ID.

Acceptance and limits

The corrected overhead must show one compact station service group and its working yard, with the surrounding elongated roof blocks and planted area in their supported locations. Do not turn all long roofs into station buildings or claim a surveyed compass orientation from the screenshot. Keep every original arrow and number intact.

Additional reference G1 Game aerial overview supplied image 1



G1 Game aerial overview supplied image 1

Visible mistakes

The outlined region is dominated by repeated white multi-storey blocks, long hip-roof bars, oversized lawn voids and simplified tree clumps. The station destination is represented by classroom architecture rather than the low gabled service buildings and open canopy in Pairs 3-5. Surface and enclosure differences disappear into green ground.


Instructions for correction

Register this camera to R3 using the through-road and station access, then to the wider reference layout only where overlap is evidenced. Replace the selected station template, recover yard and boundary geometry, and check each neighbouring long roof independently. Retain courtyard buildings only after their outlines and open spaces agree with the real maps. Match building massing before recolouring.

Acceptance

Re-render this aerial without arrival panel, destination label, yellow beam or browser UI obscuring the result. The source blue outline is a review area, not a surveyed perimeter. The corrected station is a low service ensemble with a yard; no camera-specific copy is added to satisfy the aerial.

Additional reference G2 Game aerial overview supplied image 2



G2 Game aerial overview supplied image 2

Visible mistakes

This angle exposes long, repetitive two-storey roof bars beside open lawn and an isolated small block across the road. The station marker lands among taller generic buildings. Real roof segmentation, paved yards, boundaries and vegetation enclosure are insufficiently represented.


Instructions for correction

Use this angle to test the length, orientation and separation of every replaced roof against R3. The road bend and access must join the same surfaces used by Pair 14. Rebuild low station gables, the canopy and the service office; do not merely reduce all scene buildings to one storey. Neighbouring blocks require their own roof outline and visible elevation evidence.

Acceptance

The corrected view shares the same object IDs and topology as G1. Hardstanding sits inside the appropriate enclosure, wooded ground remains wooded, and unsupported large grass gaps or oversized classroom walls no longer define the station. Keep screen overlays out of comparison renders.

Additional reference G3 Game aerial overview supplied image 3



G3 Game aerial overview supplied image 3

Visible mistakes

The oblique again shows repetitive long classroom bars, a large roof-and-court structure at the left and a broad paved car area near the road. A dense artificial tree patch and generic bright lawn stand in for distinct planted and service spaces. The annotation does not reveal which unlabelled game building corresponds to each real roof.


Instructions for correction

Compare repeated roof corners with G1 and G2 to identify the same assets. Test courtyard perimeter, inner openings and nearby trees against the appropriate real map after road alignment; do not assume the large game courtyard is R1 solely because both contain courts. Correct parking and ground surfaces from real evidence, keeping cars as removable props. Resolve identity before making global replacements.

Acceptance

Every repaired footprint is supported by an aligned aerial target, and each confirmed street facade belongs to that footprint. The shared station remains low and recognizable. A second aerial camera cannot introduce a new yard, different canopy or extra boundary to hide a placement error.

Additional reference G4 Game aerial overview supplied image 4



G4 Game aerial overview supplied image 4

Visible mistakes

From this angle the selected area still reads as a generic institutional campus: elongated roof bars, almost identical white facades, broad lawn sheets and regularly placed palms. The road-mouth and parking apron dominate the foreground, while the real service architecture and irregular enclosure are missing.


Instructions for correction

Check road-mouth shape against R3 and Pair 14 before moving the adjacent buildings. Reconstruct separate low station volumes and practical service access. Adjust each roof length and orientation from the real outline rather than reusing one long bar. Replace the palm repetition with the mixed mature canopy supported by the street views, preserving verified neighbouring assets outside the selected work.

Acceptance

Road, yard and roofs remain consistent with G1-G3, and every painted base, facade opening and roof ridge has a local evidence basis. Large voids that are paved courts, wooded parcels or enclosed yards in real references must no longer default to lawn.

Additional reference G5 Game aerial reverse overview supplied image 5



G5 Game aerial reverse overview supplied image 5

Visible mistakes

The reverse angle exposes the same excessive roof-bar lengths, unsupported upper floors and simplified grass/woodland boundary. A distant large road corridor is visible, but this crop and the supplied local real maps do not establish all of its geometry or a continuous surveyed connection to every parcel.


Instructions for correction

Use this view to inspect backs, shared corners and terrain joins of the same replacements. Check that courtyard openings remain open, the station canopy is not a solid roof box and tree density agrees across opposing angles. Preserve distant roads and buildings unless their membership in this correction zone is verified; do not import the earlier Legon Road and La Bawaleshie project from the sample PDF.

Acceptance

The reverse aerial agrees with the forward views without intersecting roofs, floating blocks or duplicate walls. Flag unmatched distant objects for location clarification. Repair only the evidenced scope; the yellow arrival beam and large title remain interface effects, never physical structures.

Additional reference G6 Game map and route overlay supplied image 6



G6 Game map and route overlay supplied image 6

What the image establishes

This is a game map crop with a player marker, road or route overlays, dotted paths and simplified footprints. It helps find the current game zone near La Road and the performing-arts/music labels. Black masked regions, coloured routes, question markers and YOU are interface content. The map is not an independent aerial photograph of correct architecture.

Instructions for correction

Use confirmed road bends, junctions and building footprints to relate the game coordinate system to R1-R3. Register each real crop locally and then connect shared road anchors; do not force one scale or rotation on differently cropped images without checking. A coloured line does not by itself define asphalt width, a building label does not define a footprint, and dotted paths must be classified before becoming roads.

Acceptance

Produce a clean overhead scene check with the corrected footprints and actual circulation, separately from the normal route UI. The player and route still track the rideable network after edits. No masked edge, label, blue route or red route is extruded into campus geometry.

Consolidated Claude prompt scope and scene audit

Implement a targeted reconstruction pass in my existing 3D University of Ghana bicycle exploration game. Work on the selected Legon fire-station vicinity, the Child Lab or Child Study Centre surroundings, E A Boateng Road and the connected areas evidenced in this brief. Use all 14 game/real street pairs, R1-R3 real annotated aerial maps and G1-G6 game aerial/map references. Follow the five correction sections under every pair. The earlier Legon Road and La Bawaleshie PDF is a format sample only; do not import its stadium, highway, commercial-frontage or 19-pair task into this pass.

Inspect the existing code, engine, scene graph, procedural building generator, imported footprints, road and terrain generation, vegetation, labels, navigation and bicycle physics before changing anything. Identify the current zone objects by stable IDs and save a baseline plus a reversible old-to-new asset mapping. Work in the existing scene rather than rebuilding the whole game. Preserve completed architecture and functioning routes elsewhere. Do not assume a particular engine or coordinate system until inspection establishes it.

Register R1 to Pairs 1-2, R2 to Pairs 7-13, and R3 to Pairs 3-6 and 14. Keep each numbered arrow exactly as supplied. Use arrow tails as approximate view zones and heads as directions, then refine with visible facade and road anchors. Some R3 arrows cross; do not turn crossings into roads or compound boundaries. Register each crop separately against shared road bends, entrances and roof corners before linking them. G6 is a game map/location aid and G1-G5 are flawed scene views, not evidence that current architecture is correct.

Real aerials constrain footprints, roof directions, courtyard gaps, tree masses and circulation. Real street photographs constrain visible heights, facade openings, roof profiles, materials, enclosure and local ground. Do not infer exact dimensions, hidden structures or surveyed heights. Keep footprint scale, setbacks, roof heights, canopy depth, local ground levels and camera parameters adjustable. If a specific arrow target remains uncertain after comparing the images, ask directly, for example Where was Pair 3 taken, and defer that target while continuing independently evidenced work.

Ignore screenshot outlines, arrow numbers, map pins, browser controls, Windows taskbar, HUD, rider, destination labels, arrival panels and yellow beam as physical objects. Keep their normal game behaviour where needed, but hide them for clean comparison captures. Physical signboards visible in street photographs, including the CEGENSA direction sign, are separate architectural evidence.

Consolidated Claude prompt footprints and architecture

Correct layout, building massing and terrain before decorative detail. Begin with a locally registered blockout: through-road and access geometry, the station parcel and working yard, neighbouring elongated roofs, R1 courtyard and opposite low building, and the R2 road bend, compact compound, court gaps and longer block. Trace each supported roof independently. Do not stretch one generic classroom template across the parcel, infer storeys from roof length or fill every gap with lawn or buildings. Check all 14 cameras and five aerial angles at blockout stage.

For Pairs 1-2, retain the distinct R1 targets. Restore the low marked wing beside the veranda complex, the open internal courtyard and cross paths. Preserve the foreground veranda projection, columns, dark openings and stone-faced raised base. For the opposite long building, match its shallow roof silhouette, largely blank pale end wall, end door and smaller side openings. Do not copy the same tall hip roof or window grid onto both targets. Roof colour is local evidence, not permission to impose one uniform terracotta material on the zone.

For Pairs 3-5, replace the station classroom masses with the observed low pale gabled buildings, black ribbed water tank on its support, dark open-sided vehicle canopy, weathered boundary walls and railings, entrance piers and hardstanding. Build the canopy with a thin sheet roof, beams and slender supports; it is not a solid building or an upper storey. Maintain one consistent gable/tank/canopy ensemble across the views. Use only legible fire-service sign wording. Vehicle props can be simplified and disabled during architecture checks.

For Pair 6, model the low off-white office with muted reddish-brown base, dark low roof edge, door, barred openings and exterior AC units. Retain the hedge-lined access, paving, short painted posts, nearby pole and supported wire spans. Separate the longer rear roof from the near office unless the aerial proves a connection. For Pair 14, fit the continuous road, low frontage enclosure, practical station access and distant mast/light silhouettes. Verify the game foreground road spur against R3 before retaining it.

For Pairs 7-8, build the perforated pale boundary screen, reddish base, central gridded gate, roofed entrance and CEDSA fascia plus adjacent information panel. Place roofed volumes behind the screen from R2 rather than modelling it as a plain house wall. For Pairs 9-11 and 13, restore the CEGENSA gabled end, high dark vent, sign panel, tall dark louvres, small tiled awning, low adjoining wings, court, gardens and freestanding direction sign. Keep CEDSA and CEGENSA names distinct. Share only roof/corner geometry confirmed across images; do not merge facilities merely because arrows cluster.

Consolidated Claude prompt terrain and surroundings

For Pair 12, reproduce the near gable details, exterior AC boxes, taller grassy foreground, narrow earth track and harder parking/circulation ground beyond. Use the red R2 arrow toward the long roofed block to establish placement. Do not assign the long block to Child Lab solely because a nearby pin uses that name, and do not invent hidden upper floors. Preserve the supported relationship to the surrounding low roofs and bus area, treating the bus as optional rather than a footprint anchor.

Create separate connected ground surfaces for road asphalt, station yard, block-paved margin, irregular tan stone courtyard, garden soil, dirt path, short lawn, taller grass and wooded ground. Remove broad green sheets where real references show paving or enclosed hardstanding. Fit building plinths, garden curbs and thresholds to local terrain. Pair 1 veranda floor sits above its planted base; Pair 12 has a modest grassy ground transition; Pair 14 includes a local drain opening. Do not invent a deep trench, steep embankment, retaining wall, stairs or terrace without image evidence.

Correct camera roll in Pair 10 before deriving site slope. Its tilted photograph must not become tilted building foundations or a steep courtyard. Leave uncertain grade and drain depth editable. Match visible paving-to-wall and curb-to-road relationships, with gentle falls only where supported. Ensure wheels follow the road and the rideable surface remains continuous through access mouths and material changes. Avoid cracks, floating curbs, buried entrances, water-tank supports that float and roofs intersecting neighbours.

Use varied mature canopy, close hedges, flowering beds, conical shrubs, small palms and patchy grass where actually visible. Replace repetitive palm avenues and uniform blob-tree spacing in the selected zone. Preserve dense vegetation seen in real aerials instead of turning it into empty lawn. Introduce restrained wall weathering, dark fascia, roof texture and surface wear only after geometry is correct. Follow local pale wall and red/brown base families, not a single paint scheme for every building.

Add only evidenced poles, light heads, thin railings, AC units, signposts and wire spans. Overhead wires can be visual with no continuous bicycle collision. Use simple collision for boundaries and substantial posts, keeping clear access and pedestrian routes. Do not build unseen interiors, roof frames or complete buildings from uncertain aerial patches. No selected photo establishes a specific unfinished building requiring a construction-state model; keep uncertain areas modest and clearly record what is unresolved.

Maintain the game route UI and player marker after geometry edits, but do not extrude G6 coloured route lines, dotted paths, map labels or black masks into objects. Classify each actual path or access using map and street evidence before assigning its surface and rideability. Preserve existing working roads beyond the validated scope, including distant geometry visible only in G5.

Consolidated Claude prompt comparison and acceptance

Save 14 comparison cameras tied to the user pair numbers. Begin from the real-map direction zones and tune heading, eye height, field of view, roll and framing before judging facade proportions. Store one scene and change cameras; never create camera-specific duplicate buildings or move a building differently for different views. Preserve source annotations in the document and record approximate camera settings separately.

Produce clean before-and-after street renders for every pair and corrected aerial renders corresponding to G1-G5. Add local overhead renders aligned to R1, R2 and R3, and a G6-style map check of the actual corrected footprint and route network. Disable arrival panels, floating labels, beam, rider and optional traffic for architecture comparisons. Keep normal gameplay UI available during actual play. Use matching framing and neutral visibility rather than dramatic lighting that hides errors.

Acceptance for R1: the blue target is a low courtyard/wing complex with an open cross-path court and retained veranda; the green target is a separate low long building with the correct end-wall and shallow-roof character. Acceptance for the station: Pairs 3-5 share low gables, one tank, open canopy, enclosure and yard; Pair 6 shows its distinct low service frontage; Pair 14 follows the same coherent road and boundary sequence. Generic tall classrooms must not remain at those specific street targets.

Acceptance for R2: Pairs 7-8 share the perforated CEDSA boundary and roofed gridded entrance. Pairs 9-11 and 13 agree on confirmed CEGENSA gable/wing features, stone court, planting and physical direction sign. Pair 12 has tall grass, an earth track and background harder circulation ground with adjustable local grade. The same corrected footprint must account for all assigned directions. Institutions are not renamed from unrelated map pins.

Ride the confirmed through-road, junction/access turns and allowed courtyard or path routes in both directions. Test braking, reverse, steering, wheel support, camera movement and existing collision responses at curbs, gates, poles and ground joins. Remove obsolete collision boxes with replaced buildings. Restrict entry where a real boundary remains closed rather than making a wall passable to hide bad placement. Check for duplicated objects, z-fighting, overlapping roofs, floating props and stale destination positions.

Return implemented code/scene changes, old-to-new object IDs, the comparison screenshots, three real-map overhead checks and five game-aerial checks. List remaining uncertain identity, roof connection, hidden height, dimension and ground-level questions. State which targets were deferred and why; do not claim surveyed precision or completed corrections without visual evidence. The result must match the documented silhouette, layout, terrain and local surface checks while preserving bicycle exploration and completed work elsewhere.