Bani Hostel

Selected chronological video snapshots, numbered map/evidence annotations, detailed architectural and environment guidance, and a consolidated Claude implementation prompt. This document covers Bani separately from Evandy.



Sources reviewed

Reviewed all 27 photographs in the supplied ZIP, the full 6.70-second Bani video and both maps. Selected **18 complementary photographs and 5 timestamped video snapshots**; all 23 selected references appear in the appendices.

M1: real-world satellite top view, image(3).png. **M2:** current flat game top view, image(4).png. **R01-R27:** original photo number order. **V01-V05:** selected snapshots in chronological order. The video shows road/boundary views, not an aerial orbit.

Evidence limit: satellite supports roof/footprint relationships; ground photographs and video support facade/height. M2 does not establish current 3D materials or physics. Exact dimensions, compass orientation and some block identities remain unresolved.

Map pins/business labels are locators, not proof of each building function. Do not transfer Evandy facade, signage or circular paving into Bani.

COMPULSORY DETAIL-INSPECTION CLAUSE / PAGES 32-34
Claude must read and apply all three pages before modeling. Original-resolution close-ups, a floor-by-floor placement ledger and a matched-angle audit are required. No invented pillars, windows, doors or wall divisions.


01 / Real-world numbered plan



1-4 four parallel orange-roof bars in the map-left group, numbered top to bottom; **5** right-group straight red-roof bar; **6** right-group L/bent red-roof footprint; **7** pale central roof/terrace-like footprint; **8** internal access/court; **9** small support-roof cluster; **10** bottom access lane; **11** map-right through-road; **12** open dirt/grass/scrub context.

Numbers are reference targets, not official block numbers. Bani Facility Block and Perseverance Block pins narrow locations but do not establish every facade identity; restaurant pins must not become physical building labels. Map-right road includes a partial RAWLINGS name; verify the exact road identity in project data before naming it.

02 / Game-map comparison



1-3 / Retain broad topology. The game map already represents four parallel bars with side/connector strips and branching internal approaches. Register these against real targets 1-4 before altering transforms. Restore observed roof forms and local setbacks rather than replacing the whole group with one building.

4-5 / Right-hand group. A straight footprint and an L-like footprint broadly correspond to real targets 5/6. Inspect the pale central area 7 and the real gaps/links before joining the volumes or roofing the entire space.

6-7 / Access and surroundings. White linework approximates internal drives and bottom lane; the through-road and verges need calibration. Beige fills and green patches are flat-map styling, not verified facade/pavement/grass colours.

No rendered 3D game view was supplied. Height, balconies, roof colour, window depth, paving texture and collisions are inspection targets until the actual scene is checked.

03 / Site matching and block identities

Register plan. Use four parallel bars, their side strips, right-hand straight/L group, bottom-road junction and internal spine. Fit common rotation/scale/translation between M1/M2; preserve one coordinate system and never mirror.

Left-group facade family. R01/R19/R22/R23 show cream/white and salmon-pink residential faces, stone-like vertical bands, turquoise/blue balcony recess accents and yellow/ochre entrance canopies. Match these to targets 1-4 by roof/court landmarks; exact photo-to-bar identity is not fully established.

Right-group facade family. R08/R11/R15/R16 and the video show taller plain white elevations, cream lower band, narrow vertical window stacks and low dark-red hipped roofs. Their association with the right-hand map group is a strong contextual inference, not a surveyed block allocation.

Height rule. The colourful residential facade in R01 clearly shows ground plus three upper tiers. Plain newer blocks show ground plus four upper window tiers in R15/video. Use separate four- and five-tier modules after exact footprint matching; no global height setting.

Low connector/amenity block. R13/R19/R23 show a two-storey pale/pink block with red tiled roof, open upper gallery and yellow/orange columns. Keep it lower than residential bars. It must be matched through courtyard endpoints before assigning a map footprint.

Names. Use Bani Hostel for the site label. Retain map-provided Facility/Perseverance names only where project evidence confirms the exact building. Do not infer restaurant locations or physical signage from map pins alone.

Uncertain central area. Real target 7 may include roof, terrace or a linking volume. Satellite texture alone does not establish its occupied height/function. Keep separate editable geometry and an unresolved note until perspective evidence/project data resolves it.

ANNOTATED EVIDENCE PLATE

04 / Colourful residential facade

R01 gives a clear four-tier elevation. It is a target for this facade family, not proof that every Bani block has four storeys.



1. Cream/off-white walls interrupted by salmon-pink panels and tan stone-like vertical strips. These materials are distinct, not one uniform pink paint.

2. Three upper rows of deep balcony recesses above the ground tier, with pale/light metal horizontal rails and blue/turquoise inner wall accents.

3. Small square/rectangular windows, darker louvre/glass openings and ground-floor security bars alternate with balcony bays.

4. Low yellow/ochre flat entrance canopy on two columns; shallow steps/landing, coloured entry recess and a red paver approach strip.

5. Terracotta/red hipped roof, projecting eaves and multiple ridge/hip changes. Follow actual wing plan; avoid a flat red cap.

05 / Residential facade geometry

Storey rhythm. Model ground tier plus three upper occupied tiers for the confirmed colourful facade. Preserve vertical stack spacing and varied balcony widths. Do not count the roof/eaves as another floor.

Balcony recess. Dark openings have real depth, sidewalls, floor edges and rails; inner walls have localized turquoise/blue/green tones. Room glazing sits behind the opening. A black rectangle pasted onto a wall cannot reproduce this.

Railings. Mostly pale/silver horizontal bars with uprights, unlike Evandy decorative loop/diagonal patterns. Preserve distinct ground security grilles, upper balcony rails and local gallery balustrades.

Stone-like bands. R22/R23 show narrow textured tan/brown vertical cladding strips from base toward eaves. Use small stone/tile-like variation and joints; do not interpret these as plain brown painted piers.

Entrance. Flat mustard/yellow canopy with cylindrical columns, shallow stairs, recessed door and planted side beds. Some other blocks have a small tiled pitched entrance canopy (R24); do not apply one entrance design universally.

Returning elevations. R03/R14 show corner/end faces with fewer balcony openings, plain windows and vertical accent strips. Corners must belong to the same mesh/volume and not end in an arbitrary solid box.

Acceptance. At R01 frontal and R22 closer views, tier count, balcony depth, strip cladding and canopy placement agree. Preserve the two-storey block at the courtyard end rather than filling it with a taller residential asset.

ANNOTATED EVIDENCE PLATE

06 / Balcony and material detail



1. Deep balcony recesses with turquoise/blue side/back accents and horizontal pale railings. Preserve room windows behind them.

2. Tan stone-like narrow vertical cladding band; use texture plus enough relief at near distance.

3. Yellow flat entrance canopy and posts, with a shaded recessed ground doorway. Keep canopy height lower than the first-floor balcony.

4. Continuous facade planting strip, palms/shrubs and small beds separate the building base from parking. They are not a large lawn rectangle.

07 / Taller plain block and boundary

R15 supports the right-group facade family and video views. Exact block name and wall construction date are not verified.



1. Plain white block: five visible occupied window tiers, with dark rectangular openings and cream/beige base band. Keep its height distinct from the four-tier colourful blocks.

2. Low dark-red/brown hipped roof, shallow overhang and visible return geometry. Roof pitch is much lower than an exaggerated steep chalet roof.

3. Rough pale grey masonry boundary wall with exposed joint pattern, posts and red-earth base; some exposed reinforcement suggests an unfinished boundary condition.

4. External road-edge verge is red soil with kerb/drain context, not interior parking pavers. Do not make the verge a deep bike-trapping trench.

08 / Plain blocks: windows and entry

Occupied levels. R15 and the roadside video show ground plus four upper window tiers. R08/R11 corroborate a tall plain end. Use this where matched; do not upscale all parallel left-group bars.

Window patterns. End faces have sparse narrow vertical window stacks and large white wall fields; long faces have repeating smaller window groups. Ground windows can have grilles. Preserve corner/return differences and the cream lower band.

Internal recess. R11 shows a recessed central access zone between plain wings, with steps and cream inner vertical band. Match the actual volume gap; do not roof/close it solely to simplify the map footprint.


Gate. R16/video show pale horizontal-slat metal gate leaves on substantial pale posts, set in a low masonry wall. Preserve open leaf position/access alignment shown in the reference, with a continuous entry drive.

Forecourt. R08/R11 show light grey/brown small-block paving or textured hardscape with inset drainage/access covers. It is distinct from the colourful block court red/grey paving and from exterior asphalt/red soil.

Small low entry building. R16/R18 show a modest low red-roof structure beside the plain blocks. Retain it separately and trace its location using map/gate landmarks. Its exact function is unresolved.

Acceptance. Compare R15 facade and R16 gate approach with V03/V05. Tier spacing, end-window stacks, boundary/gate and roof silhouette must align in the same game asset.

09 / Entrance route and gate




1. Tall plain white block with low dark-red hip roof, narrow window stacks and cream base. The entrance approach remains clear of the building.

2. Pale gate post and open horizontal-slat gate leaf. Model a real opening, not a gate texture painted across a wall.

3. Separate small pale low building with red roof inside the grounds. Exact function/footprint match requires corroboration.

4. Paved drive/threshold joins the exterior road. Maintain shallow level transitions and sufficient bicycle/vehicle turning space.

10 / Low block in courtyard



1. Two-storey amenity/connector-like block with orange/red tiled hip roof and lower height than the residential bars.

2. Open upper gallery with pale horizontal rails, coloured recess, warm yellow columns and sheltered ground entrance. Avoid Evandy-style gabled arch details not present here.

3. Tall narrow conifer-like ornamental trees and palms in the court. Preserve their distinct vertical silhouettes; do not replace them with broad generic trees.

4. Small grey/beige interlocking paver court with red paver paths/bands and geometric patches. This is not Evandy circular-disc paving.

11 / Courtyard composition and paving

Facing blocks. R19/R26 show residential bars facing each other across a court with the low block at one end. Keep enough open width for routes, parked cars and trees; do not merge the facing wings.

Paver pattern. R23 shows small grey/beige interlocking units with reddish bands that turn/change direction; R26 shows tan/brown block paving under shade. Match surface regions under consistent daylight; variation is not proof of separate different buildings.

Entry paths. Red paver strips run toward yellow-canopy entries and branch across the court. Low pink/pale kerbs enclose planting beds; steps/landings are local to entrances.

Plant beds. Rounded entrance-side beds include palms and white/light stone mulch, with clipped shrubs and flowering plants. Preserve the bed outline and lower facade strip, not a uniform large grass fill.


Cars and clothing. Use a modest set of parked vehicles to show court scale; clothes, bins and delivery vans are transient context. Do not reproduce all reference people/objects as mandatory architectural fixtures.

Drainage. Plain-block court has rectangular inset covers visible in R11. Add shallow covers/textures at supported positions; do not create open holes or gaps in rideable surfaces.

Acceptance. At R23 overhead-ish and R19 road-level views, low block, entry canopies, red path bands and planting align. The court must remain open and different from asphalt roads.

ANNOTATED EVIDENCE PLATE

12 / Paving, canopy and planting



1. Grey/beige small-block pavers with red bands through the court. Use an appropriately scaled texture; do not model thousands of individual paving colliders.

2. Yellow/ochre flat canopy with round columns, shallow steps and recessed entrance. Pale stone mulch and palms frame the approach.

3. Palms in individual rounded beds and facade planting strips. Keep pedestrian/drive clearances between beds.

4. Two-storey low block with red tiled roof, coloured gallery recess and warm columns. Its roof/material module is different from taller plain blocks.

13 / Roofs, colour and facade variants

Primary roofs. Map targets 1-4 have orange/terracotta tiled hip roofs; match observed lengths, ridges and eaves. Targets 5/6 have darker reddish roofs, distinct L/straight plans and lower-looking roof pitches in ground views.

Central roof/terrace 7. Pale central footprint between right-group roofs must stay separate and unresolved if its construction is not visible. Do not put a single giant hip roof over the entire group or fill any access gap.

Colourful walls. Cream/off-white with salmon/pink panels, tan stone-like vertical bands, ochre/yellow canopies and localized blue/turquoise/green recessed surfaces. Colours occur in specific patches, not random per-room paint.

Plain walls. White with cream/beige base course, dark window openings and minimal ornament. Keep separate materials/geometry from colourful courtyard blocks.

Other entrances. R24/R25 show another four-tier balcony facade with pale rails and small tiled entrance canopy. Maintain this supported variant rather than repeating the flat yellow canopy at every doorway.

Weathering. Subtle faded paint, wall-base dirt, roof tile wear, paver colour changes and rough boundary masonry are visible. Lighting/capture processing affects apparent colour; compare repeated references under neutral game daylight.

Efficient details. Use textures for tile rows, stone joints and small pavers; geometry for recesses, railings near the rider, canopy posts, steps and roof silhouette. Instance repeated modules without erasing variant elevations.

14 / Small structures and environs

Support cluster 9. M1 shows small pale/grey/red roof units near the upper internal drive. M2 has small corresponding rectangles. Inventory roof islands individually and preserve visible rotations/spacing; exact heights/functions remain unknown.

Roadside shops. R04/R20 show low commercial/utility-type structures, dark/pale roof edges, shaded front openings and sidewalk/verge context. Place them only after matching nearby boundary/road landmarks; unreadable names remain unspecified.

Low court block. R13/R19/R23 establishes a two-storey roofed amenity/connector-like building. It is architectural evidence even when its precise map allocation is uncertain; retain an explicit matching task rather than omit it.

Bottom lane 10. The real map shows the precinct frontage along a lower access lane. Preserve side entries, small southern roofs and verges, not just the road centreline. M2 white line width is schematic.

Through-road 11. Roadside video and R17/R20 show asphalt, grass/red-earth edges, boundary walls and occasional utility poles. Maintain continuity with the existing campus road system. Verify the partial Rawlings name using project map data.

Ground outside. Open dirt/grass field to the map-left and patchy scrub behind/right of the buildings are distinct from internal manicured beds. Do not add unrelated large developments to fill the crop.

Hidden structures. Vegetation and map crop obscure some roofs. Model only supported visible extents, retain provisional heights and do not invent precise rear elevations or businesses.

15 / Trees, bushes and surface transitions

Tree types. Tall conifer-like ornamentals stand around the low court block; palms flank entrances; mature spreading trees shade courts and road edges. R13/R19 establish narrow vs broad canopy silhouettes. Exact botanical species is not verified.

Lawn strips. Narrow lawns and facade beds are separated by raised pale/pink edging. Main internal courts are paved; do not cover them with grass.

Outside vegetation. Grass, low scrub and trees mix with exposed reddish/brown soil outside the boundary. Satellite provides cover distribution, not a count of every plant.

Bush construction. Use compact low-poly volumetric foliage meshes per continuous bush patch or cullable chunk, shared textures and controlled height variation. Keep landmark trees and palms as separate assets; do not generate many full trees for clipped shrub banks.

Kerbs and borders. Shallow planter edges and entrance steps should match source geometry. Keep a continuous bicycle collider beneath transitions from asphalt to pavers, gravel or allowed soil routes.

Damage depiction. R20 shows damaged/drain-like road-edge conditions. Cosmetic roughness is appropriate; do not recreate a trapping hole unless the gameplay explicitly includes that hazard.

Acceptance. Court trees frame views without hiding entrances; plants stay within beds; visible lawns/soil/asphalt/paving remain separate and all permitted routes are navigable.

16 / Signage and evidence confidence

Site label. Bani Hostel is the confirmed site name. Keep a correct map/navigation label. Physical facade wording is not consistently readable in this set; do not invent an observed pediment or Evandy-style blue arch lettering.

Facility/Perseverance. The real map pins include Bani Facility Block and Bani Hostel Perseverance Block, but exact pin-to-wing allocation is uncertain. Use these names on physical models only when existing project data or readable signage resolves it.

Restaurant pins. HOG EGGS and Mr Wu's Chinese Fast Food are map locators. They are not proof that the nearest large residential bar has that name or of the current tenant/function of a small roof.

Source overlays. Bandicam, player controls, coloured cursor dot and faint usernames are video overlays, not game world objects. Preserve source frame appearance in this PDF, but never reproduce overlays as architectural detail.

Four/five tiers. Supported in specific facade views, not a surveyed height schedule. Keep exact metre heights provisional until project/world scale is calibrated.

No unseen game errors. M2 gives a flat footprint baseline. Current 3D colours, windows, storeys, roof materials and collision faults require actual-scene inspection before being stated as confirmed defects.

Review labels. Map target IDs 1-12 are debug/review annotations only. Do not put them on the physical hostel as official block numbers.

17 / Snapshot selection and order

Reviewed clip. One 6.70-second, 30 fps portrait recording. It pans along the external boundary and road, then toward the plain white block and gate. It is not an aerial layout source.

Selected five views. V01: initial gate/end facade; V02: road/grass boundary context; V03: clearer main plain facade behind wall; V04: adjacent/plain group and tree/gate relationship; V05: final gate/end-face approach.

Selection method. Reviewed the full clip as half-second samples, then compared nearby candidates around each useful view for sharpness and obstruction. Avoided pole-dominated frames around 2 seconds and redundant repeated gate views.

Chronology. V01-V05 remain in ascending extraction time. Exact seconds are printed beneath each selected image in the appendix. This does not establish photo/video capture dates or the chronology of construction.

Photo selection. Selected 18 stills spanning colourful facades, stone/balcony detail, low court block, taller plain blocks, gate, paved ground, tree types, roadside context and the alternative tiled entry canopy.

Excluded photos. R02 duplicates R01 with narrower framing; R06 repeats tree/parking context; R07/R21 have tilted, partly obscured facades; R09/R10/R12 include obstruction/portrait context already covered better; R18 is dimmer; R26 repeats the court view; R27 is retained for balcony/service-side detail.

Source fidelity. Extracted frames keep original resolution/content. No invented sharpening, repainting or removal of obscured architectural details. Use the source photographs where video compression hides fine detail.

18 / Game audit and rebuild sequence

1. Establish baseline. Inspect actual Bani scene objects/map data and capture overhead/front/court views. M2 is the initial footprint guide, not a rendered model inspection.

2. Register maps. Use four parallel bars, right straight/L group, bottom junction and internal spine. Align scale/rotation/translation once, then correct local setbacks/gaps. Never move the entire precinct because a map pin is offset.

3. Build masses. Separate targets 1-4, 5/6, unresolved central area 7 and support units 9. Match facade photographs to footprints and apply four-/five-tier and two-storey low modules only where supported.

4. Build roofs/facades. Correct hip/roof planes and eaves; add balcony recesses/rails, stone strips, pink/cream/blue patches, yellow flat canopies and the alternative tiled canopy. Plain-block facades remain distinct.

5. Finish grounds. Pavers and red bands, entrance beds, stone mulch, palms/conifers/mature trees, gate/wall, road/verges and small structures. Do not reuse Evandy circular paving.

6. Verify physics. Continuous gate/approach/internal routes, safe thresholds, no building overlap or invisible wall, and no planter/verge holes.

7. Compare/profile. Require source-matched views and target 1-12 checklist; report measured performance where possible. Optimise repeats/foliage without deleting low buildings or filling court gaps.

19 / Acceptance and rider checks

Overhead. Compare M1/M2 after registration: four parallel bars, side strips, right straight/L roofs, central area, support cluster and road approaches retain their correct relationships. Courtyard gaps stay open.

Colourful block. Match R01/R22/R23: four occupied tiers, stone-like bands, recessed balconies, light horizontal rails, yellow canopy and red/grey paving/plant beds.

Plain group. Match R15/R16/V03/V05: five visible occupied tiers, end-window stacks, low red hip, cream base, masonry wall and slat gate.

Low block. Match R13/R19 for two-storey height, tiled hip roof, open gallery, yellow columns and tall narrow trees. Do not replace it with another tall bar.

Alternative entrance. Match R24/R25 for pale balcony rails, ground grilles and small tiled entrance canopy. Reproduce the variant only on the matched elevation.

Ride test. Drive/bicycle the through-road, bottom lane, confirmed entries, court approaches and permitted internal links. Check steps, planter edges, paver/asphalt boundaries, wall/gate clearance and parked props.

Completion evidence. Provide before/after source-matched screenshots, changed files/objects, target checklist, collision results, performance measurements and explicit unresolved heights/identities. Do not claim checks that were not run.

20 / Claude prompt: plan and architecture

Task. Rebuild Bani Hostel and its supported immediate environs in the existing LEGONRUSH game using this separate Bani brief, M1 real satellite map, M2 game map, selected R-series photographs and V01-V05 snapshots. Do not modify or replace the Evandy document/assets as part of this task.

Inspect/register. Inspect existing Bani scene/map data, objects, transforms, roofs, materials and colliders. Register four map-left bars, right straight/L group, bottom-road junction and internal spine between M1/M2. Keep existing campus world coordinates and road continuity.

Plan targets. Preserve targets 1-4 parallel hostel bars, 5 straight right-hand roof, 6 bent/L right-hand roof, 7 separate uncertain central roof/terrace-like area, 8 court/drive, 9 support cluster, 10 bottom lane, 11 through-road and 12 dirt/scrub context. Do not fill genuine gaps or merge every roof.

Height families. Colourful residential facade in R01 has ground plus three upper tiers; plain white blocks in R15/video have ground plus four upper tiers; low court block in R13/R19 has two storeys. Match each photo to footprint before assigning height. Exact metre heights remain provisional.

Colourful facades. Cream/off-white and salmon/pink wall panels, tan stone-like vertical strips, deep balcony recesses with turquoise/blue accents, pale horizontal rails and varied small windows/ground grilles. Yellow/ochre flat canopy and round posts at confirmed entrances.

Plain facades. White walls, cream/beige base, sparse stacked end windows and repeated smaller long-face groups. Preserve central access recess and low roofs. Do not apply pink bands or ornate Evandy pediments universally.

Roofs and variants. Orange/terracotta tiled hips over main bars, darker reddish low roofs over plain blocks, localized tiled entrance canopy on R24/R25 elevation. Keep roof slope/valley/overhang consistent with footprint and courtyard voids.

> **MANDATORY ADDITION TO THIS CLAUDE PROMPT / PAGES 32-34**
> The compulsory clause is an inseparable part of this prompt and its acceptance criteria. Inspect original-resolution crops; record each visible pillar, partition, opening and roof junction; then verify counts and positions floor by floor. Correct every known mismatch before marking verified elevations complete. Unclear details remain provisional.

21 / Claude prompt: grounds and scope

Low block. Rebuild the two-storey court-end block with tiled red hip roof, open upper gallery, coloured recess and yellow/orange columns. Match R13/R19/R23; its exact function and map placement require landmark matching.

Ground materials. Small grey/beige/tan interlocking pavers, red path bands/geometric patches, pale thresholds, grey hardscape/drain covers, dark external asphalt and red-earth verges. Bani does not use Evandy's large circular-disc paving as its default court texture.

Landscape. Rounded pale/pink-edged entrance beds with palms, light stone mulch, shrubs/flowers; tall conifer-like ornamentals beside low block; mature spreading court trees; patchy scrub/grass/red soil outside. Keep routes, parking and entrances open.

Boundary and gate. Grey/pale blockwork wall, visible posts/joints, cream gateposts and pale horizontal-slat gate leaves. Preserve real drive opening and small low red-roof structure by the entry. No invisible wall across the gate.

Small structures. Inventory roof cluster 9 and visible roadside/low roofs; use project map data and source landmarks before naming or precisely placing them. Hidden elevations/functions stay unresolved, not invented.

Naming. Correct Bani site/map label; exact Facility/Perseverance allocation requires confirmation from project evidence. Do not put restaurant pins, source overlays or invented block names on residential facades.

Efficient construction. Instance repeated balcony/window/rail modules and share textures. Use low-poly volumetric bush meshes per continuous patch/cullable chunk; preserve palms/conifers/landmark trees separately. Fine roof/paver detail uses textures; near silhouette/recesses use geometry.

MANDATORY ADDITION TO THIS CLAUDE PROMPT / PAGES 32-34
The compulsory clause is an inseparable part of this prompt and its acceptance criteria. Inspect original-resolution crops; record each visible pillar, partition, opening and roof junction; then verify counts and positions floor by floor. Correct every known mismatch before marking verified elevations complete. Unclear details remain provisional.

22 / Claude prompt: verification and delivery

Scope/control. Keep changes local to Bani and supported environs; preserve existing Evandy/UGMC/Noguchi work. Make generation modular and reproducible. Remove superseded overlaps/colliders only after replacement alignment is verified.

Collision. Continuous road/drive/paver surfaces and permitted court links. Ensure clearance through gate, around canopy posts, plants and parked vehicles. Avoid wall/roof overlap, invisible blockers, grass/verge holes and unnecessary step traps.

Required images. Deliver registered overhead against M1/M2 with review targets 1-12; matched R01/R22 colourful facade; R23 paving/entrance; R13/R19 low block; R15/R16/V03/V05 plain group/gate; R24 alternative tiled canopy; R17/R20 road context.

Required tests. Ride through-road, bottom lane, confirmed entry and internal court approaches. Report actual collision/clearance results and fix any sticking/falling problems. Never claim a test passed without running it.

Performance. Measure before/after representative frame time, draw calls and triangles where available. Use levels of detail/spatial culling without losing nearby balcony depth, roof silhouettes, low structures or landscape types.

Report. List changed files/objects and transforms, height choices, facade/roof variants, material choices and a target checklist. Distinguish observed source facts from inferred footprint matches and unresolved central area/height/name details.

Completion. Layout, occupied tiers, balcony depth, colours, roof forms, small blocks, paving, boundary and landscape must agree across overhead and ground views. Do not fabricate exact dimensions or block identities to conceal missing evidence.

MANDATORY ADDITION TO THIS CLAUDE PROMPT / PAGES 32-34
The compulsory clause is an inseparable part of this prompt and its acceptance criteria. Inspect original-resolution crops; record each visible pillar, partition, opening and roof junction; then verify counts and positions floor by floor. Correct every known mismatch before marking verified elevations complete. Unclear details remain provisional.

Video references / 01-02



V01 / Bani video / 0.62 s
Gate/end facade and roadside approach.



V02 / Bani video / 1.28 s
Road alignment, verge vegetation and utility context.

Video references / 03-04



V03 / Bani video / 3.72 s
Plain white facade behind blockwork boundary wall.



V04 / Bani video / 4.92 s
Adjacent plain group, mature tree and gate relationship.

Video references / 05-05



V05 / Bani video / 5.48 s
Final gate opening, five-tier end face and drive.

Selected photographs / 01-04



R01 / photo_1_2026-10-14_01-54-08.jpg
Clear colourful four-tier facade, balcony recesses and yellow entrance.



R03 / photo_3_2026-10-14_01-54-08.jpg
Returning cream/pink facades, tree/planted margins and roofs.




R04 / photo_4_2026-10-14_01-54-08.jpg
Low roadside structure and block-paved walkway/verge.




R05 / photo_5_2026-10-14_01-54-08.jpg
Palms, mature trees, paver court and residential facade context.

Selected photographs / 05-08



R08 / photo_8_2026-10-14_01-54-08.jpg
Tall plain end facade and court, dark roof/base band.



R11 / photo_11_2026-10-14_01-54-08.jpg
Plain wings/access recess, shallow steps and inset court covers.



R13 / photo_13_2026-10-14_01-54-08.jpg
Two-storey low court block, conifer-like trees and paver paths.



R14 / photo_14_2026-10-14_01-54-08.jpg
Corner balcony/turquoise recess, lawn/planted edge.

Selected photographs / 09-12



R15 / photo_15_2026-10-14_01-54-08.jpg
Five-tier plain block behind rough masonry wall.



R16 / photo_16_2026-10-14_01-54-08.jpg
Plain block gate approach, slat gate and small low entry structure.



R17 / photo_17_2026-10-14_01-54-08.jpg
Street approach, boundary, palms and road context.



R19 / photo_19_2026-10-14_01-54-08.jpg
Facing colourful bars, low court-end block and tall narrow trees.


Selected photographs / 13-16



R20 / photo_20_2026-10-14_01-54-08.jpg
External road, roadside building and damaged verge/drain context.



R22 / photo_22_2026-10-14_01-54-08.jpg
Stone-like strips, balcony detail, yellow canopy and planted base.



R23 / photo_23_2026-10-14_01-54-08.jpg
Paver/red-band ground, entrance steps, stone mulch and palms.



R24 / photo_24_2026-10-14_01-54-08.jpg
Four-tier balcony variant with small tiled entrance canopy.

Selected photographs / 17-18



R25 / photo_25_2026-10-14_01-54-08.jpg
Alternative entrance/balcony facade beneath mature trees.



R27 / photo_27_2026-10-14_01-54-08.jpg
Service-side balcony detail and turquoise recess accents; tilted image.

Mandatory inspection: evidence first

Bani Hostel / This clause supplements the original brief. Read all three pages before implementation.

BINDING REQUIREMENT - READ BEFORE EDITING. These three pages are part of the consolidated Claude prompt and its acceptance criteria. They take precedence over any generic repetition, inferred symmetry or simplification that would contradict visible architectural detail. Do not begin detailed facade, opening, pillar or roof placement until the evidence record below is prepared for that elevation.

1 / Inspect original-resolution evidence. Open the original photographs and video frames, not only the reduced PDF thumbnails. For each visible building face, inspect the whole elevation, then crop by wing, floor and facade bay. Zoom to native detail; magnification does not create missing information. Review neighboring video frames when blur, shadows, trees or people conceal a feature. Do not use generated enhancement as evidence of a new opening.

2 / Register the actual building face. Match the roof shape, entrance, stair bay, courtyard and neighboring buildings to identify the wing and viewing direction. Record a stable elevation ID and source IDs/timestamps. Do not attach a close-up to the wrong wing, mirror its left/right order or treat a returning side face as the front elevation.

3 / Produce an annotated close-up pack. For every sufficiently visible elevation, submit one overview plus enlarged crops of the ground level, each upper level, stair/entrance bays and roof junctions. Number the visible pillars/piers, solid wall segments and openings. Include source IDs and crop boundaries so the annotations can be checked against the uncropped image.

4 / Read structure, not just colour. Distinguish load-bearing-looking piers/columns, wall returns, gallery dividers, railings, louvre screens, ventilation blocks, closed shutters and shadowed corridor voids. Do not label every dark rectangle a window or every white vertical strip a freestanding pillar. Do not infer structural engineering roles from a photograph.

STOP CONDITION. If the original reference cannot be opened or an important placement remains obscured, flag that affected bay as unresolved and keep it provisional. Continue verified areas. Do not silently substitute a generic facade, invent a window/door or claim inspection that was not performed.

Local focus: Audit the Bani gallery and stair/entry faces separately, including differences between taller wings and the lower court-edge block. Do not copy one elevation pattern across the precinct.

Mandatory placement record and build

Bani Hostel / This clause supplements the original brief. Read all three pages before implementation.

5 / Create a floor-by-floor evidence ledger. Before placing details, provide a table with: building/elevation ID; floor; bay number ordered left-to-right in the registered view; feature type; source ID/timestamp; visible count; relative position and width/height; recess/projection; observed state; confidence; and unresolved notes. Separate directly observed facts from estimates. Use normalized facade coordinates if exact project dimensions are unavailable.

6 / Record every visible wall division. Trace the outer wall outline, floor/slab bands, parapets, vertical dividers, stair volumes, recess boundaries and changes between solid wall and gallery. Record uninterrupted blank wall spans explicitly. Check where divisions align between floors and where they change. Do not create a universal bay grid until repetition is confirmed on that particular face.

7 / Place pillars only where supported. Map each visible column/pier to its correct floor and bay, including its relation to gallery edges, entrances and wall returns. Preserve observed width, spacing, depth and offsets. No evenly spaced decorative pillars may be added to a plain wall. A railing post, drainpipe or shadow must not become a structural column.

8 / Place windows and doors individually. Confirm count, left/right order, sill/head height, proportions, frame divisions, louvres/shutters, recess and floor location. Distinguish a genuine opening from a closed panel or gallery void. Record whether a window/door is shown open or closed, and whether it swings, slides or is uncertain. Preserve supported differences; do not animate an unsupported mechanism.

9 / Inspect roof and canopy junctions. Map each roof plane, ridge, hip/gable, eave, fascia, overhang, height break, stair cap and canopy. Verify where roofs terminate or overlap and where a gap remains. Match entrance roofs separately from main roofs. Roof fixtures require positive evidence; do not scatter tanks, vents or masts by assumption.

10 / Build from the ledger. Translate each confirmed feature into geometry or a faithful material detail at the mapped position. Share meshes only after matching repetition. Keep per-elevation exceptions. Do not stamp an identical pillar/window pattern onto all wings, floors or sides, and do not borrow architecture from Evandy or another hall.

Mandatory verification and rejection

Bani Hostel / This clause supplements the original brief. Read all three pages before implementation.

11 / Compare at matched camera angles. For each completed elevation, render an overview and close-ups matching the reference direction and approximate perspective. Use side-by-side crops or aligned overlays. Compare floor by floor and bay by bay; an overhead screenshot alone cannot verify window, door or pillar placement.

12 / Run a count-and-position audit. Check modeled versus observed pillar/piers, windows, doors, blank wall spans, gallery partitions, stair screens and roof breaks. Verify their floor, order, spacing and relationship to entrances. Compare proportions in image space when exact measurements are missing; report deviations rather than inventing surveyed tolerances.

13 / Required correction cycle. If a pillar occupies the wrong bay, a window cuts a verified blank wall, a door appears on the wrong floor, wall partitions are missing, galleries are flattened or roof joints disagree, mark that elevation FAILED. Correct it, recapture the comparison and audit again before calling the elevation complete.

14 / Completion evidence. Deliver the annotated close-up pack, completed feature ledger, matched reference/render comparisons, discrepancy list with fixes, and explicit unresolved items. The discrepancy list must identify elevation/floor/bay, expected feature, current result and correction. Assertions such as "looks similar" or "details added" are insufficient.

15 / Honest limits and priorities. Inspect every identifiable detail available at source resolution. Never claim hidden, blurred or obstructed details are confirmed. Mark estimates and defer unsupported decoration. Optimise after placement is verified; preserve all supported opening locations, blank walls, partitions and landmark silhouettes when reducing detail.

FINAL ACCEPTANCE RULE. The reconstruction is not complete until every adequately documented elevation passes the placement audit. Unresolved elevations must remain explicitly provisional. Zero known unexplained placement errors are acceptable in verified areas. Do not claim a whole-building pass if an affected face is unverified.