Evandy ground floor partition fix

Main correction: replace the circled constant-profile rectangular posts with the observed tapered projecting wall dividers between the ground-floor window bays. Reconstruct the divider, recesses and window treatment as one coordinated facade bay.

G1 / current game Screenshot 2026-10-14 172716.png



R1 / real target Screenshot 2026-10-14 173349.png




The real fins have a sloping profile beneath the balcony and a narrower lower return toward the wall. The game shows straight box-like members and shallow-looking grey louvred openings. This PDF addresses those marked ground-floor bays, not every pillar on Evandy.

The photographs establish appearance; exact dimensions, hidden joinery and structural engineering roles remain unmeasured. Do not claim these fins are load-bearing solely from the image.

01 / Enlarged real evidence

Native-resolution crop of the rightmost circled bay in R1. Aspect ratio is preserved; no generated detail or stretching is used.



1 Upper junction. The divider meets the underside of the projecting balcony or slab. Preserve the local soffit and wall return.


2 Sloping fin profile. The exposed edge changes projection down the height. Reproduce this taper in geometry; a straight rectangular prism does not match.

3 Lower return. The narrower lower portion joins the facade near the ground. Do not leave a detached freestanding post or a diagonal fin floating above paving.

4 and 5 Window bays. Two dark framed and barred openings sit behind the outer bay edges. Keep actual wall beneath the windows, recess depth, grilles and frame layout.

02 / Current game and specific errors

Native crop of the nearest circled game divider. G1 and R1 have different perspectives; compare architectural shape rather than raw pixel widths.



Constant profile. The game member has straight parallel sides and reads as a full-height rectangular post. The observed real divider has a tapered or wedge-like projecting side profile.

Wrong wall relationship. The game member appears detached in front of a flatter window wall. The real divider belongs to the partition between recessed bays and connects into the facade/slab.

Insufficient recess. The windows and wall returns must form a deep enough bay to produce the observed shadow and depth. Enlarging a flat window texture cannot reproduce this.

Wrong opening material. Grey horizontal louvres in G1 differ from the dark framed windows and security-bar appearance visible in R1. Rebuild the visible frame and grille arrangement; do not assume all dark lines are glass mullions.

Proportion and placement. Divider thickness, projection, windows and wall spans must be calibrated together. Do not fix the error by merely widening or leaning the existing box.

03 / Geometry specification


Model the side profile. Use a custom mesh or extruded profile whose outward projection is greater near the upper slab and reduces toward the lower wall connection. Preserve the visible slope and a coherent narrower lower portion. Do not taper the entire building or rotate the whole facade.

Separate thickness from projection. The fin has width across the facade and depth outward from it. Those are different parameters. Match both to the native crop; a trapezoid drawn in the frontal plane alone may give the wrong side silhouette.

Keep real junctions. Join the fin to the confirmed slab underside and facade return. Preserve vertical surrounding walls, level balcony slab and room/window datums. Do not create unsupported column capitals or thick extra beams.

Use adjustable parameters. Record top projection, lower projection, transition height, fin width, bay width, soffit height and window recess as provisional project-scale parameters. Tune them by matched views; no exact metre values are claimed here.

Schematic side profile / conceptual only, not a measured section.



Perspective can change the apparent lean. Validate the profile from an oblique view and the bay layout from a frontal view. Keep uncertain hidden thickness/junction detail explicitly provisional.

04 / Placement and window bay ledger

Before editing, assign a stable ID to each marked ground-floor divider on both sides of the central entrance. The real image has several circled examples; markers do not prove the total number of dividers in hidden or cropped areas.

Record	Required evidence
Object and bay	Facade wing, floor 0, left-to-right bay ID and source crop
Fin shape	Width, top/lower projection, slope, transition and wall join
Placement	Between which window bays; relation to upper divider/slab
Window openings	Count, order, sill/head height, width and recess
Frames and bars	Visible panel divisions and security-bar pattern
Blank wall	Solid wall under windows and uninterrupted adjacent strips
Confidence	Observed details versus estimated dimensions or hidden faces

Preserve openings. Do not move or enlarge windows merely to accommodate an incorrectly sized fin. Set the supported bay geometry first, then fit frames and bars at their observed positions.

No indiscriminate repetition. Apply this profile only to confirmed circled ground-floor middle dividers. Outer full-height piers, central entry columns and upper balcony dividers are separate features.

Match window state. Use the dark framed/barred appearance of R1. Treat the exact unseen glazing or opening mechanism as uncertain; do not invent hinged shutters or use generic silver louvres.

05 / Implementation and acceptance

1 Inspect source and generator. Find the owning front-facade object or procedural module. Record current fin geometry, window bays, material instances, transforms and colliders. Save baseline frontal and oblique screenshots.

2 Build one verified bay. Create one corrected fin and its two neighboring recessed window bays. Compare the slab connection, top projection, slope, lower return, wall spans and frame/grille placement against the native R1 crop.

3 Validate before instancing. Render at a similar oblique angle and a frontal angle. Fix the prototype before copying it to other confirmed ground-floor bays. Retain bay-specific offsets and exceptions.

4 Remove stale boxes. Replace the original rectangular posts at their source. Do not leave duplicate box colliders or put a tapered shell over the old post. Reload/regenerate to verify persistence.

5 Check ground access. Synchronise fin/wall collisions with visible geometry and preserve the facade-side route. Plants must not hide erroneous lower joins; paving must not cover the true base connection.

Acceptance criteria. Verified members have the supported tapered profile, upper slab join, lower facade return and correct bay position. Windows sit behind the outer edges with the observed frames/bars. No extra pillar or opening is introduced.

Required proof. Submit annotated source crops, filled placement ledger, before/after frontal and oblique renders, changed files/object IDs, actual collision/persistence checks and unresolved assumptions. Known unexplained placement errors mean the bay is not complete.

06 / Consolidated Claude prompt 1 of 2

Task. Correct only the marked middle ground-floor partitions on Evandy main block frontage using this complete PDF, G1 current game image and R1 real target. The current straight box-like posts do not match the tapered projecting wall fins in the real photograph.

Mandatory inspection. Open original-resolution images and enlarged crops. Register each marked bay on the actual facade. Produce a ledger for fin width/depth/profile, slab join, lower return, window locations/recess, frame/bar pattern and blank wall spans before placing geometry.

Required mesh. Replace each confirmed rectangular post with a custom tapered projecting wall-divider mesh. Its outward projection is greater beneath the balcony slab and reduces toward the lower wall connection. Match the visible side contour and bay thickness; do not merely tilt a rectangular prism or draw a flat trapezoid texture.

Required connections. Join the fin coherently to the slab underside and facade partition between the windows. Keep the surrounding walls vertical and balcony slab level. Do not add capitals, beams, freestanding supports or unsupported floor changes.

Window correction. Rebuild the neighboring recessed ground-floor openings with the visible dark frames and security-bar treatment. Replace incompatible generic grey horizontal louvres at these verified bays. Preserve supported sill/head height, wall beneath windows and correct left/right order.

Scope guard. Apply the profile only to confirmed ground-floor middle dividers. Do not convert every upper balcony divider, outer pier or central entrance column to this shape. Hidden faces and exact dimensions remain provisional.

07 / Consolidated Claude prompt 2 of 2

Implementation sequence. Audit the owning source; correct one fin-and-window prototype; render frontal and oblique comparisons; fix mismatches; then repeat only in confirmed bays. Modify procedural source data where needed and remove old boxes and stale colliders.

Calibration. Compare relative top projection, sloping side edge, lower return, slab connection and window recess depth at the same view direction. Perspective affects apparent width and lean; do not derive exact dimensions from marker outlines.

Reject these results. Constant-profile rectangular post, tilted whole facade, fin detached from the wall, floating lower return, added unsupported pillar, wrong window position, false horizontal louvre treatment or flattened recesses fail the affected bay.

Verification. Submit native source crops with feature IDs, the completed placement ledger and before/after frontal plus oblique screenshots. Check that all adequately visible ground-floor examples follow the same supported design with local placement differences retained.

Testing. Reload or regenerate to verify the correction persists. Check nearby movement/collision and that no invisible old post blocks access. Report only tests actually run; do not invent a completed game test.

Required response. List changed files/object IDs, explain the fin and window corrections, provide the matched renders and actual test results, and identify unmeasured or concealed details. Do not claim completion while known shape or placement errors remain.

Completion rule. Every confirmed marked bay must pass both silhouette and placement checks. A white surface or generic visual resemblance is insufficient; the real tapered wall profile and recessed opening relationship must be reproduced.