
Campus corrections for Claude

Main gate, School of Law, Bani-side vegetation, International House, fire-service environs, unfinished foundations and the road behind JQB. This brief refines the user's corrections into evidence-based modeling instructions and mandatory verification criteria.



Read before editing

Use Pictures 1-20 in the exact supplied order. The numbered pictures, existing blue/yellow/red/green markings and written user corrections form the task specification. Each section gives the defect, required change and acceptance check. The consolidated prompt at the end incorporates all sections.

Do not repeat previous facade-placement errors: inspect enlarged original images, map every visible wall division, pillar, window, door and roof junction, then verify each floor and bay. Do not invent openings or copy one facade pattern across unrelated buildings.

Authority and limits: the user explicitly confirms single-storey buildings in the marked gate/fire-service zones, unfinished foundations and the ascent/descent direction. Satellite imagery supports footprints and vegetation distribution; it does not measure storeys, tree heights or road elevations. No game project has been edited or tested by this document.

01 / Exact picture-to-source index

Use these original files when zooming. Numbering follows upload order, including files whose names are timestamps. Existing annotations are retained unchanged.

01 / image(7).png

02 / image(8).png

03 / image(9).png

04 / image(10).png

05 / law_school_2_labeled.png

06 / law_school_1_labeled.png

07 / law_school_layout_labeled.png

08 / image(20261014-062313).png

09 / Screenshot 2026-10-12 213439.png

10 / image(20261014-062458).png

11 / international_programmes_office_1_labeled.png

12 / international_programmes_office_2_labeled.png

13 / image(20261014-062710).png

14 / image(20261014-062714).png

15 / Screenshot 2026-10-14 060823.png

16 / image(20261014-063137).png

17 / Screenshot 2026-10-14 060951.png

18 / image(20261014-064015).png

19 / image(20261014-064213).png

20 / image(20261014-064545).png

Game views: 1-4, 8, 10, 13-14, 16, 18-19. **Real views/maps:** 5-7, 9, 11-12, 15, 17. **Annotated game-route map:** 20. Markers and screen/map labels are reference aids, not physical objects to build.

Names: International House is associated with the International Programmes Office reference images; retain project naming until checked. The Limbo Museum map label identifies the marked foundation site in this task, not evidence of a completed museum building. JQB denotes the Jones-Quartey Building.

02 / Compulsory close inspection

Before placing geometry. Open every original reference at its native resolution. Inspect whole-building context, then crops by wing, floor, bay, entrance and roof edge. Inspect the source detail; digital zoom does not recover missing information. Do not use generated images to invent hidden structure.

Register each elevation. Match the correct building face and viewing direction through roof, entry, adjacent block and road/court relationships. Give each elevation a stable ID. Do not mirror left/right or apply a rear-elevation window pattern to the front.

Mandatory feature ledger. Record building/elevation, floor, bay ordered left-to-right, feature type, count, relative position/size, recess/projection, observed state, source picture, confidence and unresolved notes. Include columns/piers, partitions, blank wall spans, windows, doors, corridor voids, roof planes and canopy junctions.

Opening discipline. A dark patch may be a shutter, louvre, shadow or gallery void. A white strip may be a wall divider rather than a column. Preserve visible sill/head levels, frame divisions and open/closed state. No extra windows on blank wall; no evenly spaced decorative pillars without evidence.

Roof and wall divisions. Trace floor bands, vertical returns, partition offsets, stair masses, roof ridges/hips/gables, eaves and overhangs separately. Confirm repeated modules on that particular elevation before instancing them.

Proof and correction. Submit annotated source crops, the feature ledger and matched-angle reference/render comparisons. Audit counts and positions floor by floor. Any known misplaced pillar, opening, partition or roof junction fails that elevation until corrected and rechecked.

Unclear evidence. Continue verified work; mark affected details provisional rather than guessing. Do not certify an obscured face as complete. Apply the user's explicit corrections even when a top-view map alone cannot establish height.

03 / Main-gate structure paint

Picture 1 / image(7).png



Current defect. The marked structure presents a large black exterior mass. The user specifies white exterior paint and black interior paint. This is a material assignment error, not permission to recolour the entire precinct.

Required correction. Separate outward-facing walls/skins from inward-facing surfaces and deep internal recesses. Apply white/off-white exterior material; apply black/charcoal to the actual inside. If a single shared/double-sided material drives both faces, split mesh surfaces or material slots so the distinction is stable.

Opening and edge rule. An opening can reveal a black interior while its external frame, sides and outer wall stay white. Do not turn interior shadows white; do not leave exterior return faces black. Inspect the circled asset and mark each affected face.


Acceptance. From the Picture 1 road angle and an opposite/oblique angle, outside surfaces read white and internal surfaces read black. Daylight shadows must not be used to excuse a black exterior material. Preserve the verified structure silhouette and neighboring white/wine buildings.

04 / Main-gate low buildings

Picture 2 / image(8).png



Picture 3 / image(9).png



Current defect. The blue-circled block has two occupied levels with repeated window rows. The user specifies that all buildings along the marked stretches on both sides of the main gate have only one ground-level floor.


Required correction. Change the owning footprint/generator records to one occupied level plus the pitched roof. Rebuild walls and roof elevations; remove the extra floor, its windows and elevated entrances. Retain the real footprint unless evidence warrants a plan correction.

Colour rule. Use white walls with a wine/reddish base band matching the yellow-circled examples. Carry the base around returning faces. Keep roof colour separate; do not paint the full facade wine.

Acceptance. Inspect the full marked gate-adjacent stretch on both sides. Every in-scope low block is single-storey, has only the supported ground-level openings and shares the white/wine scheme. Do not apply this rule to the Law School or International House.

05 / Law School: main frontage

Picture 4 / image(10).png



Picture 5 / law_school_2_labeled.png




Observed mismatch. Picture 4 uses a straight glazed connecting entrance and a broad pale forecourt. Picture 5 shows a rounded projecting entrance, a curved upper glazing band, a tall framed glazed lower entry and broad shallow steps across the front.

Required change. Correct the entrance volume and facade before placing landscaping. Restore the curved frontage, actual glazing divisions, entrance frame/doors, broad stair apron and adjacent wing relationship. Do not replace the curved volume with another flat glass bridge.

Height caution. The game right-hand block shows several rows of identical dark openings. Real openings vary in size and position by level. Count occupied levels and opening bands from Pictures 5-6; do not confuse the row of tiny squares with a full repeated window floor.

06 / Law School: detail and site

Picture 6 / law_school_1_labeled.png



Picture 7 / law_school_layout_labeled.png



Entrance. Picture 6 shows a curved white/light-clad drum, continuous upper dark-blue glazing, lower tall glass bays with light/gold-toned frames, central doors and the LAW identity on the solid band. Model the curve and actual recesses.

Plan and landscape. Picture 7 shows a curved building end tied into roofed wings, an open paved approach and distinct dense tree crowns near the right/lower edges. Trace pavement and tree zones separately; do not fill the full forecourt with trees or grass.

Interpretation. Photographs establish facade details; satellite establishes plan/landscape positions. The labels, arrows and blue doorway outlines are annotations only. Exact step count and unseen landing geometry require closer originals or project evidence.

07 / Law School: strict build rules

Facade and cladding. Replace uniform beige walls with the observed light cream/tan panel finish and visible joint grid where shown. Retain white/light curved entry cladding and differing adjacent wing faces. Verify wall returns and opening positions against Pictures 5-6.

Windows and small openings. Preserve the upper recessed/ribbon-like opening zone, larger dark grid windows and lower row of much smaller square openings as different features. Do not stamp one identical window across all levels. Place local AC units only where supported.

Steps. Create the broad shallow front flight with a consistent riser/tread rhythm and continuous landing connected to the doors. Read the count from the original, not a reduced contact sheet. If partly hidden, mark the count provisional. Avoid a single vertical platform or steep decorative staircase.

Forecourt. Separate step/landing surface, paved approach, kerbs and planted edges. Use photograph appearance for surface finish and satellite footprint for coverage. Do not claim an exact paving product or colour code from these images.

Trees. Locate the canopy zones using Picture 7, then match their relation to entry approach in game. Keep the entrance and broad stairs visible. Tree planting must not replace the required staircase or conceal facade errors.

Acceptance views. Match Picture 5 front angle, Picture 6 close entry angle and Picture 7 overhead crop. Compare stair profile, curved projection, doorway width, mullion grid, wall divisions, roof junctions and tree/paving boundaries. A matching roof footprint alone is insufficient.

08 / Trees on the Bani-side stretch

Picture 8 / image(20261014-062313).png



Picture 9 / Screenshot 2026-10-12 213439.png



Observed mismatch. The game arrows identify the stretch to correct; the real street view shows a more continuous, varied cluster of roadside trees with lower foliage, natural trunk/crown shapes and dusty ground beneath. A few regularly spaced stylized trees do not reproduce this composition.

Required change. Register the same stretch before planting. Restore clusters and gaps, canopy overlap, lower shrubs/undergrowth and natural variation. Keep the roadside edge and sightlines open where the real view shows openings.

Evidence limit. Picture 9 records September 2024 Street View, while game/reference dates differ. Use its vegetation structure rather than copying traffic, people, every temporary billboard detail or a precise individual tree count.

09 / Bush corridor behind Bani

User-confirmed condition. Behind Bani Hostel toward Atomic, the intended environment is predominantly dense bush. Treat this as a separate vegetation region from the sparse foundation sites near International House/JQB.

Spatial boundary. Locate Bani, the rear edge of its grounds, existing routes and the Atomic direction in project map data. Build continuous irregular bush zones along that corridor; do not treat the whole campus as one uniform forest or cross the public road blindly.

Vegetation form. Use compact layered shrub masses, uneven heights, small scrub patches and occasional supported taller trees. Separate bush geometry from standalone tree assets; avoid endless tall trunks with large identical umbrella crowns.


Efficient rendering. Use low-poly volumetric bush chunks with shared foliage textures/materials and instancing where useful. Preserve irregular silhouettes close to the bicycle. One flat green polygon is insufficient at eye level; large continuous masses can replace hundreds of individual bushes.

Ground and clearance. Blend soil, patchy grass and scrub edges. Maintain verified paths, drainage and road clearance. Use simple collision where necessary; dense visual foliage must not create invisible bicycle traps.

Acceptance. Roadside Picture 8/9 comparisons show natural grouped foliage. A rear-of-Bani traverse shows predominantly bush toward Atomic, with route gaps intact. The foundation zones still retain their explicitly sparse planting and exposed concrete/soil.

10 / International House comparison

Picture 10 / image(20261014-062458).png



Picture 11 / international_programmes_office_1_labeled.png



Current defect. The game uses uniform large dark window rows, a small simplified entrance attachment and lawn/road strips around the facade. The real facade has a finer bay rhythm, recessed vertical strips, differing opening sizes, local AC units and a larger paved entrance/parking forecourt.

Required correction. Map the actual floor/bay pattern before modifying windows. Rebuild the entrance as the observed light triangular pediment/canopy with wine/brown semicircular inset and recessed lower entry. Restore facade-wide paving and the correct relation of lawn, approach and parking.

Floor rule. The references show ground level plus three upper occupied window levels on the clear frontage. Verify this count and the ground glazing height in the original images. The single-storey rule for gate/fire-service blocks does not apply here.

11 / International House: site finish

Picture 12 / international_programmes_office_2_labeled.png



Facade. White/light walls, long terracotta pitched roof, repeated vertical light piers/divisions and more varied framed window bays. Preserve visible curtains/panel variations as restrained material variation, not arbitrary new openings.

Entry and paving. Picture 12 corroborates the central pediment and curved dark/wine inset, ground-level glass band, paved forecourt and planting/island edges. Model depth and landing/access rather than placing a small black box in the lawn.

Landscape. Use the foreground lawn/planting geometry and paved extent supported by Pictures 11-12. Cars obscure portions of the ground: distinguish observed paving from hidden portions and avoid inventing exact bay stripes.


Acceptance. Compare both front angles and the game view. Verify bay counts, window proportions, blank strips, entrance width/projection, sign position, roof eaves, ground glazing and forecourt coverage. Do not copy the Law School's curved drum entrance onto this building.

12 / Fire-service environs: wrong height

Picture 13 / image(20261014-062710).png



Picture 14 / image(20261014-062714).png



Current defect. The circled game groups contain conspicuous two-level blocks with repeated dark/glass-like openings. The user confirms no two-storey buildings in this marked surrounding zone.

Required correction. Inventory the circled buildings behind, beside and around the Legon fire-service area, match them to Picture 15 and set each in-scope building to one ground-level occupied floor. Rebuild the low roof/wall relationship instead of just hiding upper windows.

Window requirement. Replace the erroneous generic glass appearance with wooden window/shutter construction appropriate to the user's correction. Do not apply modern curtain walls or large glossy blue panes to these low blocks.

Scope boundary. This rule covers the user-marked surrounding buildings, not every unrelated campus building or an unverified internal fire-service asset. Use the outlined area and matched footprints to determine the affected object IDs.

13 / Fire-service plan and wood detail

Picture 15 / Screenshot 2026-10-14 060823.png



Footprints. Trace the distinct roof patches, orientation, spacing, access lanes and courtyard/yard gaps. Keep small structures as separate assets. Do not convert the whole area into long uniform barracks merely because several roofs are aligned.


Height authority. The single-storey requirement comes from the user's explicit local knowledge. Satellite roof outlines establish plan, not reliable storey counts or exact pitch/height. Use conservative provisional dimensions until ground evidence is available.

Wooden openings. Model visible wooden panels, shutters or louvres with frame depth and restrained brown/painted-wood appearance as evidence permits. Exact colour and layout are not resolved by the satellite map; avoid inventing them. Preserve blank wall where unsupported.


Grounds and acceptance. Restore the irregular green/bare-soil balance and trees without covering roof silhouettes or access gaps. At overhead and bicycle level, the marked zone reads as low one-floor buildings with wooden openings; no extra upper facade tier remains.

14 / Replace the invented building

Picture 16 / image(20261014-063137).png



Picture 17 / Screenshot 2026-10-14 060951.png




Identity A. The blue outline/arrows in Picture 17 mark the unfinished site near International House/International Student Office. Picture 16 points to a completed-looking multi-level game block there. The user explicitly says this building does not exist as a completed structure.

Required replacement. Remove the invented upper walls, windows, doors and roof for that matched asset. Reconstruct exposed concrete foundation/slab/plinth strips following the actual map footprint, with open interior ground and vegetation where visible. Keep it low; do not create a new completed hall.

Protect neighbors. Keep International House, JQB and surrounding finished buildings. Do not confuse this blue-marked foundation with the separately red-marked Limbo Museum site, discussed next. Remove stale finished-building labels/colliders attached to the invented block.

15 / Foundation vegetation: two sites

Picture 18 / image(20261014-064015).png



Identity B: red site in Picture 17. The larger foundation labeled Limbo Museum is beside K. A. Busia Building and behind/near JQB. It is a separate exposed concrete site. The user says its surroundings are not uniformly covered in huge trees; most growth is short shrubs and only a minority is taller.

Blue circle in Picture 18. Replace the excessive large-tree wall with a spatial mix of low shrubs, scattered modest-height vegetation, a small minority of taller plants, exposed foundation surfaces and open soil/grass. Preserve the concrete outline and internal voids visible in Picture 17.

Red circle in Picture 18. The user accepts the approximate height of these front-of-foundation clumps near site A but identifies them as bushes. Keep their approximate visual height while changing tree-like trunk/crown construction into dense bush masses as needed.

Do not merge conditions. Dense bushes behind Bani toward Atomic are a different instruction. They do not justify a forest around either foundation. Register each plant region to the appropriate marked site before changing it.


Acceptance. Overhead comparison reveals the foundations and open soil/grass patches. Eye-level view has mostly short shrubs at site B and bush-shaped clumps at the red Picture 18 area, with no continuous wall of giant trunks hiding the sites.

16 / Road behind JQB: target route

Picture 19 / image(20261014-064213).png



Picture 20 / image(20261014-064545).png



Route identity. Picture 19 identifies the road behind JQB; Picture 20 marks the route in red. The blue and green lines communicate travel direction and relative slope along that route, not independent new roads to add.

Required vertical sequence. From Evandy/Pent/Engineering toward the Law School: ascend along the blue-arrow section, transition through a rounded crest in the gap between arrows, then descend from the unfinished-building/International House vicinity along the green-arrow section toward the main-road junction.

Existing work. The user thinks the ascent may already be correct. Inspect its current height profile and preserve verified portions. The principal correction is the descent start, direction, continuity and meeting elevation at the main road.

17 / Hill profile: implementation

Register route stations. Trace the actual red centerline in Picture 20 using project road IDs; identify approach, Law School crest zone, unfinished-site descent start and green-arrow end junction. Use station distance s along the path, not screenshot pixel Y or a guessed global axis.

Record baseline heights. Sample existing road and terrain height along the centerline and road edges. Mark the blue-arrow ascent, inter-arrow crest transition and green-arrow descent in a station/elevation plot. This distinguishes an existing correct incline from the faulty descent.

Ascent and crest. The blue section increases in height along travel direction. Reduce the positive gradient smoothly to a near-level rounded crest through the inter-arrow space. The user's semicircle analogy specifies a smooth top transition, not an exact circular road plan or numerical arc.

Descent. From the unfinished-site/International House vicinity, decrease height continuously in the green-arrow direction until the road meets the main road at the junction's actual scene height. Do not descend on the wrong side, stay flat behind JQB or introduce a second crest without evidence.

Smooth interpolation. Use a constrained spline or monotone smoothstep segments with matched endpoint slopes. Prevent overshoot, sudden grade reversals and a sharp apex. Keep the rise, crest length and drop configurable; no measured elevations, gradients or exact metres are supplied.

Whole cross-section. Update road mesh, terrain beneath it, shoulders, pavements, kerbs, drains, junction transitions and collider together. Blend adjacent ground instead of leaving floating asphalt, vertical soil walls or a flat collision plane under a sloped visual road.

Acceptance. Plot shows positive grade on ascent, a smooth near-level transition and negative grade on descent, ending at the main-road elevation. Ride both directions across the crest and junction; verify bicycle contact, camera continuity and absence of bumps, holes or collider discontinuities.

18 / Edit order and regression checks

1 / Audit. Resolve object IDs and owning generators for all marked assets/regions. Save matching camera positions, overhead views, opening counts and road heights. Change source data when procedural generation would overwrite scene patches.

2 / Correct factual geometry. Make gate-side/fire-service in-scope buildings single-storey; replace the blue-marked invented block with foundation A; preserve separate foundation B. Correct Law School and International House entry/facade masses using the feature ledger.

3 / Correct materials and detail. Split white exterior/black interior surfaces on Picture 1. Add white/wine gate bands and wooden fire-zone openings. Place confirmed partitions, pillars, doors and windows individually; correct roofs and paving.

4 / Correct vegetation. Use registered region boundaries: roadside clusters, dense Bani-to-Atomic bush corridor, Law School edge trees, International House plantings and sparse short-shrub foundation environments. Avoid one global vegetation preset.

5 / Correct road grade. Preserve verified ascent, construct smooth crest and green-arrow descent, fit the main-road junction and conform terrain/collision. Recheck nearby paths and foundation elevations after terrain changes.

6 / Prove the result. Capture every marked game view against the matching reference, plus original-resolution facade crops. Submit road station/height plot and a real route test log. Do not claim in-game tests from static images.

Regression. Reload/regenerate the scene to confirm fixes persist. Verify no duplicate meshes, stale building labels, extra roof/window tiers, floating objects, mismatched terrain collisions or vegetation overgrowth. Measure rendering cost along the same route before/after.

19 / Consolidated Claude prompt: 1/3

Task and authority. Implement the corrections in this entire 20-picture brief in LEGONRUSH. Treat all detailed sections and the compulsory close-inspection protocol as part of this prompt. Use the exact picture-to-file index; keep user markings and corrected site identities distinct.

Mandatory first action. Inspect original images, register each building face, create annotated close-up crops and a floor/bay feature ledger. Map pillars, wall partitions, blank spans, windows, doors, opening states and roof junctions before placing them. No invented openings or generic repeated facades.

Pictures 1-3. Change only the marked structure's exterior to white and its actual interior to black using separate surfaces/material slots. Make all in-scope buildings along both marked main-gate stretches single-storey with white walls and wine/reddish bases matching the yellow examples. Remove the extra structural/window tier and rebuild roofs at correct height.

Pictures 4-7. Correct the School of Law using the real rounded projecting entrance, upper curved glazing, tall lower framed glass entry, actual adjacent-wing opening bands, broad shallow front stair flight, landings, paving and mapped tree edges. Count detail from full-resolution images; do not paint a curved entry onto a flat box.

Pictures 8-9 and Bani rear. Restore the indicated roadside tree/shrub composition with natural groups, overlap and ground texture. Behind Bani toward Atomic, add predominantly dense irregular bush zones while preserving routes. Use efficient volumetric bush assets rather than hundreds of unnecessary individual trees.

Scope. These are local corrections. The single-storey rule does not apply to the Law School or International House. Do not import Evandy/Bani/other-hall facade modules where the references differ.

20 / Consolidated Claude prompt: 2/3

Pictures 10-12. Rebuild International House / International Programmes Office facade divisions and real window rhythm from the originals. Match ground-plus-three-upper-level frontage, entrance pediment with curved wine/dark inset, recessed doors, roof, local AC details and the substantial paved forecourt/planting relationship.

Pictures 13-15. Within the user-marked fire-service surrounding zone, replace all incorrect two-storey blocks with single-storey buildings and wooden window/shutter construction. Trace actual distinct roof patches and access gaps. Satellite supports footprint; single-storey authority is the user's statement, not a fabricated height measurement.

Pictures 16-17: foundation A. Remove the invented completed multi-level building at the blue-marked unfinished site beside International House. Model the low exposed foundation footprint with visible concrete strips/slab/plinth and open ground. Remove stale upper-floor colliders/labels; protect International House and JQB.

Pictures 17-18: foundation B. Treat the red-marked Limbo Museum foundation beside K. A. Busia/behind JQB as a separate site. Remove the excessive giant-tree coverage; reproduce exposed concrete, open soil/grass, mostly short shrubs and only a minority of taller vegetation.

Picture 18 red-circle bushes. Keep the approximate accepted height of front-of-foundation A clumps, but make them bushes rather than trunk-and-crown trees. Do not misapply the dense Bani-to-Atomic vegetation instruction to either foundation.

Evidence discipline. Do not infer exact hidden openings, wood paint colour, storey heights, tree heights or roof pitch from satellite alone. Mark uncertain details explicitly. Every source-supported exception to repetition must be retained.

21 / Consolidated Claude prompt: 3/3

Pictures 19-20: road grade. Register the red route behind JQB. Preserve a verified uphill approach from Evandy/Pent/Engineering in the blue-arrow direction toward Law School; form a smooth rounded crest in the inter-arrow space; descend starting near the unfinished-site/International House section in the green-arrow direction to the main road. No literal semicircular path is required.

Terrain and physics. Sample and plot existing/final road station heights. Use smooth monotone grade segments with a continuous crest transition and correct junction elevation. Update road, terrain, pavements, kerbs, drainage and bicycle collision together. Do not use unmeasured exact gradients or solve descent by floating the road above terrain.

Required visual evidence. Submit matching game views for all correction groups, annotated source close-ups, feature ledger and reference/render comparisons. Audit each documented facade floor/bay for counts, order, positions, blank spans, partitions, recesses and roof breaks.

Required technical evidence. List modified files/object IDs/generator settings. Supply the baseline/final grade plot, collision/route checks in both directions, persistence after reload/regeneration and comparable performance measurements. State actual tests run; do not invent testing.

Rejection criteria. Fail and correct any wrong-floor pillar, unsupported opening, missing wall partition, wrong entrance, extra low-zone storey, completed building on foundation A, merged foundation identities, huge-tree blanket on foundation B or wrong/abrupt descent. Re-render and recheck before marking that area complete.

Completion. Provide a concise discrepancy/fix log and unresolved-assumption list. Every verified zone must have zero known unexplained placement errors. Obscured areas remain provisional; do not claim a perfect whole-campus match from these 20 pictures alone.