Okponglo entrance correction audit

Restore the missing University of Ghana Okponglo gatehouse, paved taxi parking and source-backed roadside environment in LEGONRUSH. Remove or relocate additions that occupy confirmed open ground, while retaining real buildings and the separate bare-earth plot.

This document combines eight still-image pairs, two satellite maps and the four previously supplied videos. The eight still pairs remain numbered exactly as uploaded: game first and real second. Video comparisons use separate VF numbers, so they do not overwrite the still-pair numbering.

The most consequential errors are the missing gatehouse in Pair 2, grass replacing asphalt in Pair 3, and unsupported kiosk/water/shelter treatment beside the road in Pairs 6 to 8. The stadium perimeter, sidewalks, drains and tree islands also need coordinated correction.

Evidence	Count	Use
Still comparisons	8 pairs	S01 to S16 in upload order
Satellite maps	2	M1 first supplied map and M2 Google view
Video Pair 1	8 game and 12 real frames	Stadium frontage toward gate
Video Pair 2	17 game and 13 real frames	Parking and trees toward gate
Correction register	16 IDs	Add remove replace or verify by evidence

This is an implementation brief for Claude, not a claim that this chat changed or tested the game. Dimensions are provisional until registered to project coordinates; concealed openings and unreadable signs remain unresolved.

Source dates and physical registration

M1 labels the common approach Jubilee Drive; M2 labels it Academic Freedom Road. Align the same road by gate, stadium and junction rather than renaming the project based on this label difference. M2 has a visible compass; use actual project axes to register the geometry.

S08 and S10 show September 2024 Street View. S12 and S14 show February 2016. S16 belongs to the corresponding bare-plot view family, although its crop does not independently display the date. The uploaded phone videos and current photos are the strongest supplied evidence for present gate and parking appearance. Capture dates of the satellite imagery are not established.

Do not combine all reference seasons into one uniform surface. The maps distinguish paved taxi parking from adjacent rough land. Use the current photo/video for the asphalt lot; use the older ground targets together with the maps for the supported bare plot. Reconcile location first, then chronology.

Establish four anchors: the gate roof spanning the approach, north-side paved taxi parking, curved stadium perimeter to the south, and the external main-road junction. Record a single rotation, translation and scale before moving objects. Register each structure footprint and view direction; camera perspective is not a building-size measurement.

Mandatory existence ledger: object ID; world footprint; source; add/remove/retain/verify decision; confidence; collider owner. A building missing from one cropped photo is not enough evidence to delete it. A source-backed empty footprint across several views and a map is stronger evidence.

The in-game HUD still displays a UGMC tour destination. That label is a capture overlay, not evidence that these images depict UGMC. Preserve the user-assigned Okponglo location and the supplied pair order.


Map 1 and correction zones



1 Gate roof spanning the road. 2 Paved north-side parking/taxi area. 3 Curved stadium and adjacent parking. 4 Bare tracks and scrub plot, distinct from asphalt. 5 External junction. 6 New University Road connection. Annotation IDs are location references, not game object numbers.

The gate and small red-roof parking pavilion both exist in the references. Add their actual forms; do not delete them because the game shows a green kiosk elsewhere. No water feature is established within this mapped correction plot.

Map 2 and existence decisions



7 Gate. 8 Asphalt parking and small red-roof pavilion. 9 Rough plot/track labeled Legon Taxi Station in the map. 10 Stadium-side road and parking edge. The taxi label is not a precise paving boundary; trace actual surfaces and the current ground evidence.

Remove or relocate only unsupported local additions: green kiosk at the photographed empty verge, blue shelters in unverified locations, and water overlapping dry mapped land. Retain the stadium, real pavilion and legitimate buildings outside the crop. Record uncertain background structures for a coordinates check.

Still image source register

Still pair	Game first	Real second
1	image(20261014-224606).png	image(20261014-224615).png
2	image(20261014-224652).png	image(20261014-224700).png
3	image(20261014-224713).png	image(20261014-224727).png
4	image(20261014-224756).png	image(20261014-224809).png
5	image(20261014-224846).png	image(20261014-224856).png
6	image(20261014-224903).png	image(20261014-224914).png
7	image(20261014-224927).png	image(20261014-224932).png
8	image(20261014-224941).png	image(20261014-224954).png

M1: Screenshot 2026-10-14 223007.png. M2: Screenshot 2026-10-14 223049.png. Original files and annotations are preserved. Pair 2 uses S03 game and S04 real: the user's Picture 4 is the real gatehouse target.

Video sources and extraction register

Video pair	Game source	Real source
1	bandicam 2026-10-14 22-14-28-475_exported.mp4	IMG_6889.MP4
2	bandicam 2026-10-14 22-17-41-461_exported.mp4	IMG_6890.MP4

G001 to G025 refer to the existing extracted game sequence, ordered first by Video Pair 1 then Video Pair 2. R001 to R025 similarly identify real frames. Times reset within each source clip. Screenshot numbers across videos are not synchronized.

Game frames are 1920 x 1080. Real video frames are 464 x 848 portrait; closer S02/S04/S06 stills have more detail. No generative enhancement or invented hidden information was used. Vehicles, people, foliage and low sun occlude parts of the architecture.

Video frame index 1

ID and video pair	Original filename	Timestamp
G001 VP1	Okponglo_Pair1_Game_001_00m00s027ms.png	00:00.027
G002 VP1	Okponglo_Pair1_Game_002_00m00s527ms.png	00:00.527
G003 VP1	Okponglo_Pair1_Game_003_00m01s027ms.png	00:01.027
G004 VP1	Okponglo_Pair1_Game_004_00m01s527ms.png	00:01.527
G005 VP1	Okponglo_Pair1_Game_005_00m02s027ms.png	00:02.027
G006 VP1	Okponglo_Pair1_Game_006_00m02s527ms.png	00:02.527
G007 VP1	Okponglo_Pair1_Game_007_00m03s027ms.png	00:03.027
G008 VP1	Okponglo_Pair1_Game_008_00m07s193ms.png	00:07.193
G009 VP2	Okponglo_Pair2_Game_001_00m00s008ms.png	00:00.008
G010 VP2	Okponglo_Pair2_Game_002_00m01s508ms.png	00:01.508
G011 VP2	Okponglo_Pair2_Game_003_00m02s008ms.png	00:02.008
G012 VP2	Okponglo_Pair2_Game_004_00m02s508ms.png	00:02.508
G013 VP2	Okponglo_Pair2_Game_005_00m03s008ms.png	00:03.008
G014 VP2	Okponglo_Pair2_Game_006_00m03s508ms.png	00:03.508
G015 VP2	Okponglo_Pair2_Game_007_00m04s008ms.png	00:04.008

Video frame index 2

ID and video pair	Original filename	Timestamp
G016 VP2	Okponglo_Pair2_Game_008_00m04s508ms.png	00:04.508
G017 VP2	Okponglo_Pair2_Game_009_00m05s008ms.png	00:05.008
G018 VP2	Okponglo_Pair2_Game_010_00m05s508ms.png	00:05.508
G019 VP2	Okponglo_Pair2_Game_011_00m06s008ms.png	00:06.008
G020 VP2	Okponglo_Pair2_Game_012_00m06s508ms.png	00:06.508
G021 VP2	Okponglo_Pair2_Game_013_00m07s008ms.png	00:07.008
G022 VP2	Okponglo_Pair2_Game_014_00m07s508ms.png	00:07.508
G023 VP2	Okponglo_Pair2_Game_015_00m08s008ms.png	00:08.008
G024 VP2	Okponglo_Pair2_Game_016_00m09s008ms.png	00:09.008
G025 VP2	Okponglo_Pair2_Game_017_00m10s475ms.png	00:10.475
R001 VP1	Okponglo_Pair1_Real_001_00m00s.png	00:00.000
R002 VP1	Okponglo_Pair1_Real_002_00m00s500ms.png	00:00.500
R003 VP1	Okponglo_Pair1_Real_003_00m01s.png	00:01.000
R004 VP1	Okponglo_Pair1_Real_004_00m01s500ms.png	00:01.500
R005 VP1	Okponglo_Pair1_Real_005_00m02s.png	00:02.000

Video frame index 3


ID and video pair	Original filename	Timestamp
R006 VP1	Okponglo_Pair1_Real_006_00m02s500ms.png	00:02.500
R007 VP1	Okponglo_Pair1_Real_007_00m03s.png	00:03.000
R008 VP1	Okponglo_Pair1_Real_008_00m03s500ms.png	00:03.500
R009 VP1	Okponglo_Pair1_Real_009_00m04s.png	00:04.000
R010 VP1	Okponglo_Pair1_Real_010_00m04s500ms.png	00:04.500
R011 VP1	Okponglo_Pair1_Real_011_00m05s.png	00:05.000
R012 VP1	Okponglo_Pair1_Real_012_00m05s533ms.png	00:05.533
R013 VP2	Okponglo_Pair2_Real_001_00m00s.png	00:00.000
R014 VP2	Okponglo_Pair2_Real_002_00m00s500ms.png	00:00.500
R015 VP2	Okponglo_Pair2_Real_003_00m01s.png	00:01.000
R016 VP2	Okponglo_Pair2_Real_004_00m01s500ms.png	00:01.500
R017 VP2	Okponglo_Pair2_Real_005_00m02s.png	00:02.000
R018 VP2	Okponglo_Pair2_Real_006_00m02s500ms.png	00:02.500
R019 VP2	Okponglo_Pair2_Real_007_00m03s.png	00:03.000
R020 VP2	Okponglo_Pair2_Real_008_00m03s500ms.png	00:03.500

Video frame index 4

ID and video pair	Original filename	Timestamp
R021 VP2	Okponglo_Pair2_Real_009_00m04s.png	00:04.000
R022 VP2	Okponglo_Pair2_Real_010_00m04s500ms.png	00:04.500
R023 VP2	Okponglo_Pair2_Real_011_00m05s.png	00:05.000
R024 VP2	Okponglo_Pair2_Real_012_00m05s500ms.png	00:05.500
R025 VP2	Okponglo_Pair2_Real_013_00m05s800ms.png	00:05.800


Pair 1 Stadium edge footway and drain

IN GAME VIEW



S01 image(20261014-224606).png

REAL WORLD REFERENCE



S02 image(20261014-224615).png

A View identification Stadium edge footway and drain. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game places the rider on lawn opposite the stadium with repeated palms, black/white kerbs and a dark rectangular lower-facade grid.

C Real target The current real view includes the red/gray striped stadium, a separate metal fence, planted verge, tan block-paved sidewalks, asphalt and a concrete drainage channel with a slotted crossing at the near edge.

D Corrections Replace the grass-only foreground with the actual footway/drain relationship. Correct the stadium base and fence separately. Preserve the main curved stadium silhouette; use the mapped footprint to calibrate setback rather than scaling from this tilted portrait photo. Issues: OKP-001, OKP-008, OKP-009, OKP-010, OKP-011, OKP-012, OKP-013.

E Detail inspection Use the enlarged numbered detail plates and original S01/S02 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance At ground level the sidewalk, channel, crossing slab, fence and lower structure are independently readable; the bicycle path uses supported cover geometry.

G Cross view check Video Pair 1 stadium sector and Still Pairs 4 and 5 confirm the approach edge.

Pair 2 Missing Okponglo gatehouse

IN GAME VIEW



S03 image(20261014-224652).png

REAL WORLD REFERENCE



S04 image(20261014-224700).png

A View identification Missing Okponglo gatehouse. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game approach has grass, generic poles and a distant parking rectangle; the recognizable gatehouse is absent from the expected road alignment.

C Real target The real target has a long white gatehouse with red/wine base, brown/red tile roof, tall open portal, side rooms, circular grille opening, decorative upper grilles, central display and barrier context.

D Corrections Add the complete gatehouse at its mapped road-spanning footprint. The vehicle opening must remain empty. Match pillars and room walls rather than extruding a solid wall; rebuild the paving/drain crossing beside it. Audit distant objects only after registration. Issues: OKP-001, OKP-008, OKP-009, OKP-010, OKP-012, OKP-016.

E Detail inspection Use the enlarged numbered detail plates and original S03/S04 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance The gate can be identified from the stadium-side approach and passed through without columns or invisible colliders blocking the lane.

G Cross view check Still Pairs 4 and 5 show the gate at the end of the approach; both real videos expose its side context.


Pair 3 Paved taxi lot and open waiting pavilion

IN GAME VIEW



S05 image(20261014-224713).png

REAL WORLD REFERENCE



S06 image(20261014-224727).png

A View identification Paved taxi lot and open waiting pavilion. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game represents the corresponding foreground as lawn with a diagonal tan strip, blue waiting shelters, water and generic trees.

C Real target The current target is an asphalt taxi lot with white bay lines and a broad clear aisle. A modest red-roof open pavilion sits at the far edge, with mature broadleaf trees around the lot.

D Corrections Restore the taxi parking footprint from the maps. Remove the lawn and diagonal path only within that paved boundary. Add bay/aisle geometry, curbed tree islands and the red-roof pavilion. Remove unsupported blue shelters/water within the correction plot. Issues: OKP-002, OKP-005, OKP-006, OKP-008, OKP-009, OKP-014, OKP-015, OKP-016.

E Detail inspection Use the enlarged numbered detail plates and original S05/S06 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance The same parking footprint and aisle relationships work in the current photo, Video Pair 2 and overhead registration.

G Cross view check Still Pairs 6 to 8 address the adjoining bare plot; do not confuse it with this paved lot.

Pair 4 Approach corridor and absent landmark

IN GAME VIEW



S07 image(20261014-224756).png

REAL WORLD REFERENCE



S08 image(20261014-224809).png

A View identification Approach corridor and absent landmark. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game A clean wide game road with two dash rows leads toward generic distant scenery; green kiosk and blue shelters line a mostly empty lawn verge.

C Real target The 2024 target has a gatehouse at the approach end, stadium fence at one side, continuous sidewalks, mixed planting, distinct lamps and a large billboard.

D Corrections Build the missing gate, register carriageway/sidewalk bends and restore the supported roadside enclosure. Remove unsupported kiosk/shelters from the mapped local verge. Treat billboard artwork as date-sensitive; keep its placement separate from permanent architecture. Issues: OKP-001, OKP-004, OKP-005, OKP-008, OKP-009, OKP-011, OKP-012, OKP-013.

E Detail inspection Use the enlarged numbered detail plates and original S07/S08 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance Matched approach shows the gate in the correct sightline, sidewalk continuity and appropriate verge/fence; no invented lane count.

G Cross view check Pair 5 is the same corridor from an adjacent view, not a second road or second gate.


Pair 5 Adjacent approach view and roadside details

IN GAME VIEW



S09 image(20261014-224846).png

REAL WORLD REFERENCE



S10 image(20261014-224856).png

A View identification Adjacent approach view and roadside details. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game repeats the same lawn/kiosk/shuttle arrangement and clean lane markings as Pair 4.

C Real target The adjacent 2024 view shows the same gate, fencing, sidewalk and roadside billboard/sign context with a different traffic pattern.

D Corrections Reuse the same issue IDs and objects as Pair 4. Cross-check curb and pavement on both sides, gate setback and foliage silhouette. Cars are temporary evidence of road scale, not a mandatory fixed parking arrangement. Issues: OKP-001, OKP-004, OKP-005, OKP-008, OKP-009, OKP-011, OKP-012, OKP-013.

E Detail inspection Use the enlarged numbered detail plates and original S09/S10 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance Corrections align in both approach views; there is one gate and one coherent corridor.

G Cross view check Pair 4 and current gate close-up Pair 2 supply the matching landmark and material detail.

Pair 6 Bare plot behind the roadside kiosk

IN GAME VIEW



S11 image(20261014-224903).png

REAL WORLD REFERENCE



S12 image(20261014-224914).png

A View identification Bare plot behind the roadside kiosk. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game shows a green kiosk, manicured grass, a blue water patch, dense rounded vegetation and large background buildings.

C Real target The dated 2016 target shows an irregular bare-earth verge/track, dry raised tree patch, broadleaf trunks and parked vehicles farther back; pavers run along the road.

D Corrections Remove the source-unsupported kiosk from the registered verge. Restore the rough plot surfaces and localized tree group, checking the maps against this older ground image. Audit water/shelters and distant buildings by footprint; never remove all distant buildings. Issues: OKP-003, OKP-004, OKP-005, OKP-006, OKP-007, OKP-009, OKP-012, OKP-016.

E Detail inspection Use the enlarged numbered detail plates and original S11/S12 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance No kiosk blocks the confirmed open plot; soil and scrub remain separate from the current asphalt taxi lot.

G Cross view check Pairs 7 and 8 turn across the same plot; maps support the split between bare land and paved parking.

Pair 7 Side view of bare access track and trees

IN GAME VIEW



S13 image(20261014-224927).png

REAL WORLD REFERENCE



S14 image(20261014-224932).png

A View identification Side view of bare access track and trees. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game replaces the open dirt edge with lawn, dense tree/bush mass and water; the green kiosk remains at the edge.

C Real target The 2016 target shows a broad reddish/tan track, uneven dry ground, a localized tree cluster and foreground paving/cover slabs.

D Corrections Trace the bare access route and modest raised planting patch in plan; match visible trunk gaps and canopy outline. Remove grass/water overlays from the confirmed dry ground and keep the roadside footway clear. Issues: OKP-003, OKP-004, OKP-006, OKP-007, OKP-009, OKP-012.

E Detail inspection Use the enlarged numbered detail plates and original S13/S14 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance The access track remains visibly open from this angle and Pair 8; there is no invented asphalt parking across the bare track.

G Cross view check Pair 6 identifies the same tree group from farther around the road; current maps limit the correction footprint.

Pair 8 Unsupported kiosk and shelters on open land

IN GAME VIEW



S15 image(20261014-224941).png

REAL WORLD REFERENCE



S16 image(20261014-224954).png

A View identification Unsupported kiosk and shelters on open land. Match by the gate, stadium, parking or tree group, not by the mini-map/HUD destination.

B Current game The game prominently places a green box and blue shuttle stop at the verge, with broad lawn and water behind.

C Real target The real target shows an open soil verge/track, a slim sign frame, localized trees, roadside lamp and paver sidewalk. No matching green kiosk occupies this photographed location.


D Corrections Remove the unsupported kiosk and audit the shuttle stop footprint. Restore the bare plot, correct sidewalk and site boundary. Preserve only supported sign/lamp furniture; its exact text is unreadable. Issues: OKP-003, OKP-004, OKP-005, OKP-006, OKP-007, OKP-009, OKP-012.

E Detail inspection Use the enlarged numbered detail plates and original S15/S16 sources. Keep game-left and real-right; do not stretch a portrait photograph to match the game frame.

F Acceptance The real empty-space relationships are restored without planting or new structures closing the bare route.

G Cross view check Use Pairs 6 and 7 and both maps for the same objects; source date and occlusion limits remain explicit.

Detail plate 1 Gatehouse form and openings



11 Brown/red tiled pitched roof with broad eaves; do not use a flat slab. 12 Tall vehicle portal and supported overhead beam; passage remains open. 13 Side-room wall with circular grille and other visible barred openings. 14 Thin portal uprights and side open bays. 15 Red/wine wall base, barrier and adjacent paver margin.

Create a facade ledger: roof edge, upper decorative grille panels, central LED/display rectangle, portal beam, individual support rows, circular opening, side doors/windows, base paint and plaques. Each is a separate observed feature. Decorative upper grilles are not ordinary room windows.

Match support width/depth and actual position from both real videos and S04. Do not put intermediate supports across the vehicle lane or fill the right-side open bays with wall. Hidden support counts must remain provisional until a second view verifies them.

Detail plate 2 Gate display and side room



16 Central rectangular display attached above the main portal. 17 Rectangular decorative grille panels above, and circular barred opening in the left side wall. 18 Visible dark barred side-room opening and pale wall face. Read these separately; do not create generic glazing in every panel.

Keep the side-room exterior white and the supported lower band reddish/wine. Apparent darkness inside the portal comes from recess/shadow, not a reason to paint the external wall black. Plaques and screen content are only copied where readable; do not invent their words.

Exact roof pitch, internal room layout and all far-side windows cannot be measured from this crop. Parameterize the portal width/height using project scale and compare its proportions to the roof and side rooms before adding fine details.

Detail plate 3 Footway drain and cover




19 Tan/brown interlocking footway. 20 Concrete-sided open channel with lower rough grass/soil. 21 Concrete cover/crossing at the edge, with supported slots/joints. The cover is not a staircase and the open channel is not an asphalt lane.

Model the sidewalk datum, channel edges and crossing as coordinated geometry. Keep the actual top of the crossing flush enough for the game route; ground level below the cover remains lower. Slots can be small-detail geometry or texture where appropriate, but an open channel needs real depth.

S04 and the real videos confirm the gate-side cover relationship. Do not repeat one drain shape on every roadside segment or cut a deep channel through the gate carriageway without evidence.

Detail plate 4 Parking and pavilion



22 Low red-roof open pavilion at the lot edge. 23 White bay line on asphalt, distinct from lawn. 24 Wide drive aisle with cars used only for scale. Parking tree islands and curbs are additionally shown in Video Pair 2.

Trace the real asphalt lot and position the pavilion using its roof footprint in both maps. Build open posts/roof rather than a solid generic house. Do not put the pavilion in the gate portal or use the green kiosk as its replacement.

Keep the bare-earth plot adjoining this parking lot distinct. New asphalt is limited to the source-backed paved polygon; do not spread it across every place where taxis appear in older Street View.

Detail plate 5 Bare plot and unsupported additions

IN GAME VIEW



Game green kiosk shuttle shelter and water

REAL WORLD REFERENCE



Real open soil verge track and localized trees




25 Broadleaf tree group with visible trunk spacing over rough raised ground. 26 Bare reddish/tan access area. 27 Paved footway and drain-cover strip at the roadside. Remove source-unsupported structures only after confirming their world footprint within this view.

Do not carpet this plot with green grass, plant a continuous wall of ball-shaped bushes or leave water under the corrected soil. Retain supported open gaps and minor scrub. Date differences affect vegetation density; permanent tracks and object locations must still be registered.


Detail plate 6 Stadium fence and cladding

IN GAME VIEW




Game lower black rectangle grid

REAL WORLD REFERENCE



Real separate fence planted verge and stadium




28 Red/gray/off-white vertical stadium cladding, not a uniform red-white-only stripe preset. 29 Independent light metal fence and visible stadium base behind it. 30 Planted roadside strip. Preserve athlete silhouettes but calibrate their placement and size to the facade.

Floodlight masts belong to the stadium lighting system; ordinary slim road lamps are different objects. Use the map and real image to establish setback and base position before changing the stadium dimensions. Do not infer the entire lower interior from dark distant pixels.


VF 1 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_001_00m00s027ms.png 00:00.027

REAL WORLD REFERENCE



Okponglo_Pair1_Real_001_00m00s.png 00:00.000


Match and corrections Stadium frontage correspondence with a different camera height/framing. Check fence/base, sidewalks, drainage, plant verges and distinct lamp types. Related still Pair 1; OKP-008 to 013. S02 is the stronger material/detail reference.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 2 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_002_00m00s527ms.png 00:00.527

REAL WORLD REFERENCE



Okponglo_Pair1_Real_003_00m01s.png 00:01.000


Match and corrections Stadium frontage correspondence with a different camera height/framing. Check fence/base, sidewalks, drainage, plant verges and distinct lamp types. Related still Pair 1; OKP-008 to 013. S02 is the stronger material/detail reference.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 3 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_003_00m01s027ms.png 00:01.027

REAL WORLD REFERENCE



Okponglo_Pair1_Real_004_00m01s500ms.png 00:01.500


Match and corrections Stadium frontage correspondence with a different camera height/framing. Check fence/base, sidewalks, drainage, plant verges and distinct lamp types. Related still Pair 1; OKP-008 to 013. S02 is the stronger material/detail reference.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.

VF 4 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_004_00m01s527ms.png 00:01.527

REAL WORLD REFERENCE



Okponglo_Pair1_Real_005_00m02s.png 00:02.000


Match and corrections Stadium frontage correspondence with a different camera height/framing. Check fence/base, sidewalks, drainage, plant verges and distinct lamp types. Related still Pair 1; OKP-008 to 013. S02 is the stronger material/detail reference.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 5 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_005_00m02s027ms.png 00:02.027

REAL WORLD REFERENCE



Okponglo_Pair1_Real_009_00m04s.png 00:04.000


Match and corrections Road-to-gate direction support, not a synchronized gate-face match. The gatehouse is absent from the expected game approach. Use S04 and map anchors to insert its footprint and reconnect paving/drain covers. Related still Pair 2; OKP-001/009/010/012.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 6 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_006_00m02s527ms.png 00:02.527

REAL WORLD REFERENCE



Okponglo_Pair1_Real_010_00m04s500ms.png 00:04.500


Match and corrections Road-to-gate direction support, not a synchronized gate-face match. The gatehouse is absent from the expected game approach. Use S04 and map anchors to insert its footprint and reconnect paving/drain covers. Related still Pair 2; OKP-001/009/010/012.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 7 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_007_00m03s027ms.png 00:03.027

REAL WORLD REFERENCE



Okponglo_Pair1_Real_011_00m05s.png 00:05.000


Match and corrections Road-to-gate direction support, not a synchronized gate-face match. The gatehouse is absent from the expected game approach. Use S04 and map anchors to insert its footprint and reconnect paving/drain covers. Related still Pair 2; OKP-001/009/010/012.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 8 Video Pair 1

IN GAME VIEW



Okponglo_Pair1_Game_008_00m07s193ms.png 00:07.193

REAL WORLD REFERENCE



Okponglo_Pair1_Real_012_00m05s533ms.png 00:05.533

Match and corrections Road-to-gate direction support, not a synchronized gate-face match. The gatehouse is absent from the expected game approach. Use S04 and map anchors to insert its footprint and reconnect paving/drain covers. Related still Pair 2; OKP-001/009/010/012.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 9 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_001_00m00s008ms.png 00:00.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_001_00m00s.png 00:00.000

Match and corrections Current parking-area sector with different framing. The game lawn/tan path must become the registered asphalt parking lot with clear bays, curbed tree islands and the source-backed red-roof pavilion. Related still Pair 3; OKP-002/014/015. Temporary people/cars do not define permanent geometry.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 10 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_002_00m01s508ms.png 00:01.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_002_00m00s500ms.png 00:00.500

Match and corrections Current parking-area sector with different framing. The game lawn/tan path must become the registered asphalt parking lot with clear bays, curbed tree islands and the source-backed red-roof pavilion. Related still Pair 3; OKP-002/014/015. Temporary people/cars do not define permanent geometry.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 11 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_003_00m02s008ms.png 00:02.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_003_00m01s.png 00:01.000


Match and corrections Current parking-area sector with different framing. The game lawn/tan path must become the registered asphalt parking lot with clear bays, curbed tree islands and the source-backed red-roof pavilion. Related still Pair 3; OKP-002/014/015. Temporary people/cars do not define permanent geometry.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 12 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_004_00m02s508ms.png 00:02.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_004_00m01s500ms.png 00:01.500

Match and corrections Current parking-area sector with different framing. The game lawn/tan path must become the registered asphalt parking lot with clear bays, curbed tree islands and the source-backed red-roof pavilion. Related still Pair 3; OKP-002/014/015. Temporary people/cars do not define permanent geometry.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 13 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_005_00m03s008ms.png 00:03.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 14 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_006_00m03s508ms.png 00:03.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_006_00m02s500ms.png 00:02.500


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 15 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_007_00m04s008ms.png 00:04.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000

Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 16 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_008_00m04s508ms.png 00:04.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 17 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_009_00m05s008ms.png 00:05.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 18 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_010_00m05s508ms.png 00:05.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 19 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_011_00m06s008ms.png 00:06.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 20 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_012_00m06s508ms.png 00:06.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 21 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_013_00m07s008ms.png 00:07.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_005_00m02s.png 00:02.000


Match and corrections Partial directional support within Video Pair 2. The real trees obscure parts of the stadium/road, so this is not a full unobstructed architectural match. Use S02 for the stadium and M1/M2 for relative position. Check parking boundary, tree-island geometry and roadside surfaces; do not build hidden details from the video.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.

VF 22 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_014_00m07s508ms.png 00:07.508

REAL WORLD REFERENCE



Okponglo_Pair2_Real_011_00m05s.png 00:05.000


Match and corrections Approach-direction support toward gate and adjacent plot, with different camera framing. S04 supplies missing gate detail and the maps supply footprint. Use OKP-001/002/008/009/012/015; no structure is deleted merely because a tree hides it in this real frame.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 23 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_015_00m08s008ms.png 00:08.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_012_00m05s500ms.png 00:05.500


Match and corrections Approach-direction support toward gate and adjacent plot, with different camera framing. S04 supplies missing gate detail and the maps supply footprint. Use OKP-001/002/008/009/012/015; no structure is deleted merely because a tree hides it in this real frame.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 24 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_016_00m09s008ms.png 00:09.008

REAL WORLD REFERENCE



Okponglo_Pair2_Real_013_00m05s800ms.png 00:05.800


Match and corrections Approach-direction support toward gate and adjacent plot, with different camera framing. S04 supplies missing gate detail and the maps supply footprint. Use OKP-001/002/008/009/012/015; no structure is deleted merely because a tree hides it in this real frame.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.


VF 25 Video Pair 2

IN GAME VIEW



Okponglo_Pair2_Game_017_00m10s475ms.png 00:10.475

REAL WORLD REFERENCE




Okponglo_Pair2_Real_013_00m05s800ms.png 00:05.800

Match and corrections Approach-direction support toward gate and adjacent plot, with different camera framing. S04 supplies missing gate detail and the maps supply footprint. Use OKP-001/002/008/009/012/015; no structure is deleted merely because a tree hides it in this real frame.

Acceptance: corrections must work in the named still pairs and the adjoining video angles. Verify the intended foreground surface and approach direction in plan before changing an object. Video times reset separately; game and real screenshot numbers are not time matches.

Cross-view evidence: Still Pairs 1 to 3 and 4 to 8 provide different sectors of one precinct. This VF entry preserves game-frame chronology and reuses stable issue IDs rather than creating a new duplicate defect.

Video contact sheets retain all real views



Half-second review sheets are navigation aids. All 25 retained real frames have exact timestamps in the index; the extracted ZIPs retain native portrait frames and original pixels. Real views not selected as a right-side match remain supporting evidence rather than being silently discarded.

Compulsory zoom and existence inspection clause

Claude must open original images and video frames at native resolution before editing. Inspect every affected structure, roof edge, partition, support, door/window opening, blank wall and ground transition. Small previews and general visual similarity do not satisfy this task.

For each building element identify its footprint, facade, floor and bay. Record visible count, width/depth, opening type, support position and unresolved occlusion. The gatehouse portal is an opening, upper grilles are decorative panels, and a circular barred opening is not a generic square window.

For every add/remove decision complete the existence ledger using at least two views plus a map where available. Confirm the missing gate at its roof footprint. Confirm kiosk/shelter/water overlap with source-backed open land. Preserve legitimate red-roof pavilion and distant buildings outside the supported boundary.

Separate present paved taxi parking from the older/current-map bare plot. Record source dates and confidence. Do not replace all taxi areas with one ground surface or infer that a mature tree in a recent video existed at the same size in 2016.

Build one verified facade/support/ground module, then render a matching frontal, oblique and overhead comparison. Inspect pillar placement and entrance clearance from plan; remove stale meshes and colliders at their source. Keep surface and terrain joins continuous on walking/bicycle routes.

Completion proof: filled feature/existence ledgers, changed files/object IDs, matched before/after views, tests actually run and unresolved details. No collision or game-change claim may be fabricated. Incorrect missing/additional structures are not acceptable even when materials look attractive.

Correction register 1

OKP 001 Okponglo gatehouse

Add missing. Pair 2 and approach Pairs 4 and 5

Finding The game approach has open grass, parked vehicles and small generic structures where the large gatehouse should anchor the road. S04 and both real clips establish the entrance.

Instruction Register the roof footprint at the road-spanning gate in M1/M2. Build the long white gatehouse, tall open vehicle portal, occupied side rooms, red/wine plinth and brown/red tiled pitched roof. Keep traffic and pedestrian openings physically open. Do not substitute a kiosk.

Evidence S04 S08 S10 M1 M2 R009 R021

Acceptance The gate is visible on the approach and aligned across the entrance road; the portal, side rooms and roof match the recent photograph.

OKP 002 Paved taxi parking

Replace wrong surface. Pair 3 and Video Pair 2

Finding Game grass and a diagonal tan path occupy the foreground paved parking/taxi area shown in S06 and IMG_6890.

Instruction Trace the specific asphalt parking polygon north of the gate road in the maps. Replace only its grass footprint with asphalt. Add white bay lines, a clear central aisle and rounded curbed tree islands. Retain adjoining bare ground as a separate surface.

Evidence S05 S06 M1 M2 R013 R014

Acceptance Plan and ground views show the parking rather than grass; aisles connect to the correct entrance and stay clear.

OKP 003 Bare roadside plot

Replace wrong terrain. Pairs 6 to 8

Finding The game depicts uniformly green lawn where the Street View targets show reddish-brown exposed ground, dry grasses and informal tracks. The maps show this plot beside the paved parking.

Instruction Trace the non-paved plot separately from the current taxi parking. Use patchy dry grass, reddish/tan soil, irregular scrub and the visible dirt access route; include local raised ground under the tree group. Do not pave all of it or convert the real asphalt lot to dirt.

Evidence S12 S14 S16 M1 M2

Acceptance The road-side verge, bare access track and slightly raised tree patch are distinct from the adjacent parking and footway.

Correction register 2

OKP 004 Green kiosk

Remove or relocate unsupported. Pairs 4 to 8

Finding A bright green square kiosk appears at the road edge and in the bare-plot views. No equivalent kiosk is established at that registered location in the supplied targets.

Instruction Find the owning object and verify its coordinates against M1/M2 and S12-S16. Remove it from the evidenced empty roadside footprint, including old collider. Relocate only if a separate source establishes its legitimate destination; do not place it inside the gate instead.

Evidence S07 S09 S11 S13 S15 S12 S14 S16

Acceptance The empty plot has no green kiosk or invisible obstruction; no guessed replacement booth appears elsewhere.

OKP 005 Shuttle shelters and waiting furniture

Remove unsupported additions after registration. Pairs 3 to 8

Finding Repeated blue shuttle-stop shelters and waiting groups populate the game grass/roadside area but are not established on the corresponding map/photograph footprints.

Instruction Audit each shelter footprint rather than deleting every campus bus stop. Remove or relocate unsupported shelters and associated benches/signage from this local area. Preserve the real red-roof taxi pavilion identified by S06 and the maps.

Evidence S05 S07 S09 S15 S06 M1 M2

Acceptance Only source-backed waiting structures remain, in registered positions; no shuttle canopy is substituted for the taxi pavilion.

OKP 006 Pond within the correction plot

Remove unsupported local water. Pairs 3 and 6 to 8

Finding A large blue water patch is visible behind the game lawn/tree mass. The supplied mapped correction plot and real ground targets show dry terrain, tracks and vegetation rather than this water feature.

Instruction Locate the water mesh precisely. Remove its overlapping part from the registered correction plot and restore the appropriate terrain. Do not delete unrelated water outside the map crop or infer a lake from a mini-map icon.

Evidence S05 S11 S13 S15 M1 M2 S12 S14 S16

Acceptance The corrected plot has continuous dry ground in aerial and side views; no stale water surface/collider remains.

Correction register 3

OKP 007 Bare-plot tree group

Reshape planting. Pairs 6 to 8

Finding Large rounded game tree clusters and many ball-like bushes form a densely landscaped lawn. Real views show a localized broadleaf group over a rough, dry raised patch with visible trunks and open gaps.

Instruction Retain the supported group footprint and match crown scale, trunk spacing and openings. Reduce unsupported scattered ornamental bushes. Model sparse scrub and dry grass below; do not turn the plot into a formal garden or a forest.

Evidence S11-S16 M1 M2

Acceptance Tree silhouettes agree from three side views and the open dirt routes remain visible.

OKP 008 Roadside palms and broadleaf trees

Correct planting distribution. Pairs 1 to 5 and both real clips

Finding Game palms form a regular avenue and broadleaf coverage is sparse. Current references show varied broadleaf trees, localized palms and shrub verges.

Instruction Place tree types from the relevant view and map canopy footprints. Keep supported palms near the gate/parking and remove unsupported regular repetitions. Use crown size and height relative to the gate and poles rather than one tree preset.

Evidence S02 S04 S06 S08 S10 R017-R025

Acceptance The road is framed by the supported trees without hiding the gate or inserting an unreferenced uniform palm row.

OKP 009 Tan interlocking footways

Add missing pedestrian surfaces. Pairs 1 and 4 to 8

Finding The game road meets grass or black-and-white kerbs without the continuous tan/brown block-paved sidewalks shown in the references.

Instruction Build the actual sidewalk strip and its road-edge kerb on each verified side. Match paver surface and local bends, drain-cover crossings and parking connections. Remove arbitrary diagonal paths where they occupy the asphalt lot.

Evidence S02 S04 S08 S10 S12 S14 S16

Acceptance A continuous walkable route follows the road and reaches the gate; asphalt, paving, soil and grass remain separate.

Correction register 4

OKP 010 Open channel and crossing slabs

Add missing drainage geometry. Pairs 1 and 2

Finding S02 exposes a concrete-sided drainage channel beside the pavers. S04 shows its slotted cover/crossing and adjacent open portion. The game presents flat grass and road margins.

Instruction Trace the channel alignment, depth relationship to the walkway, concrete edges and actual crossing slabs. Keep open sections open and model the supported slab joints/slots at the gate approach. Provide continuous collision on the route over covers; do not create a random trench across the road.

Evidence S02 S04 R006 R009 R010

Acceptance Ground views distinguish open channel, paver footway and covered crossing; the intended route remains traversable.

OKP 011 Stadium base and boundary fence

Correct stadium edge. Pair 1 and approach Pairs 4 and 5

Finding Game lower facade reads as a repeated row of large black rectangles with white crossbars. The real stadium edge shows structural/open base detail behind a separate light metal boundary fence and planted verge.

Instruction Inspect the actual base before replacing any structural bay. Stop using a generic dark-window grid for every lower opening. Add the separate fence/posts and visible setbacks/planting; retain the recognizable red/gray/off-white vertical cladding and athlete silhouettes.

Evidence S01 S02 S08 S10 R001-R004

Acceptance Fence, actual lower base and main cladding read as separate elements from the road; no invented room windows are added.

OKP 012 Gate approach carriageway and kerbs

Correct road treatment. Pairs 1 to 8

Finding The game road has an overly uniform clean surface, bright repeated lane dashes and strongly painted black/white kerbs. Real targets have local bends, worn asphalt, tan/light concrete edges and differentiated sidewalks.

Instruction Register the same road geometry in both maps, then tune carriageway edges and the gate connection. Match local markings where visible; do not invent three lanes from two dash rows. Use unpainted kerb finishes where supported and preserve known junctions.

Evidence M1 M2 S02 S04 S08 S10 S12 S14

Acceptance Approach bends, curb offsets and gate alignment agree in plan; ground views show the supported surface/marking pattern.

Correction register 5

OKP 013 Lights signs and billboards

Add supported road furniture with date check. Pairs 1 4 and 5

Finding The game uses generic poles and lacks the conspicuous billboard/support arrangement and small roadside signs seen in the 2024 views. Stadium floodlight masts differ from ordinary streetlights.

Instruction Use distinct assets for stadium floodlights and slim streetlight poles. Register sign supports and boards in the relevant roadside strip. Treat advertising artwork and 2024 billboard presence as time-specific: confirm the chosen scene date before adding them. Do not copy blurred advertising text.

Evidence S02 S08 S10 M1 M2

Acceptance Poles and supported signs occupy the correct verge with clear pedestrian space; dated advertising is not asserted as current permanent architecture.

OKP 014 Taxi pavilion

Add missing source-backed shelter. Pair 3

Finding S06 shows a low red-roof open waiting pavilion beside the paved taxi area. Game blue shelters/large distant buildings are not an equivalent.

Instruction Match the red-roof footprint in the north parking area of M1/M2. Build a modest low pitched roof, slender supports and open sides as seen in S06. Keep its boundary separate from the gate and taxi drive aisle; hidden wall details remain provisional.

Evidence S06 M1 M2

Acceptance The pavilion is low, open and correctly positioned at the taxi lot edge; no solid generic house is used in its place.

OKP 015 Curbed tree islands

Add missing parking landscape. Pair 3 and Video Pair 2

Finding IMG_6890 shows parking bay ends curving around raised planted islands, a lamp, broadleaf canopy and localized palm. The game leaves broad featureless grass in this area.

Instruction Trace island footprints within the asphalt lot, create pale concrete kerbs, modest soil/grass level changes, supported trees and the lamp position. Keep asphalt aisle around each island and white bay lines terminating at the proper edges.

Evidence S06 M1 M2 R015-R021

Acceptance Island shape, crown and bay endings agree together from the parking and gate-facing views.

Correction register 6

OKP 016 Large buildings and extra structures

Audit uncertain background objects. Pairs 2 3 and 6

Finding Several large game buildings are visible beyond the local plot. The cropped maps do not establish every distant building and the views are not perfectly camera-matched.

Instruction Record each footprint and sightline. Remove or relocate only a structure proven to occupy source-backed open ground within the correction boundary. Preserve real small red-roof structures, stadium buildings and legitimate distant campus masses. No bulk deletion from absence in one cropped photo.

Evidence S03 S05 S11 M1 M2 S12 S14

Acceptance An object-by-object add/remove/retain ledger accompanies the changes; unresolved distant objects remain explicit.

Implementation order and checks

1 Register gate road, stadium curve, paved lot and bare plot to the same world axes. Record the correction boundary and an object-by-object existence ledger.

2 Add the missing gatehouse and taxi pavilion; remove/relocate source-unsupported kiosk and local shelters/water after the coordinate check. Keep valid existing stadium massing and real background structures.

3 Correct asphalt, bare earth, footways, curb edges, drainage and entrance covers together. Restore parking aisle, bay lines and tree islands. Keep gate and vehicle routes unobstructed.

4 Reconstruct gate roof, supports, upper grilles, circular opening, side doors/windows, white/wine paint and supported barriers. Correct stadium boundary/base without inventing interior room windows.

5 Match localized broadleaf planting, supported palms and scrub. Add distinct lamps/floodlights and supported signage. Use one coherent scene date for temporary advertisements and seasonal vegetation.

6 Validate an overhead, both approach directions, gate close-up, parking-to-gate pan and bare-plot side views. Test bicycle and vehicle envelopes through relevant lanes, cover slabs and paths. Rebuild/reload to confirm source corrections persist.

Consolidated Claude prompt

Correct the Okponglo University of Ghana entrance precinct in the existing LEGONRUSH game using this full Word/PDF audit and original sources. This is a targeted correction, not a new generic campus scene. Implement the changes in the actual source code/geometry and provide review evidence.

The eight still pairs are S01/S02 through S15/S16, game first and real second. Keep their original order. Video Pair 1 is Bandicam 22-14-28 followed by IMG_6889; Video Pair 2 is Bandicam 22-17-41 followed by IMG_6890. VF1-VF25 use retained game frames chronologically and supporting real angles. No time-synchronization or exact camera match is claimed where absent.

First follow the compulsory zoom/existence clause. Identify each building, face, opening, pillar and blank span. Register M1/M2 using gate, stadium, paved parking and external junction; their road labels differ but refer to the same physical corridor. The HUD UGMC destination is unrelated to location identification.

Critical gate task: Pair 2 real Picture 4 is S04. Add its missing road-spanning gatehouse at the mapped footprint. Reproduce white side rooms, wine/red base, brown/red tiled pitched roof, decorative upper grille panels, circular barred opening, central display, thin verified uprights, open vehicle portal, recessed doors, barriers and adjacent paving/drain cover. Do not fill the portal or place posts across traffic.

Critical terrain task: restore the current asphalt taxi parking from Pair 3/video/maps and keep it separate from the bare roadside plot in Pairs 6-8. Remove local unsupported kiosk/shelter/water geometry only after verifying footprints. Keep the real open red-roof taxi pavilion and legitimate distant campus buildings.

Work in this order: plan and existence; missing structures and unsupported additions; road/parking/footway/drain surfaces; gate and stadium detail; planting and furniture; multi-view verification. Preserve already matching sections. No hidden facade, exact dimension, unclear sign text or unsupported structure may be invented.

Claude prompt issue instructions 1

OKP 001 Okponglo gatehouse

Add missing. Register the roof footprint at the road-spanning gate in M1/M2. Build the long white gatehouse, tall open vehicle portal, occupied side rooms, red/wine plinth and brown/red tiled pitched roof. Keep traffic and pedestrian openings physically open. Do not substitute a kiosk.

References: Pair 2 and approach Pairs 4 and 5; S04 S08 S10 M1 M2 R009 R021. Acceptance: The gate is visible on the approach and aligned across the entrance road; the portal, side rooms and roof match the recent photograph.

OKP 002 Paved taxi parking

Replace wrong surface. Trace the specific asphalt parking polygon north of the gate road in the maps. Replace only its grass footprint with asphalt. Add white bay lines, a clear central aisle and rounded curbed tree islands. Retain adjoining bare ground as a separate surface.

References: Pair 3 and Video Pair 2; S05 S06 M1 M2 R013 R014. Acceptance: Plan and ground views show the parking rather than grass; aisles connect to the correct entrance and stay clear.

OKP 003 Bare roadside plot

Replace wrong terrain. Trace the non-paved plot separately from the current taxi parking. Use patchy dry grass, reddish/tan soil, irregular scrub and the visible dirt access route; include local raised ground under the tree group. Do not pave all of it or convert the real asphalt lot to dirt.

References: Pairs 6 to 8; S12 S14 S16 M1 M2. Acceptance: The road-side verge, bare access track and slightly raised tree patch are distinct from the adjacent parking and footway.

OKP 004 Green kiosk

Remove or relocate unsupported. Find the owning object and verify its coordinates against M1/M2 and S12-S16. Remove it from the evidenced empty roadside footprint, including old collider. Relocate only if a separate source establishes its legitimate destination; do not place it inside the gate instead.

References: Pairs 4 to 8; S07 S09 S11 S13 S15 S12 S14 S16. Acceptance: The empty plot has no green kiosk or invisible obstruction; no guessed replacement booth appears elsewhere.

Claude prompt issue instructions 2

OKP 005 Shuttle shelters and waiting furniture

Remove unsupported additions after registration. Audit each shelter footprint rather than deleting every campus bus stop. Remove or relocate unsupported shelters and associated benches/signage from this local area. Preserve the real red-roof taxi pavilion identified by S06 and the maps.

References: Pairs 3 to 8; S05 S07 S09 S15 S06 M1 M2. Acceptance: Only source-backed waiting structures remain, in registered positions; no shuttle canopy is substituted for the taxi pavilion.

OKP 006 Pond within the correction plot

Remove unsupported local water. Locate the water mesh precisely. Remove its overlapping part from the registered correction plot and restore the appropriate terrain. Do not delete unrelated water outside the map crop or infer a lake from a mini-map icon.

References: Pairs 3 and 6 to 8; S05 S11 S13 S15 M1 M2 S12 S14 S16. Acceptance: The corrected plot has continuous dry ground in aerial and side views; no stale water surface/collider remains.

OKP 007 Bare-plot tree group

Reshape planting. Retain the supported group footprint and match crown scale, trunk spacing and openings. Reduce unsupported scattered ornamental bushes. Model sparse scrub and dry grass below; do not turn the plot into a formal garden or a forest.

References: Pairs 6 to 8; S11-S16 M1 M2. Acceptance: Tree silhouettes agree from three side views and the open dirt routes remain visible.

OKP 008 Roadside palms and broadleaf trees

Correct planting distribution. Place tree types from the relevant view and map canopy footprints. Keep supported palms near the gate/parking and remove unsupported regular repetitions. Use crown size and height relative to the gate and poles rather than one tree preset.

References: Pairs 1 to 5 and both real clips; S02 S04 S06 S08 S10 R017-R025. Acceptance: The road is framed by the supported trees without hiding the gate or inserting an unreferenced uniform palm row.

Claude prompt issue instructions 3

OKP 009 Tan interlocking footways

Add missing pedestrian surfaces. Build the actual sidewalk strip and its road-edge kerb on each verified side. Match paver surface and local bends, drain-cover crossings and parking connections. Remove arbitrary diagonal paths where they occupy the asphalt lot.

References: Pairs 1 and 4 to 8; S02 S04 S08 S10 S12 S14 S16. Acceptance: A continuous walkable route follows the road and reaches the gate; asphalt, paving, soil and grass remain separate.

OKP 010 Open channel and crossing slabs

Add missing drainage geometry. Trace the channel alignment, depth relationship to the walkway, concrete edges and actual crossing slabs. Keep open sections open and model the supported slab joints/slots at the gate approach. Provide continuous collision on the route over covers; do not create a random trench across the road.

References: Pairs 1 and 2; S02 S04 R006 R009 R010. Acceptance: Ground views distinguish open channel, paver footway and covered crossing; the intended route remains traversable.

OKP 011 Stadium base and boundary fence

Correct stadium edge. Inspect the actual base before replacing any structural bay. Stop using a generic dark-window grid for every lower opening. Add the separate fence/posts and visible setbacks/planting; retain the recognizable red/gray/off-white vertical cladding and athlete silhouettes.

References: Pair 1 and approach Pairs 4 and 5; S01 S02 S08 S10 R001-R004. Acceptance: Fence, actual lower base and main cladding read as separate elements from the road; no invented room windows are added.

OKP 012 Gate approach carriageway and kerbs

Correct road treatment. Register the same road geometry in both maps, then tune carriageway edges and the gate connection. Match local markings where visible; do not invent three lanes from two dash rows. Use unpainted kerb finishes where supported and preserve known junctions.

References: Pairs 1 to 8; M1 M2 S02 S04 S08 S10 S12 S14. Acceptance: Approach bends, curb offsets and gate alignment agree in plan; ground views show the supported surface/marking pattern.

Claude prompt issue instructions 4

OKP 013 Lights signs and billboards

Add supported road furniture with date check. Use distinct assets for stadium floodlights and slim streetlight poles. Register sign supports and boards in the relevant roadside strip. Treat advertising artwork and 2024 billboard presence as time-specific: confirm the chosen scene date before adding them. Do not copy blurred advertising text.

References: Pairs 1 4 and 5; S02 S08 S10 M1 M2. Acceptance: Poles and supported signs occupy the correct verge with clear pedestrian space; dated advertising is not asserted as current permanent architecture.

OKP 014 Taxi pavilion

Add missing source-backed shelter. Match the red-roof footprint in the north parking area of M1/M2. Build a modest low pitched roof, slender supports and open sides as seen in S06. Keep its boundary separate from the gate and taxi drive aisle; hidden wall details remain provisional.

References: Pair 3; S06 M1 M2. Acceptance: The pavilion is low, open and correctly positioned at the taxi lot edge; no solid generic house is used in its place.

OKP 015 Curbed tree islands

Add missing parking landscape. Trace island footprints within the asphalt lot, create pale concrete kerbs, modest soil/grass level changes, supported trees and the lamp position. Keep asphalt aisle around each island and white bay lines terminating at the proper edges.

References: Pair 3 and Video Pair 2; S06 M1 M2 R015-R021. Acceptance: Island shape, crown and bay endings agree together from the parking and gate-facing views.

OKP 016 Large buildings and extra structures

Audit uncertain background objects. Record each footprint and sightline. Remove or relocate only a structure proven to occupy source-backed open ground within the correction boundary. Preserve real small red-roof structures, stadium buildings and legitimate distant campus masses. No bulk deletion from absence in one cropped photo.

References: Pairs 2 3 and 6; S03 S05 S11 M1 M2 S12 S14. Acceptance: An object-by-object add/remove/retain ledger accompanies the changes; unresolved distant objects remain explicit.

Claude prompt verification and final response

Provide matched overhead and ground-level before/after renders for all eight still-pair directions. Show the gate from the approach and beneath its portal, taxi parking toward the pavilion/gate, and the bare plot from Pairs 6-8. Reconcile all views around the connected road rather than matching one camera.

Change the owning procedural/map source and remove stale geometry/colliders. Test gate access, parking aisles, footway crossings and drain covers using the actual game movement envelope. Verify regeneration/reload. Report tests actually run; do not describe a completed game test based on this PDF alone.

Deliver completed OKP IDs, changed files and stable object IDs, feature and existence ledgers, real-source references, before/after renders, actual tests and unresolved coordinates/details. Dated billboards, concealed support counts, distant background buildings and unreadable plaques remain explicit verification items.

Reject a result with a missing gate, grass occupying verified asphalt parking, an unsupported kiosk on confirmed open ground, arbitrary water in the dry plot, blocked portal/route, repeated generic windows replacing grilles or a paved lot incorrectly changed to bare soil. These are completion failures, not optional polish.