UGMC reconstruction audit

In game aerial views and real world references

Correct the existing UGMC reconstruction in LEGONRUSH while preserving the portions that already match. This audit retains all 89 chronological game screenshots, registers the real references, and supplies a shared correction ledger and a complete implementation prompt for Claude.

The strongest visible discrepancies concern Patient Tower glazing, wall bands and entrance geometry, the main clinical roof assembly and plant, and the treatment of roads, parking and planting. The real forecourt entrance glass must recess inward; the reported game reversal requires a registered plan check because the recorded dialog partly obscures that geometry.

Coverage matters. Most of the game orbit follows Patient Tower and the main roof. The 47 real aerial screenshots concentrate on Women and Children and the central forecourt. Many comparisons therefore use clearly labeled supporting views rather than a falsely matched building or camera.

Source class	Count	Role
Game screenshots	89	G001 to G089 in video order
Real aerial screenshots	47	R001 to R047 in numeric filename order
Additional images	42	A001 to A042 in original photo number order
Current satellite maps	2	M1 unlabelled crop and M2 labelled Google view
Earlier brief	49 pages	Context only; actual images govern corrections

Recipient: Claude implementing the game correction. This document describes the audit; no source-code edits, game collision tests or completed game rebuild are claimed here.

Reading the evidence and matching the views

A direct feature match identifies the same structure but may still have a different camera elevation. A supporting angle provides reliable detail from another view. No direct matching angle means the focal game face has no equivalent real photograph: its screenshot remains in sequence, with what can and cannot be checked stated explicitly.

Stable block identifiers: C1 main Emergency and Diagnostics core; W2 Women and Children; O3 Outpatients and Administration; T4 Medical Training and Simulation Center; P5 Patient Tower; L6 elongated low building of unconfirmed use. These are audit identifiers, not arbitrary hospital signage. Map pins may overlap departments and do not define surveyed boundaries.

Use one rotation, scale and translation to register M1 and M2 to project coordinates. Anchor C1 roof, the planted central roundabout, P5 footprint and L6. Never mirror the site. Identify the actual facade from glazing, mast, adjoining wing and entry before interpreting a window pattern.

The earlier 49-page PDF was retrieved and its implementation guidance reviewed. Its source A01-A47 corresponds to this audit R001-R047; its E01-E42 corresponds to A001-A042. Earlier wording described curved entrances without explicitly fixing the signed direction. The current curve instructions and uncertainty classification take priority.

All real images were reviewed. A001-A010 are only 128 pixels wide and cannot establish pane counts or exact dimensions. A011-A042 are larger; A006/A030/A036 are interior references, and A035/A037 have uncertain external placement. Do not upscale small thumbnails and claim recovered architectural detail.

Game dialogs, floating destination labels, HUD, watermark and final browser chrome are capture artifacts. They are retained in the evidence; no new architecture is inferred behind them. Facade signs are separate physical features.


Satellite registration and block locations



1 C1 main roof; 2 W2; 3 O3 courtyard block; 4 T4; 5 P5; 6 L6 long low building; 7 main planted roundabout; 8 W2 crescent garden. Numbers are location annotations, not clinical department numbering.

Trace the true roof/ground boundaries, courtyard voids, road edges and planting separately. This is a satellite footprint record: it does not measure floor heights, door positions or hidden roof pitch.

Google labels and physical identity



M2 labels Women and Children, Outpatients and Administration, Surgical Unit and Orthopaedic Unit. Use Patient Tower facade wording in A024/A041 to identify P5; do not rename its facade according to the nearest floating Google pin.

The two maps depict the same physical arrangement with different crops and labels. Neither is a new in-game overview map. Compass orientation and exact scale are not supplied here; solve world axes from actual project coordinates.

Real source register 1

ID	Original filename	Pixels	Use
R001	Screenshot (2261).png	1920 x 1080	Aerial ensemble
R002	Screenshot (2262).png	1920 x 1080	Aerial ensemble
R003	Screenshot (2263).png	1920 x 1080	Aerial ensemble
R004	Screenshot (2264).png	1920 x 1080	Women and Children close/roof
R005	Screenshot (2265).png	1920 x 1080	Women and Children close/roof
R006	Screenshot (2266).png	1920 x 1080	Women and Children close/roof
R007	Screenshot (2267).png	1920 x 1080	Women and Children close/roof
R008	Screenshot (2268).png	1920 x 1080	Women and Children close/roof
R009	Screenshot (2269).png	1920 x 1080	Forecourt and curved entries
R010	Screenshot (2270).png	1920 x 1080	Forecourt and curved entries
R011	Screenshot (2271).png	1920 x 1080	Forecourt and curved entries
R012	Screenshot (2272).png	1920 x 1080	Forecourt and curved entries
R013	Screenshot (2273).png	1920 x 1080	Forecourt and curved entries
R014	Screenshot (2274).png	1920 x 1080	Forecourt and curved entries

Real source register 2

ID	Original filename	Pixels	Use
R015	Screenshot (2275).png	1920 x 1080	Forecourt and curved entries
R016	Screenshot (2276).png	1920 x 1080	Forecourt and curved entries
R017	Screenshot (2277).png	1920 x 1080	Forecourt and curved entries
R018	Screenshot (2278).png	1920 x 1080	Forecourt and curved entries
R019	Screenshot (2279).png	1920 x 1080	Forecourt and curved entries
R020	Screenshot (2280).png	1920 x 1080	Women and Children frontage/parking
R021	Screenshot (2281).png	1920 x 1080	Women and Children frontage/parking
R022	Screenshot (2282).png	1920 x 1080	Women and Children frontage/parking
R023	Screenshot (2283).png	1920 x 1080	Women and Children frontage/parking
R024	Screenshot (2284).png	1920 x 1080	Women and Children frontage/parking
R025	Screenshot (2285).png	1920 x 1080	Women and Children frontage/parking
R026	Screenshot (2286).png	1920 x 1080	Women and Children frontage/parking
R027	Screenshot (2287).png	1920 x 1080	Women and Children frontage/parking
R028	Screenshot (2288).png	1920 x 1080	Women and Children frontage/parking

Real source register 3

ID	Original filename	Pixels	Use
R029	Screenshot (2289).png	1920 x 1080	Clinical ensemble and roofs
R030	Screenshot (2290).png	1920 x 1080	Clinical ensemble and roofs
R031	Screenshot (2291).png	1920 x 1080	Clinical ensemble and roofs
R032	Screenshot (2292).png	1920 x 1080	Clinical ensemble and roofs
R033	Screenshot (2293).png	1920 x 1080	Clinical ensemble and roofs
R034	Screenshot (2294).png	1920 x 1080	Clinical ensemble and roofs
R035	Screenshot (2295).png	1920 x 1080	Clinical ensemble and roofs
R036	Screenshot (2296).png	1920 x 1080	Clinical ensemble and roofs
R037	Screenshot (2297).png	1920 x 1080	Clinical ensemble and roofs
R038	Screenshot (2298).png	1920 x 1080	Clinical ensemble and roofs
R039	Screenshot (2299).png	1920 x 1080	Women and Children garden elevation
R040	Screenshot (2300).png	1920 x 1080	Women and Children garden elevation
R041	Screenshot (2301).png	1920 x 1080	Women and Children garden elevation
R042	Screenshot (2302).png	1920 x 1080	Women and Children garden elevation

Real source register 4

ID	Original filename	Pixels	Use
R043	Screenshot (2303).png	1920 x 1080	Women and Children garden elevation
R044	Screenshot (2304).png	1920 x 1080	Women and Children garden elevation
R045	Screenshot (2305).png	1920 x 1080	Women and Children garden elevation
R046	Screenshot (2306).png	1920 x 1080	Women and Children garden elevation
R047	Screenshot (2307).png	1920 x 1080	Women and Children garden elevation
A001	photo_1_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A002	photo_2_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A003	photo_3_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A004	photo_4_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A005	photo_5_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A006	photo_6_2026-10-13_23-23-08.jpg	128 x 107	Tiny thumbnail support only
A007	photo_7_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A008	photo_8_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only
A009	photo_9_2026-10-13_23-23-08.jpg	128 x 91	Tiny thumbnail support only

Real source register 5

ID	Original filename	Pixels	Use
A010	photo_10_2026-10-13_23-23-08.jpg	128 x 107	Tiny thumbnail support only
A011	photo_11_2026-10-13_23-23-08.jpg	1280 x 1070	Additional photo; facade or grounds
A012	photo_12_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A013	photo_13_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A014	photo_14_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A015	photo_15_2026-10-13_23-23-08.jpg	765 x 1020	Additional photo; facade or grounds
A016	photo_16_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A017	photo_17_2026-10-13_23-23-08.jpg	1280 x 910	Additional photo; facade or grounds
A018	photo_18_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A019	photo_19_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A020	photo_20_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A021	photo_21_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A022	photo_22_2026-10-13_23-23-08.jpg	765 x 1020	Additional photo; facade or grounds
A023	photo_23_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds

Real source register 6

ID	Original filename	Pixels	Use
A024	photo_24_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A025	photo_25_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A026	photo_26_2026-10-13_23-23-08.jpg	1280 x 964	Additional photo; facade or grounds
A027	photo_27_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A028	photo_28_2026-10-13_23-23-08.jpg	720 x 540	Additional photo; facade or grounds
A029	photo_29_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A030	photo_30_2026-10-13_23-23-08.jpg	1280 x 960	Interior or unresolved placement
A031	photo_31_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A032	photo_32_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A033	photo_33_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A034	photo_34_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A035	photo_35_2026-10-13_23-23-08.jpg	768 x 1020	Interior or unresolved placement
A036	photo_36_2026-10-13_23-23-08.jpg	1280 x 960	Interior or unresolved placement
A037	photo_37_2026-10-13_23-23-08.jpg	1280 x 960	Interior or unresolved placement

Real source register 7

ID	Original filename	Pixels	Use
A038	photo_38_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A039	photo_39_2026-10-13_23-23-08.jpg	720 x 540	Additional photo; facade or grounds
A040	photo_40_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A041	photo_41_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds
A042	photo_42_2026-10-13_23-23-08.jpg	1280 x 960	Additional photo; facade or grounds

Game screenshot index 1

Pair and source	Original game filename	Video timestamp
1 G001	UGMC_Game_001_00m00s.png	00:00.000
2 G002	UGMC_Game_002_00m01s767ms.png	00:01.767
3 G003	UGMC_Game_003_00m02s.png	00:02.000
4 G004	UGMC_Game_004_00m02s267ms.png	00:02.267
5 G005	UGMC_Game_005_00m02s500ms.png	00:02.500
6 G006	UGMC_Game_006_00m02s767ms.png	00:02.767
7 G007	UGMC_Game_007_00m03s.png	00:03.000
8 G008	UGMC_Game_008_00m04s.png	00:04.000
9 G009	UGMC_Game_009_00m05s.png	00:05.000
10 G010	UGMC_Game_010_00m06s.png	00:06.000
11 G011	UGMC_Game_011_00m07s.png	00:07.000
12 G012	UGMC_Game_012_00m08s.png	00:08.000
13 G013	UGMC_Game_013_00m09s.png	00:09.000
14 G014	UGMC_Game_014_00m10s.png	00:10.000
15 G015	UGMC_Game_015_00m11s.png	00:11.000
16 G016	UGMC_Game_016_00m12s.png	00:12.000
17 G017	UGMC_Game_017_00m13s.png	00:13.000
18 G018	UGMC_Game_018_00m14s.png	00:14.000

Chronological index from Phase One. Every listed screenshot appears in its numbered comparison. Exact decoded frame timestamps are retained; filenames and ordering are unchanged.

Game screenshot index 2

Pair and source	Original game filename	Video timestamp
19 G019	UGMC_Game_019_00m15s.png	00:15.000
20 G020	UGMC_Game_020_00m16s.png	00:16.000
21 G021	UGMC_Game_021_00m17s.png	00:17.000
22 G022	UGMC_Game_022_00m18s.png	00:18.000
23 G023	UGMC_Game_023_00m19s.png	00:19.000
24 G024	UGMC_Game_024_00m20s.png	00:20.000
25 G025	UGMC_Game_025_00m21s.png	00:21.000
26 G026	UGMC_Game_026_00m22s.png	00:22.000
27 G027	UGMC_Game_027_00m23s.png	00:23.000
28 G028	UGMC_Game_028_00m24s.png	00:24.000
29 G029	UGMC_Game_029_00m25s.png	00:25.000
30 G030	UGMC_Game_030_00m26s.png	00:26.000
31 G031	UGMC_Game_031_00m27s.png	00:27.000
32 G032	UGMC_Game_032_00m28s.png	00:28.000
33 G033	UGMC_Game_033_00m29s.png	00:29.000
34 G034	UGMC_Game_034_00m30s.png	00:30.000
35 G035	UGMC_Game_035_00m31s.png	00:31.000
36 G036	UGMC_Game_036_00m32s.png	00:32.000

Chronological index from Phase One. Every listed screenshot appears in its numbered comparison. Exact decoded frame timestamps are retained; filenames and ordering are unchanged.

Game screenshot index 3

Pair and source	Original game filename	Video timestamp
37 G037	UGMC_Game_037_00m33s.png	00:33.000
38 G038	UGMC_Game_038_00m34s.png	00:34.000
39 G039	UGMC_Game_039_00m35s.png	00:35.000
40 G040	UGMC_Game_040_00m36s.png	00:36.000
41 G041	UGMC_Game_041_00m37s.png	00:37.000
42 G042	UGMC_Game_042_00m38s.png	00:38.000
43 G043	UGMC_Game_043_00m39s.png	00:39.000
44 G044	UGMC_Game_044_00m40s.png	00:40.000
45 G045	UGMC_Game_045_00m41s.png	00:41.000
46 G046	UGMC_Game_046_00m42s.png	00:42.000
47 G047	UGMC_Game_047_00m43s.png	00:43.000
48 G048	UGMC_Game_048_00m44s.png	00:44.000
49 G049	UGMC_Game_049_00m45s.png	00:45.000
50 G050	UGMC_Game_050_00m45s500ms.png	00:45.500
51 G051	UGMC_Game_051_00m46s.png	00:46.000
52 G052	UGMC_Game_052_00m47s.png	00:47.000
53 G053	UGMC_Game_053_00m48s.png	00:48.000
54 G054	UGMC_Game_054_00m49s.png	00:49.000

Chronological index from Phase One. Every listed screenshot appears in its numbered comparison. Exact decoded frame timestamps are retained; filenames and ordering are unchanged.

Game screenshot index 4

Pair and source	Original game filename	Video timestamp
55 G055	UGMC_Game_055_00m50s.png	00:50.000
56 G056	UGMC_Game_056_00m50s500ms.png	00:50.500
57 G057	UGMC_Game_057_00m51s.png	00:51.000
58 G058	UGMC_Game_058_00m52s.png	00:52.000
59 G059	UGMC_Game_059_00m53s.png	00:53.000
60 G060	UGMC_Game_060_00m54s.png	00:54.000
61 G061	UGMC_Game_061_00m55s.png	00:55.000
62 G062	UGMC_Game_062_00m55s500ms.png	00:55.500
63 G063	UGMC_Game_063_00m56s.png	00:56.000
64 G064	UGMC_Game_064_00m57s.png	00:57.000
65 G065	UGMC_Game_065_00m58s.png	00:58.000
66 G066	UGMC_Game_066_00m59s.png	00:59.000
67 G067	UGMC_Game_067_01m00s.png	01:00.000
68 G068	UGMC_Game_068_01m00s500ms.png	01:00.500
69 G069	UGMC_Game_069_01m01s.png	01:01.000
70 G070	UGMC_Game_070_01m02s.png	01:02.000
71 G071	UGMC_Game_071_01m03s.png	01:03.000
72 G072	UGMC_Game_072_01m04s.png	01:04.000

Chronological index from Phase One. Every listed screenshot appears in its numbered comparison. Exact decoded frame timestamps are retained; filenames and ordering are unchanged.

Game screenshot index 5

Pair and source	Original game filename	Video timestamp
73 G073	UGMC_Game_073_01m05s.png	01:05.000
74 G074	UGMC_Game_074_01m05s500ms.png	01:05.500
75 G075	UGMC_Game_075_01m06s.png	01:06.000
76 G076	UGMC_Game_076_01m07s.png	01:07.000
77 G077	UGMC_Game_077_01m08s.png	01:08.000
78 G078	UGMC_Game_078_01m09s.png	01:09.000
79 G079	UGMC_Game_079_01m10s.png	01:10.000
80 G080	UGMC_Game_080_01m11s.png	01:11.000
81 G081	UGMC_Game_081_01m12s.png	01:12.000
82 G082	UGMC_Game_082_01m13s.png	01:13.000
83 G083	UGMC_Game_083_01m14s.png	01:14.000
84 G084	UGMC_Game_084_01m15s.png	01:15.000
85 G085	UGMC_Game_085_01m20s.png	01:20.000
86 G086	UGMC_Game_086_01m25s.png	01:25.000
87 G087	UGMC_Game_087_01m30s.png	01:30.000
88 G088	UGMC_Game_088_01m35s.png	01:35.000
89 G089	UGMC_Game_089_01m39s800ms.png	01:39.800

Chronological index from Phase One. Every listed screenshot appears in its numbered comparison. Exact decoded frame timestamps are retained; filenames and ordering are unchanged.

Game to real matching table 1

Pair	Primary right image	Additional support	Match classification
1	A028	A040 M1 M2	No direct matching angle
2	R026	A026 R030 M1	Same identifiable frontage with different camera height
3	R017	R030 R038 A032 M1	Supporting ensemble view at a different camera angle
4	R017	R030 R038 A032 M1	Supporting ensemble view at a different camera angle
5	R017	R011 A025 A032 A039 R038	Same entrance typology and core with different oblique angle
6	R017	R011 A025 A032 A039 R038	Same entrance typology and core with different oblique angle
7	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
8	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
9	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
10	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
11	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
12	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face

Game to real matching table 2

Pair	Primary right image	Additional support	Match classification
13	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
14	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
15	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
16	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
17	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
18	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
19	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
20	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
21	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
22	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
23	M1	A024 A041 R020 R038	No direct matching real aerial angle for the focal Patient Tower face
24	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle

Game to real matching table 3

Pair	Primary right image	Additional support	Match classification
25	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
26	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
27	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
28	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
29	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
30	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
31	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
32	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
33	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
34	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
35	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
36	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle

Game to real matching table 4

Pair	Primary right image	Additional support	Match classification
37	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
38	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
39	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
40	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
41	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
42	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
43	M1	A024 A041 R020	No direct matching rear or outer-side photographic angle
44	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
45	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
46	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
47	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
48	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle

Game to real matching table 5

Pair	Primary right image	Additional support	Match classification
49	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
50	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
51	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
52	A041	A024 M1 M2	Supporting entrance facade from a substantially different aerial angle
53	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
54	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
55	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
56	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
57	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
58	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
59	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
60	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height

Game to real matching table 6

Pair	Primary right image	Additional support	Match classification
61	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
62	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
63	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
64	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
65	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
66	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
67	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
68	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
69	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
70	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
71	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height
72	A041	A016 A024 M1 M2	Same Patient Tower entrance face with different viewing height

Game to real matching table 7

Pair	Primary right image	Additional support	Match classification
73	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
74	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
75	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
76	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
77	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
78	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
79	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
80	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
81	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
82	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
83	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height
84	A024	A041 M1 M2 R038	Supporting Patient Tower entrance oblique with different height

Game to real matching table 8

Pair	Primary right image	Additional support	Match classification
85	M1	A024 A041 R038	No direct matching focal aerial angle; repeat orbit checkpoint
86	M1	A024 A041 R038	No direct matching focal aerial angle; repeat orbit checkpoint
87	M1	A024 A041 R038	No direct matching focal aerial angle; repeat orbit checkpoint
88	M1	A024 A041 R038	No direct matching focal aerial angle; repeat orbit checkpoint
89	M1	A024 A041 R038	No direct matching focal aerial angle; repeat orbit checkpoint

Pair 1 Ground entrance approach and hospital sign

IN GAME VIEW



UGMC_Game_001_00m00s.png 00:00.000

REAL WORLD REFERENCE



A028 photo_28_2026-10-13_23-23-08.jpg No direct matching angle

A View identification Ground entrance approach and hospital sign. No direct matching angle. Camera correspondence uses building features, not upload order.

B What the game shows Large overhead entrance sign, straight road, grass and parking behind the arrival dialog.

C What the references show Security-post photographs show small roofed glazed booths, paved margins and gate context; they do not show this same sign or establish which post serves this camera. Supporting sources: A040 M1 M2.

D Required corrections UGMC-018 is unverified. Register the actual entry before moving a booth or deleting the overhead sign. UGMC-010/011 apply only to the road/parking portions that can be matched.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G001 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Compare the same gate footprint and approach direction; no gate identity from a thumbnail or name alone.

G Cross view consistency Pair 2 shows the next ascent view. Consult adjacent Pair 1 and Pair 2 for continuity. UI-covered features remain unresolved.

Pair 2 Women and Children parking frontage during ascent

IN GAME VIEW



UGMC_Game_002_00m01s767ms.png 00:01.767

REAL WORLD REFERENCE



R026 Screenshot (2286).png Same identifiable frontage with different camera height

A View identification Women and Children parking frontage during ascent. Same identifiable frontage with different camera height. Camera correspondence uses building features, not upload order.

B What the game shows White multi-level frontage, dark signed center glazing, small repeated windows and parked cars. The ascent gives only a short glimpse.

C What the references show R026 and A026 identify the dark Women and Children signed frontage, off-white wings, paired horizontal bands and differentiated window rhythm. R030 exposes the low portal and inner masses. Supporting sources: A026 R030 M1.

D Required corrections UGMC-014 targets supported finish/recess detail; UGMC-011 targets the matched parking field. UGMC-015 requires a fuller W2 game view before whole-block changes.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G002 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Keep the signed center and confirmed floor rhythm; inspect the other W2 elevations separately.

G Cross view consistency Early ascent pairs and R004-R008/R020-R030 establish W2 identity. Consult adjacent Pair 1 and Pair 3 for continuity. UI-covered features remain unresolved.

Pair 3 Main roof and central clinical ensemble during ascent

IN GAME VIEW



UGMC_Game_003_00m02s.png 00:02.000

REAL WORLD REFERENCE



R017 Screenshot (2277).png Supporting ensemble view at a different camera angle

A View identification Main roof and central clinical ensemble during ascent. Supporting ensemble view at a different camera angle. Camera correspondence uses building features, not upload order.

B What the game shows Broad pale main roof, simplified equipment and tan/white linked volumes; portions of glazing and roads are obscured by the dialog.

C What the references show R017 identifies C1 entrance and W2 beside it; R038 details C1 rooftop covered runs and equipment. The view is not a complete frontal curve assessment. Supporting sources: R030 R038 A032 M1.

D Required corrections UGMC-003/004 correct the roof assembly and plant. UGMC-001 requires separate registered curve endpoints; do not infer the middle of a concealed wall.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G003 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Roof connections and plant must match R038 independently of glass direction.

G Cross view consistency Next ascent pairs expose the curved glass more clearly; later main-roof pairs revisit this roof. Consult adjacent Pair 2 and Pair 4 for continuity. UI-covered features remain unresolved.

Pair 4 Main roof and central clinical ensemble during ascent

IN GAME VIEW



UGMC_Game_004_00m02s267ms.png 00:02.267

REAL WORLD REFERENCE



R017 Screenshot (2277).png Supporting ensemble view at a different camera angle

A View identification Main roof and central clinical ensemble during ascent. Supporting ensemble view at a different camera angle. Camera correspondence uses building features, not upload order.

B What the game shows Broad pale main roof, simplified equipment and tan/white linked volumes; portions of glazing and roads are obscured by the dialog.

C What the references show R017 identifies C1 entrance and W2 beside it; R038 details C1 rooftop covered runs and equipment. The view is not a complete frontal curve assessment. Supporting sources: R030 R038 A032 M1.

D Required corrections UGMC-003/004 correct the roof assembly and plant. UGMC-001 requires separate registered curve endpoints; do not infer the middle of a concealed wall.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G004 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Roof connections and plant must match R038 independently of glass direction.

G Cross view consistency Next ascent pairs expose the curved glass more clearly; later main-roof pairs revisit this roof. Consult adjacent Pair 3 and Pair 5 for continuity. UI-covered features remain unresolved.

Pair 5 Emergency and Diagnostics curved entry and main roof

IN GAME VIEW



UGMC_Game_005_00m02s500ms.png 00:02.500

REAL WORLD REFERENCE



R017 Screenshot (2277).png Same entrance typology and core with different oblique angle

A View identification Emergency and Diagnostics curved entry and main roof. Same entrance typology and core with different oblique angle. Camera correspondence uses building features, not upload order.

B What the game shows Dark bowed glazing, an opaque pale projecting canopy and a glazed link are briefly visible beside the equipment roof. The dialog hides part of the wall.

C What the references show R017/A032 identify C1 and its relationship to O3; R011/A025/A039 separately establish the inward Outpatients frontage and its framed canopy. R038 supplies roof construction. Supporting sources: R011 A025 A032 A039 R038.

D Required corrections UGMC-001: audit each curve separately in plan, then correct any outward bow. UGMC-002: rebuild the verified canopy frame/supports. UGMC-003/004: replace simplified roof routing and plant; UGMC-017 is a bridge verification task.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G005 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Use inward signed sagitta, correct endpoints, canopy clearance and a matched aerial plus frontage render.

G Cross view consistency All early ascent comparisons share UGMC-001 to 004; this is not proof that every hospital glass bay has the same curve. Consult adjacent Pair 4 and Pair 6 for continuity. UI-covered features remain unresolved.

Pair 6 Emergency and Diagnostics curved entry and main roof

IN GAME VIEW



UGMC_Game_006_00m02s767ms.png 00:02.767

REAL WORLD REFERENCE



R017 Screenshot (2277).png Same entrance typology and core with different oblique angle

A View identification Emergency and Diagnostics curved entry and main roof. Same entrance typology and core with different oblique angle. Camera correspondence uses building features, not upload order.

B What the game shows Dark bowed glazing, an opaque pale projecting canopy and a glazed link are briefly visible beside the equipment roof. The dialog hides part of the wall.

C What the references show R017/A032 identify C1 and its relationship to O3; R011/A025/A039 separately establish the inward Outpatients frontage and its framed canopy. R038 supplies roof construction. Supporting sources: R011 A025 A032 A039 R038.

D Required corrections UGMC-001: audit each curve separately in plan, then correct any outward bow. UGMC-002: rebuild the verified canopy frame/supports. UGMC-003/004: replace simplified roof routing and plant; UGMC-017 is a bridge verification task.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G006 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Use inward signed sagitta, correct endpoints, canopy clearance and a matched aerial plus frontage render.

G Cross view consistency All early ascent comparisons share UGMC-001 to 004; this is not proof that every hospital glass bay has the same curve. Consult adjacent Pair 5 and Pair 7 for continuity. UI-covered features remain unresolved.

Pair 7 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_007_00m03s.png 00:03.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G007 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 6 and Pair 8 for continuity. UI-covered features remain unresolved.

Pair 8 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_008_00m04s.png 00:04.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G008 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 7 and Pair 9 for continuity. UI-covered features remain unresolved.

Pair 9 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_009_00m05s.png 00:05.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G009 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 8 and Pair 10 for continuity. UI-covered features remain unresolved.

Pair 10 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_010_00m06s.png 00:06.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G010 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 9 and Pair 11 for continuity. UI-covered features remain unresolved.

Pair 11 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_011_00m07s.png 00:07.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G011 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 10 and Pair 12 for continuity. UI-covered features remain unresolved.

Pair 12 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_012_00m08s.png 00:08.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G012 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 11 and Pair 13 for continuity. UI-covered features remain unresolved.

Pair 13 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_013_00m09s.png 00:09.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G013 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 12 and Pair 14 for continuity. UI-covered features remain unresolved.

Pair 14 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_014_00m10s.png 00:10.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G014 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 13 and Pair 15 for continuity. UI-covered features remain unresolved.

Pair 15 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_015_00m11s.png 00:11.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G015 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 14 and Pair 16 for continuity. UI-covered features remain unresolved.

Pair 16 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_016_00m12s.png 00:12.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G016 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 15 and Pair 17 for continuity. UI-covered features remain unresolved.

Pair 17 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_017_00m13s.png 00:13.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G017 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 16 and Pair 18 for continuity. UI-covered features remain unresolved.

Pair 18 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_018_00m14s.png 00:14.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G018 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 17 and Pair 19 for continuity. UI-covered features remain unresolved.

Pair 19 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_019_00m15s.png 00:15.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G019 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 18 and Pair 20 for continuity. UI-covered features remain unresolved.

Pair 20 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_020_00m16s.png 00:16.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G020 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 19 and Pair 21 for continuity. UI-covered features remain unresolved.

Pair 21 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_021_00m17s.png 00:17.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G021 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 20 and Pair 22 for continuity. UI-covered features remain unresolved.

Pair 22 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_022_00m18s.png 00:18.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G022 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 21 and Pair 23 for continuity. UI-covered features remain unresolved.

Pair 23 Patient Tower rear or side approach with main roof and L6

IN GAME VIEW



UGMC_Game_023_00m19s.png 00:19.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching real aerial angle for the focal Patient Tower face

A View identification Patient Tower rear or side approach with main roof and L6. No direct matching real aerial angle for the focal Patient Tower face. Camera correspondence uses building features, not upload order.

B What the game shows Regular white multi-level wings and roof boxes behind the main clinical roof, a long broad gray patterned low roof and simple dark site strips.

C What the references show M1 locates P5 beside L6 and C1. A024/A041 show its entrance-facing design; R020 has a distant P5 candidate in the ensemble but is not a matching rear elevation. Supporting sources: A024 A041 R020 R038.

D Required corrections UGMC-012 addresses the L6 roof surface. UGMC-003/004 address the exposed C1 roof. UGMC-013 remains probable for P5 massing; no invented rear window or door correction from the entrance photograph.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G023 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Register footprints first and preserve visible occupied tiers until a face-specific ledger supports change.

G Cross view consistency Later Patient Tower entrance pairs show UGMC-005 to 009 more directly. Consult adjacent Pair 22 and Pair 24 for continuity. UI-covered features remain unresolved.

Pair 24 Patient Tower long outer elevation and corner orbit

IN GAME VIEW



UGMC_Game_024_00m20s.png 00:20.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching rear or outer-side photographic angle

A View identification Patient Tower long outer elevation and corner orbit. No direct matching rear or outer-side photographic angle. Camera correspondence uses building features, not upload order.

B What the game shows Rows of similar dark windows, white flat roof/parapet, repeated tall end volumes, neighboring low roof and a narrow dark road loop.

C What the references show M1 supplies P5/L6 plan relationships. A024/A041 establish end strips, bands and the low entrance, but not the exact rear-face window schedule shown here. Supporting sources: A024 A041 R020.

D Required corrections UGMC-010/012 target exposed site and low-roof treatment. UGMC-013/014 target supported mass offsets/material detail only. UGMC-005/006 become directly actionable on identifiable entrance ends, not arbitrary rear bays.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G024 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Do not transplant the Women and Children ribbon elevation R043 onto this Patient Tower face; preserve unknown opening counts.

G Cross view consistency The orbit turns toward the mast and entrance after this sector; use those pairs for end-face details. Consult adjacent Pair 23 and Pair 25 for continuity. UI-covered features remain unresolved.

Pair 25 Patient Tower long outer elevation and corner orbit

IN GAME VIEW



UGMC_Game_025_00m21s.png 00:21.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching rear or outer-side photographic angle

A View identification Patient Tower long outer elevation and corner orbit. No direct matching rear or outer-side photographic angle. Camera correspondence uses building features, not upload order.

B What the game shows Rows of similar dark windows, white flat roof/parapet, repeated tall end volumes, neighboring low roof and a narrow dark road loop.

C What the references show M1 supplies P5/L6 plan relationships. A024/A041 establish end strips, bands and the low entrance, but not the exact rear-face window schedule shown here. Supporting sources: A024 A041 R020.

D Required corrections UGMC-010/012 target exposed site and low-roof treatment. UGMC-013/014 target supported mass offsets/material detail only. UGMC-005/006 become directly actionable on identifiable entrance ends, not arbitrary rear bays.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G025 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Do not transplant the Women and Children ribbon elevation R043 onto this Patient Tower face; preserve unknown opening counts.

G Cross view consistency The orbit turns toward the mast and entrance after this sector; use those pairs for end-face details. Consult adjacent Pair 24 and Pair 26 for continuity. UI-covered features remain unresolved.

Pair 26 Patient Tower long outer elevation and corner orbit

IN GAME VIEW



UGMC_Game_026_00m22s.png 00:22.000

REAL WORLD REFERENCE



M1 Screenshot 2026-10-14 220150.png No direct matching rear or outer-side photographic angle

A View identification Patient Tower long outer elevation and corner orbit. No direct matching rear or outer-side photographic angle. Camera correspondence uses building features, not upload order.

B What the game shows Rows of similar dark windows, white flat roof/parapet, repeated tall end volumes, neighboring low roof and a narrow dark road loop.

C What the references show M1 supplies P5/L6 plan relationships. A024/A041 establish end strips, bands and the low entrance, but not the exact rear-face window schedule shown here. Supporting sources: A024 A041 R020.

D Required corrections UGMC-010/012 target exposed site and low-roof treatment. UGMC-013/014 target supported mass offsets/material detail only. UGMC-005/006 become directly actionable on identifiable entrance ends, not arbitrary rear bays.

E Crops and annotations Use the enlarged numbered detail plates after the pair sequence. Open G026 and the listed original references at native resolution. A satellite image is plan support, not a facade match.

F Acceptance checks Do not transplant the Women and Children ribbon elevation R043 onto this Patient Tower face; preserve unknown opening counts.

G Cross view consistency The orbit turns toward the mast and entrance after this sector; use those pairs for end-face details. Consult adjacent Pair 25 and Pair 27 for continuity. UI-covered features remain unresolved.