

 **PdM Dashboard — Engine · Alternator · Hydraulic Pump**

Two-Stage model

ET + LGBM + CatBoost

gate 0.90

inputs: pressure, current, vdc, vac

[Dashboard](#) [Window Data](#) [Glossary](#)

1 · SENSOR LOG

 Drag and drop file here
Limit 200MB per file • XLSX, CSV

Browse files

Sample dataset
Leakage_factor.xlsx

2 · MACHINE STATUS


SYSTEM STATUS
●  **Fault detected**
Leakage_factor.xlsx · 9 windows

DIAGNOSIS
● **Leakage**
Pressure pattern is consistent with a hydraulic leak....

ANOMALOUS WINDOWS
● **100%**
share beyond the healthy baseline (Stage 1)

CONFIDENCE
● **100%**
see Glossary for the per-verdict definition

3 · ALARM TREND (STAGE 1)



4 · DIAGNOSIS

Verdict share
windows assigned to each verdict

Unknown fault	0%
PumpDisplacement	0%
Leakage	100%
GeneratorFault	0%
Healthy	0%

Why this diagnosis
top deviating features
Mean deviation from the healthy baseline, in robust standard units (σ). What the model actually reacted to.

- vdc_speclow — 36,515 σ below healthy
- current_speclow — 20,223 σ below healthy
- vdc_speccen — 2,249 σ above healthy
- current_dstd — 1,673 σ below healthy
- vdc_dstd — 1,512 σ below healthy



● Healthy ● GeneratorFault ● Leakage ● PumpDisplacement ● Unknown fault

5 - EVENT LOG

window	t_start [s]	event
1	0.1	Cro

6 - SENSOR SIGNALS

> Cleaned signals vs healthy baseline band

Channel status

Pump pressure
✓ OK

Load current
✓ OK

DC bus voltage
✓ OK

Alternator AC voltage
✓ OK

Export report

- ↓ Verdict summary (.txt)
- ↓ Window table (.csv)

Model trust panel

> Validation evidence (leave-one-run-out)

> ▶ Live replay (demo) — stream this log window by window