Microplastic Detection in Water

Microscopy analysis report - trained YOLOv8 fragment detector

Analysis: 2026-10-03T16:15:25.380141+00:00 | ID: 61fdd081a2c748c786927a9927314717

Input: test_sample_01.jpg

Particles: 4 | Mean confidence: 66.1% | Image count band: Low

Class counts: {'microplastic_fragment': 4}

Inference: 100.3 ms | Threshold: 0.25

Calibration: Not provided; dimensions are in pixels.




Image-based predictions identify suspected microplastic fragments. They do not chemically confirm plastic or polymer composition. Count bands are project-defined image indicators, not water-quality or safety standards.

Count bands: Low < 10, Moderate 10-29, High >= 30. These thresholds are configurable demonstrations.

Detected particles

ID	Dataset class	Confidence	Width (px)	Height (px)
1	microplastic fragment	82.5%	31.8	31.1
2	microplastic fragment	78.9%	68.4	68.1
3	microplastic fragment	57.0%	52.1	82.8
4	microplastic fragment	46.0%	58.7	41.7